



Status Report

FALCON 900 S/N 037 N38TV

OWNER: THRESHOLD VENTURES, INC.
ADDRESS: 8700 EAST VISTA BONITA DRIVE
 SCOTTSDALE AZ 85255
PHONE: 480 209 5107
FAX:

OPERATOR: THRESHOLD VENTURES, INC.
ADDRESS: 8700 EAST VISTA BONITA DRIVE
 SCOTTSDALE AZ 85255
PHONE: 480 209 5107
FAX:

ANALYST: MARIO LEMITE
EMAIL: MLEMITE@CAMPSYSTEMS.COM

1-631-619-4554 (DIRECT)
 877-411-CAMP (2267) (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; Time Accrued/Remaining: CHECKED; Without Relation: CHECKED; Sort By: TASK NUMBER;

AIRCRAFT SERIAL/REGNO: 037/N38TV **MODEL:** FALCON 900 **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	11-JAN-1988	8049.2 A/C HRS	as of 29-JUN-2023	A/C HRS	as of ___/___/___
INSERVICE DATE:	07-JUN-1988	3853 AFL	as of 29-JUN-2023	AFL	as of ___/___/___
		3756 APH	as of 18-JAN-2023	APH	as of ___/___/___

APU SERIAL/PART: P-139/3800188-1 **MODEL:** GTCP36-150(F) **MANUFACTURER:** HONEYWELL

INSTALLED ON 11-JAN-1988		LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS		3756 APU HRS	as of 18-JAN-2023	APU HRS	as of ___/___/___
0 APUS		6024 APUS	as of 18-JAN-2023	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P-97161C/3075330-3 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 14-JAN-2016		LAST ACTUALS		CURRENT ACTUAL	
7039 ENG. HRS	7386.3 A/C HRS	7701.9 ENG. HRS	as of 29-JUN-2023	ENG. HRS	as of ___/___/___
3533 ENC		3720 ENC	as of 29-JUN-2023	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P-97147C/3075330-3 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 11-DEC-2009		LAST ACTUALS		CURRENT ACTUAL	
5863.4 ENG. HRS	6063.8 A/C HRS	7848.8 ENG. HRS	as of 29-JUN-2023	ENG. HRS	as of ___/___/___
2938 ENC		3735 ENC	as of 29-JUN-2023	ENC	as of ___/___/___

ENGINE NO. 3 SERIAL/PART: P-97149C/3075330-3 **MODEL:** TFE731-5BR-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 01-JAN-2005		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	7677.3 ENG. HRS	as of 29-JUN-2023	ENG. HRS	as of ___/___/___
0 ENC		3704 ENC	as of 29-JUN-2023	ENC	as of ___/___/___



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05-08-00-200-800-05	12 M/800 FH INSPECTION								
+									
	PKG 5	MOS	12	+1m		21-JUN-2023	21-JUN-2024	21-JUL-2024	339 d
		HRS/MSC	800	+40		8047.2	8847.2	8887.2	798
	REF: See Workcard	AFL				3851			
<hr/>									
05-08-00-200-800-06	24 M/1600 FH INSPECTION								
+									
	PKG 6	MOS	24	+1m		21-JUN-2023	21-JUN-2025	21-JUL-2025	704 d
		HRS/MSC	1600	+40		8047.2	9647.2	9687.2	1598
	REF: MPD 05-10-00	AFL				3851			
<hr/>									
05-08-00-200-800-07	36 M/2400 FH INSPECTION								
+									
	PKG 7	MOS	36	+1m		21-JUN-2023	21-JUN-2026	21-JUL-2026	1069 d
		HRS/MSC	2400	+40		8047.2	10447.2	10487.2	2398
	REF: MPD 05-10-00	AFL				3851			
<hr/>									
05-08-00-200-800-15	12 M INSPECTION								
+									
	PKG 15	MOS	12	+1m		21-JUN-2023	21-JUN-2024	21-JUL-2024	339 d
		HRS/MSC				8047.2			
	REF: MPD 05-10-00	AFL				3851			
<hr/>									
05-08-00-200-800-16	24 M INSPECTION								
+									
	PKG 16	MOS	24	+1m		21-JUN-2023	21-JUN-2025	21-JUL-2025	704 d
		HRS/MSC				8047.2			
	REF: MPD 05-10-00	AFL				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-08-00-200-800-17 +	36 M INSPECTION								
	PKG 17	MOS	36	+1m		21-JUN-2023	21-JUN-2026	21-JUL-2026	1069 d
	REF: MPD 05-10-00	HRS/MSC AFL				8047.2 3851			
05-08-00-200-800-21 +	1B INSPECTION								
	PKG 21	MOS	1600	+40	-5.5	11-NOV-2015	8950	8990	900.8
	REF: MPD 05-10-00	HRS/MSC AFL				7355.5 3656			
05-08-00-200-800-22 +	2B INSPECTION								
	PKG 22	MOS	3200	+40	-21.6	27-APR-2009	8950	8990	900.8
	REF: MPD 05-10-00	HRS/MSC AFL				5771.6 2919			
05-08-00-200-800-23 +	3B INSPECTION								
	PKG 23	MOS	4800	+40		03-SEP-2003	8950	8990	900.8
	REF: MPD 05-10-00	HRS/MSC AFL				4150 2320			
05-08-00-200-800-24 +	4B INSPECTION								
	PKG 24	MOS	N/A			11-JAN-1988			
	REF: MPD 05-10-00	HRS/MSC AFL				0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-08-00-200-800-31	1C INSPECTION								
+									
	PKG 31	MOS	72	+2m		21-JUN-2023	21-JUN-2029	21-AUG-2029	2165 d
		HRS/MSC				8047.2			
	REF: MPD 05-10-00	AFL	3750			3851	7601		3748
05-08-00-200-800-32	2C INSPECTION								
+									
	PKG 32	MOS	144	+2m		21-JUN-2023	21-JUN-2035	21-AUG-2035	4356 d
		HRS/MSC				8047.2			
	REF: MPD 05-10-00	AFL	7500			3851	11351		7498
05-08-00-200-800-33	3C INSPECTION								
+									
	PKG 33	MOS	N/A			15-MAY-2006			
		HRS/MSC				4812.3			
	REF: MPD 05-10-00	AFL				2521			
05-08-00-200-800-34	4C INSPECTION								
+									
	PKG 34	MOS	N/A			21-JUL-2012			
		HRS/MSC				6985.1			
	REF: MPD 05-10-00	AFL				3525			
ENGINE NO. 1 Model : TFE731-5BR Serial # P-97161C Part # 3075330-3									
057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION								
+									
	PKG 1	MOS	150	+100		27-JUN-2023	(7851.9) 8199.2	7951.9	150
		HRS/MSC				7701.9			
	REF: LMM 72-00-00	ENC				3720			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
057120 +	NO. 1 ENGINE - 300 TO 400 HOUR INSPECTION								
	PKG 2	MOS				31-MAY-2022			
		HRS/MSC	300	+100		7619.7	(7919.7) 8267	8019.7	217.8
	REF: LMM 72-00-00	ENC				3694			
057140	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION								
	PKG 4	MOS				14-JAN-2016			
		HRS/MSC	800	+50		7039	(7839) 8186.3	7889	137.1
	REF: See Workcard	ENC				3533			
057160 +	NO. 1 ENGINE - 1000 TO 1400 HOUR INSPECTION								
	PKG 0	MOS				14-JAN-2016			
		HRS/MSC	1200	+200		7039	(8239) 8586.3	8439	537.1
	REF: See Workcard	ENC				3533			
057170	NO. 1 ENGINE - 1200 TO 1650 HOUR INSPECTION								
	PKG 5	MOS				14-JAN-2016			
		HRS/MSC	1600	+50		7039	(8639) 8986.3	8689	937.1
	REF: See Workcard	ENC				3533			
ENGINE NO. 2 Model : TFE731-5BR Serial # P-97147C Part # 3075330-3									
057110 +	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION								
	PKG 1	MOS				27-JUN-2023			
		HRS/MSC	150	+100		7848.8	(7998.8) 8199.2	8098.8	150
	REF: LMM 72-00-00	ENC				3735			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
057120 +	NO. 2 ENGINE - 300 TO 400 HOUR INSPECTION								
	PKG 2	MOS				31-MAY-2022			
		HRS/MSC	300	+100		7766.6	(8066.6) 8267	8166.6	217.8
	REF: LMM 72-00-00	ENC				3709			
057140	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION								
	PKG 4	MOS				19-NOV-2019			
		HRS/MSC	800	+50		7604.8	(8404.8) 8605.2	8454.8	556
	REF: See Workcard	ENC				3661			
057160 +	NO. 2 ENGINE - 1000 TO 1400 HOUR INSPECTION								
	PKG 0	MOS				16-JUL-2012			
		HRS/MSC	1200	+200		6784.7	(7984.7) 8185.1	8184.7	135.9
	REF: See Workcard	ENC				3407			
057170	NO. 2 ENGINE - 1200 TO 1650 HOUR INSPECTION								
	PKG 5	MOS				28-NOV-2018			
		HRS/MSC	1600	+50		7474.6	(9074.6) 9275	9124.6	1225.8
	REF: See Workcard	ENC				3626			
ENGINE NO. 3 Model : TFE731-5BR Serial # P-97149C Part # 3075330-3									
057110 +	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION								
	PKG 1	MOS				27-JUN-2023			
		HRS/MSC	150	+100		7677.3	(7827.3) 8199.2	7927.3	150
	REF: LMM 72-00-00	ENC				3704			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
057120 +	NO. 3 ENGINE - 300 TO 400 HOUR INSPECTION								
	PKG 2	MOS				31-MAY-2022			
		HRS/MSC	300	+100		7595.1	(7895.1) 8267	7995.1	217.8
	REF: LMM 72-00-00	ENC				3678			
057140	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION								
	PKG 4	MOS				28-NOV-2018			
		HRS/MSC	800	+50		7303.1	(8103.1) 8475	8153.1	425.8
	REF: See Workcard	ENC				3595			
057160 +	NO. 3 ENGINE - 1000 TO 1400 HOUR INSPECTION								
	PKG 0	MOS				21-OCT-2011			
		HRS/MSC	1200	+200		6419.5	(7619.5) 7991.4	7819.5	TOL
	REF: See Workcard	ENC				3274			
057170	NO. 3 ENGINE - 1200 TO 1650 HOUR INSPECTION								
	PKG 5	MOS				21-OCT-2011			
		HRS/MSC	1600	+50		6419.5	(8019.5) 8391.4	8069.5	342.2
	REF: See Workcard	ENC				3274			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE <small>(ENG/APU) A/C</small>	MAX LIMIT	TIME REMAINING
CHAPTER 00	INFORMATION									
6892-161220	REVIEW MPD CHAPTER 5 REVISION 7	MOS								(EBT)
REQUIREMENT CHANGE FORMS	REF: See Workcard	HRS/MSC - AFL								
<hr/>										
6892-170901	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 8-01 DATED SEPTEMBER 2017	MOS								(EBT)
REQUIREMENT CHANGE FORMS	REF: RCF 6892	HRS/MSC - AFL								
<hr/>										
6892-170901A	REVIEW FALCON 900B MAINTENANCE MANUAL 5-40 REVISION 23 - SEPTEMBER 2017	MOS								(EBT)
REQUIREMENT CHANGE FORMS	REF: RCF 6892	HRS/MSC - AFL								
<hr/>										
6892-180322	REVIEW DOCUMENT DISCREPANCIES 1-307191003 AND 1-303915014	MOS								
REQUIREMENT CHANGE FORMS	REF: RCF 6892	HRS/MSC - AFL								
<hr/>										
6892-180405	REVIEW FALCON 900 MPD DOCUMENT DISCREPANCY 1-310597778 CHANGES	MOS								
	REF: RCF 6892	HRS/MSC - AFL								
<hr/>										
6892-180406	REVIEW FALCON 900B MPD DOCUMENT DISCREPANCY 1-311875774	MOS								
	REF: RCF 6892	HRS/MSC - AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
ADS-B OUT STATUS	AUTOMATIC DEPENDENT SURVEILLANCE-BROADCAST (ADS-B) OUT COMPLIANT									
	CONFIRMATION FROM FLIGHT AWARE DATA	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF:	AFL		N:0			0			

APU Model : GTCP36-150(F) Serial # P-139 Part # 3800188-1

A009-170607	APU - REVIEW GTCP36-150(F) MM REV 7									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF A009	HRS/MSC	-							
		APUS								

A009-171115	APU - REVIEW GTCP-150(F) EMM TR 49-42									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF A009	HRS/MSC	-							
		APUS								

A009-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	HRS/MSC	-							
		APUS								

ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3

E006-170921	NO. 1 ENGINE - REVIEW SB TFE731-72-3263 REV 16									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	HRS/MSC	-							
		ENC								

ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
E006-170921	NO. 2 ENGINE - REVIEW SB TFE731-72-3263 REV 16									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	HRS/MSC -								
		ENC								

ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3										
E006-170921	NO. 3 ENGINE - REVIEW SB TFE731-72-3263 REV 16									
		MOS					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E006	HRS/MSC -								
		ENC								

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS										
05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE									
24.270		MOS					11-JAN-1988			
	REF: AMM 05-50-00-100-801	HRS/MSC A/R					0			
		AFL					0			
		APH					0			
05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT									
09.010		MOS					11-JAN-1988			
	REF: AMM 05-50-00-200-801	HRS/MSC A/R					0			
		AFL					0			
		APH					0			
05-50-00-200-802-01	CHECK AFTER HAILSTORM									
51.110		MOS					11-JAN-1988			
	REF: AMM 05-50-00-200-802	HRS/MSC A/R					0			
		AFL					0			
		APH					0			
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE									
51.100		MOS					11-JAN-1988			
	REF: AMM 05-50-00-200-803	HRS/MSC A/R					0			
		AFL					0			
		APH					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING									
32.880	REF: AMM 05-50-00-200-804	MOS HRS/MSC AFL APH	A/R				11-JAN-1988 0 0 0			
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE									
51.120	REF: AMM 05-50-00-200-805	MOS HRS/MSC AFL APH	A/R				11-JAN-1988 0 0 0			
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS									
	REF: AMM 05-50-00-200-806	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
05-50-00-200-809-01	INSPECTION AFTER SLAT OPERATION IN OVERSPEED CONDITION									
57.305	REF: AMM 05-50-00-200-809	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
05-50-00-200-810-01	INSPECTION AFTER FLAP OPERATION IN OVERSPEED CONDITION									
57.310	REF: AMM 05-50-00-200-810	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION									
	REF: AMM 05-50-00-200-812	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING - CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE.	MOS						11-JAN-1988		
	REF: AMM 05-50-00-200-813	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-200-817-01	CHECK AFTER COLLISION WITH FOREIGN OBJECT	MOS						11-JAN-1988		
	REF: AMM 05-50-00-200-817	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-200-822-01	OPERATION TO BE PERFORMED AFTER VMO/MMO EXCEEDANCE	MOS						11-JAN-1988		
	REF: AMM 05-50-00-200-822	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-200-823-01	CHECK OF THE SLATS AFTER OVERHEATING - LH WING	MOS						11-JAN-1988		
	REF: AMM 05-50-00-200-823	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-200-823-02	CHECK OF THE SLATS AFTER OVERHEATING - RH WING	MOS						11-JAN-1988		
	REF: AMM 05-50-00-200-823	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-620-801-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS	MOS						11-JAN-1988		
	REF: AMM 05-50-00-620-801	HRS/MSC	A/R					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR A/C OPERATING IN COLD WEATHER									
05.020	REF: AMM 05-50-00-620-803	MOS HRS/MSC AFL APH	A/R					11-JAN-1988 0 0 0		
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES									
51.130	REF: AMM 05-50-00-620-804	MOS HRS/MSC AFL APH	A/R					11-JAN-1988 0 0 0		
05-50-00-620-805-01	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION - CRITERIA TO DEFINE A/C AT RISK OF FUEL CONTAMINATION									
	REF: AMM 05-50-00-620-805	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
05-50-00-620-805-02	SPECIFIC MAINTENANCE TO PREVENT FUEL CONTAMINATION									
	REF: AMM 05-50-00-620-805	MOS HRS/MSC AFL	A/R					11-JAN-1988 0 0		
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION									
	REF: AMM 05-50-00-700-801	MOS HRS/MSC AFL APH	A/R					11-JAN-1988 0 0 0		
05-50-00-700-803-01	CHECK AFTER FIRE EXTINGUISHER PERCUSSION									
20.050	REF: See Workcard	MOS HRS/MSC AFL APH	A/R					11-JAN-1988 0 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-806	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
05-50-00-700-807-01	CHECK AFTER LANDING ON A DRY AND DIRTY RUNWAY	MOS						11-JAN-1988		
32.850	REF: AMM 05-50-00-700-807	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING	MOS						11-JAN-1988		
32.840	REF: AMM 05-50-00-700-808	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
05-50-00-700-810-01	CHECK AFTER SAND CONDITION - CHECKS AFTER EACH FLIGHT THROUGH SAND	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-810	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-700-810-02	CHECK AFTER SAND CONDITION - FURTHER INSPECTIONS IN CASE OF SAND DEPOSITS AFTER FLIGHT THROUGH SAND	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-810	HRS/MSC	O/C					0		
		AFL						0		
05-50-00-700-810-03	CHECK AFTER SAND CONDITION - PERIODIC INSPECTIONS AND CHECKS AFTER FLIGHTS THROUGH SAND	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-810	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-700-810-04	CHECK AFTER SAND CONDITION - INSPECTIONS AND CHECKS AFTER A SANDSTORM (AIRCRAFT PARKED)	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-810	HRS/MSC	O/C					0		
		AFL						0		
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-818	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-822	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-700-822-02	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - FURTHER CHECKS AFTER A FLIGHT THROUGH A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-822	HRS/MSC	O/C					0		
		AFL						0		
05-50-00-700-822-03	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS AFTER EXCEPTIONAL FLIGHT THROUGH A HIGH VOLCANIC ASH CONCENTRATION AREA	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-822	HRS/MSC	O/C					0		
		AFL						0		
05-50-00-700-822-04	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A LOW OR MEDIUM VOLCANIC ASH CONCENTRATION AREA	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-822	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
05-50-00-700-822-05	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES - OPERATIONS AND CHECKS ON AN AIRCRAFT PARKED IN A HEAVY VOLCANIC ASH FALLOUT AREA	MOS						11-JAN-1988		
	REF: AMM 05-50-00-700-822	HRS/MSC	O/C					0		
		AFL						0		
05-50-00-730-801-01	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - FILTER CLOGGING	MOS						11-JAN-1988		
29.290	REF: AMM 05-50-00-730-801	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
05-50-00-730-801-02	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - PUMP FAILURE	MOS						11-JAN-1988		
29.300	REF: AMM 05-50-00-730-801	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION/STOP AFTER TROUBLESHOOTING	MOS						11-JAN-1988		
	REF: AMM 05-50-00-730-802	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-860-801-01	CHECK AND PREPARATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE	MOS						11-JAN-1988		
	REF: AMM 05-50-00-860-801	HRS/MSC	A/R					0		
		AFL						0		
05-50-00-910-801-01 (s)	AIRCRAFT CHECK FLIGHT							PKG		
	PKG 31	MOS	72	+2m				21-JUN-2023		
51.070	REF: AMM 05-50-00-910-801	HRS/MSC						8047.2		
		AFL	3750					3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 05-60-00-200-801-01	BASIC INSPECTION									
05.010		MOS	12	+1m		-254	27-JUN-2023	17-OCT-2023	17-NOV-2023	91 d (+31)
	REF: See Workcard	HRS/MSC	400	+40			8049.2	8449.2	8489.2	400 (+40)
		AFL					3853			
05-60-00-200-801-03	BASIC INSPECTION - GROUND SERVICING CHECKS									
05.010		MOS	12	+1m		-254	27-JUN-2023	17-OCT-2023	17-NOV-2023	91 d (+31)
	REF: See Workcard	HRS/MSC	400	+40			8049.2	8449.2	8489.2	400 (+40)
		AFL					3853			

ENGINE NO. 1	Model : TFE731-5BR-1C	Serial # P-97161C	Part # 3075330-3
E006-170919	NO. 1 ENGINE - REVIEW TFE731-5BR LMM TR 72-232		
		MOS	(EBT)
		HRS/MSC -	
REQUIREMENT CHANGE FORMS	REF: RCF E006	ENC	

ENGINE NO. 2	Model : TFE731-5BR-1C	Serial # P-97147C	Part # 3075330-3
E006-170919	NO. 2 ENGINE - REVIEW TFE731-5BR LMM TR 72-232		
		MOS	(EBT)
		HRS/MSC -	
REQUIREMENT CHANGE FORMS	REF: RCF E006	ENC	

ENGINE NO. 3	Model : TFE731-5BR-1C	Serial # P-97149C	Part # 3075330-3
E006-170919	NO. 3 ENGINE - REVIEW TFE731-5BR LMM TR 72-232		
		MOS	(EBT)
		HRS/MSC -	
REQUIREMENT CHANGE FORMS	REF: RCF E006	ENC	

CHAPTER 07 LIFTING AND SHORING



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
07-10-00-910-801-01	JACKING THE AIRCRAFT	MOS						11-JAN-1988		
	REF: AMM 07-10-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
07-10-00-910-802-01	JACKING THE AIRCRAFT BY ONE LANDING GEAR LEG	MOS						11-JAN-1988		
	REF: AMM 07-10-00-910-802	HRS/MSC	O/C					0		
		AFL						0		
07-10-00-910-804-01	JACKING THE AIRCRAFT BY ONE MLG LEG WITH A WHEEL RAMP	MOS						11-JAN-1988		
	REF: AMM 07-10-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
07-10-00-910-805-01	JACKING THE AIRCRAFT FOR DIMENSIONAL CHECKS AND/OR REPAIR OF THE MLG BALL-JOINT BEARING BORES	MOS						11-JAN-1988		
	REF: AMM 07-10-00-910-805	HRS/MSC	O/C					0		
		AFL						0		
07-10-00-910-810-01	HOISTING THE COMPLETE AIRCRAFT	MOS						11-JAN-1988		
	REF: AMM 07-10-00-910-810	HRS/MSC	O/C					0		
		AFL						0		
CHAPTER 08 LEVELING AND WEIGHING										
08-10-00-910-801-01	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON WHEELS	MOS						11-JAN-1988		
	REF: AMM 08-10-00-910-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
08-10-00-910-801-02	WEIGHING THE AIRCRAFT - WEIGHING THE AIRCRAFT ON JACKS REF: AMM 08-10-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
08-20-00-910-801-01	LEVELING THE AIRCRAFT REF: AMM 08-20-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
CHAPTER 09 TOWING AND TAXING										
09-10-00-910-801-01	TOWING THE AIRCRAFT WITH A TOWBAR REF: AMM 09-10-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
09-10-00-910-802-01	TOWING THE AIRCRAFT WITH A TOWBARLESS TOWING VEHICLE REF: AMM 09-10-00-910-802	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
09-10-00-910-805-01	TOWING THE AIRCRAFT WITH A TOWBARLESS REMOTE CONTROL TUG REF: AMM 09-10-00-910-805	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
09-10-00-910-810-01	DEBOGGING THE AIRCRAFT REF: AMM 09-10-00-910-810	MOS HRS/MSC AFL APH	A/R					11-JAN-1988 0 0 0		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS	MOS						11-JAN-1988		
	REF: AMM 10-10-00-200-801	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
10-10-00-550-801-10	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - NON-FLYING AND NON-STORED PERIOD	MOS						11-JAN-1988		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C					0		
		AFL						0		
10-10-00-550-801-11	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 2 MONTHS	MOS						11-JAN-1988		
20.090	REF: AMM 10-10-00-550-801	HRS/MSC	O/C					0		
		AFL						0		
		APH						0		
10-10-00-550-801-12	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - ADDITIONAL OPERATIONS FOR STORAGE FROM 2 TO 12 MONTHS	MOS						11-JAN-1988		
20.090	REF: AMM 10-10-00-550-801	HRS/MSC	O/C					0		
		AFL						0		
		APH						0		
10-10-00-550-801-13	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - STORAGE OF THE AIRCRAFT FOR A PERIOD OF 12 TO 18 MONTHS	MOS						11-JAN-1988		
	REF: AMM 10-10-00-550-801	HRS/MSC	O/C					0		
		AFL						0		
10-10-00-550-801-14	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY MONTH	MOS						11-JAN-1988		
20.090	REF: AMM 10-10-00-550-801	HRS/MSC	O/C					0		
		AFL						0		
		APH						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
10-10-00-550-801-15	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 2 MONTHS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				11-JAN-1988 0 0 0			
10-10-00-550-801-16	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - PERIODIC CHECKS EVERY 6 MONTHS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				11-JAN-1988 0 0 0			
10-10-00-550-801-17	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AT THE END OF THE 2 MONTHS OR LESS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				11-JAN-1988 0 0 0			
10-10-00-550-801-18	STORAGE / RETURN TO SERVICE OF THE AIRCRAFT - REMOVAL FROM STORAGE AFTER MORE THAN 2 MONTHS									
20.090	REF: AMM 10-10-00-550-801	MOS HRS/MSC AFL APH	O/C				11-JAN-1988 0 0 0			
10-10-00-910-801-01	PARKING THE AIRCRAFT									
	REF: AMM 10-10-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
10-20-00-910-801-01	MOORING THE AIRCRAFT									
	REF: AMM 10-20-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL									
10.010		MOS					11-JAN-1988			
	REF: AMM 10-20-00-910-802	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
CHAPTER 11 PLACARDS AND MARKINGS										
11-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE INTERNAL AND EXTERNAL MARKINGS AND PLACARDS						PKG			
	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 11-00-00-210-801	HRS/MSC					8047.2			
		AFL	3750				3851			
11-00-00-960-801-01	REPLACEMENT OF THE SELF-ADHESIVE PLACARDS									
		MOS					11-JAN-1988			
	REF: AMM 11-00-00-960-801	HRS/MSC	O/C				0			
		AFL					0			
11-00-00-960-802-01	REPLACEMENT OF THE DECALS									
		MOS					11-JAN-1988			
	REF: AMM 11-00-00-960-802	HRS/MSC	O/C				0			
		AFL					0			
11-00-00-960-803-01	REPLACEMENT OF THE STERLING TAPE FOR PIPE MARKINGS									
		MOS					11-JAN-1988			
	REF: AMM 11-00-00-960-803	HRS/MSC	O/C				0			
		AFL					0			
CHAPTER 20 STANDARD PRACTICES - AIRFRAME										
20-00-00-910-801-01	GENERAL MAINTENANCE AND SAFETY PRECAUTIONS									
20.000		MOS					30-APR-1996			
	REF: AMM 20-00-00-910-801	HRS/MSC	A/R				1950			
		AFL					1399			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-00-00-910-803-01	USE OF THE AIRCRAFT MAINTENANCE PROCEDURES									
20.010	REF: AMM 20-00-00-910-803	MOS HRS/MSC AFL APH	A/R				11-JAN-1988 0 0 0			
20-00-00-910-805-01	MAINTENANCE INSTRUCTION SPECIFIC TO S/N 1									
20.030	REF: AMM 20-00-00-910-805	MOS HRS/MSC AFL APH	N/A				11-JAN-1988 0 0 0			
20-00-00-910-806-01	MAINTENANCE INSTRUCTION SPECIFIC TO S/N 2									
20.040	REF: AMM 20-00-00-910-806	MOS HRS/MSC AFL APH	N/A				11-JAN-1988 0 0 0			
20-00-00-910-807-01	GENERAL GUIDANCE AND SAFETY PRECAUTIONS FOR DANGEROUS PRODUCTS									
	REF: AMM 20-00-00-910-807	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-00-00-910-810-01	GENERAL SAFETY PRECAUTIONS FOR PARTS CONTAINING ASBESTOS									
	REF: AMM 20-00-00-910-810	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-10-00-280-801-01	GENERAL INSTRUCTIONS FOR 3D SCANNING									
	REF: AMM 20-10-00-280-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-20-00-900-801-01	REMOVAL / INSTALLATION OF THE ELECTRICAL BONDING BRAIDS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-20-00-900-801	AFL		N:0				0		
20-20-00-910-801-01	ELECTRICAL BONDING PRINCIPLES AND CHECK									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-20-00-910-801	AFL						0		
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT									
51.090		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM 20-30-00-330-801	AFL						0		
		APH						0		
20-30-00-910-803-01	ELECTROSTATIC DISCHARGE (ESD) STANDARD PRACTICES									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-30-00-910-803	AFL						0		
20-30-00-910-804-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITH POLYURETHANE GASKET)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-30-00-910-804	AFL						0		
20-30-00-910-805-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITHOUT O-RING)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-30-00-910-805	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-30-00-910-806-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ANTENNAS (WITH O-RING)	MOS						11-JAN-1988		
	REF: AMM 20-30-00-910-806	HRS/MSC	O/C					0		
		AFL						0		
20-30-00-910-808-01	GENERAL INSTRUCTIONS FOR REMOVAL / INSTALLATION OF ACCESS PANELS AND OPENING / CLOSING OF SERVICE DOORS	MOS						11-JAN-1988		
	REF: AMM 20-30-00-910-808	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-802-01	CLEANING OF COCKPIT EQUIPMENT AND INTERIOR FURNISHING	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-802	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-804-01	CLEANING OF THE WING AND AIR INTAKE LEADING EDGES	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-804	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-01	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE LH FEEDER TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-02	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE RH FEEDER TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-31-00-100-806-03	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE CTR FEEDER TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-04	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE LH CENTER-WING TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-05	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE RH CENTER-WING TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-06	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE REAR TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-07	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE LH WING TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-806-08	CLEANING OF FUEL TANKS AND EQUIPMENT - CLEANING OF THE RH WING TANK	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-806	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-31-00-100-807-01	DRY CLEANING OF THE AIRCRAFT EXTERIOR	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-807	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-808-01	WET CLEANING OF THE AIRCRAFT EXTERIOR - CLEANING THE AIRCRAFT EXTERIOR WITH CONVENTIONAL EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-808	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-808-02	WET CLEANING OF THE AIRCRAFT EXTERIOR - CLEANING THE AIRCRAFT EXTERIOR WITH HIGH-PRESSURE EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-808	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-100-809-01	DRY ICE CLEANING	MOS						11-JAN-1988		
	REF: AMM 20-31-00-100-809	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR	MOS						11-JAN-1988		
20.060	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-350-801-01	BRIGHTENING/POLISHING OF CLADDED ALUMINUM SURFACES OR STAINLESS STEEL SURFACES - BRIGHTENING	MOS						11-JAN-1988		
	REF: AMM 20-31-00-350-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-31-00-350-801-02	BRIGHTENING/POLISHING OF CLADDED ALUMINUM SURFACES OR STAINLESS STEEL SURFACES - POLISHING	MOS						11-JAN-1988		
	REF: AMM 20-31-00-350-801	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-910-801-01	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - DE-ICING TREATMENT	MOS						11-JAN-1988		
20.070	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-910-801-02	ON-GROUND DE-ICING AND ANTI-ICING TREATMENT - ANTI-ICING TREATMENT	MOS						11-JAN-1988		
	REF: AMM 20-31-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-31-00-910-803-01	USE OF PUROGENE	MOS						11-JAN-1988		
	REF: AMM 20-31-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-360-803-01	PROVISIONAL REPAIR OF LEAKY SCREWS OR RIVETS ON FUEL TANKS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-360-803	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-360-804-01	HELIUM LEAK TEST OF FUEL TANKS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-360-804	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-32-00-360-805-01	AIR AND FUEL LEAK TEST OF THE FUEL TANK - AIR LEAK TEST	MOS						11-JAN-1988		
	REF: AMM 20-32-00-360-805	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-360-805-02	AIR AND FUEL LEAK TEST OF THE FUEL TANK - FUEL LEAK TEST	MOS						11-JAN-1988		
	REF: AMM 20-32-00-360-805	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-390-801-01	BASIC SEALING METHODS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-390-801	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-390-802-01	BASIC SEALING METHOD USING PR1422, PR1431, PR1432, PR1436 AND PR1750 SEALANTS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-390-802	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-910-801-01	APPLICATION OF FILLERLU	MOS						11-JAN-1988		
	REF: AMM 20-32-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-910-802-01	ACCEPTANCE CRITERIA FOR HYDRAULIC LEAKS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-910-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-32-00-910-803-01	ACCEPTANCE CRITERIA FOR DAMAGE TO FUEL TANK SEALANT	MOS						11-JAN-1988		
	REF: AMM 20-32-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-32-00-910-804-01	BONDING OF SEALS ON RETAINERS	MOS						11-JAN-1988		
	REF: AMM 20-32-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
20-33-00-300-801-01	LAGGING OF AIR CONDITIONING LINES	MOS						11-JAN-1988		
	REF: AMM 20-33-00-300-801	HRS/MSC	O/C					0		
		AFL						0		
20-33-00-300-803-01	REPAIR OF A T40 HYDRAULIC PIPE USING PERMASWAGE UNION FITTINGS	MOS						11-JAN-1988		
	REF: AMM 20-33-00-300-803	HRS/MSC	O/C					0		
		AFL						0		
20-33-00-300-804-01	TEMPORARY REPAIR OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS	MOS						11-JAN-1988		
	REF: AMM 20-33-00-300-804	HRS/MSC	A/R					0		
		AFL						0		
		APH						0		
20-33-00-300-805-01	REPAIR OF THE F1024 FLEXIBLE WATER HOSES	MOS						11-JAN-1988		
	REF: AMM 20-33-00-300-805	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-33-00-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PIPES PN SN-UNKNOWN REF: AMM 20-33-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
20-33-00-900-803-01	REMOVAL / INSTALLATION OF THE FOAM INSULATION ON THE WATER PIPES PN SN-UNKNOWN REF: AMM 20-33-00-900-803	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
20-33-00-900-806-01	REMOVAL / INSTALLATION OF THE FUEL PIPES PN SN-UNKNOWN REF: AMM 20-33-00-900-806	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
20-33-00-910-801-01	ACCEPTANCE CRITERIA FOR HOSES AND PIPES REF: AMM 20-33-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-33-00-910-802-01	STRAPPING OF THE OXYGEN CAPILLARY TUBE REF: AMM 20-33-00-910-802	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-33-00-960-803-01	REPLACEMENT OF THE MINCO TYPE HEATERS ON WATER PIPES REF: AMM 20-33-00-960-803	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-35-01-910-801-01	GENERAL INSTRUCTIONS APPLICABLE TO CABLES - INSPECTION, DAMAGE CRITERIA, LUBRICATION	MOS						11-JAN-1988		
	REF: AMM 20-35-01-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-35-02-910-802-01	GENERAL INSTRUCTIONS AND REPAIR APPLICABLE TO "TELEFORCE" FLEXIBLE CONTROL CABLES	MOS						11-JAN-1988		
	REF: AMM 20-35-02-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-35-02-910-803-01	TORQUE INSTRUCTIONS APPLICABLE TO "TELEFORCE" CONTROL CABLE NUTS	MOS						11-JAN-1988		
	REF: AMM 20-35-02-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-41-00-400-801-01	INSTALLATION OF HARRISON COUPLINGS ON PIPING	MOS						11-JAN-1988		
	REF: AMM 20-41-00-400-801	HRS/MSC	O/C					0		
		AFL						0		
20-41-00-400-803-01	INSTALLATION OF COUPLINGS EQUIPPED WITH A SNAP RING	MOS						11-JAN-1988		
	REF: AMM 20-41-00-400-803	HRS/MSC	O/C					0		
		AFL						0		
20-41-00-900-801-01	REMOVAL / INSTALLATION OF WIGGINS W991 COUPLINGS	MOS						11-JAN-1988		
	PN									
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 20-41-00-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-41-00-900-803-01	REMOVAL / INSTALLATION OF WIG-O-FLEX COUPLINGS - WIG-O-FLEX 3601, 3605, 3615, 3655, 3665, 3751 AND 3753 COUPLINGS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-803	AFL		N:0				0		
20-41-00-900-809-01	REMOVAL / INSTALLATION OF FLEXINOX CLAMPS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-809	AFL		N:0				0		
20-41-00-900-811-01	REMOVAL / INSTALLATION OF JANITROL AND RIGID BESTOBELL CLAMPS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-811	AFL		N:0				0		
20-41-00-900-813-01	REMOVAL / INSTALLATION OF MARMAN TYPE "18276" AND "234-538" CLAMPS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-813	AFL		N:0				0		
20-41-00-900-814-01	REMOVAL / INSTALLATION OF GENERAL CONNECTOR HEAT-EXPANSION COUPLINGS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-814	AFL		N:0				0		
20-41-00-900-815-01	REMOVAL / INSTALLATION OF SEMCA COUPLINGS									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-815	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-41-00-900-816-01	REMOVAL / INSTALLATION OF TYPES BA 2755, BA 2755-1, BA 4005 FLEXIBLE COUPLINGS AND FLEXIBLE PIPING									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-816	AFL		N:0				0		
20-41-00-900-817-01	REMOVAL / INSTALLATION OF BRIGGS COUPLINGS ON OXYGEN LINE									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-00-900-817	AFL		N:0				0		
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-41-00-910-801	AFL						0		
20-41-00-910-802-01	GENERAL INSTRUCTIONS FOR USE OF QUICK-DISCONNECT SELF-BLANKING COUPLINGS									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-41-00-910-802	AFL						0		
20-41-00-960-802-01	REPLACEMENT OF THE TIGHTENING CONES									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 20-41-00-960-802	AFL						0		
20-41-05-900-801-01	TECHNICAL STANDARD ST78651									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 20-41-05-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-41-05-900-802-01	TECHNICAL STANDARD ST78652 PN SN-UNKNOWN REF: AMM 20-41-05-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
20-41-05-900-803-01	TECHNICAL STANDARD ST78653 PN SN-UNKNOWN REF: AMM 20-41-05-900-803	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
20-41-05-900-804-01	TECHNICAL STANDARD ST78654 PN SN-UNKNOWN REF: AMM 20-41-05-900-804	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
20-41-05-900-805-01	TECHNICAL STANDARD ST78650 PN SN-UNKNOWN REF: AMM 20-41-05-900-805	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
20-41-05-900-806-01	TECHNICAL STANDARD ST78750 PN SN-UNKNOWN REF: AMM 20-41-05-900-806	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
20-41-05-900-807-01	TECHNICAL STANDARD ST78751 PN SN-UNKNOWN REF: AMM 20-41-05-900-807	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-42-01-960-802-01	REPLACEMENT OF THE LOCKWIRES REF: AMM 20-42-01-960-802	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-42-01-960-803-01	REPLACEMENT OF THE SNAP WIRES REF: AMM 20-42-01-960-803	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-42-01-960-804-01	REPLACEMENT OF THE SAFE-T CABLES REF: AMM 20-42-01-960-804	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-43-00-900-801-01	REMOVAL / INSTALLATION OF L'HOTELLIER P710 LOCKS PN SN-UNKNOWN REF: AMM 20-43-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
20-43-00-910-801-01	STANDARD TORQUES APPLICABLE TO THE AIRCRAFT REF: AMM 20-43-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-43-00-910-804-01	FASTENERS STANDARD PRACTICES REF: AMM 20-43-00-910-804	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-02-910-801-01	TECHNICAL STANDARD ST38260	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-802-01	TECHNICAL STANDARD ST38150	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-803-01	TECHNICAL STANDARD ST33186	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-805-01	TECHNICAL STANDARD ST38145	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-805	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-807-01	TECHNICAL STANDARD ST38476	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-807	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-809-01	TECHNICAL STANDARD ST38471	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-809	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-02-910-810-01	TECHNICAL STANDARD ST38472	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-810	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-812-01	TECHNICAL STANDARD ST33188	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-812	HRS/MSC	O/C					0		
		AFL						0		
20-43-02-910-813-01	TECHNICAL STANDARD ST39840	MOS						11-JAN-1988		
	REF: AMM 20-43-02-910-813	HRS/MSC	O/C					0		
		AFL						0		
20-43-05-910-801-01	TECHNICAL STANDARD ST39584	MOS						11-JAN-1988		
	REF: AMM 20-43-05-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-43-05-910-802-01	TECHNICAL STANDARD ST33731	MOS						11-JAN-1988		
	REF: AMM 20-43-05-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-200-801-01	INSPECTION OF THE RIVETS	MOS						11-JAN-1988		
	REF: AMM 20-43-06-200-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-06-910-801-01	TECHNICAL STANDARD ST35780	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-802-01	TECHNICAL STANDARD ST35770	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-803-01	TECHNICAL STANDARD ST35050	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-804-01	TECHNICAL STANDARD ST35072	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-804	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-805-01	TECHNICAL STANDARD ST35053	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-805	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-806-01	TECHNICAL STANDARD ST35067	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-806	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-06-910-807-01	TECHNICAL STANDARD ST35073	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-807	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-808-01	TECHNICAL STANDARD ST35656	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-808	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-809-01	TECHNICAL STANDARD ST35655	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-809	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-810-01	TECHNICAL STANDARD ST35760	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-810	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-811-01	TECHNICAL STANDARD ST35750	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-811	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-812-01	TECHNICAL STANDARD NAS1097 - SPECIFIC 4-MM DIA. RIVETS	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-812	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-06-910-813-01	TECHNICAL STANDARD ST35731	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-813	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-814-01	TECHNICAL STANDARD ST35075	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-814	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-815-01	TECHNICAL STANDARD ST35110	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-815	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-816-01	TECHNICAL STANDARD ST35070	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-816	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-817-01	TECHNICAL STANDARD ST35660	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-817	HRS/MSC	O/C					0		
		AFL						0		
20-43-06-910-818-01	TECHNICAL STANDARD ST35661	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-818	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-43-06-910-819-01	TECHNICAL STANDARD ST35666	MOS						11-JAN-1988		
	REF: AMM 20-43-06-910-819	HRS/MSC	O/C					0		
		AFL						0		
20-43-09-910-801-01	REMOVAL / INSTALLATION OF HI-LOK, HI-LITE AND HI-TIGUE FASTENERS	MOS						11-JAN-1988		
	REF: AMM 20-43-09-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-43-09-910-802-01	REMOVAL / INSTALLATION OF HELI-COIL THREAD INSERTS	MOS						11-JAN-1988		
	REF: AMM 20-43-09-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-44-00-960-801-01	REPLACEMENT OF THE VELCRO TYPE STRAPS	MOS						11-JAN-1988		
	REF: AMM 20-44-00-960-801	HRS/MSC	O/C					0		
		AFL						0		
20-45-00-960-802-01	REPLACEMENT OF THE SARMA-ADR BEARINGS AND BALL-JOINTS OR EQUIVALENT	MOS						11-JAN-1988		
	REF: AMM 20-45-00-960-802	HRS/MSC	O/C					0		
		AFL						0		
20-45-00-960-803-01	REPLACEMENT OF HUB-MOUNTED BEARINGS	MOS						11-JAN-1988		
	REF: AMM 20-45-00-960-803	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-49-00-300-801-01	REPAIR / MODIFICATION OF INSULATION BLANKETS	MOS						11-JAN-1988		
	REF: AMM 20-49-00-300-801	HRS/MSC	O/C					0		
		AFL						0		
20-49-00-910-801-01	BONDING OF INSULATION MATERIAL	MOS						11-JAN-1988		
	REF: AMM 20-49-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
20-49-00-960-801-01	REPLACEMENT OF THE SELF-ADHESIVE INSULATION	MOS						11-JAN-1988		
	REF: AMM 20-49-00-960-801	HRS/MSC	O/C					0		
		AFL						0		
20-50-00-300-801-01	TREATMENT OF SCRATCHES ON BRIGHTENED SURFACES	MOS						11-JAN-1988		
	REF: AMM 20-50-00-300-801	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-801-01	APPLICATION OF ALODINE	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-801	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-802-01	GENERAL PAINTING INSTRUCTIONS - COMPLETE PAINT RENEWAL	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-802-02	GENERAL PAINTING INSTRUCTIONS - PAINT TOUCH-UPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-802	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-803-01	APPLICATION OF PU66 CELOMER PAINT SCHEME	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-803	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-804-01	APPLICATION OF CELOGLISS PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-804	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-805-01	APPLICATION OF MAP AERO STATIC F PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-805	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-806-01	APPLICATION OF BOLICONE M4 BOLLORE PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-806	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-807-01	APPLICATION OF ANTI-VAPOR TOP COAT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-807	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-809-01	APPLICATION OF TYPE 5014 AND 5015 POLYURETHANE PRIMERS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-809	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-810-01	APPLICATION OF NEXTEL PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-810	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-811-01	APPLICATION OF SINGLE-COAT DIRECT-ADHERENCE PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-811	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-812-01	APPLICATION OF JET GLO PAINT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-812	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-813-01	APPLICATION OF THE PAINT SCHEME ON COMPOSITE COMPONENTS	MOS						11-JAN-1988		
20.080	REF: See Workcard	HRS/MSC	A/R					0		
		AFL						0		
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)	MOS						11-JAN-1988		
	D22801100-11-/-13	HRS/MSC	O/C					0		
	U86							0		
	REF: AMM 20-60-00-370-816	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF) D22802100-11-/-13 U38 REF: AMM 20-60-00-370-816	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5) D22805100-6 U88 REF: AMM 20-60-00-370-816	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5) D22806100-6 U39 REF: AMM 20-60-00-370-816	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF) D22811200-14-/-16-19 U71 REF: AMM 20-60-00-370-816	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-60-00-370-817-01	APPLICATION OF PREKOTE REF: AMM 20-60-00-370-817	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
20-60-00-370-818-01	APPLICATION OF THE PPG EXTERIOR UNDERCOAT REF: AMM 20-60-00-370-818	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-819-01	APPLICATION OF ANTI-SLIP FINISH ON HIGH VOC PAINT SCHEMES	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-819	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-821-01	APPLICATION OF MAPAERO WATER-BASED PAINT SCHEME	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-821	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-823-01	APPLICATION OF SOL-GEL PRODUCTS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-823	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-826-01	APPLICATION OF SHERWIN-WILLIAMS LOW VOC UNDERCOATS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-826	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-827-01	APPLICATION OF TOP COATS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-827	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-828-01	POLISHING OF PPG CA8800 EXTERIOR FINISH	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-828	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-829-01	APPLICATION OF PPG INTERIOR PAINT SCHEME	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-829	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-830-01	REACTIVE POLYMER TREATMENT FOR EXTERNAL SURFACES	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-830	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-832-01	APPLICATION / REMOVAL OF ANTI-CORROSION PROTECTION	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-832	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-835-01	POLISHING OF JETGLO EXPRESS 840 SERIES FINISH	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-835	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-01	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - LH HORIZONTAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-02	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - RH HORIZONTAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-836-03	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - VERTICAL STABILIZER LEADING EDGE ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-04	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - LH ENGINE PYLONS ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-05	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - RH ENGINE PYLONS ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-08	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - ATC, DME AND VHF ANTENNAS ADHESIVE ANTI-EROSION STRIPS	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-09	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - NOSE CONE ADHESIVE ANTI-EROSION BOOT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-836-10	REMOVAL / INSTALLATION OF THE ADHESIVE ANTI-EROSION PROTECTIONS - SATCOM ANTENNA FAIRING ADHESIVE ANTI-EROSION BOOT	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-836	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-00-370-837-01	GENERAL INSTRUCTIONS FOR SURFACE PREPARATION	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-837	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-838-01	GENERAL INSTRUCTIONS FOR MASKING OF AREAS - MASKING INSTALLATION	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-838	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-370-838-02	GENERAL INSTRUCTIONS FOR MASKING OF AREAS - MASKING REMOVAL	MOS						11-JAN-1988		
	REF: AMM 20-60-00-370-838	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-970-801-01	MEASUREMENT OF PAINT THICKNESS ON COMPOSITE COMPONENTS USING A PAINT BORER	MOS						11-JAN-1988		
	REF: AMM 20-60-00-970-801	HRS/MSC	O/C					0		
		AFL						0		
20-60-00-970-802-01	MEASUREMENT OF PAINT THICKNESS ON COMPOSITE COMPONENTS USING A RADIOELECTRIC GAGE	MOS						11-JAN-1988		
	REF: AMM 20-60-00-970-802	HRS/MSC	O/C					0		
		AFL						0		
20-60-10-370-801-01	GENERAL RULES FOR APPLICATION OF CORROSION INHIBITOR COMPOUND	MOS						11-JAN-1988		
	REF: AMM 20-60-10-370-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-60-10-370-802-01	CORROSION PROTECTION AND TREATMENT ON FLIGHT CONTROL EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 20-60-10-370-802	HRS/MSC	O/C					0		
		AFL						0		
20-70-00-230-801-01	FLUORESCENT PENETRANT DETECTION OF CRACKS	MOS						11-JAN-1988		
	REF: AMM 20-70-00-230-801	HRS/MSC	O/C					0		
		AFL						0		
20-70-00-250-801-01	EDDY-CURRENT DETECTION OF CRACKS	MOS						11-JAN-1988		
	REF: AMM 20-70-00-250-801	HRS/MSC	O/C					0		
		AFL						0		
20-70-00-250-802-01	EDDY-CURRENT INSPECTION OF BORES	MOS						11-JAN-1988		
	REF: AMM 20-70-00-250-802	HRS/MSC	O/C					0		
		AFL						0		
20-70-00-250-803-01	CHECK FOR LOCAL OVERHEAT BY ELECTRICAL CONDUCTIVITY MEASUREMENT ON ALUMINUM ALLOYS	MOS						11-JAN-1988		
	REF: AMM 20-70-00-250-803	HRS/MSC	O/C					0		
		AFL						0		
20-70-00-270-801-01	ULTRASONIC INSPECTION OF COMPOSITE AND METALLIC COMPONENTS	MOS						11-JAN-1988		
	REF: AMM 20-70-00-270-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-70-00-270-802-01	ULTRASONIC MEASUREMENT OF PMMA PARTS REF: AMM 20-70-00-270-802	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-70-00-280-801-01	TAP TESTING REF: AMM 20-70-00-280-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-70-00-280-803-01	SETTINGS FOR NON-DESTRUCTIVE TESTS REF: AMM 20-70-00-280-803	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-90-00-200-801-01	INSPECTION / CHECK OF ELECTRICAL AND ELECTRONIC SYSTEMS REF: AMM 20-90-00-200-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
20-90-05-900-801-01	REMOVAL / INSTALLATION OF THE WIRING FEED-THROUGH FITTINGS PN SN-UNKNOWN REF: AMM 20-90-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
20-91-00-910-801-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH A-INITIAL) REF: AMM 20-91-00-910-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-91-00-910-802-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH B-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-803-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH C-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-804-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH D-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-805-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH E-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-805	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-807-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH G-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-807	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-808-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH H-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-808	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-91-00-910-809-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH I-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-809	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-810-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH J-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-810	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-812-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH L-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-812	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-813-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH M-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-813	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-816-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH P-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-816	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-818-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH R-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-818	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-91-00-910-819-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH S-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-819	HRS/MSC	O/C					0		
		AFL						0		
20-91-00-910-820-01	CONNECTOR REPAIR INFORMATION (VENDORS WITH T-INITIAL)	MOS						11-JAN-1988		
	REF: AMM 20-91-00-910-820	HRS/MSC	O/C					0		
		AFL						0		
20-94-00-760-802-01	MEASUREMENT OF THE VHF COAXIAL CABLES INSULATION RESISTANCE	MOS						11-JAN-1988		
	REF: AMM 20-94-00-760-802	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-300-801-01	REPAIR OF OPTICAL FIBER CABLES	MOS						11-JAN-1988		
	REF: AMM 20-95-00-300-801	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-400-801-01	INSTALLATION OF ENGINE ELECTRIC WIRING ON RIGID PIPES	MOS						11-JAN-1988		
	REF: AMM 20-95-00-400-801	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-910-801-01	INSERTION AND EXTRACTION OF A WIRE FITTED WITH A LOCK-IN CONTACT	MOS						11-JAN-1988		
	REF: AMM 20-95-00-910-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-95-00-910-802-01	THREADED TERMINAL CONNECTIONS AND TIGHTENING TORQUES	MOS						11-JAN-1988		
	REF: AMM 20-95-00-910-802	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-910-803-01	GENERAL INSTRUCTIONS FOR INSTALLATION OF CF- OR DR-TYPE CABLES	MOS						11-JAN-1988		
	REF: AMM 20-95-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-910-804-01	GENERAL INSTRUCTIONS FOR FILOTEX A0861 / A1861 AND FILECA 1741 KAPTON-INSULATED ELECTRICAL CABLES	MOS						11-JAN-1988		
	REF: AMM 20-95-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
20-95-00-960-801-01	REPLACEMENT OF A FUEL GAGE CUT-OFF SOCKET CONNECTOR, DEUTSCH 9602 OR SN620 TYPE OR EQUIVALENT	MOS						11-JAN-1988		
	REF: AMM 20-95-00-960-801	HRS/MSC	O/C					0		
		AFL						0		
20-95-03-300-801-01	REPAIR OF THE PILOT AND COPILOT AND FRONT WINDSHIELD WIRES	MOS						11-JAN-1988		
	REF: AMM 20-95-03-300-801	HRS/MSC	O/C					0		
		AFL						0		
CHAPTER 21 AIR CONDITIONING										
21-00-00-790-801	LEAK CHECK OF THE AIR CONDITIONING SYSTEM	MOS						11-JAN-1988		
	REF: AMM 21-00-00-790-801	HRS/MSC	A/R					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-00-00-790-801-01	LEAK CHECK OF THE AIR CONDITIONING SYSTEM	MOS					11-JAN-1988			
	REF: AMM 21-00-00-790-801	HRS/MSC O/C					0			
		AFL					0			
21-00-00-960-801-01	DISCARD OF THE AIR CONDITIONING SYSTEM WIGGINS COUPLING SEALS	MOS					11-JAN-1988			
	REF: AMM 21-00-00-960-801	HRS/MSC O/C					0			
		AFL					0			
21-20-00-900-801-01	REMOVAL / INSTALLATION OF THE CABIN AIR-CONDITIONING ELECTRIC VALVE - CABIN AIR CONDITIONING ELECTRIC VALVE (3HN2)	MOS					11-JAN-1988			
21.140	BYLB51003E	HRS/MSC O/C		N:0			0			
	76	AFL					0			
	REF: AMM 21-20-00-900-801						0			
21-20-01-350-801-01	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - LH FLOW LIMITER (L501HN)	MOS					02-AUG-2017			
21.020	2742A020100	HRS/MSC	4800	+3%			7552.9	12352.9	12496.9	4303.7 (+144)
OVERHAUL	023	AFL					3710			
	REF: AMM 21-20-01-350-801	APH					3578			
21-20-01-350-801-02	RESTORATION OF THE FLOW LIMITERS (OVERHAUL) - RH FLOW LIMITER (R501HN)	MOS					02-AUG-2017			
21.020	2742A020100	HRS/MSC	4800	+3%			7552.9	12352.9	12496.9	4303.7 (+144)
OVERHAUL	297	AFL					3710			
	REF: AMM 21-20-01-350-801	APH					3578			
21-20-01-900-801-01	REMOVAL / INSTALLATION OF THE FLOW LIMITERS - LH FLOW LIMITER (L501HN)	MOS					08-FEB-2000			
21.020	2742A020100	HRS/MSC O/C		N:168 O:0			3067			
	023	AFL		O:0			1929			
	REF: AMM 21-20-01-900-801			O:0						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-20-01-900-801-02	REMOVAL / INSTALLATION OF THE FLOW LIMITERS - RH FLOW LIMITER (R501HN)									
21.020	2742A020100 297 REF: AMM 21-20-01-900-801	MOS HRS/MSC AFL	O/C	N:105 O:0 O:0 O:0			08-FEB-2000 3067 1929			
21-22-19-900-801-01	REMOVAL / INSTALLATION OF THE GASPER PRESSURE CONTROL VALVE - GASPER PRESSURE REGULATING VALVE (508HN)									
21.040	B17DA1002 202 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
21-23-01-710-801-01	OPERATIONAL TEST OF THE CABIN / COCKPIT ISOLATION VALVE									
	REF: AMM 21-23-01-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 21-28-00-710-801-01 (s)	OPERATIONAL TEST OF THE EFIS VENTILATION SYSTEM						PKG			
21.175	PKG 21 REF: AMM 21-28-00-710-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
21-29-00-550-801-01	INHIBITION / ACTIVATION OF THE BATTERY COOLING SUPPLY									
	REF: AMM 21-29-00-550-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
21-30-00-790-801-01	GROUND CHECK OF CABIN SEALING									
	REF: AMM 21-30-00-790-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-30-00-790-802-01 (s)	IN-FLIGHT CHECK OF CABIN SEALING						PKG			
21.180	PKG 21	MOS					11-NOV-2015			
	REF: AMM 21-30-00-790-802	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
21-30-00-790-803	PRESSURIZATION LEAK TEST									
		MOS					11-JAN-1988			
	REF: AMM 21-30-00-790-803	HRS/MSC	A/R				0			
		AFL					0			
21-30-00-790-803-01	PRESSURIZATION LEAK TEST WITH EXTERNAL SOURCE OF AIR - TEST WITH THE AIRCRAFT IN MAINTENANCE CONFIGURATION									
		MOS					11-JAN-1988			
	REF: AMM 21-30-00-790-803	HRS/MSC	O/C				0			
		AFL					0			
21-30-00-790-803-02	PRESSURIZATION LEAK TEST WITH EXTERNAL SOURCE OF AIR - TEST WITH THE AIRCRAFT AT THE ENGINE RUN-UP AREA									
		MOS					11-JAN-1988			
	REF: AMM 21-30-00-790-803	HRS/MSC	O/C				0			
		AFL					0			
21-30-01-900-801-01	REMOVAL / INSTALLATION OF THE AUTOMATIC PRESSURIZATION CONTROLLER - AUTOMATIC PRESSURIZATION CONTROLLER (3HP)									
21.280	22250J032100	MOS					11-FEB-2011			
	120	HRS/MSC	O/C				6561.2			
	REF: AMM 21-30-01-900-801	AFL					3315			
+ 21-30-09-720-801-01	FUNCTIONAL TEST OF THE ALTITUDE ALERT OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (7HP)									
21.290	720-15900-413	MOS					27-JUN-2023			
	1279	HRS/MSC	4000	+3%			8049.2	12049.2	12169.2	4000 (+120)
	REF: AMM 21-30-09-720-801	AFL					3853			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-30-09-900-801-01	REMOVAL / INSTALLATION OF THE TRIPLE INDICATOR - TRIPLE INDICATOR (7HP)									
21.290	720-15900-413 1279 REF: AMM 21-30-09-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-JAN-2003 3996.7 2278			
21-31-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PNEUMATIC ACTUATOR (506HP)						PKG			
	PKG 21 REF: AMM 21-31-00-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
21-31-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM - PRESSURE RELIEF VALVE (507HP)						PKG			
	PKG 21 REF: AMM 21-31-00-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
+ 21-31-01-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM						PKG			
21.150	PKG 21 REF: AMM 21-31-01-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
21-31-09-350-801-01	RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (3HQ)									
	AE1103A01 00828 REF: AMM 21-31-09-350-801	MOS HRS/MSC AFL APH	N/A							
21-31-09-350-802-01	RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS AND CHECK OF BRUSHES) - NOSE CONE FAN (3HQ)									
	AE1103A01 00828 REF: AMM 21-31-09-350-802	MOS HRS/MSC AFL APH	N/A							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-31-09-710-801-01	OPERATIONAL TEST OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (3HQ)									
21.160	REF: AMM 21-31-09-710-801	MOS HRS/MSC AFL	O/C					25-JAN-2008 5308.9 2695		
21-31-09-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE VENTILATION FAN - NOSE CONE FAN (3HQ)									
21.160	REF: AMM 21-31-09-900-801	AE1103A01 00828 AFL	MOS HRS/MSC O/C AFL					R:9 R:0 R:0 28-NOV-2018 7675 3744		
21-31-25-220-801-01	CHECK / REPLACEMENT OF THE NOSE CONE VENTILATION FAN BRUSHES (TECHNOFAN P/N EVT608A) - NOSE CONE FAN (3HQ)									
	REF: AMM 21-31-25-220-801	AE1103A01 00828 AFL APH	MOS HRS/MSC N/A AFL							
21-31-33-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE BUTTERFLY VALVE PROXIMITY SWITCH - NOSE CONE BUTTERFLY VALVE PROXIMITY SWITCH (6HQ)									
	REF: AMM 21-31-33-900-801	PN SN-UNKNOWN AFL	MOS HRS/MSC O/C AFL					N:0 N:0 N:0 11-JAN-1988 0 0		
+ 21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM									
21.200	REF: AMM 21-32-00-710-801	PKG 21 MOS HRS/MSC AFL	1600 +40					PKG 11-NOV-2015 7355.5 3656		
+ 21-32-00-710-802-01 (s)	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY									
21.190	REF: AMM 21-32-00-710-802	PKG 21 MOS HRS/MSC AFL	1600 +40					PKG 11-NOV-2015 7355.5 3656		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-32-00-790-801-01 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L13FL) PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
21-32-00-790-801-02 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R13FL) PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
21-32-00-790-801-03 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - LH STAND-BY STATIC PRESSURE PROBE (L501FL) PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
21-32-00-790-801-04 (s)	LEAK CHECK AROUND THE STATIC PRESSURE PROBES - RH STAND-BY STATIC PRESSURE PROBE (R501FL) PKG 16 REF: AMM 21-32-00-790-801	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
21-32-06-200-801-01	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF ELECTROPNEUMATIC VALVE (4HP) 2097D010400 101 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640	+3%			27-JUN-2023 8049.2 3853	9689.2	9738.4	1640 (+49.2)
21-32-06-200-801-02	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CLEANING OF PNEUMATIC VALVE (5HP) 2099E010400 120 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640	+3%			27-JUN-2023 8049.2 3853	9689.2	9738.4	1640 (+49.2)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-32-06-200-801-03	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF ELECTROPNEUMATIC VALVE (4HP)									
21.260	2097D010400 101 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				27-JUN-2023 8049.2 3853	9689.2		1640
+ 21-32-06-200-801-03A	CHECK ELECTROPNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)									
21.260 MANDATORY 5-40	2097D010400 101 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				27-JUN-2023 8049.2 3853	9689.2		1640
+ 21-32-06-200-801-04	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE TIGHTNESS OF PNEUMATIC VALVE (5HP)									
21.270	2099E010400 120 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				27-JUN-2023 8049.2 3853	9689.2		1640
+ 21-32-06-200-801-04A	CHECK PNEUMATIC VALVE OVERPRESSURE TIGHTNESS (MANDATORY 5-40)									
21.270 MANDATORY 5-40	2099E010400 120 REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				27-JUN-2023 8049.2 3853	9689.2		1640
21-32-06-200-801-05	INSPECTION / CHECK OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (975HP) AND (976HP)									
21.530	REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	1640				27-JUN-2023 8049.2 3853	9689.2		1640
21-32-06-200-801-05A	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY 5-40)									
21.530 MANDATORY 5-40	REF: AMM 21-32-06-200-801	MOS HRS/MSC AFL	7500				27-JUN-2023 8049.2 3853	15549.2		7500



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-32-06-720-801-01	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - ELECTROPNEUMATIC VALVE (4HP) 2097D010400 101 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	4840				07-FEB-2011 6561.2 3315	11401.2		3352
+ 21-32-06-720-801-01A	FUNCTIONAL TEST ELECTROPNEUMATIC VALVE (MANDATORY 5-40) 2097D010400 101 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	14300				07-FEB-2011 6561.2 3315	20861.2		12812
	21.260 MANDATORY 5-40									
21-32-06-720-801-02	FUNCTIONAL TEST OF THE ELECTROPNEUMATIC AND PNEUMATIC VALVES - PNEUMATIC VALVE (5HP) 2099E010400 120 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	4840				07-FEB-2011 6561.2 3315	11401.2		3352
+ 21-32-06-720-801-02A	FUNCTIONAL TEST PNEUMATIC VALVE (MANDATORY 5-40) 2099E010400 120 REF: AMM 21-32-06-720-801	MOS HRS/MSC AFL	14300				07-FEB-2011 6561.2 3315	20861.2		12812
	21.270 MANDATORY 5-40									
+ 21-32-06-720-802-01 (s)	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - ELECTROPNEUMATIC VALVE (4HP) PKG 31 REF: AMM 21-32-06-720-802	MOS HRS/MSC AFL	72 3750				PKG 21-JUN-2023 8047.2 3851			
+ 21-32-06-720-802-02 (s)	FUNCTIONAL TEST OF THE CABIN ALTITUDE LIMITATION - PNEUMATIC VALVE (5HP) PKG 31 REF: AMM 21-32-06-720-802	MOS HRS/MSC AFL	72 3750				PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-32-06-900-801-01	REMOVAL / INSTALLATION OF THE ELECTROPNEUMATIC VALVE - ELECTROPNEUMATIC VALVE (4HP)									
21.260	2097D010400 101 REF: AMM 21-32-06-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-FEB-2011 6561.2 3315			
21-32-06-900-802-01	REMOVAL / INSTALLATION OF THE PNEUMATIC VALVE - PNEUMATIC VALVE (5HP)									
21.270	2099E010400 120 REF: AMM 21-32-06-900-802	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			07-FEB-2011 6561.2 3315			
+ 21-32-17-200-801-01 (s)	INSPECTION OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - PRESSURE-RELIEF VALVE (L505HP)						PKG			
21.350	PKG 21 REF: AMM 21-32-17-200-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
+ 21-32-17-200-801-02 (s)	INSPECTION OF THE BAGGAGE COMPARTMENT PRESSURE RELIEF VALVES - PRESSURE-RELIEF VALVE (R505HP)						PKG			
21.360	PKG 21 REF: AMM 21-32-17-200-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
+ 21-32-33-710-801-01 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION VALVE - BAGGAGE COMPARTMENT ISOLATION VALVE (24HP)						PKG			
21.120	PKG 5 REF: AMM 21-32-33-710-801	MOS HRS/MSC AFL	12 800	+1m +40			21-JUN-2023 8047.2 3851			
+ 21-32-37-200-801-01 (s)	INSPECTION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - NEGATIVE PRESSURE RELIEF VALVES (L508HP) / (R508HP)						PKG			
21.370	PKG 21 REF: AMM 21-32-37-200-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 21-32-37-720-801-01	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - LH NEGATIVE PRESSURE RELIEF VALVE (L508HP)									
21.370	2827A01 172 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			27-JUN-2023 8049.2 3853	12049.2	12169.2	4000 (+120)
+ 21-32-37-720-801-02	FUNCTIONAL TEST OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - RH NEGATIVE PRESSURE RELIEF VALVE (R508HP)									
21.380	2827A01 170 REF: AMM 21-32-37-720-801	MOS HRS/MSC AFL	4000	+3%			27-JUN-2023 8049.2 3853	12049.2	12169.2	4000 (+120)
21-32-37-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - LH NEGATIVE PRESSURE RELIEF VALVE (L508HP)									
21.370	2827A01 172 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C		N:0		11-JAN-1988 0 0			
21-32-37-900-801-02	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVES - RH NEGATIVE PRESSURE RELIEF VALVE (R508HP)									
21.380	2827A01 170 REF: AMM 21-32-37-900-801	MOS HRS/MSC AFL	O/C		N:0		11-JAN-1988 0 0			
+ 21-32-41-200-801-01 (s)	INSPECTION OF THE NICOTINE FILTER CARTRIDGE - CABIN AIR FILTER (504HP)									
21.250	PKG 31 REF: AMM 21-32-41-200-801	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
+ 21-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WATER REINJECTION SYSTEM									
21.440	PKG 22 REF: AMM 21-52-00-710-801	MOS HRS/MSC AFL	3200	+40			PKG 27-APR-2009 5771.6 2919			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-52-05-350-801	RESTORATION OF THE TURBOCOOLER (OVERHAUL)	MOS					11-JAN-1988			
	REF: AMM 21-52-05-350-801	HRS/MSC	A/R				0			
		AFL					0			
21-52-05-350-801-01	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - TURBOCOOLER (504HN)	MOS		I:0			11-FEB-2009			
21.410	3269B0102A	HRS/MSC	3000	+3%			5698.4	8698.4	8788.4	649.2 (+90)
OVERHAUL	136	AFL		I:0			2880			
	REF: AMM 21-52-05-350-801									
+ 21-52-05-610-801-01	TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL TOP-UP	MOS					27-JUN-2023			
	REF: AMM 21-52-05-610-801	HRS/MSC	200				8049.2	8249.2		200
		AFL					3853			
21-52-05-610-801-02 (s)	TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL DRAINING AND REFILLING	MOS	12	+1m			PKG			
	PKG 5	HRS/MSC	800	+40			21-JUN-2023			
	REF: AMM 21-52-05-610-801	AFL					8047.2			
							3851			
21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - TURBOCOOLER (504HN)	MOS								
	REF: GENERIC NO REF	HRS/MSC	O/C				(EBT)			
		AFL								
21-52-05-900-801	REMOVAL / INSTALLATION OF THE TURBOCOOLER	MOS		N:0			11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 21-52-05-900-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-52-05-900-801-01	REMOVAL / INSTALLATION OF THE TURBOCOOLER - TURBOCOOLER (504HN)									
21.410	3269B0102A 136 REF: AMM 21-52-05-900-801	MOS HRS/MSC AFL	H/T	N:252 O:0 N:5698.4 O:0 N:2880 O:0			11-FEB-2009 5698.4 2880			
+ 21-52-09-210-802-01	GENERAL VISUAL INSPECTION OF THE ECU HEAT EXCHANGER GRID									
21.410	REF: AMM 21-52-09-210-802	MOS HRS/MSC AFL	O/C				17-OCT-2017 7585.5 3720			
21-52-17-900-801-01	REMOVAL / INSTALLATION OF THE HP WATER SEPARATOR - HP WATER SEPARATOR (505HN)									
21.420	8903D04 00551 REF: AMM 21-52-17-900-801	MOS HRS/MSC AFL	O/C	N:15 N:0 N:0			16-JUL-2012 6985.1 3525			
21-52-18-100-801-01	CLEANING OF THE HP WATER SEPARATOR FILTER - HP WATER SEPARATOR (505HN)									
21.420	REF: AMM 21-52-18-100-801	MOS HRS/MSC AFL	24 1200	+1m +40	-41		30-NOV-2022 8031.4 3845	20-OCT-2024 9231.4	20-NOV-2024 9271.4	460 d (+31) 1182.2 (+40)
21-52-19-200-801	INSPECTION / CHECK OF THE LP WATER SEPARATOR COMPONENTS									
	REF: AMM 21-52-19-200-801	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
21-52-19-200-801-01 (s)	INSPECTION / CHECK OF THE LP WATER SEPARATOR COMPONENTS - LP WATER SEPARATOR (506HN)									
21.430	PKG 15 REF: AMM 21-52-19-200-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-52-21-350-801	RESTORATION OF THE TURBOFAN (OVERHAUL)	MOS						11-JAN-1988		
	REF: AMM 21-52-21-350-801	HRS/MSC	A/R					0		
		AFL						0		
21-52-21-350-801-01	RESTORATION OF THE TURBOFAN (OVERHAUL) - TURBOFAN (23HN)	MOS		I:0				05-OCT-2009		
21.400	TVT107-28H4	HRS/MSC		I:0				6001.5		
OVERHAUL	REF: AMM 21-52-21-350-801	AFL	3000	+3%	-18			3018	6000	6090
										2147 (+90)
21-52-21-710-801	OPERATIONAL TEST OF THE TURBOFAN	MOS						11-JAN-1988		
	REF: AMM 21-52-21-710-801	HRS/MSC	A/R					0		
		AFL						0		
21-52-21-710-801-01	OPERATIONAL TEST OF THE TURBOFAN	MOS						11-JAN-1988		
	REF: AMM 21-52-21-710-801	HRS/MSC	O/C					0		
		AFL						0		
21-52-21-900-801-01	REMOVAL / INSTALLATION OF THE TURBOFAN - TURBOFAN (23HN)	MOS		O:0				05-OCT-2009		
21.400	TVT107-28H4	HRS/MSC	H/T	O:0				6001.5		
	REF: AMM 21-52-21-900-801	AFL		O:0	-18			3018		
21-52-21-900-802-01	REMOVAL / INSTALLATION OF THE TURBOFAN BY-PASS ELECTRIC VALVE - TURBOFAN BY-PASS ELECTRIC VALVE (22HN)	MOS		O:0				27-JUN-2023		
21.460	BYLB51035-1	HRS/MSC	O/C	O:0				8049.2		
	REF: AMM 21-52-21-900-802	AFL		O:0				3853		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-52-33-900-801-01	REMOVAL / INSTALLATION OF THE TURBINE ANTI-ICING VALVE - TURBINE ANTI-ICING ELECTRIC VALVE (44HN)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 21-52-33-900-801	AFL		N:0			0			
21-60-00-710-801-01	OPERATIONAL TEST OF THE COCKPIT / CABIN TEMPERATURE CONTROL FUNCTION									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 21-60-00-710-801	AFL					0			
+ 21-71-01-350-801-01	RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - LH OZONE CONVERTER (L517HN)									
36.030	D20425-1	MOS					19-OCT-2006			
	0166	HRS/MSC	5000	+3%			4921.5	9921.5	10071.5	1872.3 (+150)
	REF: AMM 21-71-01-350-801	AFL					2564			
+ 21-71-01-350-801-02	RESTORATION OF THE OZONE CONVERTERS (FUNCTIONAL TEST AND CLEANING) - RH OZONE CONVERTER (R517HN)									
36.030	D20425-1	MOS					19-OCT-2006			
	0145	HRS/MSC	5000	+3%			4921.5	9921.5	10071.5	1872.3 (+150)
	REF: AMM 21-71-01-350-801	AFL					2564			
21-90-01-900-801-01	AFT AVIONICS RACK COOLING VALVE									
	PN	MOS		N:0			11-JAN-1988			
	NOT INSTALLED	HRS/MSC	O/C	N:0			0			
	REF: GENERIC CMM	AFL		N:0			0			
		APH		N:0			0			
212121	LH COLD AIR CHECK VALVE									
21.030	CYLB50713-1	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: GENERIC NO REF	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212131	RH COLD AIR CHECK VALVE CYLB50713-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
212151	AERATOR CHECK VALVE CYLB50712 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
212161	PASSENGER COMPARTMENT COLD AIR CHECK VALVE CYLB51162 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
212171	CREW COLD AIR CHECK VALVE CYLB51162 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
212181	PILOT AERATOR 2368 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
212191	COPILOT AERATOR 2368 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212251	PASSENGER COMPARTMENT AIR CONDITIONING CHECK VALVE CYLB51111	MOS					11-JAN-1988			
21.070	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			
212261	CREW AIR CONDITIONING CHECK VALVE CYLB51111	MOS					11-JAN-1988			
21.070	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			
212271	BAGGAGE COMPARTMENT ELECTRIC CHECK VALVE CYLB50414	MOS					11-JAN-1988			
21.080	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			
212281	FRONT PRECONDITIONING FLOOD DUCT PN	MOS					11-JAN-1988			
21.090	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			
212291	REAR PRECONDITIONING FLOOD DUCT PN	MOS					11-JAN-1988			
21.090	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			
212321	NOSE CONE ISOLATION RESTRICTOR VALVE PN	MOS					11-JAN-1988			
21.100	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0			0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212341	COCKPIT/CABIN SYSTEM INTERCONNECTION FLAP ASSEMBLY									
21.110	BYLB51603 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
212361	BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE									
21.120	3188-000 39 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
212381	BAGGAGE COMPARTMENT SUPPLY ELECTRIC VALVE									
21.130	B97-26-551A 20100 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
212401	COCKPIT CONDITIONING ELECTRIC VALVE									
21.140	BYLB51003 P5 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-DEC-1989 426 275			
212441	NOSE CONE THERMOSTAT									
21.150	784-756-1 155 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213101	NO. 1 ENGINE PRESSURE SUPPLY CHECK VALVE									
21.230	2506AC01 902 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
213121	NO. 2 ENGINE PRESSURE SUPPLY CHECK VALVE									
21.230	2506AC01 851 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213127	APU SUPPLY PRESSURE CHECK VALVE									
21.230	2506AC01 850 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213131	PRESSURIZATION JET PUMP									
21.240	FGFB722602A1 039 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213141	ANTI-NICOTINE FILTER									
21.250	234A0101 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213281	EMERGENCY PRESSURIZATION PANEL									
21.300	911A0301 114 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
213301	NOSE CONE PNEUMATIC ACTUATOR									
21.310	7021-200 K10145 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:9 N:0 N:0			28-NOV-2018 7675 3744			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
213321	PNEUMATIC ACTUATOR CONTROLLED VALVE									
21.320	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213331	NOSE CONE PRESSURE RELIEF VALVE									
21.330	6025-300A 46 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213351	NOSE CONE ISOLATION VALVE									
21.335	B97M19-203-1 20039 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213501	NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE									
21.350	985C63-21 54 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
213531	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE									
21.360	985C63-21 98 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
215101	PRIMARY HEAT EXCHANGER									
21.390	11-831149-1 42 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
215181	NO. 1 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE									
21.405	2506AC01 967 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
215191	NO. 2 HIGH PRESSURE/LOW PRESSURE TURBINE BRAKE CHECK VALVE									
21.405	2506AC01 849 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
215271	LOW PRESSURE WATER SEPARATOR									
21.430	B31WA3023 00829 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-APR-2013 7079.7 3562			
215301	TURBINE ANTI-ICING AMPLIFIER									
21.450	784-688 133 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
215311	TURBINE ANTI-ICING TUBING SENSOR									
21.450	784-646 261 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-OCT-1991 911 616			
215321	TURBINE ANTI-ICING ELECTRIC VALVE									
21.450	784-723-1AB 137 REF: AMM 21-52-33-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
215341	ECU OVERHEATING SENSOR									
21.460	RP129-00 427 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
215A04	WATER TRAP LP COALESCER									
	B31WA3010-053 1105021267 REF:	MOS HRS/MSC AFL	O/C	R:7 R:0 R:0			26-DEC-2020 7883.1 3800			
216101	CONDITIONING BOX									
21.470	5897-655-80-13 156 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
216111	COCKPIT THERMO RESISTOR									
21.470	HYLZ50514-31 884H REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-JAN-2002 3702 2175			
216121	CABIN THERMO RESISTOR									
21.470	HYLZ50514-31 833H REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-JAN-2002 3702 2175			
216131	COCKPIT TEMPERATURE REGULATION DUAL ELECTRIC VALVE									
21.480	BYLB51034-002E 38 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
216141	CABIN TEMPERATURE REGULATION DUAL ELECTRIC VALVE									
21.480	BYLB51226-001D 58 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
216151	COCKPIT SHEATH SENSOR									
21.490	AYLF50425 750 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
216161	CABIN SHEATH SENSOR									
21.490	AYLF50425 733 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
216171	COCKPIT THERMOSTAT									
21.500	150T346 425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
216191	CABIN THERMOSTAT									
21.500	150T346 419 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			

CHAPTER 22 AUTO FLIGHT

+ 22-10-00-710-801-01 (s)	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						PKG			
22.030	PKG 16	MOS HRS/MSC	24	+1m			21-JUN-2023 8047.2			
RVSM	REF: AMM 22-10-00-710-801	AFL					3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
22-10-01-900-801-01	REMOVAL / INSTALLATION OF THE FLIGHT GUIDANCE CONTROLLER - GUIDANCE CONTROLLER (32CA)									
22.010	7003975-805 95111873 REF: AMM 22-10-01-900-801	MOS HRS/MSC AFL	O/C					11-JUL-2017 7552.9 3710		
22-10-01-960-801-01	REPLACEMENT OF THE FLIGHT GUIDANCE CONTROLLER LAMPS									
	REF: AMM 22-10-01-960-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
+ 22-10-07-700-801-01 (s)	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - AILERON									
22.085	PKG 31 REF: AMM 22-10-07-700-801	MOS HRS/MSC AFL	72	+2m				PKG 21-JUN-2023 8047.2 3851		
+ 22-10-07-700-801-02 (s)	CHECK OF THE AUTOPILOT SERVOMOTOR CABLES AND PULLEYS - ELEVATOR									
22.085	PKG 31 REF: AMM 22-10-07-700-801	MOS HRS/MSC AFL	72	+2m				PKG 21-JUN-2023 8047.2 3851		
22-13-01-900-801-01	REMOVAL / INSTALLATION OF THE YAW DAMPER ACTUATOR - YAW DAMPER LINEAR ACTUATOR (22CA)									
22.050	7002800-914AB 87030233 REF: AMM 22-13-01-900-801	MOS HRS/MSC AFL	O/C		N:0			11-JAN-1988 0 0		
221031	PILOT AUTOPILOT COMPUTER									
22.020	7003974-719 96064491 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		R:3 R:0 R:0			04-DEC-2017 7593.7 3722		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
221041	COPILOT AUTOPILOT COMPUTER									
22.020	7003974-719 89071851 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-JUN-2019 7735.4 3764			
221101	AILERON AUTOPILOT SERVO MOTOR									
22.040	7002260-621 88122383 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 N:4307.8 R:0 N:2297 R:0			24-NOV-2004 4535.8 2438			
221121	ELEVATOR AUTOPILOT SERVO MOTOR									
22.060	7002260-621 89092840 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 N:4153.8 R:0 N:2202 R:0			24-NOV-2004 4535.8 2438			
221201	NO. 1 AUTOPILOT AILERON CABLE									
22.070	59054 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
221211	NO. 2 AUTOPILOT AILERON CABLE									
22.070	59054 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
221231	NO. 1 AUTOPILOT ELEVATOR CABLE									
22.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
221241	NO. 2 AUTOPILOT ELEVATOR CABLE									
22.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
221301	PILOT ADVISORY DISPLAY									
22.090	7003652-631 94022226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-OCT-2008 5543.9 2810			
221311	COPILOT ADVISORY DISPLAY									
22.090	7003652-631 86050348 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-JUN-2011 6671 3365			
221701	AILERON AUTOPILOT CAPSTAN									
22.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
221711	ELEVATOR AUTOPILOT CAPSTAN									
22.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			

CHAPTER 23 COMMUNICATIONS

23-00-00-200-801-01	INSPECTION / CHECK OF THE COMMUNICATION SYSTEM COMPONENTS									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 23-00-00-200-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
23-00-00-710-802-01	OPERATIONAL TEST OF THE OPTIONAL COMMUNICATION OR SECURITY SYSTEM EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 23-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
23-11-00-710-802-01	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 1 SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-11-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
23-11-00-710-802-02	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 2 SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-11-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
23-11-00-710-802-03	OPERATIONAL TEST OF THE VHF COMMUNICATION SYSTEM - VHF 3 SYSTEM (OPTION)	MOS						11-JAN-1988		
	REF: AMM 23-11-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
23-11-05-900-801-01	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 1 ANTENNA (L5RC)	MOS						11-JAN-1988		
23.020	ANV142SZA	HRS/MSC	O/C	N:0				0		
	550	AFL						0		
	REF: AMM 23-11-05-900-801							0		
23-11-05-900-801-02	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF 2 ANTENNA (R5RC)	MOS						11-JAN-1988		
23.030	S65-8280-10	HRS/MSC	O/C	N:0				0		
	424	AFL						0		
	REF: AMM 23-11-05-900-801							0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
23-11-05-900-801-03 23.035	REMOVAL / INSTALLATION OF THE VHF ANTENNAS - VHF3 ANTENNA (25RC) S65-8280-4 1476 REF: AMM 23-11-05-900-801	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
23-12-00-710-801-01	OPERATIONAL TEST OF THE HF COMMUNICATION SYSTEM - HF 1 SYSTEM REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
23-12-09-610-801-01	SERVICING OF THE HF ANTENNA COUPLER - HF1 COUPLER (L23RE) REF: AMM 23-12-09-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
23-12-09-610-801-02	SERVICING OF THE HF ANTENNA COUPLER - HF2 COUPLER (R23RE) REF: AMM 23-12-09-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
23-12-13-900-801-01 23.050	REMOVAL / INSTALLATION OF THE HF ANTENNA - HF ANTENNA (5RE) FGFB312001 SO41/231 REF: AMM 23-12-13-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
23-14-00-710-801-01	OPERATIONAL TEST OF THE UHF SYSTEM REF: AMM 23-14-00-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
23-50-00-710-801-01	OPERATIONAL TEST OF THE AUDIO INTEGRATING SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-50-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
23-50-01-820-801-01	ADJUSTMENT OF THE INTERCOM SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-50-01-820-801	HRS/MSC	O/C					0		
		AFL						0		
+ 23-60-00-760-801-01 (s)	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS						PKG			
23.090	PKG 21	MOS						11-NOV-2015		
	REF: AMM 23-60-00-760-801	HRS/MSC	1600	+40				7355.5		
		AFL						3656		
23-60-01-900-801-01	REMOVAL / INSTALLATION OF THE STATIC DISCHARGERS	PN						11-JAN-1988		
	SN-UNKNOWN	MOS			N:0			0		
	REF: AMM 23-60-01-900-801	HRS/MSC	O/C		N:0			0		
		AFL			N:0			0		
23-74-00-710-804-01	OPERATIONAL TEST OF THE SHEPERD VIGILANT SECURITY SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-74-00-710-804	HRS/MSC	O/C					0		
		AFL						0		
23-74-00-710-805-01	OPERATIONAL TEST OF THE SECURAPLANE 500 SECURITY SYSTEM	MOS						11-JAN-1988		
	REF: AMM 23-74-00-710-805	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
230A05	NOISE FUEL PUMP #1 FILTER 7700216-507 012 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-MAY-1991 807 560			
230A06	NOISE FUEL PUMP #2 FILTER 7700216-507 013 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-MAY-1991 807 560			
230A07	NOISE FUEL PUMP #3 FILTER 7700216-507 039 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-MAY-1991 807 560			
231101 23.020	NO. 1 VHF CONTROL 622-6520-005 4610 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
231111 23.030	NO. 2 VHF CONTROL 622-6520-005 4610 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				24-APR-2001 3474 2084			
231116 23.035	NO. 3 VHF CONTROL 400-0038-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231121	NO. 1 VHF TRANSCEIVER 622-6153-001 23796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
231131	NO. 2 VHF TRANSCEIVER 622-6153-001 23801 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
231136	NO. 3 VHF TRANSCEIVER 400-0023-010 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 12			
231201	NO. 1 HF COUPLER AMPLIFIER 064-1017-02 13717 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			07-SEP-2016 7448.9 3681			
231206	NO. 2 HF COUPLER AMPLIFIER 064-1017-02 11447 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			07-SEP-2016 7448.9 3681			
231211	NO. 1 HF TRANSCEIVER 064-1015-01 25855 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 N:7448.9 R:0 R:0			07-SEP-2016 7448.9 3681			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231216	NO. 2 HF TRANSCEIVER									
23.045	064-1015-01 25556 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			07-SEP-2016 7448.9 3681			
231221	NO. 1 HF CONTROL									
23.040	064-1016-03 4570 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
231226	NO. 2 HF CONTROL									
23.045	064-1016-03 3881 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-JAN-2010 6123.7 3087			
231241	HF ANTENNA TUNING VARIABLE CAPACITOR									
23.055	071-1270-01 1389 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
231711	NO. 1 VHF AUDIO INTERFACE									
23.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
231721	NO. 2 VHF AUDIO INTERFACE									
23.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
232001	SELCAL RECEIVER									
23.100	800-0012-102 00484 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2666 N:1764			21-JAN-1999 2696 1777			
232101	COMMUNICATION ANNUNCIATOR PANEL									
23.110	872TS06Y SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
233101	PILOT AUDIO CONTROL									
23.060	M1045FBAAHJB7 8612115 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
233121	COPILLOT AUDIO CONTROL									
23.060	M1045FBAAHJB7 8612129 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
233151	PUBLIC ADDRESS AMPLIFIER									
23.070	M2050C 8710215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
233201	PILOT LOUD SPEAKER									
23.080	5FUA SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-JUN-1994 1552 1081			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
233211	COPILOT LOUD SPEAKER									
23.080	5FU4-8 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
233A01	AUDIO CABIN AMPLIFIER									
	M1052A 870239 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
233A02	FM AUDIO CABIN ANTENNA									
	S65-8210-21 244 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
233A06	CASSETTE VIDEO PLAYER									
	AG-1900 NOT INST. REF:	MOS HRS/MSC AFL	O/C				22-APR-1994 1513 1054			
233A08	COMPACT DISC PLAYER									
	CDX-R88 NOT INST. REF:	MOS HRS/MSC AFL	O/C				22-APR-1994 1513 1054			
233A11	PREAMP,COMP DISC PLAYER									
	M1080A NOT INST. REF:	MOS HRS/MSC AFL	O/C				22-APR-1994 1513 1054			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
233A19	PREAMP, VIDEO SYSTEM M1080A NOT INST. REF:	MOS HRS/MSC AFL	O/C				22-APR-1994 1513 1054			
234A01	FLITEFONE ANTENNA 121-0011-000 1347 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
234A03	FLITEFONE COCKPIT CONTROL 400-0138-005 676 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
234A06	FLITEFONE COCKPIT HANDSET 400-0101-200 3281 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
234A08	FLITEFONE TRANSCEIVER 400-0125-000 1981 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
234A11	FLITEFONE CABN #1 CONTROL 400-0123-210 2067 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			

CHAPTER 24 ELECTRICAL POWER



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-00-00-220-801-01	DETAILED INSPECTION OF THE FEEDTHROUGH 11FT / 12FT	MOS						11-JAN-1988		
	REF: AMM 24-00-00-220-801	HRS/MSC	O/C					0		
		AFL						0		
24-00-00-860-801-01	ENERGIZATION / DE-ENERGIZATION OF THE AIRCRAFT SYSTEMS - ENERGIZATION FROM BATTERIES	MOS						11-JAN-1988		
	REF: AMM 24-00-00-860-801	HRS/MSC	O/C					0		
		AFL						0		
24-00-00-860-801-02	ENERGIZATION / DE-ENERGIZATION OF THE AIRCRAFT SYSTEMS - ENERGIZATION WITH ELECTRICAL GROUND POWER UNIT	MOS						11-JAN-1988		
	REF: AMM 24-00-00-860-801	HRS/MSC	O/C					0		
		AFL						0		
24-00-00-910-801-01	ELECTRICAL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS	MOS						11-JAN-1988		
	REF: AMM 24-00-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
24-20-05-710-801-01	OPERATIONAL TEST OF THE GROUND FAULT INTERRUPTER (GFI)	MOS						11-JAN-1988		
	REF: AMM 24-20-05-710-801	HRS/MSC	N/A					0		
		AFL						0		
		APH						0		
24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 1							PKG		
	PKG 21	MOS						11-NOV-2015		
	REF: AMM 24-30-00-710-801	HRS/MSC	1600	+40				7355.5		
		AFL						3656		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-30-00-710-801-02 (s)	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 2 PKG 21	MOS					PKG			
	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
24-30-00-710-801-03 (s)	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - ENGINE 3 PKG 21	MOS					PKG			
	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
24-30-00-710-801-04 (s)	OPERATIONAL TEST OF THE VOLTAGE MONITORING CIRCUITS - APU PKG 21	MOS					PKG			
	REF: AMM 24-30-00-710-801	HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
+ 24-30-00-710-802-01 (s)	OPERATIONAL TEST OF THE APU SHUTDOWN SAFETIES WITH "MASTER" APU CONTROL PKG 21	MOS					PKG			
24.180	REF: AMM 24-30-00-710-802	HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
24-30-05-900-801-01	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - GENERATOR 1 AMMETER SHUNT (1PD1) PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 24-30-05-900-801	AFL						0		
24-30-05-900-801-02	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - GENERATOR 2 AMMETER SHUNT (1PD2) PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 24-30-05-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-30-05-900-801-03	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - GENERATOR 3 AMMETER SHUNT (1PD3)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-30-05-900-801	AFL		N:0				0		
24-30-05-900-801-04	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - APU GENERATOR SHUNT (23PA)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-30-05-900-801	AFL		N:0				0		
24-30-05-900-801-05	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - BATTERY 1 AMMETER SHUNT (L1PF)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-30-05-900-801	AFL		N:0				0		
24-30-05-900-801-06	REMOVAL / INSTALLATION OF THE NEGATIVE FEEDERS SHUNT - BATTERY 2 AMMETER SHUNT (R1PF)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-30-05-900-801	AFL		N:0				0		
24-30-08-900-801-01	EMERGENCY POWER SUPPLY									
	PN	MOS		N:0				11-JAN-1988		
	NOT INSTALLED	HRS/MSC	O/C	N:0				0		
	REF: GENERIC NO REF	AFL		N:0				0		
		APH		N:0				0		
24-31-00-720-801-01	FUNCTIONAL TEST OF THE DC GENERATION SYSTEM									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-31-00-720-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-09-900-801-01	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - APU GCU (22PA)									
24.120	D22-501 5033-79 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C				24-JAN-2002 3702 2174			
24-31-09-900-801-02	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 1 (3PA1)									
24.110	D22-501 5216-22 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C				24-JAN-2002 3702 2174			
24-31-09-900-801-03	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 2 (3PA2)									
24.120	D22-501 5033-08 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C				24-JAN-2002 3702 2174			
24-31-09-900-801-04	REMOVAL / INSTALLATION OF THE GENERATOR CONTROL UNITS (GCU) - GCU 3 (3PA3)									
24.110	D22-501 5115-19 REF: AMM 24-31-09-900-801	MOS HRS/MSC AFL	O/C				24-JAN-2002 3702 2174			
24-31-13-350-801-01	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 1 STARTER-GENERATOR (L1PA)									
24.080 OVERHAUL	8060-160 1263 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%			02-MAY-2018 7638.1 3733	8878.1	8915.3	828.9 (+37.2)
24-31-13-350-801-02	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 2 STARTER-GENERATOR (M1PA)									
24.090 OVERHAUL	TRACKED ITEM 8060-160 1292 REF: AMM 24-31-13-350-801	MOS HRS/MSC AFL	1240	+3%	I:178		09-JUL-2020 7856.2 3792	8918.2	8955.4	869 (+37.2)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-13-350-801-03	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - ENGINE 3 STARTER-GENERATOR (R1PA)									
24.080	8060-160	MOS					19-DEC-2014			
OVERHAUL	2305	HRS/MSC	1240	+3%			7252.5	8492.5	8529.7	443.3 (+37.2)
	REF: AMM 24-31-13-350-801	AFL					3622			
24-31-13-350-801-04	RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (21PA)									
24.100	8060-160	MOS					09-JUL-2020			
OVERHAUL	2166	HRS/MSC					7856.2			
	REF: AMM 24-31-13-350-801	AFL					3792			
		APH	1240	+3%	1:861.3		3677	4055.7	4092.9	299.7 (+37.2)
24-31-13-900-803-01	REMOVAL / INSTALLATION OF THE ENGINES 1 AND 3 STARTER-GENERATORS - ENGINE 1 STARTER-GENERATOR (L1PA)									
24.080	8060-160	MOS		O:1			02-MAY-2018			
	1263	HRS/MSC	O/C	O:0			7638.1			
	REF: AMM 24-31-13-900-803	AFL		O:0			3733			
24-31-13-900-803-02	REMOVAL / INSTALLATION OF THE ENGINES 1 AND 3 STARTER-GENERATORS - ENGINE 3 STARTER-GENERATOR (R1PA)									
24.080	8060-160	MOS		O:3			19-DEC-2014			
	2305	HRS/MSC	O/C	O:0			7252.5			
	REF: AMM 24-31-13-900-803	AFL		O:0			3622			
24-31-13-900-804-01	REMOVAL / INSTALLATION OF THE ENGINE 2 STARTER-GENERATOR - ENGINE 2 STARTER-GENERATOR (M1PA)									
24.090	8060-160	MOS					09-JUL-2020			
	1292	HRS/MSC	O/C				7856.2			
	REF: AMM 24-31-13-900-804	AFL					3792			
24-31-13-960-801-01	REPLACEMENT OF ONE OF THE ENGINE STARTER-GENERATORS WITH THE APU STARTER-GENERATOR - ENGINE 1 STARTER-GENERATOR (L1PA)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 24-31-13-960-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-13-960-801-02	REPLACEMENT OF ONE OF THE ENGINE STARTER-GENERATORS WITH THE APU STARTER-GENERATOR - ENGINE 2 STARTER-GENERATOR (M1PA)	MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-31-13-960-801	AFL						0		
24-31-13-960-801-03	REPLACEMENT OF ONE OF THE ENGINE STARTER-GENERATORS WITH THE APU STARTER-GENERATOR - ENGINE 3 STARTER-GENERATOR (R1PA)	MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-31-13-960-801	AFL						0		
24-31-17-220-803-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA)	MOS						28-NOV-2018		
	8060-160	HRS/MSC	N/A					7675		
	1263	AFL						3744		
	REF: See Workcard									
24-31-17-220-803-02	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA)	MOS								
	8060-160	HRS/MSC	N/A							
	1292	AFL								
	REF: See Workcard									
24-31-17-220-803-03	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA)	MOS						29-MAY-2020		
	8060-160	HRS/MSC	N/A					7851.7		
	2305	AFL						3791		
	REF: See Workcard									
+ 24-31-17-220-804-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 1 STARTER-GENERATOR (L1PA)	MOS						28-NOV-2018		
	8060-160	HRS/MSC	N/A					7675		
	1263	AFL						3744		
	REF: AMM 24-31-17-220-804									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 24-31-17-220-804-02	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 2 STARTER-GENERATOR (M1PA)									
	8060-160	MOS					09-JUL-2020			
	1292	HRS/MSC	600	+60			7856.2	8278.2	8338.2	229 (+60)
	REF: AMM 24-31-17-220-804	AFL					3792			
+ 24-31-17-220-804-03	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - ENGINE 3 STARTER-GENERATOR (R1PA)									
	8060-160	MOS					29-MAY-2020			
	2305	HRS/MSC	600	+60			7851.7	8451.7	8511.7	402.5 (+60)
	REF: AMM 24-31-17-220-804	AFL					3791			
+ 24-31-17-220-805-01	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 1 STARTER-GENERATOR (L1PA)									
	8060-160	MOS					28-NOV-2018			
	1263	HRS/MSC	600	+60			7675	8275	8335	225.8 (+60)
	REF: AMM 24-31-17-220-805	AFL					3744			
+ 24-31-17-220-805-02	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 2 STARTER-GENERATOR (M1PA)									
	8060-160	MOS								
	1292	HRS/MSC	N/A							
	REF: AMM 24-31-17-220-805	AFL								
+ 24-31-17-220-805-03	CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - ENGINE 3 STARTER-GENERATOR (R1PA)									
	8060-160	MOS					29-MAY-2020			
	2305	HRS/MSC	600	+60			7851.7	8451.7	8511.7	402.5 (+60)
	REF: AMM 24-31-17-220-805	AFL					3791			
24-31-17-480-802-01	CHECK AND MODIFICATION OF STARTER-GENERATOR BRUSH GAUGE P/N 031023									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 24-31-17-480-802	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-31-17-960-801-01	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA)	MOS						11-JAN-1988		
	REF: AMM 24-31-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-31-17-960-801-02	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA)	MOS						11-JAN-1988		
	REF: AMM 24-31-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-31-17-960-801-03	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA)	MOS						11-JAN-1988		
	REF: AMM 24-31-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-31-17-960-801-04	REPLACEMENT OF THE ENGINE AND APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA)	MOS						11-JAN-1988		
	REF: AMM 24-31-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-00-710-801-01	OPERATIONAL TEST OF THE BATTERY OVERHEAT DETECTION CIRCUIT	MOS						11-JAN-1988		
	REF: AMM 24-32-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-01-350-801-01	RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 1 (L1PE)	MOS								
24.030	RG380E/40B	HRS/MSC	N/A							
	41215946	AFL								
	REF: AMM 24-32-01-350-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-01-350-801-02	RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (R1PE)									
24.035	RG380E40B 41215563 REF: AMM 24-32-01-350-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-801-01	REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)									
24.030	RG380E/40B 41215946 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-801-02	REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)									
24.035	RG380E40B 41215563 REF: AMM 24-32-01-700-801	MOS HRS/MSC AFL	N/A							
24-32-01-700-802-01	REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 1 (L1PE)									
24.030	RG380E/40B 41215946 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	12	+1m			27-JUN-2023 8049.2 3853	27-JUN-2024	27-JUL-2024	345 d (+30)
24-32-01-700-802-02	REGULAR CHECK OF A MAIN LEAD / ACID BATTERY - BATTERY 2 (R1PE)									
24.035	RG380E40B 41215563 REF: AMM 24-32-01-700-802	MOS HRS/MSC AFL	12	+1m			27-JUN-2023 8049.2 3853	27-JUN-2024	27-JUL-2024	345 d (+30)
24-32-01-710-801-01	OPERATIONAL TEST OF THE MAIN BATTERIES - BATTERY 1 (L1PE)									
	REF: AMM 24-32-01-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-01-710-801-02	OPERATIONAL TEST OF THE MAIN BATTERIES - BATTERY 2 (R1PE)	MOS						11-JAN-1988		
	REF: AMM 24-32-01-710-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-01-900-801-01	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 1 (L1PE)	MOS		N:0				27-JUN-2023		
24.030	RG380E/40B	HRS/MSC	H/T	N:0				8049.2		
	41215946	AFL		N:0				3853		
	REF: AMM 24-32-01-900-801									
24-32-01-900-801-02	REMOVAL / INSTALLATION OF THE MAIN BATTERIES - BATTERY 2 (R1PE)	MOS		N:0				08-JUL-2022		
24.035	RG380E40B	HRS/MSC	H/T	N:0				7967		
	41215563	AFL		N:0				3827		
	REF: AMM 24-32-01-900-801									
24-32-01-960-801-01	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 1 (L1PE)	MOS						27-JUN-2023		
	RG380E/40B	HRS/MSC	O/C					8049.2		
	41215946	AFL						3853		
	REF: AMM 24-32-01-960-801									
24-32-01-960-801-02	DISCARD OF THE MAIN LEAD / ACID BATTERIES - BATTERY 2 (R1PE)	MOS						08-JUL-2022		
	RG380E40B	HRS/MSC	O/C					7967		
	41215563	AFL						3827		
	REF: AMM 24-32-01-960-801									
24-32-05-710-801-01	OPERATIONAL TEST OF THE BATTERY FAN - BATTERY FAN (4PE)	MOS						11-JAN-1988		
	REF: AMM 24-32-05-710-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-610-801-01	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)									
24.210	100-0540-02 1127321 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							
24-32-09-610-801-02	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)									
24.220	100-0540-02 2066 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							
24-32-09-610-801-03	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)									
24.220	804747 2058 REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	12	+3%			27-JUN-2023 8049.2 3853	27-JUN-2024	07-JUL-2024	345 d (+10)
24-32-09-610-801-04	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 BATTERY (32FP)									
24.230	PN NOT INSTALLED REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
24-32-09-610-801-05	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)									
24.250	PN NOT INSTALLED REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
24-32-09-610-801-06	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - EMERGENCY BATTERY (123F)									
24.240	PN NOT INSTALLED REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL	N/A							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-610-801-07	SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - FMS 3 STAND-BY BATTERY (42RJ)									
24.260	PN NOT INSTALLED REF: AMM 24-32-09-610-801	MOS HRS/MSC AFL APH	N/A				11-JAN-1988 0 0 0			
24-32-09-710-802-01	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)									
24.210	100-0540-02 1127321 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	12	+3%			27-JUN-2023 8049.2 3853	27-JUN-2024	07-JUL-2024	345 d (+10)
24-32-09-710-802-02	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)									
24.220	100-0540-02 2066 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	12	+3%			27-JUN-2023 8049.2 3853	27-JUN-2024	07-JUL-2024	345 d (+10)
24-32-09-710-802-03	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)									
24.220	804747 2058 REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A							
24-32-09-710-802-04	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - IRS 3 BATTERY (32FP)									
24.230	PN NOT INSTALLED REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
24-32-09-710-802-05	OPERATIONAL TEST VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.250	PN NOT INSTALLED REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A				0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-710-802-06 24.240	OPERATIONAL TEST OF "SECURAPLANE" XL245 TYPE STAND-BY BATTERIES - EMERGENCY BATTERY (123F) PN NOT INSTALLED REF: AMM 24-32-09-710-802	MOS HRS/MSC AFL	N/A							
24-32-09-720-801-01	CAPACITY TESTING OF THE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG) 100-0540-02 1127321 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C							
24-32-09-720-801-02	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP) 100-0540-02 2066 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C							
24-32-09-720-801-03	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP) 804747 2058 REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C							
24-32-09-720-801-04	CAPACITY TESTING OF THE STAND-BY BATTERIES - IRS 3 BATTERY (32FP) PN NOT INSTALLED REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
24-32-09-720-801-05	CAPACITY TESTING OF THE STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC) PN NOT INSTALLED REF: AMM 24-32-09-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-720-801-06	CAPACITY TESTING OF THE STAND-BY BATTERIES - EMERGENCY BATTERY (123F)									
	PN	MOS						11-JAN-1988		
	NOT INSTALLED	HRS/MSC	N/A					0		
	REF: AMM 24-32-09-720-801	AFL						0		
		APH						0		
24-32-09-720-801-07	CAPACITY TESTING OF THE STAND-BY BATTERIES - FMS 3 STAND-BY BATTERY (42RJ)									
	PN	MOS						11-JAN-1988		
	NOT INSTALLED	HRS/MSC	O/C					0		
	REF: AMM 24-32-09-720-801	AFL						0		
24-32-09-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)									
	100-0540-02	MOS		N:119				01-NOV-2021		
24.210	1127321	HRS/MSC	H/T					7940.3		
	REF: AMM 24-32-09-900-801	AFL						3817		
24-32-09-900-801-02	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)									
	100-0540-02	MOS		R:1				30-NOV-2022		
24.220	2066	HRS/MSC	H/T					8031.4		
	REF: AMM 24-32-09-900-801	AFL						3845		
24-32-09-900-801-03	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)									
	804747	MOS		N:0				27-JUN-2023		
24.220	2058	HRS/MSC	O/C					8049.2		
	REF: AMM 24-32-09-900-801	AFL		N:0				3853		
24-32-09-900-801-04	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - IRS 3 BATTERY (32FP)									
	PN	MOS						11-JAN-1988		
	NOT INSTALLED	HRS/MSC	O/C					0		
24.230	REF: AMM 24-32-09-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-900-801-05	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)									
24.250	PN NOT INSTALLED REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
24-32-09-900-801-06	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - EMERGENCY BATTERY (123F)									
24.240	PN NOT INSTALLED REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL	O/C					16-NOV-2016 7448.9 3681		
24-32-09-900-801-07	REMOVAL / INSTALLATION OF THE STAND-BY BATTERIES - FMS 3 STAND-BY BATTERY (42RJ)									
24.260	PN NOT INSTALLED REF: AMM 24-32-09-900-801	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0				11-JAN-1988 0 0 0		
24-32-09-960-801-01	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (4FG)									
	REF: AMM 24-32-09-960-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
24-32-09-960-801-02	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 1 BATTERY (L12FP)									
	REF: AMM 24-32-09-960-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
24-32-09-960-801-03	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 2 BATTERY (R12FP)									
	REF: AMM 24-32-09-960-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-960-801-04	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - IRS 3 BATTERY (32FP)	MOS						11-JAN-1988		
	REF: AMM 24-32-09-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-09-960-801-05	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - VHF 3 STAND-BY BATTERY (28RC)	MOS						11-JAN-1988		
	REF: AMM 24-32-09-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-09-960-801-06	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - EMERGENCY BATTERY (123F)	MOS						11-JAN-1988		
	REF: AMM 24-32-09-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-09-960-801-07	REPLACEMENT OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERY PACKS - FMS 3 STAND-BY BATTERY (42RJ)	MOS						11-JAN-1988		
	REF: AMM 24-32-09-960-801	HRS/MSC	O/C					0		
		AFL						0		
24-32-09-960-802-01	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - STAND-BY HORIZON BATTERY (4FG)	MOS	48					01-APR-2020	01-APR-2024	258 d
24.210	100-0540-02	HRS/MSC								
LIFE LIMIT	1127321	AFL								
	REF: AMM 24-32-09-960-802									
24-32-09-960-802-02	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 1 BATTERY (L12FP)	MOS	48					30-NOV-2022	30-NOV-2026	1231 d
24.220	100-0540-02	HRS/MSC						8031.4		
LIFE LIMIT	2066	AFL						3845		
	REF: AMM 24-32-09-960-802									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-32-09-960-802-03	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 2 BATTERY (R12FP)									
24.220	804747 2058 REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A							
24-32-09-960-802-04	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - IRS 3 BATTERY (32FP)									
24.230	PN NOT INSTALLED REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A	I:0				11-JAN-1988 0 0		
24-32-09-960-802-05	DISCARD VHF 3 STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY ONLY)									
24.250	PN NOT INSTALLED REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A	I:0				11-JAN-1988 0 0		
24-32-09-960-802-06	DISCARD OF THE "SECURAPLANE" XL245 TYPE STAND-BY BATTERY PACKS - EMERGENCY BATTERY (123F)									
24.240	PN NOT INSTALLED REF: AMM 24-32-09-960-802	MOS HRS/MSC AFL	N/A							
24-33-01-900-801-01	REMOVAL / INSTALLATION OF THE APU STARTER-GENERATOR - APU STARTER-GENERATOR (21PA)									
24.100	8060-160 2166 REF: AMM 24-33-01-900-801	MOS HRS/MSC AFL APH	O/C					09-JUL-2020 7856.2 3792 3677		
24-33-01-960-801-01	REPLACEMENT OF THE APU STARTER-GENERATOR WITH ONE OF THE ENGINE STARTER-GENERATORS - APU STARTER-GENERATOR (21PA)									
	REF: AMM 24-33-01-960-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-33-05-220-803-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA) 8060-160 2166 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				09-JUL-2020 7856.2 3792 3677			
+ 24-33-05-220-804-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 1 - APU STARTER-GENERATOR (21PA) 8060-160 2166 REF: AMM 24-33-05-220-804	MOS HRS/MSC AFL APH	600	+60			31-MAY-2022 7967 3827 3726	4326	4386	570 (+60)
+ 24-33-05-220-805-01	CHECK OF THE APU STARTER-GENERATOR BRUSHES P/N 8060-160 OPTION 2 - APU STARTER-GENERATOR (21PA) 8060-160 2166 REF: AMM 24-33-05-220-805	MOS HRS/MSC AFL APH	N/A							
+ 24-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB - EXTERNAL POWER RECEPTACLE OVERVOLTAGE PCB (CI11) PKG 21 24.170 REF: AMM 24-40-00-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE CHARGING FUNCTION REF: AMM 24-41-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES REF: AMM 24-41-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-41-01-900-801-01	REMOVAL / INSTALLATION OF THE BATTERY CHARGING BOXES - LH BATTERY CHARGING BOX (332J1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-41-01-900-801	AFL		N:0				0		
24-41-01-900-801-02	REMOVAL / INSTALLATION OF THE BATTERY CHARGING BOXES - RH BATTERY CHARGING BOX (332J2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-41-01-900-801	AFL		N:0				0		
24-61-01-700-801-01	CHECK AFTER REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOX - MAIN ELECTRICAL BOX (6PA)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-61-01-700-801	AFL						0		
24-61-01-900-801-01	REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOX - MAIN ELECTRICAL BOX (6PA)									
24.165	671GC01Y02E	MOS						11-JAN-1988		
	139	HRS/MSC	O/C	N:0				0		
	REF: AMM 24-61-01-900-801	AFL						0		
24-61-05-700-801-01	CHECKS AFTER REMOVAL / INSTALLATION OF THE MAIN ELECTRICAL BOX LINE REPLACEABLE UNITS (LRU'S)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-61-05-700-801	AFL						0		
24-61-07-960-801-01	REPLACEMENT OF THE GENERATION CURRENT SENSOR IN MAIN ELECTRICAL BOX - LH GENERATION CURRENT SENSOR UNIT (HES135)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 24-61-07-960-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-61-07-960-801-02	REPLACEMENT OF THE GENERATION CURRENT SENSOR IN MAIN ELECTRICAL BOX - RH GENERATION CURRENT SENSOR UNIT (HES246)	MOS						11-JAN-1988		
	REF: AMM 24-61-07-960-801	HRS/MSC AFL	O/C					0 0		
+ 24-63-13-710-801-01 (s)	OPERATIONAL TEST OF THE DOME LIGHT PCB - DOME LIGHT CONTROL PCB (CH12)	MOS						11-NOV-2015		
24.200	PKG 21	HRS/MSC AFL	1600	+40				7355.5 3656		
24-66-01-910-801-01	CONNECTIONS TO CIRCUIT BREAKER PANEL - CIRCUIT BREAKER PANEL	MOS						11-JAN-1988		
	REF: AMM 24-66-01-910-801	HRS/MSC AFL	O/C					0 0		
24-90-01-900-801-01	GROUND FAULT (GFI) INTERRUPTER	MOS						11-JAN-1988		
	PN	HRS/MSC AFL	O/C					0 0		
	SN-UNKNOWN	APH						0		
	REF: GENERIC NO REF							0		
243191	NO. 1 BATTERY TEMPERATURE PROBE	MOS						11-JAN-1988		
24.040	P600-14B	HRS/MSC AFL	O/C					0 0		
	03436							0		
	REF: GENERIC NO REF							0		
243201	NO. 2 BATTERY TEMPERATURE PROBE	MOS						11-JAN-1988		
24.040	P600-14B	HRS/MSC AFL	O/C					0 0		
	04659							0		
	REF: GENERIC NO REF							0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243211	BATTERY TEMPERATURE INDICATOR									
24.050	BTI600-3A 5414 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243221	BATTERY BLOWER									
24.060	VA0906XXAA 10691 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243251	NO. 1 BATTERY REVERSE CURRENT RELAY									
24.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243261	NO. 2 BATTERY REVERSE CURRENT RELAY									
24.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243501	NO. 1 GENERATOR REVERSE CURRENT RELAY									
24.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243511	NO. 2 GENERATOR REVERSE CURRENT RELAY									
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243521	NO. 3 GENERATOR REVERSE CURRENT RELAY									
24.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243531	APU GENERATOR REVERSE CURRENT RELAY									
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243601	LH DC AMMETER									
24.150	2396-323-0A 549 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243611	RH DC AMMETER									
24.150	2396-323-0A 643 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243621	LH DC VOLTMETER									
24.160	2396-118-0A 935 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
243631	RH DC VOLTMETER									
24.160	2396-118-0A 936 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243701	UPPER ELECTRICAL PANEL									
24.165	401TS06YAB 139 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
244101	GROUND POWER RECEPTACLE									
24.170	280CA 471 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 25 EQUIPMENT/FURNISHINGS										
25-00-00-910-801-01	FURNISHINGS MAINTENANCE AND SAFETY PRECAUTIONS									
	REF: AMM 25-00-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-00-00-910-802-01	FURNISHINGS GAP RULES									
	REF: AMM 25-00-00-910-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-00-01-200-801-01	INSPECTION OF THE ONBOARD KIT									
25.065	REF: AMM 25-00-01-200-801	MOS HRS/MSC AFL APH	O/C				04-DEC-2017 7593.7 3722 3592			
25-00-05-200-801-01 (s)	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSSES AND SAFETY BELTS									
25.010	PKG 31 REF: AMM 25-00-05-200-801	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-11-01-900-801-01	REMOVAL / INSTALLATION OF THE PILOT SEATS - LH PILOT SEAT (L2MG)									
25.020	132-051-100A-E 38 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
25-11-01-900-801-02	REMOVAL / INSTALLATION OF THE PILOT SEATS - RH PILOT SEAT (R2MG)									
25.020	132-050-100A-E 38 REF: AMM 25-11-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
25-11-05-200-801-01	VISUAL INSPECTION OF BUCKLE SPRING OF ANJOU AERONAUTIQUE SAFETY BELTS AND RESTRAINT SYSTEM (TYPE 343 AND 343-1)									
	REF: AMM 25-11-05-200-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-11-05-200-801-01A	VISUAL INSPECTION OF PASSENGER SEAT BELT BUCKLES (MANDATORY 5-40)									
25.030	REF: AMM 25-11-05-200-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-11-13-640-801-01 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - LH PILOT SEAT (L2MG)									
25.020	PKG 21 REF: AMM 25-11-13-640-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
25-11-13-640-801-02 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTINGS - RH PILOT SEAT (R2MG)									
25.020	PKG 21 REF: AMM 25-11-13-640-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-11-19-960-801-01 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT (L2MG) PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-11-19-960-801	HRS/MSC AFL					8047.2 3851			
25-11-19-960-801-02 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT (R2MG) PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-11-19-960-801	HRS/MSC AFL					8047.2 3851			
25-11-25-200-801-01 (s)	INSPECTION OF THE PILOT SEAT ROLLER PINS - LH PILOT SEAT (L2MG) PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-11-25-200-801	HRS/MSC AFL					8047.2 3851			
25-11-25-200-801-02 (s)	INSPECTION OF THE PILOT SEAT ROLLER PINS - RH PILOT SEAT (R2MG) PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-11-25-200-801	HRS/MSC AFL					8047.2 3851			
25-11-25-900-801-01	REMOVAL / INSTALLATION OF THE PILOT SEAT ROLLER PINS - LH PILOT SEAT (L2MG) PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-11-25-900-801	AFL						0		
25-11-25-900-801-02	REMOVAL / INSTALLATION OF THE PILOT SEAT ROLLER PINS - RH PILOT SEAT (R2MG) PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-11-25-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-12-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT - THIRD CREW MEMBER SEAT (M1001MP) PKG 5 REF: AMM 25-12-00-210-801	MOS HRS/MSC AFL	12 800	+1m +40			PKG 21-JUN-2023 8047.2 3851			
25-13-31-900-801-01	REMOVAL / INSTALLATION OF THE YAW PEDAL CASINGS PN SN-UNKNOWN REF: AMM 25-13-31-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
25-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - PASSENGER DOOR ASSIST HANDLE PKG 31 REF: AMM 25-20-00-210-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			
25-20-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - AFT LAVATORY ASSIST HANDLE PKG 31 REF: AMM 25-20-00-210-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			
25-20-00-220-801-01	INSPECTION / TEST OF THE WASTE CONTAINERS - INSPECTION / TEST OF WASTE CONTAINERS REF: AMM 25-20-00-220-801	MOS HRS/MSC AFL	1000	+40			27-JUN-2023 8049.2 3853	9049.2	9089.2	1000 (+40)
25-20-00-220-802-01 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS PKG 31 REF: AMM 25-20-00-220-802	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-20-00-220-802-02 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF THE POP OUT WORK SURFACE PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-20-00-220-802	HRS/MSC AFL					8047.2 3851			
25-20-00-220-802-05 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - OPERATIONAL TEST OF TAMBOUR DOOR POWER CUT OFF FUNCTION PKG 31	MOS	72	+2m			PKG	21-JUN-2023		
	REF: AMM 25-20-00-220-802	HRS/MSC AFL					8047.2 3851			
25-20-00-710-801-01	OPERATIONAL TEST OF THE CABIN OPTIONAL EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 25-20-00-710-801	HRS/MSC AFL	O/C				0 0			
25-21-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE SINGLE AND DOUBLE SEATS PKG 7	MOS	36	+1m			PKG	21-JUN-2023		
	REF: AMM 25-21-00-220-801	HRS/MSC AFL	2400	+40			8047.2 3851			
25-21-00-220-801-02 (s)	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE DIVAN PKG 7	MOS	36	+1m			PKG	21-JUN-2023		
	REF: AMM 25-21-00-220-801	HRS/MSC AFL	2400	+40			8047.2 3851			
25-21-33-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER SEAT RESTRAINT SYSTEMS PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-21-33-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-22-01-210-801-01	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT	MOS						28-NOV-2018		
	REF: AMM 25-22-01-210-801	HRS/MSC AFL	O/C					7675 3744		
25-22-01-210-801-02	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLE IN FRONT OF EMERGENCY EXIT (IF INSTALLED)	MOS						11-JAN-1988		
	REF: AMM 25-22-01-210-801	HRS/MSC AFL APH	O/C					0 0 0		
+ 25-22-01-210-801-03 (s)	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES							PKG		
	PKG 31	MOS	72	+2m				21-JUN-2023		
	REF: AMM 25-22-01-210-801	HRS/MSC AFL						8047.2 3851		
25-22-01-820-801-01	ADJUSTMENT OF THE CONSOLE TABLES	MOS						11-JAN-1988		
	REF: AMM 25-22-01-820-801	HRS/MSC AFL	O/C					0 0		
25-22-05-220-802-01 (s)	DETAILED INSPECTION OF THE DINING TABLE							PKG		
	PKG 31	MOS	72	+2m				21-JUN-2023		
	REF: AMM 25-22-05-220-802	HRS/MSC AFL						8047.2 3851		
25-23-61-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE TRACKING MAGAZINE RACK - INSPECTION OF THE TRACKING MAGAZINE RACK							PKG		
	PKG 6	MOS	24	+1m				21-JUN-2023		
	REF: AMM 25-23-61-210-801	HRS/MSC AFL	1600	+40				8047.2 3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-25-00-720-801-01	FUNCTIONAL TEST OF THE OPENING MECHANISM OF ELECTRICALLY-OPERATED CURTAINS	MOS						11-JAN-1988		
	REF: AMM 25-25-00-720-801	HRS/MSC	O/C					0		
		AFL						0		
25-25-01-900-801-01	REMOVAL / INSTALLATION OF THE CURTAIN MOTORS	MOS						11-JAN-1988		
	PN			N:0				0		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-25-01-900-801	AFL		N:0				0		
25-25-05-900-801-01	REMOVAL / INSTALLATION OF THE CURTAIN MOTOR BELTS	MOS						11-JAN-1988		
	PN			N:0				0		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-25-05-900-801	AFL		N:0				0		
25-25-09-900-801-01	REMOVAL / INSTALLATION OF THE CURTAIN DRIVE BELTS	MOS						11-JAN-1988		
	PN			N:0				0		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-25-09-900-801	AFL		N:0				0		
25-25-13-900-801-01	REMOVAL / INSTALLATION OF THE CURTAINS	MOS						11-JAN-1988		
	PN			N:0				0		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 25-25-13-900-801	AFL		N:0				0		
25-25-17-700-801-01	PULL TEST OF THE VALANCE PANELS	MOS						11-JAN-1988		
	REF: AMM 25-25-17-700-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-25-17-900-801-01	REMOVAL / INSTALLATION OF THE VALANCE PANELS PN SN-UNKNOWN REF: AMM 25-25-17-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
25-25-33-900-801-01	REMOVAL / INSTALLATION OF THE FLOORING PN SN-UNKNOWN REF: AMM 25-25-33-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
25-26-25-900-801-01	REMOVAL / INSTALLATION OF THE MOISTURE BARRIER PN SN-UNKNOWN REF: AMM 25-26-25-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
25-28-47-900-801-01	REMOVAL / INSTALLATION OF THE MIRRORS PN SN-UNKNOWN REF: AMM 25-28-47-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
25-30-33-900-801-01	CONVECTION OVEN PN SN-UNKNOWN REF: AMM 25-33-00-900-801	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0				11-JAN-1988 0 0 0		
25-33-00-710-801-01	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF COFFEE BREWER REF: AMM 25-33-00-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-33-00-710-801-02	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF COFFEE MAKER	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-801-03	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF CONVECTION OVEN	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-801-04	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF ESPRESSO MACHINE	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-801-05	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF HOT CUP	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-801-06	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF MICROWAVE OVEN	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-801-07	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF MICROWAVE OVEN BEHIND TAMBOUR DOOR	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-33-00-710-801-08	OPERATIONAL TEST OF THE GALLEY OPTIONAL EQUIPMENT - OPERATIONAL TEST OF WARMER	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-710-802-01	OPERATIONAL TEST OF THE AUXILIARY GALLEY OPTIONAL EQUIPMENT	MOS						11-JAN-1988		
	REF: AMM 25-33-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
25-33-00-900-801-01	REMOVAL / INSTALLATION OF THE GALLEY & VANITY ELECTRICAL EQUIPMENT	PN						11-JAN-1988		
	SN-UNKNOWN	MOS		N:0				0		
	REF: AMM 25-33-00-900-801	HRS/MSC	O/C	N:0				0		
		AFL		N:0				0		
25-33-09-210-801-01	INSPECTION OF THE COFFEE MAKER / ESPRESSO MACHINE	MOS						21-JUL-2012		
	REF: AMM 25-33-09-210-801	HRS/MSC	A/R					6985.1		
		AFL						3525		
25-33-17-210-801-01	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN	MOS						28-OCT-2021		
	REF: AMM 25-33-17-210-801	HRS/MSC	N/A					7940.3		
		AFL						3817		
25-33-17-440-801-01	MANUAL RESET OF MICROWAVE OVEN MAGNETRON THERMOSTAT	MOS						11-JAN-1988		
	REF: AMM 25-33-17-440-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-33-17-710-801-01	OPERATIONAL TEST OF THE MICROWAVE OVEN DOOR ELECTRICAL POWER CUT-OFF FUNCTION PN NOT INSTALLED REF: AMM 25-33-17-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
25-33-17-720-801-01	TEST OF HEATING PERFORMANCE OF THE MICROWAVE OVEN REF: AMM 25-33-17-720-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
25-40-00-710-801-01	OPERATIONAL TEST OF THE LAVATORY OPTIONAL EQUIPMENT REF: AMM 25-40-00-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
25-42-13-390-801-01	SEALING OF THE AFT LAVATORY WASH BASIN CABINET REF: AMM 25-42-13-390-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
+ 25-60-00-200-801-02 (s)	INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT PKG 16 25.060 REF: AMM 25-60-00-200-801	MOS HRS/MSC AFL	24	+1m				PKG 21-JUN-2023 8047.2 3851		
25-60-00-200-801-03 (s)	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT PKG 16 REF: AMM 25-60-00-200-801	MOS HRS/MSC AFL	24	+1m				PKG 21-JUN-2023 8047.2 3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-60-01-900-801-01	NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C							
25-60-01-900-801-02	NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C							
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) MANDATORY REF: AMM GENERIC 1	MOS HRS/MSC AFL	12				27-JUN-2023 8049.2 3853	27-JUN-2024		345 d
25-61-00-710-801-01 25.070	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 UNIT CONTROLS REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				15-NOV-2013 7168.1 3589			
25-61-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT 96/97 COCKPIT CONTROLS REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-61-00-710-801-03	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT 96/97 REF: AMM 25-61-00-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-61-00-710-801-04	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - OPERATIONAL TEST OF ELT 90/91	MOS						11-JAN-1988		
	REF: AMM 25-61-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
25-61-01-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) G-SWITCH - ELT (32RC)	MOS						04-DEC-2017		
	REF: AMM 25-61-01-710-801	HRS/MSC	O/C					7593.7		
		AFL						3722		
		APH						3592		
25-61-01-900-803-01	REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACKS (ELT 90 / 91 OR ELT 96 / 97) - ELT (32RC)	MOS						04-DEC-2017		
25.070	453-5060	HRS/MSC	O/C					7593.7		
	01500	AFL						3722		
	REF: AMM 25-61-01-900-803	APH						3592		
25-61-01-900-804-01	REMOVAL / INSTALLATION OF THE ELT AND REPLACEMENT OF THE ELT BATTERY PACK (JOLLIET JE2)	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 25-61-01-900-804									
25-61-13-200-801-01	VISUAL INSPECTION OF THE ELT BATTERY PACK (JOLLIET JE2) - ELT (32RC)	MOS						11-JAN-1988		
	REF: AMM 25-61-13-200-801	HRS/MSC	O/C					0		
		AFL						0		
25-61-13-960-801-01	DISCARD OF THE ELT BATTERY PACKS - ELT (32RC)	MOS						27-JUN-2023	01-JAN-2025 M	533 d
25.070	453-5060	HRS/MSC	DUE					8049.2		
	01500	AFL						3853		
	REF: AMM 25-61-13-960-801									
	LIFE LIMIT									
	Expiry Date: 01-JAN-2025									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-61-21-900-801-01	REMOVAL / INSTALLATION OF THE ELT ANTENNA - ELT ANTENNA (34RC)									
25.170	110-340 4014410 REF: AMM 25-61-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-NOV-2004 4519.6 2432			
25-62-01-720-801-01	FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)									
31.070	DK120/90 AT118123 REF: AMM 25-62-01-720-801	MOS HRS/MSC AFL	25	+3%			27-JUN-2023 8049.2 3853	27-JUL-2025	19-AUG-2025	740 d (+23)
25-62-01-720-801-02	FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)									
31.100	DK120/90 AT137135 REF: AMM 25-62-01-720-801	MOS HRS/MSC AFL	25	+3%			27-JUN-2023 8049.2 3853	27-JUL-2025	19-AUG-2025	740 d (+23)
25-62-05-960-801-01	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - CVR ULB BATTERY (900RK1)									
31.070 LIFE LIMIT	DK120/90 AT118123 REF: AMM 25-62-05-960-801	MOS HRS/MSC AFL	DUE				28-FEB-2020 7825.6 3786	30-SEP-2025 M		805 d
25-62-05-960-801-02	RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR ULB BATTERY (900FZ1)									
31.100 LIFE LIMIT	DK120/90 AT137135 REF: AMM 25-62-05-960-801	MOS HRS/MSC AFL	DUE				30-JAN-2020 7825.6 3786	30-JUN-2026 M		1078 d
25-63-00-350-801-01	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - PILOT EVAS UNIT (L9510MP)									
	REF: AMM 25-63-00-350-801	MOS HRS/MSC AFL	N/A							
25-63-00-350-801-02	RESTORATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) (OVERHAUL) - COPILOT EVAS UNIT (R9510MP)									
	REF: AMM 25-63-00-350-801	MOS HRS/MSC AFL	N/A							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-63-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - PILOT EVAS UNIT (L9510MP) PN NOT INSTALLED REF: AMM 25-63-00-710-801	MOS HRS/MSC AFL	O/C							
25-63-00-710-801-02	OPERATIONAL TEST OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - COPILOT EVAS UNIT (R9510MP) PN NOT INSTALLED REF: AMM 25-63-00-710-801	MOS HRS/MSC AFL	O/C							
25-63-00-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - PILOT EVAS UNIT (L9510MP) PN SN-UNKNOWN REF: AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
25-63-00-900-801-02	REMOVAL / INSTALLATION OF THE EMERGENCY VISION ASSURANCE SYSTEM (EVAS) - COPILOT EVAS UNIT (R9510MP) PN SN-UNKNOWN REF: AMM 25-63-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
25-63-01-960-801-01	DISCARD OF THE EVAS BATTERY - PILOT EVAS UNIT (L9510MP) REF: AMM 25-63-01-960-801	MOS HRS/MSC AFL	N/A							
25-63-01-960-801-02	DISCARD OF THE EVAS BATTERY - COPILOT EVAS UNIT (R9510MP) REF: AMM 25-63-01-960-801	MOS HRS/MSC AFL	N/A							
+ 25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 1 LIFE RAFT 1015FAUL-630-1-600 10UL-01221 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			21-JUL-2021 7907.8 3809	21-JUL-2024	23-AUG-2024	369 d (+33)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 2 LIFE RAFT 1015FAUL-390-1-100 10UL-02852 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			24-AUG-2020 7856.2 3792	24-AUG-2023	26-SEP-2023	37 d (+33)
+ 25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 3 LIFE RAFT PN SN-UNKNOWN REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-13-200-801-01	INSPECTION OF LIFE RAFT - NO. 4 LIFE RAFT PN SN-UNKNOWN REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-13-350-801-01 25.130	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 1 LIFE RAFT (15ME) 1015FAUL-630-1-600 10UL-01221 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	72	+3%			21-JUL-2021 7907.8 3809	21-JUL-2027	25-SEP-2027	1464 d (+66)
+ 25-64-13-350-801-01 25.130	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 2 LIFE RAFT (15ME) 1015FAUL-390-1-100 10UL-02852 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	72	+3%			24-AUG-2020 7856.2 3792	24-AUG-2026	28-OCT-2026	1133 d (+65)
25-64-13-350-801-01 25.135	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 3 LIFE RAFT (15ME) PN SN-UNKNOWN REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-64-13-350-801-01 25.135	RESTORATION OF THE LIFE RAFT (OVERHAUL) - NO. 4 LIFE RAFT (15ME) PN SN-UNKNOWN REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-13-900-801-01	NO. 1 LIFE RAFT									
25.130	1015FAUL-630-1-600 10UL-01221 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:149 O:1 N:2209.4 O:0 N:929 O:0			21-JUL-2021 7907.8 3809			
25-64-13-900-801-02	NO. 2 LIFE RAFT									
25.130	1015FAUL-390-1-100 10UL-02852 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			24-AUG-2020 7856.2 3792			
25-64-13-900-801-03	NO. 3 LIFE RAFT									
25.135	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
25-64-13-900-801-04	NO. 4 LIFE RAFT									
25.135	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-13-960-801-01	DISCARD OF THE LIFE RAFT - NO. 1 LIFE RAFT									
	1015FAUL-630-1-600 10UL-01221 REF: AMM 25-64-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-13-960-801-01	DISCARD OF THE LIFE RAFT - NO. 2 LIFE RAFT									
	1015FAUL-390-1-100 10UL-02852 REF: AMM 25-64-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-13-960-801-01	DISCARD OF THE LIFE RAFT - NO. 3 LIFE RAFT									
	PN SN-UNKNOWN REF: AMM 25-64-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-13-960-801-01	DISCARD OF THE LIFE RAFT - NO. 4 LIFE RAFT PN SN-UNKNOWN REF: AMM 25-64-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 25-64-17-200-802-01	INSPECTION LH PILOT LIFE VEST P01074-209 12060840002 REF:	MOS HRS/MSC AFL	120				31-AUG-2022	31-AUG-2032		3332 d
+ 25-64-17-200-802-02	INSPECTION RH PILOT LIFE VEST P01074-209 12060840004 REF:	MOS HRS/MSC AFL	120				31-AUG-2022	31-AUG-2032		3332 d
+ 25-64-17-200-802-03	INSPECTION THIRD CREW MEMBER LIFE VEST P01074-201C 17032320090 REF:	MOS HRS/MSC AFL	120				01-MAR-2017	01-MAR-2027		1322 d
+ 25-64-17-200-803-01	INSPECTION NO. 01 PASSENGER LIFE VEST P01074-201 14090640001 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d
+ 25-64-17-200-803-02	INSPECTION NO. 02 PASSENGER LIFE VEST P01074-201 14090640011 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d
+ 25-64-17-200-803-03	INSPECTION NO. 03 PASSENGER LIFE VEST P01074-201 14090640016 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-17-200-803-04	INSPECTION NO. 04 PASSENGER LIFE VEST S11150-1300 87-82967 REF:	MOS HRS/MSC AFL	66				27-JUN-2023	27-DEC-2028		1989 d
25.095										
+ 25-64-17-200-803-05	INSPECTION NO. 05 PASSENGER LIFE VEST P01074-201 14090640021 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d
25.100										
+ 25-64-17-200-803-06	INSPECTION NO. 06 PASSENGER LIFE VEST P01074-201 14090640026 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d
25.100										
+ 25-64-17-200-803-07	INSPECTION NO. 07 PASSENGER LIFE VEST P01074-201 14090640066 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025		563 d
25.105										
+ 25-64-17-200-803-08	INSPECTION NO. 08 PASSENGER LIFE VEST S11150-1300 87-83025 REF:	MOS HRS/MSC AFL	24				31-JAN-2015	17-AUG-2026 M		1126 d
25.105										
+ 25-64-17-200-803-09	INSPECTION NO. 09 PASSENGER LIFE VEST P01074-201 14090640086 REF:	MOS HRS/MSC AFL	120				31-JAN-2015	11-SEP-2024 M		421 d
25.110										
+ 25-64-17-200-803-10	INSPECTION NO. 10 PASSENGER LIFE VEST P01074-201 16040640012 REF:	MOS HRS/MSC AFL	108				22-MAR-2017	22-MAR-2026		978 d
25.110										
LIFE LIMIT*										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 25-64-17-200-803-11	INSPECTION NO. 11 PASSENGER LIFE VEST P01074-201 160814300030 REF:	MOS HRS/MSC AFL	113				22-MAR-2017	22-AUG-2026		1131 d
25.120										
+ 25-64-17-200-803-12	INSPECTION NO. 12 PASSENGER LIFE VEST P01074-201 16081430068 REF:	MOS HRS/MSC AFL	120				22-MAR-2017	17-AUG-2026 M		1126 d
25.120										
+ 25-64-17-200-803-13	INSPECTION NO. 13 PASSENGER LIFE VEST P01074-201 16081436100 REF:	MOS HRS/MSC AFL	120				22-MAR-2017	17-AUG-2026 M		1126 d
25.125										
+ 25-64-17-200-803-14	INSPECTION NO. 14 PASSENGER LIFE VEST P01074-201 16081430105 REF:	MOS HRS/MSC AFL	120				22-MAR-2017	17-AUG-2026 M		1126 d
25.125										
25-64-17-350-802-01	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME) P01074-209 12060840002 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	O/C				31-AUG-2022 7981.8 3831			
25-64-17-350-802-02	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME) P01074-209 12060840004 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	O/C				31-AUG-2022 7981.8 3831			
25-64-17-350-802-03	RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME) P01074-201C 17032320090 REF: AMM 25-64-17-350-802	MOS HRS/MSC AFL	O/C					31-MAR-2027 M		1352 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-350-803-01	RESTORATION NO. 15 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 1 PASSENGER LIFE VEST P01074-201 14090640001 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 10 PASSENGER LIFE VEST P01074-201 16040640012 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				22-MAR-2017 7485.5 3693	13-APR-2026 M		1000 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 11 PASSENGER LIFE VEST P01074-201 160814300030 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				22-MAR-2017 7485.5 3693	17-AUG-2026 M		1126 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 12 PASSENGER LIFE VEST P01074-201 16081430068 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				22-MAR-2017 7485.5 3693	17-AUG-2026 M		1126 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 13 PASSENGER LIFE VEST P01074-201 16081436100 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				22-MAR-2017 7485.5 3693	17-AUG-2026 M		1126 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 14 PASSENGER LIFE VEST P01074-201 16081430105 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				22-MAR-2017 7485.5 3693	17-AUG-2026 M		1126 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 16 PASSENGER LIFE VEST PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 17 PASSENGER LIFE VEST PN NOT INSTALLED REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C							
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 2 PASSENGER LIFE VEST P01074-201 14090640011 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 3 PASSENGER LIFE VEST P01074-201 14090640016 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 4 PASSENGER LIFE VEST S11150-1300 87-82967 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				07-FEB-2011 6561.2 3315	13-APR-2026 M		1000 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 5 PASSENGER LIFE VEST P01074-201 14090640021 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 6 PASSENGER LIFE VEST P01074-201 14090640026 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 7 PASSENGER LIFE VEST P01074-201 14090640066 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 8 PASSENGER LIFE VEST S11150-1300 87-83025 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				07-FEB-2011 6561.2 3315	17-AUG-2026 M		1126 d
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 9 PASSENGER LIFE VEST P01074-201 14090640086 REF: AMM 25-64-17-350-803	MOS HRS/MSC AFL	O/C				08-FEB-2015 7279 3629	11-SEP-2024 M		421 d
25-64-17-900-802-01 25.080	PILOT LIFE VEST P01074-209 12060840002 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:122 O:0 N:996.7 O:0 N:306 O:0			31-AUG-2022 7981.8 3831			
25-64-17-900-802-02 25.080	COPILOT LIFE VEST P01074-209 12060840004 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:122 O:0 N:996.7 O:0 N:306 O:0			31-AUG-2022 7981.8 3831			
25-64-17-900-802-03 25.085	THIRD CREW MEMBER LIFE VEST P01074-201C 17032320090 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			28-NOV-2018 7675 3744			
25-64-17-900-803-01 25.090	NO. 1 PASSENGER LIFE VEST P01074-201 14090640001 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-900-803-02	NO. 2 PASSENGER LIFE VEST									
25.090	P01074-201 14090640011 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-03	NO. 3 PASSENGER LIFE VEST									
25.095	P01074-201 14090640016 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-04	NO. 4 PASSENGER LIFE VEST									
25.095	S11150-1300 87-82967 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				07-FEB-2011 6561.2 3315			
25-64-17-900-803-05	NO. 5 PASSENGER LIFE VEST									
25.100	P01074-201 14090640021 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-06	NO. 6 PASSENGER LIFE VEST									
25.100	P01074-201 14090640026 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-07	NO. 7 PASSENGER LIFE VEST									
25.105	P01074-201 14090640066 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-08	NO. 8 PASSENGER LIFE VEST									
25.105	S11150-1300 87-83025 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				07-FEB-2011 6561.2 3315			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-900-803-09	NO. 9 PASSENGER LIFE VEST									
25.110	P01074-201 14090640086 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-FEB-2015 7279 3629			
25-64-17-900-803-10	NO. 10 PASSENGER LIFE VEST									
25.110	P01074-201 16040640012 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAR-2017 7485.5 3693			
25-64-17-900-803-11	NO. 11 PASSENGER LIFE VEST									
25.120	P01074-201 160814300030 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAR-2017 7485.5 3693			
25-64-17-900-803-12	NO. 12 PASSENGER LIFE VEST									
25.120	P01074-201 16081430068 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAR-2017 7485.5 3693			
25-64-17-900-803-13	NO. 13 PASSENGER LIFE VEST									
25.125	P01074-201 16081436100 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAR-2017 7485.5 3693			
25-64-17-900-803-14	NO. 14 PASSENGER LIFE VEST									
25.125	P01074-201 16081430105 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-MAR-2017 7485.5 3693			
25-64-17-900-803-15	NO. 15 PASSENGER LIFE VEST									
25.140	PN NOT INSTALLED REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-64-17-900-803-16	NO. 16 PASSENGER LIFE VEST									
25.140	PN NOT INSTALLED REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C							
25-64-17-900-803-17	NO. 17 PASSENGER LIFE VEST									
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C							
25-64-17-900-804-01	NO. 1 INFANT LIFE VEST									
	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
25-90-01-900-801-03	THIRD CREW MEMBER SEAT									
	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
25-90-19-900-801-01	MICROWAVE OVEN									
	PN NOT INSTALLED REF: AMM 25-33-00-900-801	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
25-92-05-900-801-01	REMOVAL / INSTALLATION OF THE EVASAN MODULE									
	PN SN-UNKNOWN REF: AMM 25-92-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
251141	PILOT SEAT BELT									
25.030	1101167-09 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
251151	COPILOT SEAT BELT 1101168-18	MOS						11-JAN-1988		
25.030	SN-UNKNOWN REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
251161	PILOT HARNESS 2825A3X03	MOS						11-JAN-1988		
25.040	SN-UNKNOWN REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
251171	COPILOT HARNESS 2825A3X03	MOS						11-JAN-1988		
25.040	SN-UNKNOWN REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
256391	LAVATORY BLOWER EVT205D	MOS						11-JAN-1988		
25.160	SN-UNKNOWN REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
256A54	NO. 1 FIRST AID KIT FAK	MOS		R:81				30-APR-2019		
	N394WJ REF:	HRS/MSC AFL	O/C	R:737.4 R:235			7722.5 3760			
25GA58	FIRST AID KIT 70002-00	MOS		R:81				30-APR-2019		
	N394WJ1 REF:	HRS/MSC AFL	O/C	R:737.4 R:235			7722.5 3760			
CHAPTER 26		FIRE PROTECTION								
+ 26-10-00-720-801-01		FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2WG)								
26.020	36017090040013 60994 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C					21-OCT-2011 6781.4 3423	14281.4	6232.2



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-10-00-720-801-02	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2WG)									
26.020	36018290040015 62094 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C				27-OCT-2015 7355.5 3656	14855.5		6806.3
+ 26-10-00-720-801-03	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2WG)									
26.030	36017090040013 61439 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	7500/E/C				10-DEC-2009 6063.8 3056	13563.8		5514.6
+ 26-10-00-720-801-04	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - APU FIRE DETECTOR (9WG)									
26.040	36018190040009 61474 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL APH	C/C 5000				17-JUN-2008 5417.7 2752 2504	7504		3748
+ 26-10-00-720-801-05	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)									
26.050	300119800270-3 59936 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	72	+3%			26-DEC-2020 7883.1 3800	26-DEC-2026	02-MAR-2027	1257 d (+66)
+ 26-10-00-720-801-06	FUNCTIONAL TEST OF THE PNEUMATIC FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)									
26.050	300119800270-3 59933 REF: AMM 26-10-00-720-801	MOS HRS/MSC AFL	72	+3%			28-NOV-2018 7675 3744	28-NOV-2024	01-FEB-2025	499 d (+65)
26-10-17-720-801-01	FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)									
26.050	REF: AMM 26-10-17-720-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
26-10-17-720-801-02	FUNCTIONAL TEST OF THE PINPOINT FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)									
26.050	REF: AMM 26-10-17-720-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-10-17-900-801-01	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR BAY PINPOINT FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)									
26.050	300119800270-3 59936 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
26-10-17-900-801-02	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR BAY PINPOINT FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)									
26.050	300119800270-3 59933 REF: AMM 26-10-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
26-10-19-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 1 FIRE DETECTOR (L2WG)									
26.020	36017090040013 60994 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
26-10-19-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 2 FIRE DETECTOR (M2WG)									
26.020	36018290040015 62094 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
26-10-19-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - ENGINE 3 FIRE DETECTOR (R2WG)									
26.030	36017090040013 61439 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
26-10-19-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - APU FIRE DETECTOR (9WG)									
26.040	36018190040009 61474 REF: AMM 26-10-19-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-10-19-900-801-05	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - LH MLG BAY FIRE DETECTOR (L22WG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 26-10-19-900-801	AFL		N:0				0		
26-10-19-900-801-06	REMOVAL / INSTALLATION OF THE ENGINE, APU AND MAIN LANDING GEAR BAY FIRE DETECTORS - RH MLG BAY FIRE DETECTOR (R22WG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 26-10-19-900-801	AFL		N:0				0		
26-10-21-710-801-01	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT SMOKE DETECTOR - SMOKE DETECTOR (23WG)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 26-10-21-710-801	AFL						0		
26-10-25-710-801-01	OPERATIONAL TEST OF THE LAVATORY COMPARTMENT SMOKE DETECTORS									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 26-10-25-710-801	AFL						0		
26-20-00-760-801-01	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (L3WB) AND (L4WB)									
26.080		MOS						28-SEP-2016		
	REF: AMM 26-20-00-760-801	HRS/MSC	O/C							
		AFL								
26-20-00-760-801-02	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (R5WB) AND (R6WB)									
26.090		MOS						27-JUL-2016		
	REF: AMM 26-20-00-760-801	HRS/MSC	O/C					7448.9		
		AFL						3681		
26-20-00-760-801-03	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (L5WB) AND (L6WB)									
26.100		MOS						29-SEP-2016		
	REF: AMM 26-20-00-760-801	HRS/MSC	O/C							
		AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-00-760-801-04	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (R3WB) AND (R4WB)									
26.110	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C					27-JUL-2016 7448.9 3681		
26-20-00-760-801-05	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS - CIRCUITS OF PERCUSSION CARTRIDGES (9WB) AND (27WB)									
26.120	REF: AMM 26-20-00-760-801	MOS HRS/MSC AFL	O/C					27-JUL-2016 7448.9 3681		
26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH" SWITCH (2WB9) (POSITION "1")						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m				21-JUN-2023 8047.2 3851		
26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 1 "DISCH" SWITCH (2WB9) (POSITION "2")						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m				21-JUN-2023 8047.2 3851		
26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH" SWITCH (2WB14) (POSITION "1")						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m				21-JUN-2023 8047.2 3851		
26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 2 "DISCH" SWITCH (2WB14) (POSITION "2")						PKG			
	PKG 31	MOS HRS/MSC AFL	72	+2m				21-JUN-2023 8047.2 3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 3 "DISCH" SWITCH (2WB19) (POSITION "1")						PKG			
	PKG 31	MOS	72	+2m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 26-20-01-760-801	AFL	3750					3851		
26-20-01-760-801-06 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - ENGINE 3 "DISCH" SWITCH (2WB19) (POSITION "2")						PKG			
	PKG 31	MOS	72	+2m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 26-20-01-760-801	AFL	3750					3851		
+ 26-20-01-760-801-07 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE APU" SWITCH (2WB3)						PKG			
26.180	PKG 31	MOS	72	+2m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 26-20-01-760-801	AFL	3750					3851		
+ 26-20-01-760-801-08 (s)	CHECK OF THE CORRECT OPERATION OF FIRE EXTINGUISHER CONTROL SWITCHES - "FIRE BAG COMP" SWITCH (2WB1)						PKG			
26.180	PKG 31	MOS	72	+2m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 26-20-01-760-801	AFL	3750					3851		
26-20-01-900-801-01	REMOVAL / INSTALLATION OF THE FIRE CONTROL PANEL - FIRE CONTROL PANEL (2WB)									
26.010	90350-1	MOS						11-JAN-1988		
	158	HRS/MSC	O/C		N:0			0		
	REF: AMM 26-20-01-900-801	AFL						0		
+ 26-20-09-220-801-01	WEIGHING OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)									
26.120	863470-01	MOS	18	+3%				08-MAY-2023	01-MAY-2024 M	17-MAY-2024 288 d (+16)
	UE001927	HRS/MSC								
	REF: AMM 26-20-09-220-801	AFL								
+ 26-20-09-220-801-02	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)									
26.080	863470-01	MOS	18	+3%				08-MAY-2023	01-MAY-2024 M	17-MAY-2024 288 d (+16)
	UE003422	HRS/MSC								
	REF: AMM 26-20-09-220-801	AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-09-220-801-03	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)									
26.100	863470-01 UE001713 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	18	+3%			08-MAY-2023	01-MAY-2024 M	17-MAY-2024	288 d (+16)
+ 26-20-09-220-801-04	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)									
26.110	861630 55245 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	12	+1m			08-MAY-2023	08-MAY-2024	08-JUN-2024	295 d (+31)
+ 26-20-09-220-801-05	WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)									
26.090	861630 57511 REF: AMM 26-20-09-220-801	MOS HRS/MSC AFL	12	+1m			04-MAY-2023	04-MAY-2024	04-JUN-2024	291 d (+31)
+ 26-20-09-350-801-01	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)									
26.120 MANDATORY	863470-01 UE001927 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				21-JUL-2021	21-JUL-2031		2925 d
+ 26-20-09-350-801-02	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)									
26.080 MANDATORY	863470-01 UE003422 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				10-NOV-2021	10-NOV-2031		3037 d
+ 26-20-09-350-801-03	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)									
26.100 MANDATORY	863470-01 UE001713 REF: AMM 26-20-09-350-801	MOS HRS/MSC AFL	120				11-NOV-2021	11-NOV-2031		3038 d

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-09-350-801-04	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)									
26.110	861630	MOS	60				31-OCT-2019	31-OCT-2024		471 d
MANDATORY	55245	HRS/MSC								
	REF: AMM 26-20-09-350-801	AFL								
+ 26-20-09-350-801-05	RESTORATION OF THE FIRE EXTINGUISHERS (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION) - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)									
26.090	861630	MOS	60				01-MAY-2023	01-MAY-2028		1749 d
MANDATORY	57511	HRS/MSC								
	REF: AMM 26-20-09-350-801	AFL								
26-20-09-900-801-01	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)									
26.120	863470-01	MOS		O:9 R:3			21-JUL-2021			
	UE001927	HRS/MSC	H/T	O:0			7907.8			
	REF: AMM 26-20-09-900-801	AFL		O:0			3809			
26-20-09-900-801-02	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)									
26.080	863470-01	MOS		O:1			17-DEC-2021			
	UE003422	HRS/MSC	H/T	O:0			7940.3			
	REF: AMM 26-20-09-900-801	AFL		O:0			3817			
26-20-09-900-801-03	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)									
26.100	863470-01	MOS		O:1			17-DEC-2021			
	UE001713	HRS/MSC	H/T	O:0			7940.3			
	REF: AMM 26-20-09-900-801	AFL		O:0			3817			
26-20-09-900-801-04	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)									
26.110	861630	MOS		O:0			24-MAR-2020			
	55245	HRS/MSC	H/T	O:0			7838			
	REF: AMM 26-20-09-900-801	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-09-900-801-05	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)									
26.090	861630	MOS		O:39				27-JUN-2023		
	57511	HRS/MSC	H/T	O:211.2				8049.2		
	REF: AMM 26-20-09-900-801	AFL		O:3853				3853		
26-20-11-700-801-01	CHECKING OF THE APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER FOR CLOGGING									
		MOS						28-NOV-2018		
		HRS/MSC	O/C					7675		
	REF: AMM 26-20-11-700-801	AFL						3744		
26-20-11-700-801-02	CHECKING OF THE NO. 1 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING									
		MOS						28-NOV-2018		
		HRS/MSC	O/C					7675		
	REF: AMM 26-20-11-700-801	AFL						3744		
26-20-11-700-801-03	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 1 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING									
		MOS						28-NOV-2018		
		HRS/MSC	O/C					7675		
	REF: AMM 26-20-11-700-801	AFL						3744		
26-20-11-700-801-04	CHECKING OF THE NO. 3 ENGINE FIRST-SHOOT, NO. 2 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING									
		MOS						28-NOV-2018		
		HRS/MSC	O/C					7675		
	REF: AMM 26-20-11-700-801	AFL						3744		
26-20-11-700-801-05	CHECKING OF THE NO. 2 ENGINE FIRST-SHOOT, NO. 3 ENGINE SECOND-SHOOT FIRE EXTINGUISHER LINES FOR CLOGGING									
		MOS						28-NOV-2018		
		HRS/MSC	O/C					7675		
	REF: AMM 26-20-11-700-801	AFL						3744		
+ 26-20-11-700-801-07 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE A									
	PKG 31	MOS	72					21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 26-20-11-700-801	AFL	3750					3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-11-700-801-08 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE B PKG 31	MOS HRS/MSC	72				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 26-20-11-700-801	AFL	3750							
+ 26-20-11-700-801-09 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE C PKG 31	MOS HRS/MSC	72				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 26-20-11-700-801	AFL	3750							
+ 26-20-11-700-801-10 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE D PKG 31	MOS HRS/MSC	72				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 26-20-11-700-801	AFL	3750							
+ 26-20-11-700-801-11 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE E PKG 31	MOS HRS/MSC	72				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 26-20-11-700-801	AFL	3750							
+ 26-20-11-700-801-12 (s)	CHECKING EXTINGUISHING LINES FOR CLOGGING - EXTINGUISHING LINE F PKG 31	MOS HRS/MSC	72				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 26-20-11-700-801	AFL	3750							
26-20-12-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L509WB) 861585A	MOS					11-JAN-1988			
26.200	207	HRS/MSC	H/T	N:0			0			
	REF: AMM 26-20-12-900-801	AFL					0			
26-20-12-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 3 SHUTTLE VALVE (R509WB) 861585A	MOS					11-JAN-1988			
26.200	210	HRS/MSC	H/T	N:0			0			
	REF: AMM 26-20-12-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-12-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 2 LH SHUTTLE VALVE (M509WB1)									
26.210	861585A 208 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	N:0			11-JAN-1988 0 0			
26-20-12-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE SHUTTLE VALVES - ENGINE 2 RH SHUTTLE VALVE (M509WB2)									
26.210	861585A 209 REF: AMM 26-20-12-900-801	MOS HRS/MSC AFL	H/T	N:0			11-JAN-1988 0 0			
26-20-12-960-801-01	DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 1 SHUTTLE VALVE (L509WB)									
SCRAP	861585A 207 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	I:0			11-JAN-1988 0 0			
26-20-12-960-801-02	DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 3 SHUTTLE VALVE (R509WB)									
SCRAP	861585A 210 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	I:0			11-JAN-1988 0 0			
26-20-12-960-801-03	DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 2 LH SHUTTLE VALVE (M509WB1)									
SCRAP	861585A 208 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	I:0			11-JAN-1988 0 0			
26-20-12-960-801-04	DISCARD OF THE ENGINE SHUTTLE VALVES - ENGINE 2 RH SHUTTLE VALVE (M509WB2)									
SCRAP	861585A 209 REF: AMM 26-20-12-960-801	MOS HRS/MSC AFL	A/R	I:0			11-JAN-1988 0 0			
26-20-13-900-801-01	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)									
	862710-00 NSN REF: AMM 26-20-13-900-801	MOS HRS/MSC AFL	H/T	N:15 N:0 N:0			17-DEC-2021 7940.3 3817			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-900-801-02	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)									
	861375	MOS		N:2				08-JUL-2017		
	SN-UNKNOWN	HRS/MSC	H/T	N:0				7550.7		
	REF: AMM 26-20-13-900-801	AFL		N:0				3709		
		APH						3576		
26-20-13-900-801-03	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)									
	862700-00	MOS		N:2				17-DEC-2021		
	NSN	HRS/MSC	H/T	N:0				7940.3		
	REF: AMM 26-20-13-900-801	AFL		N:0				3817		
26-20-13-900-801-04	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)									
	861385	MOS		N:2				08-JUL-2017		
	SN-UNKNOWN	HRS/MSC	H/T	N:0				7550.7		
	REF: AMM 26-20-13-900-801	AFL		N:0				3709		
		APH						3576		
26-20-13-900-801-05	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)									
	862710-00	MOS		N:15				17-DEC-2021		
	NSN	HRS/MSC	H/T	N:0				7940.3		
	REF: AMM 26-20-13-900-801	AFL		N:0				3817		
26-20-13-900-801-06	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)									
	861375	MOS		N:2				08-JUL-2017		
	SN-UNKNOWN	HRS/MSC	H/T	N:0				7550.7		
	REF: AMM 26-20-13-900-801	AFL		N:0				3709		
		APH						3576		
26-20-13-900-801-07	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)									
	862700-00	MOS		N:2				17-DEC-2021		
	N/A	HRS/MSC	H/T	N:0				7940.3		
	REF: AMM 26-20-13-900-801	AFL		N:0				3817		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-900-801-08	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)									
	861385	MOS		N:2			08-JUL-2017			
	SN-UNKNOWN	HRS/MSC	H/T	N:0			7550.7			
	REF: AMM 26-20-13-900-801	AFL		N:0			3709			
		APH					3576			
26-20-13-900-801-09	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (27WB)									
	862700-00	MOS		N:25			21-JUL-2021			
	SN-UNKNOWN	HRS/MSC	H/T	N:0			7907.8			
	REF: AMM 26-20-13-900-801	AFL		N:0			3809			
26-20-13-900-801-10	REMOVAL / INSTALLATION OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (9WB)									
	862710-00	MOS		N:30			21-JUL-2021			
	SN-UNKNOWN	HRS/MSC	H/T	N:0			7907.8			
	REF: AMM 26-20-13-900-801	AFL		N:0			3809			
26-20-13-960-801-01	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)									
26.080	862710-00	MOS					17-DEC-2021			
	NSN	HRS/MSC	O/C							
	REF: AMM 26-20-13-960-801	AFL								
26-20-13-960-801-01M	DISCARD NO. 1 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (L3WB) CARTRIDGE (LIFE LIMIT)									
26.080	862710-00	MOS	120				16-SEP-2020	16-SEP-2030		2617 d
	NSN	HRS/MSC								
LIFE LIMIT	REF: AMM 26-20-13-960-801	AFL								
26-20-13-960-801-02	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)									
26.110	861375	MOS	60				08-JUL-2022	08-JUL-2027		1451 d
	SN-UNKNOWN	HRS/MSC								
SCRAP	REF: AMM 26-20-13-960-801	AFL								
26-20-13-960-801-02M	DISCARD NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE (LIFE LIMIT)									
26.110	861375	MOS	84				08-MAR-2022	08-MAR-2029		2060 d
	SN-UNKNOWN	HRS/MSC								
LIFE LIMIT	REF: AMM 26-20-13-960-801	AFL								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-960-801-03	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)							17-DEC-2021		
26.080	862700-00 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	O/C							
26-20-13-960-801-03M	DISCARD NO. 2 ENGINE SECOND SHOOT LH FIRE EXTINGUISHER PERCUSSION (L4WB) CARTRIDGE (LIFE LIMIT)							27-OCT-2021	27-OCT-2031	3023 d
26.080	862700-00 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	120							
LIFE LIMIT										
26-20-13-960-801-04	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)							08-JUL-2022	08-JUL-2027	1451 d
26.110	861385 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60							
SCRAP										
26-20-13-960-801-04M	DISCARD NO. 2 ENGINE SECOND SHOOT RH FIRE EXTINGUISHER PERCUSSION (R4WB) CARTRIDGE (LIFE LIMIT)							08-MAR-2022	08-MAR-2029	2060 d
26.110	861385 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84							
LIFE LIMIT										
26-20-13-960-801-05	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)							17-DEC-2021		
26.100	862710-00 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	O/C							
26-20-13-960-801-05M	DISCARD NO. 1 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (L5WB) CARTRIDGE (LIFE LIMIT)							16-SEP-2020	16-SEP-2030	2617 d
26.100	862710-00 NSN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	120							
LIFE LIMIT										
26-20-13-960-801-06	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)							08-JUL-2022	08-JUL-2027	1451 d
26.090	861375 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60							
SCRAP										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-960-801-06M	DISCARD NO. 3 ENGINE SECOND SHOOT FIRE EXTINGUISHER PERCUSSION (R5WB) CARTRIDGE (LIFE LIMIT) 861375 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				08-MAR-2022	08-MAR-2029		2060 d
26.090 LIFE LIMIT										
26-20-13-960-801-07	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB) 862700-00 N/A REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	O/C				17-DEC-2021			
26.100										
26-20-13-960-801-07M	DISCARD NO. 2 ENGINE FIRST SHOOT LH FIRE EXTINGUISHER PERCUSSION (L6WB) CARTRIDGE (LIFE LIMIT) 862700-00 N/A REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	120				27-OCT-2021	27-OCT-2031		3023 d
26.100 LIFE LIMIT										
26-20-13-960-801-08	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB) 861385 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	60				08-JUL-2022	08-JUL-2027		1451 d
26.090 SCRAP										
26-20-13-960-801-08M	DISCARD NO. 2 ENGINE FIRST SHOOT RH FIRE EXTINGUISHER PERCUSSION (R6WB) CARTRIDGE (LIFE LIMIT) 861385 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	84				08-MAR-2022	08-MAR-2029		2060 d
26.090 LIFE LIMIT										
26-20-13-960-801-09	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - APU PERCUSSION CARTRIDGE (27WB) 862700-00 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	O/C				21-JUL-2021			
26.120										
26-20-13-960-801-09M	DISCARD APU FIRE EXTINGUISHER PERCUSSION (27WB) CARTRIDGE (LIFE LIMIT) 862700-00 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	120				01-JUN-2019	01-JUN-2029		2145 d
26.120 LIFE LIMIT										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-20-13-960-801-10	DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (9WB)									
26.120	862710-00 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	O/C				21-JUL-2021			
26-20-13-960-801-10M	DISCARD BAGGAGE COMPARTMENT FIRE EXTINGUISHER PERCUSSION (9WB) CARTRIDGE (LIFE LIMIT)									
26.120 LIFE LIMIT	862710-00 SN-UNKNOWN REF: AMM 26-20-13-960-801	MOS HRS/MSC AFL	120				01-JAN-2019	01-JAN-2029		1994 d
+ 26-20-15-720-801-01	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)									
26.130	C352 Y-455833 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			24-MAY-2023	24-MAY-2024	04-JUN-2024	311 d (+11)
+ 26-20-15-720-801-02	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)									
26.140	C352 Y-455849 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			15-JUN-2023	15-JUN-2024	25-JUN-2024	333 d (+10)
+ 26-20-15-720-801-03	WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)									
26.150	C352 Y-455834 REF: AMM 26-20-15-720-801	MOS HRS/MSC AFL	12	+3%			15-JUN-2023	15-JUN-2024	25-JUN-2024	333 d (+10)
+ 26-20-15-790-801-01	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)									
26.130	C352 Y-455833 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				01-JUL-2013	01-JUL-2025		714 d
+ 26-20-15-790-801-02	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)									
26.140	C352 Y-455849 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				01-JUL-2013	01-JUL-2025		714 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 26-20-15-790-801-03	HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)									
26.150	C352 Y-455834 REF: AMM 26-20-15-790-801	MOS HRS/MSC AFL	144				01-JUL-2013	01-JUL-2025		714 d
26-20-19-720-801-01	WEIGHING OF THE DISPOSABLE FIRE EXTINGUISHER - DISPOSABLE FIRE EXTINGUISHER (L7513ME)									
	PN NOT INSTALLED REF: AMM 26-20-19-720-801	MOS HRS/MSC AFL	N/A							
26-90-01-900-801-01	DISPOSABLE FIRE EXTINGUISHER									
	PN NOT INSTALLED REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
261251	BAGGAGE COMPARTMENT SMOKE DETECTOR									
26.060	FR2210-2 385 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				02-JAN-1998 2279 1626			
261301	NO. 1 AND NO. 3 ENGINE MONITOR BOX									
26.070	6342-01 295 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
261311	NO. 2 ENGINE AND APU FIRE MONITOR BOX									
26.070	6342-01 291 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
262601	COCKPIT PORTABLE HALON FIRE EXTINGUISHER									
26.130	C352 Y-455833 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:5 N:0 N:0			03-DEC-2013 7168.1 3589			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
262651	FORWARD CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.140	C352 Y-455849 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:5 N:0 N:0			03-DEC-2013 7168.1 3589			
262701	AFT CABIN PORTABLE HALON FIRE EXTINGUISHER									
26.150	C352 Y-455834 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:5 N:0 N:0			03-DEC-2013 7168.1 3589			
262751	BAGGAGE COMPARTMENT PORTABLE EXTINGUISHER									
	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	N/A							
CHAPTER 27 FLIGHT CONTROLS										
27-00-00-220-801-01	INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 27-00-00-220-801-01A	INTEGRITY CHECK AND VISUAL INSPECTION FOR CORROSION AND EXTERNAL LEAKS ON FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY 5-40)									
27.010 MANDATORY 5-40		MOS HRS/MSC AFL	4000				16-JUL-2012 6985.1 3525	10985.1		2935.9
27-00-00-270-801-01	ULTRASONIC INSPECTION OF FLIGHT CONTROL SYSTEM COMPOSITE RODS									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-00-00-640-801-01 (s)	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - LHAILERON SERVO-ACTUATOR (L521CC)									
27.065	PKG 32 REF: AMM 27-00-00-640-801	MOS HRS/MSC AFL	144 7500	+2m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-640-801-02 (s)	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RH AILERON SERVO-ACTUATOR (R521CC)						PKG			
27.065	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-801	AFL	7500							
27-00-00-640-801-03 (s)	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - RUDDER SERVO-ACTUATOR (571CC)						PKG			
27.125	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-801	AFL	7500							
27-00-00-640-801-04 (s)	PRESSURE GREASING OF THE SERVO-ACTUATOR BEARINGS - ELEVATOR SERVO-ACTUATOR (522CW)						PKG			
27.200	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-801	AFL	7500							
27-00-00-640-803-01 (s)	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA						PKG			
27.020	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-803	AFL	7500							
27-00-00-640-804-01 (s)	PRESSURE GREASING / LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS OUTSIDE PRESSURIZED AREA						PKG			
27.015	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-804	AFL	7500							
+ 27-00-00-640-806-01 (s)	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES - RUDDER						PKG			
27.155	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-806	AFL	7500							
+ 27-00-00-640-806-02 (s)	VISUAL INSPECTION AND GREASING OF YAW AND PITCH CONTROL SEALED BOXES - ELEVATOR						PKG			
27.252	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-640-806	AFL	7500							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-710-801-01 (s)	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 1 PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
	REF: AMM 27-00-00-710-801									
27-00-00-710-801-02 (s)	OPERATIONAL TEST OF THE FLIGHT CONTROLS - HYDRAULIC SYSTEM 2 PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
	REF: AMM 27-00-00-710-801									
27-00-00-710-802-01 (s)	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL TRIM PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 27-00-00-710-802		3750							
27-00-00-710-802-02 (s)	OPERATIONAL TEST OF THE TRIM SYSTEMS - ROLL EMERGENCY TRIM PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 27-00-00-710-802		3750							
+ 27-00-00-710-802-03 (s)	OPERATIONAL TEST OF THE TRIM SYSTEMS - YAW TRIM PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
27.075	REF: AMM 27-00-00-710-802		3750							
+ 27-00-00-720-803-01 (s)	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L522CC) PKG 32	MOS HRS/MSC AFL	144	+2m			PKG 21-JUN-2023 8047.2 3851			
27.095	REF: AMM 27-00-00-720-803		7500							
+ 27-00-00-720-803-01A	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - LH ROLL AAFU (L522CC) (MANDATORY 5-40) PKG 32	MOS HRS/MSC AFL	10000				21-JUN-2023 8047.2 3851	18047.2		9998
27.095 MANDATORY 5-40	REF: AMM 27-00-00-720-803									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-00-00-720-803-02 (s)	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R522CC)						PKG			
27.095	PKG 32	MOS	144	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 27-00-00-720-803	HRS/MSC AFL	7500							
+ 27-00-00-720-803-02A	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - RH ROLL AAFU (R522CC) (MANDATORY 5-40)									
27.095		MOS					21-JUN-2023 8047.2 3851	18047.2		9998
MANDATORY 5-40	REF: AMM 27-00-00-720-803	HRS/MSC AFL	10000							
+ 27-00-00-720-803-03 (s)	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (523CW)						PKG			
27.230	PKG 32	MOS	144	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 27-00-00-720-803	HRS/MSC AFL	7500							
+ 27-00-00-720-803-03A	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - PITCH AAFU (523CW) (MANDATORY 5-40)									
27.230		MOS					21-JUN-2023 8047.2 3851	18047.2		9998
MANDATORY 5-40	REF: AMM 27-00-00-720-803	HRS/MSC AFL	10000							
+ 27-00-00-720-803-04 (s)	FUNCTIONAL TEST OF THE AUXILIARY AFU (AAFU CONNECTION AND VISUAL INSPECTION) - YAW AAFU (572CC)						PKG			
27.165	PKG 32	MOS	144	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 27-00-00-720-803	HRS/MSC AFL	7500							
+ 27-00-00-720-803-04A	FUNCTIONAL CHECK (AAFU CONNECTION AND VISUAL INSPECTION) (MANDATORY 5-40)									
27.165		MOS					21-JUN-2023 8047.2 3851	18047.2		9998
MANDATORY 5-40	REF: AMM 27-00-00-720-803	HRS/MSC AFL	10000							
27-00-00-720-806-01	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - ROLL									
		MOS					11-JAN-1988 0 0			
	REF: AMM 27-00-00-720-806	HRS/MSC AFL	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-720-806-02	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - YAW	MOS					11-JAN-1988			
	REF: AMM 27-00-00-720-806	HRS/MSC	O/C				0			
		AFL					0			
27-00-00-720-806-03	BRIEF CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - PITCH	MOS					11-JAN-1988			
	REF: AMM 27-00-00-720-806	HRS/MSC	O/C				0			
		AFL					0			
27-00-00-720-807-01	DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - AILERON	MOS					11-JAN-1988			
	REF: AMM 27-00-00-720-807	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-720-807-02	DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - RUDDER	MOS					11-JAN-1988			
	REF: AMM 27-00-00-720-807	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-720-807-03	DETAILED CHECK OF THE FLIGHT CONTROL FORCE PATTERNS - ELEVATOR	MOS					11-JAN-1988			
	REF: AMM 27-00-00-720-807	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
27-00-00-790-804-01 (s)	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L521CC)						PKG			
	PKG 31	MOS	72	+2m			21-JUN-2023			
27.065	REF: AMM 27-00-00-790-804	HRS/MSC					8047.2			
		AFL	3750				3851			
27-00-00-790-804-02 (s)	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R521CC)						PKG			
	PKG 31	MOS	72	+2m			21-JUN-2023			
27.065	REF: AMM 27-00-00-790-804	HRS/MSC					8047.2			
		AFL	3750				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-790-804-03 (s)	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - RUDDER SERVO-ACTUATOR (571CC)						PKG			
27.125	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-790-804	AFL	3750							
27-00-00-790-804-04 (s)	CHECK OF THE INTERNAL LEAKS OF SERVO-ACTUATORS - ELEVATOR SERVO-ACTUATOR (522CW)						PKG			
27.200	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 27-00-00-790-804	AFL	3750							
27-00-00-900-806-01	REMOVAL / INSTALLATION OF THE AIRBRAKE / TAILPLANE / TRIM CONTROL BOX - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF)									
27.035	013015-14	MOS					11-JAN-1988	0	0	
	1171	HRS/MSC	O/C	N:0						
	REF: AMM 27-00-00-900-806	AFL								
27-00-00-910-801-01	FLIGHT CONTROL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS									
		MOS					11-JAN-1988	0	0	
	REF: AMM 27-00-00-910-801	HRS/MSC	O/C							
		AFL								
27-00-00-910-802-01	PRECAUTIONS TO BE TAKEN WHEN REPLACING FLIGHT CONTROL SYSTEM COMPONENTS									
		MOS					11-JAN-1988	0	0	
	REF: AMM 27-00-00-910-802	HRS/MSC	O/C							
		AFL								
27-00-00-910-803-01	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - ROLL TRIM ACTUATOR (13CC)									
		MOS					11-JAN-1988	0	0	
	REF: AMM 27-00-00-910-803	HRS/MSC	O/C							
		AFL								
27-00-00-910-803-02	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - ROLL EMERGENCY TRIM ACTUATOR (22CC)									
		MOS					11-JAN-1988	0	0	
	REF: AMM 27-00-00-910-803	HRS/MSC	O/C							
		AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-910-803-03	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - YAW TRIM ACTUATOR (3CC)	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-803-04	SETTING THE FLIGHT CONTROL TRIMS TO THE NEUTRAL POSITION - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-803	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-804-01	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - AILERON	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-804-02	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - RUDDER	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-804-03	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - ELEVATOR	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-804-04	USE OF THE FLIGHT CONTROL SURFACE DEFLECTION MEASURING FIXTURES - HORIZONTAL STABILIZER	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-804	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-805-01	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - ROLL CONTROL LINKAGE	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-805	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-00-00-910-805-02	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - YAW CONTROL LINKAGE	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-805	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-805-03	REMOVAL / INSTALLATION OF THE FLIGHT CONTROL RIGGING PINS - PITCH CONTROL LINKAGE	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-805	HRS/MSC	O/C					0		
		AFL						0		
27-00-00-910-806-01	FLIGHT CONTROL RODS: ACCEPTANCE CRITERIA	MOS						11-JAN-1988		
	REF: AMM 27-00-00-910-806	HRS/MSC	O/C					0		
		AFL						0		
27-10-00-720-801-01	FUNCTIONAL TEST OF AILERON DEFLECTION	MOS						11-JAN-1988		
	REF: AMM 27-10-00-720-801	HRS/MSC	O/C					0		
		AFL						0		
27-10-00-820-801-01	ADJUSTMENT / TEST OF THE ROLL CONTROL	MOS						11-JAN-1988		
	REF: AMM 27-10-00-820-801	HRS/MSC	O/C					0		
		AFL						0		
27-12-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - LH AILERON SERVO-ACTUATOR (L521CC)	MOS						27-JUN-2023		
27.065	103117-05	HRS/MSC	O/C	R:0				8049.2		
	479	AFL		N:8049.2 R:0				3853		
	REF: AMM 27-12-01-900-801			R:0						
27-12-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERON SERVO-ACTUATORS - RH AILERON SERVO-ACTUATOR (R521CC)	MOS						06-NOV-2015		
27.065	103117-06	HRS/MSC	O/C	R:0				7355.5		
	5002	AFL		N:746 R:0				3656		
	REF: AMM 27-12-01-900-801			N:336 R:0						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA PKG 31	MOS	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 27-13-01-640-806	AFL	3750							
27-13-01-640-808-01 (s) 27.050	GREASING OF THE ROLL CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA PKG 16	MOS	24	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 27-13-01-640-808	AFL								
27-13-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L500CC) PN	MOS		N:0			11-JAN-1988 0			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-13-01-900-801	AFL		N:0			0			
27-13-01-900-801-02	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R500CC) PN	MOS		N:0			11-JAN-1988 0			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-13-01-900-801	AFL		N:0			0			
27-13-01-900-801-03	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (501CC) PN	MOS		N:0			11-JAN-1988 0			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-13-01-900-801	AFL		N:0			0			
27-13-01-900-801-04	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (502CC) PN	MOS		N:0			11-JAN-1988 0			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-13-01-900-801	AFL		N:0			0			
27-13-01-900-801-05	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (503CC) PN	MOS		N:0			11-JAN-1988 0			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 27-13-01-900-801	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-900-801-08	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (506CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-09	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (507CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-11	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L509CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-12	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R509CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-13	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L510CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-14	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R510CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-15	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L511CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-900-801-16	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R511CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-17	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L512CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-18	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R512CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-19	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L513CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-20	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R513CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-21	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L514CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-22	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R514CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-900-801-23	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L515CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-24	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R515CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-25	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L516CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-26	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R516CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-27	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (517CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-28	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH AILERON SERVO-ACTUATOR DRIVE ROD (L518CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-29	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH AILERON SERVO-ACTUATOR DRIVE ROD (R518CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-900-801-30	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L519CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-31	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R519CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-32	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH AILERON DRIVE CONTROL (L520CC1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-33	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - LH AILERON DRIVE CONTROL (L520CC2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-34	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH AILERON DRIVE CONTROL (R520CC1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-35	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - RH AILERON DRIVE CONTROL (R520CC2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		
27-13-01-900-801-36	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (T504CC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-13-01-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-01-900-801-37	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (T505CC) PN SN-UNKNOWN REF: AMM 27-13-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
27-13-01-900-801-38	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL EMERGENCY TRIM ACTUATOR (22CC) PN SN-UNKNOWN REF: AMM 27-13-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
27-13-01-900-801-39	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (L508CC) PN SN-UNKNOWN REF: AMM 27-13-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
27-13-01-900-801-40	REMOVAL / INSTALLATION OF THE ROLL CONTROL RODS - ROLL CONTROL ROD (R508CC) PN SN-UNKNOWN REF: AMM 27-13-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
27-13-01-900-802-01	REMOVAL / INSTALLATION OF THE CONTROL WHEEL - PILOT CONTROL WHEEL (10CR) FGFB215250850 047 REF: AMM 27-13-01-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-13-01-900-802-02	REMOVAL / INSTALLATION OF THE CONTROL WHEEL - COPILOT CONTROL WHEEL (20CR) FGFB215500850 045 REF: AMM 27-13-01-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-13-03-960-801-01 (s)	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - LH FR15 ROLL BELLCRANK BALL BEARINGS PKG 31 REF: AMM 27-13-03-960-801	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-13-03-960-801-02 (s)	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - RH FR15 ROLL BELLCRANK BALL BEARINGS PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 27-13-03-960-801	AFL	3750							
+ 27-13-05-640-801-01 (s)	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES - LH ROLL PRESSURE-SEALED BOX (L14CC) PKG 32	MOS HRS/MSC	144	+2m			PKG 21-JUN-2023 8047.2 3851			
27.097	REF: AMM 27-13-05-640-801	AFL	7500							
+ 27-13-05-640-801-02 (s)	VISUAL INSPECTION AND GREASING OF ROLL CONTROL SEALED BOXES - RH ROLL PRESSURE-SEALED BOX (R14CC) PKG 32	MOS HRS/MSC	144	+2m			PKG 21-JUN-2023 8047.2 3851			
27.097	REF: AMM 27-13-05-640-801	AFL	7500							
+ 27-14-01-350-801-01	RESTORATION OF THE ROLL TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL TRIM ACTUATOR (13CC) 021057-32	MOS HRS/MSC	144	+3%		-159	16-JUL-2012 6985.1 3525	08-FEB-2024	17-JUN-2024	205 d (+130)
27.080	7636 REF: AMM 27-14-01-350-801	AFL								
27-14-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL TRIM ACTUATOR - ROLL TRIM ACTUATOR (13CC) 021057-32	MOS HRS/MSC	O/C		R:0 N:6921.1 R:0 R:0		16-JUL-2012 6985.1 3525			
27.080	7636 REF: AMM 27-14-01-900-801	AFL								
+ 27-14-03-350-801-01	RESTORATION OF THE ROLL EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST) - ROLL EMERGENCY TRIM ACTUATOR (22CC) 021127	MOS HRS/MSC	144	+3%			09-DEC-2016 6985.1 3525	09-DEC-2028	18-APR-2029	1971 d (+130)
27.070	143 REF: AMM 27-14-03-350-801	AFL								
27-14-03-720-802-01	FUNCTIONAL TEST OF THE ROLL EMERGENCY TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (22CC) MOS	HRS/MSC	O/C				11-JAN-1988 0 0			
	REF: AMM 27-14-03-720-802	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-14-03-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY ROLL TRIM ACTUATOR - ROLL EMERGENCY TRIM ACTUATOR (22CC)									
27.070	021127 143 REF: AMM 27-14-03-900-801	MOS HRS/MSC AFL	O/C	R:23 R:0 R:0			28-NOV-2018 7675 3744			
+ 27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS - ROLL TRIM RELAY BOX (12CC)						PKG			
27.085	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			21-JUN-2023 8047.2 3851			
+ 27-14-05-720-801-01A	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAYS - ROLL TRIM RELAY BOX (12CC) (MANDATORY 5-40)									
27.085 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				21-JUN-2023 8047.2 3851	28047.2		19998
27-15-00-720-801-01	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK MONITORING SYSTEM									
	REF: AMM 27-15-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-15-01-640-801-01 (s)	PRESSURE GREASING OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS - ROLL ARTHUR VARIABLE BELLCRANK (33CW)						PKG			
27.060	PKG 32 REF: AMM 27-15-01-640-801	MOS HRS/MSC AFL	144 7500	+2m			21-JUN-2023 8047.2 3851			
+ 27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (33CW)						PKG			
27.060	PKG 31 REF: AMM 27-15-01-720-801	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
27-15-01-900-801-01	REMOVAL / INSTALLATION OF THE ROLL ARTHUR VARIABLE BELLCRANK - ROLL ARTHUR VARIABLE BELLCRANK (33CW)									
27.060	106043-28 1988 REF: AMM 27-15-01-900-801	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			17-DEC-2021 7940.3 3817			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-15-03-960-801-01	REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLING OF THE ROLL ARTHUR VARIABLE BELLCRANK	MOS HRS/MSC AFL	O/C							
	REF: AMM 27-15-03-960-801									
27-15-05-350-801-01	RESTORATION OF THE ROLL MAIN AFU (FUNCTIONAL TEST / SERVICING) - ROLL MAIN AFU (523CC)	MOS HRS/MSC AFL	144	+3%			16-JUL-2012 6985.1 3525	16-JUL-2024	25-NOV-2024	364 d (+132)
	105124 45 REF: AMM 27-15-05-350-801									
27-15-05-900-801-01	REMOVAL / INSTALLATION OF THE ROLL MAIN AFU - ROLL MAIN AFU (523CC)	MOS HRS/MSC AFL	O/C	R:2 N:6985.1 R:0 R:0			16-JUL-2012 6985.1 3525			
	105124 45 REF: AMM 27-15-05-900-801									
27-15-07-640-801-01 (s)	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - LH ROLL AAFU (L522CC)	MOS HRS/MSC AFL	144	+2m			PKG 21-JUN-2023 8047.2 3851			
	PKG 32 27.095 REF: AMM 27-15-07-640-801									
27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE ROLL AUXILIARY AFU BEARING - RH ROLL AAFU (R522CC)	MOS HRS/MSC AFL	144	+2m			PKG 21-JUN-2023 8047.2 3851			
	PKG 32 27.095 REF: AMM 27-15-07-640-801									
27-15-07-900-801-01	REMOVAL / INSTALLATION OF THE ROLL AUXILIARY AFU - LH ROLL AAFU (L522CC)	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
	PN SN-UNKNOWN REF: AMM 27-15-07-900-801									
27-20-00-720-801-01	FUNCTIONAL TEST OF THE RUDDER CONTROL SURFACE DEFLECTION	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-20-00-720-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-20-00-820-801-01	ADJUSTMENT / TEST OF THE YAW CONTROL	MOS					11-JAN-1988			
	REF: AMM 27-20-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
+ 27-22-01-350-801-01	RESTORATION OF THE RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) - RUDDER SERVO-ACTUATOR (571CC)	MOS					26-DEC-2020			
27.125	103103-18	HRS/MSC	4000				7883.1	11883.1		3833.9
	1213	AFL					3800			
	REF: AMM 27-22-01-350-801									
+ 27-22-01-350-801-01A	RESTORATION RUDDER SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10)	MOS					26-DEC-2020			
27.125	103103-18	HRS/MSC	4000				7883.1	11883.1		3833.9
	1213	AFL					3800			
	REF: AMM 27-22-01-350-801									
	MANDATORY 5-40									
27-22-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER SERVO-ACTUATOR - RUDDER SERVO-ACTUATOR (571CC)	MOS					26-DEC-2020			
27.125	103103-18	HRS/MSC	O/C	R:13			7883.1			
	1213	AFL		N:3863 R:0			3800			
	REF: AMM 27-22-01-900-801			N:1715 R:0						
27-23-01-640-806-01 (s)	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA	MOS	72	+2m			21-JUN-2023			
27.115	PKG 31	HRS/MSC					8047.2			
	REF: AMM 27-23-01-640-806	AFL	3750				3851			
27-23-01-640-807-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA	MOS	72	+2m			21-JUN-2023			
27.110	PKG 31	HRS/MSC					8047.2			
	REF: AMM 27-23-01-640-807	AFL	3750				3851			
27-23-01-640-808-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA	MOS	24	+1m			21-JUN-2023			
27.105	PKG 16	HRS/MSC					8047.2			
	REF: AMM 27-23-01-640-808	AFL					3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-23-01-900-801-01	REMOVAL / INSTALLATION OF THE YAW CONTROL RODS PN SN-UNKNOWN REF: AMM 27-23-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 27-24-01-350-801-01	RESTORATION OF THE YAW TRIM ACTUATOR (FUNCTIONAL TEST) - YAW TRIM ACTUATOR (3CC) 021057-28 7716 REF: AMM 27-24-01-350-801	MOS HRS/MSC AFL	144	+3%			16-JUL-2012 6985.1 3525	16-JUL-2024	25-NOV-2024	364 d (+132)
27-24-01-900-801-01	REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW TRIM ACTUATOR (3CC) 021057-28 7716 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			16-JUL-2012 6985.1 3525			
27-24-01-900-801-02	REMOVAL / INSTALLATION OF THE YAW MAIN AFU / YAW TRIM ACTUATOR ASSEMBLY - YAW MAIN AFU (573CC) 105125 35 REF: AMM 27-24-01-900-801	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			16-JUL-2012 6985.1 3525			
+ 27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM RELAY BOX (2CC) PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m 7500			21-JUN-2023 8047.2 3851			
+ 27-24-05-720-802-01A	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS - YAW TRIM RELAY BOX (2CC) (MANDATORY 5-40) 27.150 MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL	20000				21-JUN-2023 8047.2 3851	28047.2		19998
27-25-05-350-801-01	RESTORATION OF THE YAW MAIN AFU (FUNCTIONAL TEST / SERVICING) - YAW MAIN AFU (573CC) 105125 35 REF: AMM 27-25-05-350-801	MOS HRS/MSC AFL	144	+3%	-159		16-JUL-2012 6985.1 3525	08-FEB-2024	17-JUN-2024	205 d (+130)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-25-07-350-801-01	RESTORATION OF THE YAW AUXILIARY AFU (FUNCTIONAL TEST / SERVICING) - YAW AAFU (572CC) 105070-04 758 REF: AMM 27-25-07-350-801	MOS HRS/MSC AFL	144	+3%		-159	16-JUL-2012 6985.1 3525	08-FEB-2024	17-JUN-2024	205 d (+130)
27-25-07-720-801-01	ADJUSTMENT / TESTS OF THE YAW AUXILIARY AFU REF: AMM 27-25-07-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-25-07-900-801-01 27.165	REMOVAL / INSTALLATION OF THE YAW AUXILIARY AFU - YAW AAFU (572CC) 105070-04 758 REF: AMM 27-25-07-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-30-00-720-801-01	FUNCTIONAL TEST OF THE ELEVATOR CONTROL SURFACE DEFLECTION REF: AMM 27-30-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-30-00-820-801-01	ADJUSTMENT / TEST OF THE PITCH CONTROL SYSTEM REF: AMM 27-30-00-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-31-01-640-801-01 (s) 27.025	GREASING OF THE CONTROL COLUMNS - PILOT CONTROL COLUMN/WHEEL (L8TB) PKG 32 REF: AMM 27-31-01-640-801	MOS HRS/MSC AFL	144	+2m			21-JUN-2023 8047.2 3851			
27-31-01-640-801-02 (s) 27.030	GREASING OF THE CONTROL COLUMNS - COPILOT CONTROL COLUMN/WHEEL (R8TB) PKG 32 REF: AMM 27-31-01-640-801	MOS HRS/MSC AFL	144	+2m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-32-01-350-801-01	RESTORATION OF THE ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) - ELEVATOR SERVO-ACTUATOR (522CW) 103129 46 REF: AMM 27-32-01-350-801	MOS HRS/MSC AFL	10000	+3%			11-JAN-1988 0 0	10000	10300	1950.8 (+300)
+ 27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO-ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-10) 103129 46 REF: AMM 27-32-01-350-801	MOS HRS/MSC AFL	14000				11-JAN-1988 0 0	14000		5950.8
27-32-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATOR SERVO-ACTUATOR - ELEVATOR SERVO-ACTUATOR (522CW) 103129 46 REF: AMM 27-32-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA PKG 31 REF: AMM 27-33-01-640-806	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA PKG 31 REF: AMM 27-33-01-640-807	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
27-33-01-640-808-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHING OUTSIDE PRESSURIZED AREA PKG 16 REF: AMM 27-33-01-640-808	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
27-33-01-900-801-01	REMOVAL / INSTALLATION OF THE PITCH CONTROL RODS PN SN-UNKNOWN REF: AMM 27-33-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM						PKG			
27.193	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
27-35-01-640-801-01 (s)	PRESSURE GREASING OF THE PITCH ARTHUR VARIABLE BELLCRANK BEARINGS - PITCH ARTHUR VARIABLE BELLCRANK (43CW)						PKG			
27.195	PKG 32 REF: AMM 27-35-01-640-801	MOS HRS/MSC AFL	144	+2m			21-JUN-2023 8047.2 3851			
27-35-01-900-801-01	REMOVAL / INSTALLATION OF THE PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (43CW)									
27.195	106126-01 55 REF: AMM 27-35-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-35-03-960-801-01	REPLACEMENT OF THE SWIVEL COUPLING SEALS ON PITCH ARTHUR VARIABLE BELLCRANK - PITCH ARTHUR VARIABLE BELLCRANK (43CW)									
	REF: AMM 27-35-03-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-35-05-350-801-01	RESTORATION OF THE PITCH MAIN AFU (FUNCTIONAL TEST / SERVICING) - PITCH MAIN AFU (524CW)									
	105122-02 35 REF: AMM 27-35-05-350-801	MOS HRS/MSC AFL	144	+3%		-159	16-JUL-2012 6985.1 3525	08-FEB-2024	17-JUN-2024	205 d (+130)
27-35-05-900-801-01	REMOVAL / INSTALLATION OF THE PITCH MAIN AFU - PITCH MAIN AFU (524CW)									
27.225	105122-02 35 REF: AMM 27-35-05-900-801	MOS HRS/MSC AFL	O/C	R:2 N:6985.1 R:0 R:0			16-JUL-2012 6985.1 3525			
27-35-07-350-801-01	RESTORATION OF THE PITCH AUXILIARY AFU (DISCARD OF BUSHINGS 1050450002) - PITCH AAFU (523CW)									
27.230 MANDATORY 5-40	105045-13 3047 REF: AMM 27-35-07-350-801	MOS HRS/MSC AFL	O/C				03-MAY-2000 3166 1975			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-35-07-350-801-01A	RESTORATION PITCH AUXILIARY ARTIFICIAL FEEL (AAFU) UNIT (DISCARD OF BUSHING 105040002) (MANDATORY 5-40)									
	105045-13	MOS					03-MAY-2000			
	3047	HRS/MSC	O/C				3166			
MANDATORY 5-40	REF: AMM 27-35-07-350-801	AFL					1975			
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS - PITCH AAFU (523CW)						PKG			
	PKG 32	MOS	144	+2m			21-JUN-2023			
27.230		HRS/MSC					8047.2			
	REF: AMM 27-35-07-640-801	AFL	7500				3851			
27-35-07-720-802-01	FUNCTIONAL TEST OF THE PITCH AUXILIARY AFU - PITCH AAFU (523CW)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 27-35-07-720-802	AFL					0			
27-35-07-720-804-01	ADJUSTMENT / TEST OF THE PITCH AUXILIARY AFU - PITCH AAFU (523CW)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 27-35-07-720-804	AFL					0			
27-35-07-900-801-01	REMOVAL / INSTALLATION OF THE PITCH AUXILIARY AFU - PITCH AAFU (523CW)									
	105045-13	MOS					16-JUL-2012			
27.230	3047	HRS/MSC	O/C				6985.1			
	REF: AMM 27-35-07-900-801	AFL					3525			
+ 27-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM						PKG			
	PKG 21	MOS					11-NOV-2015			
27.245		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-40-00-720-801	AFL					3656			
+ 27-40-01-210-802-01	VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)									
	021121-11	MOS	72	+3%			28-NOV-2018	28-NOV-2024	01-FEB-2025	499 d (+65)
27.255	230	HRS/MSC					7675			
	REF: AMM 27-40-01-210-802	AFL	3750	+3%			3744	7494	7606.5	3641 (+112.5)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-40-01-350-801-01	RESTORATION OF THE HORIZONTAL STABILIZER ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT) - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)									
27.255	021121-11 230 REF: AMM 27-40-01-350-801	MOS HRS/MSC AFL	144 7500	+3% +3%		-159	16-JUL-2012 6985.1 3525	08-FEB-2024 11025	17-JUN-2024 11250	205 d (+130) 7172 (+225)
27-40-01-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)									
27.255	PKG 5 REF: AMM 27-40-01-640-802	MOS HRS/MSC AFL	12 800	+1m +40			21-JUN-2023 8047.2 3851			
27-40-01-720-801-01 (s)	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - NORMAL ELECTRIC MOTOR (93CFA)									
27.250	PKG 21 REF: AMM 27-40-01-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
27-40-01-720-801-02 (s)	MEASUREMENT OF THE HORIZONTAL STABILIZER ACTUATOR SLIP - EMERGENCY ELECTRIC MOTOR (93CFB)									
	PKG 21 REF: AMM 27-40-01-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
27-40-01-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)									
27.255	021121-11 230 REF: AMM 27-40-01-900-801	MOS HRS/MSC AFL	O/C			O:149 R:0 N:9391.1 O:3918.1 R:0 O:1596 R:0	16-JUL-2012 6985.1 3525			
+ 27-40-03-100-802-01	CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (93CFA)									
27.260	REF: AMM 27-40-03-100-802	MOS HRS/MSC AFL	O/C				25-JAN-2008 5308.9 2695			
27-40-03-100-803-01	CHECK / CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER ACTUATOR EMERGENCY MOTOR - EMERGENCY ELECTRIC MOTOR (93CFB)									
	REF: AMM 27-40-03-100-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-40-03-760-801-01	MEASUREMENT OF THE DROP-OUT CURRENT OF THE ELECTROMAGNETIC BRAKE OF HS ACTUATOR NORMAL MOTOR - NORMAL ELECTRIC MOTOR (93CFA)									
27.260	REF: AMM 27-40-03-760-801	MOS HRS/MSC AFL	O/C				10-AUG-2004 4408.2 2403			
27-40-03-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL MOTOR OF THE HORIZONTAL STABILIZER ACTUATOR - NORMAL ELECTRIC MOTOR (93CFA)									
27.260	REF: AMM 27-40-03-900-801	993 SN-UNKNOWN AFL	MOS HRS/MSC O/C AFL	N:0			11-JAN-1988 0 0			
27-40-05-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER POSITION REPEATER BOX - HS POSITION REPEATER BOX (4CF)									
27.262	REF: AMM 27-40-05-900-801	016092-02 103 AFL	MOS HRS/MSC O/C AFL				02-AUG-1991 880 595			
27-40-07-220-801-01	REMOVAL / INSTALLATION, INSPECTION AND GREASING OF HS REPEATER MICROMETRIC ROD - HS REPEATER MICROMETRIC ROD (94CF)									
	REF: AMM 27-40-07-220-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF)						PKG			
27.270	REF: AMM 27-40-15-710-801	PKG 32 MOS HRS/MSC AFL	144 O/C 7500	+2m			21-JUN-2023 8047.2 3851			
+ 27-40-15-710-801-01A	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY - AIRBRAKE/TAILPLANE/TRIM CONTROL BOX (2CF) (MANDATORY 5-40)									
27.270 MANDATORY 5-40	REF: AMM 27-40-15-710-801	MOS HRS/MSC AFL	16000 O/C				21-JUN-2023 8047.2 3851	24047.2		15998
+ 27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (91CF)						PKG			
27.265	REF: AMM 27-40-17-720-801	PKG 23 MOS HRS/MSC AFL	4800 O/C	+40			03-SEP-2003 4150 2320			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W (ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX - HS RELAY BOX (91CF) (MANDATORY 5-40)									
27.265		MOS					03-SEP-2003			
MANDATORY 5-40	REF: AMM 27-40-17-720-801	HRS/MSC	5000				4150	9150		1100.8
		AFL					2320			
27-50-00-640-801-01 (s)	GREASING / LUBRICATION OF FLAP MECHANISMS						PKG			
27.515	PKG 16	MOS	24	+1m			21-JUN-2023			
	REF: AMM 27-50-00-640-801	HRS/MSC					8047.2			
		AFL					3851			
+ 27-50-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						PKG			
27.290	PKG 21	MOS					11-NOV-2015			
	REF: AMM 27-50-00-720-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
+ 27-50-00-720-802-01 (s)	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM						PKG			
27.285	PKG 21	MOS					11-NOV-2015			
	REF: AMM 27-50-00-720-802	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
+ 27-50-00-720-802-01A	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)									
27.285		MOS					11-NOV-2015			
MANDATORY 5-40	REF: AMM 27-50-00-720-802	HRS/MSC	1800				7355.5	9155.5		1106.3
		AFL					3656			
27-50-00-720-803-01 (s)	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE						PKG			
	PKG 21	MOS					11-NOV-2015			
	REF: AMM 27-50-00-720-803	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
27-50-00-820-801-01	ADJUSTMENT OF THE FLAP ELECTRO-MECHANICAL CONTROL									
		MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-50-00-860-802-01	EXTENSION / RETRACTION OF THE SLATS / FLAPS FOR MAINTENANCE	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-50-00-860-802									
27-51-01-900-801-01	REMOVAL / INSTALLATION OF THE SLATS / FLAPS CONTROL BOX - SLATS/FLAPS CONTROL BOX (2CG)	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.040	013016-21C 697									
	REF: AMM 27-51-01-900-801									
27-51-09-820-801-01	ADJUSTMENT OF THE FLAP POSITION POTENTIOMETERS - LH FLAP POSITION POTENTIOMETER (L4DL)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-51-09-820-801									
27-51-09-820-801-02	ADJUSTMENT OF THE FLAP POSITION POTENTIOMETERS - RH FLAP POSITION POTENTIOMETER (R4DL)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-51-09-820-801									
27-52-01-900-801-01	REMOVAL / INSTALLATION OF THE FLAP POWER DRIVE UNIT - FLAP POWER DRIVE UNIT (3CG)	MOS HRS/MSC AFL	O/C	N:1876			30-NOV-1993 1458 1006			
27.300	021138-05 216									
	REF: AMM 27-52-01-900-801									
+ 27-52-13-200-801-01 (s)	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - LH WING	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
27.295	PKG 31									
	REF: AMM 27-52-13-200-801									
27-52-13-200-801-02 (s)	CHECK / GREASING OF FLAP CONTROL ROD SPLINES - RH WING	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	PKG 31									
	REF: AMM 27-52-13-200-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-52-13-900-804-01	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH OUTBOARD FLAP ROTATING ROD (L513CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-02	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH OUTBOARD FLAP ROTATING ROD (L512CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-03	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH INBOARD FLAP ROTATING ROD (L511CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-04	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH INBOARD FLAP ROTATING ROD (L510CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-05	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH INBOARD FLAP ROTATING ROD (L509CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-06	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - LH INBOARD FLAP ROTATING ROD (L508CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-07	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - CENTER ROTATING ROD (507CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-52-13-900-804-08	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH INBOARD FLAP ROTATING ROD (R508CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-09	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH INBOARD FLAP ROTATING ROD (R509CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-10	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH INBOARD FLAP ROTATING ROD (R510CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-11	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH INBOARD FLAP ROTATING ROD (R511CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-12	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH OUTBOARD FLAP ROTATING ROD (R512CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-52-13-900-804-13	REMOVAL / INSTALLATION OF THE FLAP CONTROL RODS - RH OUTBOARD FLAP ROTATING ROD (R513CG)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 27-52-13-900-804	AFL		N:0				0		
27-53-01-220-801-01 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-220-801-02 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		
27-53-01-220-801-03 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		
27-53-01-220-801-04 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		
27-53-01-220-801-05 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		
27-53-01-220-801-06 (s)	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502CG)						PKG			
	PKG 5	MOS	12	+1m				21-JUN-2023		
		HRS/MSC	800	+40				8047.2		
	REF: AMM 27-53-01-220-801	AFL						3851		
27-53-01-350-801-01	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH OUTBOARD FLAP SCREW JACK (L502CG)									
	021137-15A	MOS						11-JAN-1988		
27.315	1421	HRS/MSC	O/C					0		
	REF: AMM 27-53-01-350-801	AFL						0		
27-53-01-350-801-01A	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40)									
	021137-15A	MOS						11-JAN-1988		
	1421	HRS/MSC	O/C					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-801-02 27.320	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG) 021137-13A 1404 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-02A MANDATORY 5-40	RESTORATION LH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-13A 1404 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-03 27.325	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - LH INBOARD FLAP CENTER SCREW JACK (L500CG) 021137-13A 1405 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-03A MANDATORY 5-40	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-13A 1405 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-04 27.330	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP CENTER SCREW JACK (R500CG) 021137-13A 1406 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-04A MANDATORY 5-40	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY 5-40) 021137-13A 1406 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-53-01-350-801-05 27.335	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG) 021137-13A 1407 REF: AMM 27-53-01-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-801-05A	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY 5-40)									
	021137-13A	MOS					11-JAN-1988			
	1407	HRS/MSC	O/C				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL					0			
27-53-01-350-801-06	RESTORATION OF THE FLAP SCREW JACKS (OVERHAUL) - RH OUTBOARD FLAP SCREW JACK (R502CG)									
	021137-14A	MOS					11-JAN-1988			
27.340	1417	HRS/MSC	O/C				0			
	REF: AMM 27-53-01-350-801	AFL					0			
27-53-01-350-801-06A	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY 5-40)									
	021137-14A	MOS					11-JAN-1988			
	1417	HRS/MSC	O/C				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-801	AFL					0			
27-53-01-350-802-01	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (L502CG)									
	021137-15A	MOS					11-JAN-1988			
	1421	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-01A	UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-15A	MOS					11-JAN-1988			
	1421	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-02	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)									
	021137-13A	MOS					11-JAN-1988			
	1404	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			
27-53-01-350-802-02A	UPGRADE LH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13A	MOS					11-JAN-1988			
	1404	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL					0			
		APH					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-802-03	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L500CG)									
	021137-13A	MOS						11-JAN-1988		
	1405	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-03A	UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13A	MOS						11-JAN-1988		
	1405	HRS/MSC	N/A					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-04	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R500CG)									
	021137-13A	MOS						11-JAN-1988		
	1406	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-04A	UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13A	MOS						11-JAN-1988		
	1406	HRS/MSC	N/A					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-05	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)									
	021137-13A	MOS						11-JAN-1988		
	1407	HRS/MSC	N/A					0		
	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		
27-53-01-350-802-05A	UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY 5-40)									
	021137-13A	MOS						11-JAN-1988		
	1407	HRS/MSC	N/A					0		
MANDATORY 5-40	REF: AMM 27-53-01-350-802	AFL						0		
		APH						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-350-802-06	UPGRADE OF THE FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (R502CG) 021137-14A 1417 REF: AMM 27-53-01-350-802	MOS HRS/MSC AFL APH	N/A					11-JAN-1988 0 0 0		
27-53-01-350-802-06A	UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY 5-40) 021137-14A 1417 MANDATORY 5-40 REF: AMM 27-53-01-350-802	MOS HRS/MSC AFL APH	N/A					11-JAN-1988 0 0 0		
27-53-01-640-802-01 (s)	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG) PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40				PKG 21-JUN-2023 8047.2 3851		
27-53-01-640-802-02 (s)	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG) PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40				PKG 21-JUN-2023 8047.2 3851		
27-53-01-640-802-03 (s)	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG) PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40				PKG 21-JUN-2023 8047.2 3851		
27-53-01-640-802-04 (s)	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG) PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40				PKG 21-JUN-2023 8047.2 3851		
27-53-01-640-802-05 (s)	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG) PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40				PKG 21-JUN-2023 8047.2 3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-640-802-06 (s)	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG) PKG 5	MOS	12	+1m			PKG	21-JUN-2023		
	REF: See Workcard	HRS/MSC AFL	800	+40			8047.2 3851			
27-53-01-720-803-01	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH OUTBOARD FLAP SCREW JACK (L502CG) 021137-15A 1421	MOS	N/A				11-JAN-1988			
	REF: AMM 27-53-01-720-803	HRS/MSC AFL APH					0 0 0			
27-53-01-720-803-01A	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40) 021137-15A 1421	MOS	N/A				11-JAN-1988			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	HRS/MSC AFL APH					0 0 0			
27-53-01-720-803-02	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP LATERAL SCREW JACK (L501CG) 021137-13A 1404	MOS	N/A				11-JAN-1988			
	REF: AMM 27-53-01-720-803	HRS/MSC AFL APH					0 0 0			
27-53-01-720-803-02A	CHECK LH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40) 021137-13A 1404	MOS	N/A				11-JAN-1988			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	HRS/MSC AFL APH					0 0 0			
27-53-01-720-803-03	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - LH INBOARD FLAP CENTER SCREW JACK (L500CG) 021137-13A 1405	MOS	N/A				11-JAN-1988			
	REF: AMM 27-53-01-720-803	HRS/MSC AFL APH					0 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-720-803-03A	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-13A	MOS					11-JAN-1988			
	1405	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-04	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP CENTER SCREW JACK (R500CG)									
	021137-13A	MOS					11-JAN-1988			
	1406	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-04A	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-13A	MOS					11-JAN-1988			
	1406	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-05	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)									
	021137-13A	MOS					11-JAN-1988			
	1407	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-05A	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-13A	MOS					11-JAN-1988			
	1407	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-803-06	CHECK OF THE SCREW / NUT PLAY ON FLAP SCREW JACKS (AVIAC) - RH OUTBOARD FLAP SCREW JACK (R502CG)									
	021137-14A	MOS					11-JAN-1988			
	1417	HRS/MSC	N/A				0			
	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-720-803-06A	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)									
	021137-14A	MOS					11-JAN-1988			
	1417	HRS/MSC	N/A				0			
MANDATORY 5-40	REF: AMM 27-53-01-720-803	AFL					0			
		APH					0			
27-53-01-720-804-01 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			
27-53-01-720-804-02 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			
27-53-01-720-804-03 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			
27-53-01-720-804-04 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			
27-53-01-720-804-05 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			
27-53-01-720-804-06 (s)	CHECK OF SCREW / NUT PLAY ON FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)						PKG			
	PKG 21	MOS					11-NOV-2015			
		HRS/MSC	1600	+40			7355.5			
	REF: AMM 27-53-01-720-804	AFL					3656			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-900-803-01	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)									
27.315	021137-15A 1421 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-900-803-02	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)									
27.320	021137-13A 1404 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-900-803-03	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)									
27.325	021137-13A 1405 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-900-803-04	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)									
27.330	021137-13A 1406 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-900-803-05	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)									
27.335	021137-13A 1407 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-900-803-06	REMOVAL / INSTALLATION OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)									
27.340	021137-14A 1417 REF: AMM 27-53-01-900-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-53-01-960-801-01	DISCARD OF THE FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)									
	021137-15A 1421 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-53-01-960-801-02	DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)									
27.320	021137-13A 1404 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
27-53-01-960-801-03	DISCARD OF THE FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)									
27.325	021137-13A 1405 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
27-53-01-960-801-04	DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)									
27.330	021137-13A 1406 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
27-53-01-960-801-05	DISCARD OF THE FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)									
27.335	021137-13A 1407 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
27-53-01-960-801-06	DISCARD OF THE FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)									
	021137-14A 1417 REF: AMM 27-53-01-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
+ 27-60-00-710-803-01 (s)	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES						PKG			
27.365	PKG 21 REF: AMM 27-60-00-710-803	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
27-60-00-720-801-01	FUNCTIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES									
	REF: AMM 27-60-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-60-00-860-801-01	EXTENSION / RETRACTION OF THE AIRBRAKES FOR MAINTENANCE	MOS HRS/MSC O/C AFL					11-JAN-1988 0 0			
	REF: AMM 27-60-00-860-801									
27-60-00-870-801-01	BLEEDING OF THE AIRBRAKE HYDRAULIC SYSTEM	MOS HRS/MSC O/C AFL					11-JAN-1988 0 0			
	REF: AMM 27-60-00-870-801									
27-61-01-720-801-01 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (L6CD)	MOS HRS/MSC 3200 AFL		+40			27-APR-2009 5771.6 2919			
	PKG 22									
	REF: AMM 27-61-01-720-801									
27-61-01-720-801-02 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (L5CD)	MOS HRS/MSC 3200 AFL		+40			27-APR-2009 5771.6 2919			
	PKG 22									
	REF: AMM 27-61-01-720-801									
27-61-01-720-801-03 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (L4CD)	MOS HRS/MSC 3200 AFL		+40			27-APR-2009 5771.6 2919			
	PKG 22									
	REF: AMM 27-61-01-720-801									
27-61-01-720-801-04 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (R4CD)	MOS HRS/MSC 3200 AFL		+40			27-APR-2009 5771.6 2919			
	PKG 22									
	REF: AMM 27-61-01-720-801									
27-61-01-720-801-05 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (R5CD)	MOS HRS/MSC 3200 AFL		+40			27-APR-2009 5771.6 2919			
	PKG 22									
	REF: AMM 27-61-01-720-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-61-01-720-801-06 (s)	FUNCTIONAL TEST OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (R6CD)						PKG			
	PKG 22	MOS						27-APR-2009		
	REF: AMM 27-61-01-720-801	HRS/MSC AFL	3200	+40				5771.6		2919
27-61-01-900-801-01	LH INBOARD AIRBRAKE POSITION MICROSWITCH MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0
27-61-01-900-801-02	LH CENTER AIRBRAKE POSITION MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0
27-61-01-900-801-03	LH OUTBOARD AIRBRAKE POSITION MICROSWITCH									
27.390	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0
27-61-01-900-801-04	RH INBOARD AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0
27-61-01-900-801-05	RH CENTER AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0
27-61-01-900-801-06	RH OUTBOARD AIRBRAKE POSITION MICROSWITCH									
27.395	602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988	0	0



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-61-01-960-801-01	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH OUTBOARD AIRBRAKE POSITION MICROSWITCH (L6CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-61-01-960-801-02	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH CENTER AIRBRAKE POSITION MICROSWITCH (L5CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-61-01-960-801-03	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - LH INBOARD AIRBRAKE POSITION MICROSWITCH (L4CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-61-01-960-801-04	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH INBOARD AIRBRAKE POSITION MICROSWITCH (R4CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-61-01-960-801-05	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH CENTER AIRBRAKE POSITION MICROSWITCH (R5CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-61-01-960-801-06	REPLACEMENT / ADJUSTMENT OF THE AIRBRAKE POSITION MICROSWITCHES - RH OUTBOARD AIRBRAKE POSITION MICROSWITCH (R6CD)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 27-61-01-960-801									
27-62-01-640-801-01 (s)	GREASING OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L502CD)						PKG			
	PKG 15	MOS	12	+1m			21-JUN-2023			
27.360	REF: AMM 27-62-01-640-801	HRS/MSC AFL					8047.2 3851			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-62-01-640-801-02 (s)	GREASING OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L501CD) PKG 15 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
27-62-01-640-801-03 (s)	GREASING OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L500CD) PKG 15 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
27-62-01-640-801-04 (s)	GREASING OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R500CD) PKG 15 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
27-62-01-640-801-05 (s)	GREASING OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R501CD) PKG 15 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
27-62-01-640-801-06 (s)	GREASING OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R502CD) PKG 15 REF: AMM 27-62-01-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
27-62-01-900-801-01 27.380	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH OUTBOARD AIRBRAKE ACTUATOR (L502CD) 106091-01 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-62-01-900-801-02 27.380	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH MIDDLE AIRBRAKE ACTUATOR (L501CD) 106091-02 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-62-01-900-801-03 27.380	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - LH INBOARD AIRBRAKE ACTUATOR (L500CD) 106091-03 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-62-01-900-801-04 27.385	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH INBOARD AIRBRAKE ACTUATOR (R500CD) 106091-03 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-62-01-900-801-05 27.385	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH MIDDLE AIRBRAKE ACTUATOR (R501CD) 106091-02 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-62-01-900-801-06 27.385	REMOVAL / INSTALLATION OF THE AIRBRAKE ACTUATORS - RH OUTBOARD AIRBRAKE ACTUATOR (R502CD) 106091-01 SN-UNKNOWN REF: AMM 27-62-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-62-03-780-802-01	CHECK AND CHARGING OF THE AIRBRAKE PRESSURE-HOLDING VALVE ACCUMULATOR - AIRBRAKE PRESSURE-HOLDING VALVE (503CD) REF: AMM 27-62-03-780-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-62-03-900-801-01 27.375	REMOVAL / INSTALLATION OF THE AIRBRAKE PRESSURE HOLDING VALVE ACCUMULATOR - AIRBRAKE PRESSURE-HOLDING VALVE (503CD) D25AB1703 19 REF: AMM 27-62-03-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-OCT-1995 1871 1317			
27-80-00-710-804-01	OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - NORMAL MODE REF: AMM 27-80-00-710-804	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-00-710-804-02	OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - EMERGENCY MODE	MOS					(EBT)			
	REF: AMM 27-80-00-710-804	HRS/MSC AFL	10000	+40				10000	10040	1950.8 (+40)
27-80-00-710-806-01	OPERATIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF-ATTACK SENSOR CONTACTS	MOS					11-JAN-1988			
	REF: AMM 27-80-00-710-806	HRS/MSC AFL	O/C				0			
+ 27-80-00-710-807-02 (s)	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - LH SOLENOID (S1)	MOS					PKG			
	PKG 21	HRS/MSC	1600	+40			11-JAN-1988			
	REF: AMM 27-80-00-710-807	AFL					0			
+ 27-80-00-710-807-03 (s)	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH AND RH SOLENOIDS - RH SOLENOID (S2)	MOS					PKG			
	PKG 21	HRS/MSC	1600	+40			11-JAN-1988			
	REF: AMM 27-80-00-710-807	AFL					0			
27-80-00-720-801-01	FUNCTIONAL TEST OF THE SLATS - NORMAL MODE	MOS					11-JAN-1988			
	REF: AMM 27-80-00-720-801	HRS/MSC AFL	O/C				0			
+ 27-80-00-720-801-02 (s)	FUNCTIONAL TEST OF THE SLATS - AUTOMATIC MODE	MOS					PKG			
	PKG 21	HRS/MSC	1600	+40			11-NOV-2015			
27.490	REF: AMM 27-80-00-720-801	AFL					7355.5			3656
27-80-00-720-801-03	FUNCTIONAL TEST OF THE SLATS - EMERGENCY MODE	MOS					11-JAN-1988			
	REF: AMM 27-80-00-720-801	HRS/MSC AFL	O/C				0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-00-870-801-01	BLEEDING OF THE SLAT HYDRAULIC SYSTEM REF: AMM 27-80-00-870-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
27-80-01-900-801-01 27.415	OUTBOARD SLAT NORMAL SOLENOID SELECTOR/MANIFOLD VALVE 108033-16 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-05-900-801-01 27.430	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH INBOARD SLAT ACTUATOR (L500CM) 106107-15 2004 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-05-900-801-02 27.435	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH INBOARD SLAT ACTUATOR (R500CM) 106107-15 2035 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-05-900-801-03 27.430	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT INBOARD ACTUATOR (L501CM) 106107-12 2015 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			12-FEB-2004 4235.9 2352			
27-80-05-900-801-04 27.435	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT INBOARD ACTUATOR (R501CM) 106107-12 1961 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-05-900-801-05 27.440	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT EMERGENCY ACTUATOR (L502CM) 106107-23 1746 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	N:767 N:361			25-JAN-1990 455 314			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-05-900-801-06 27.440	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT EMERGENCY ACTUATOR (R502CM) 106107-23 1749 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C				25-JAN-1990 455 314			
27-80-05-900-801-07 27.430	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - LH OUTBOARD SLAT OUTBOARD ACTUATOR (L503CM) 106107-13 1977 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-05-900-801-08 27.435	REMOVAL / INSTALLATION OF THE SLAT ACTUATORS - RH OUTBOARD SLAT OUTBOARD ACTUATOR (R503CM) 106107-13 1978 REF: AMM 27-80-05-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			12-FEB-2004 4235.9 2352			
+ 27-80-17-720-802-01 (s) 27.465	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (L2DX) PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-02 (s) 27.460	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (L15CM) PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-03 (s) 27.470	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (L3DX) PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-04 (s) 27.475	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (L16CM) PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 27-80-17-720-802-05 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (R2DX)						PKG			
27.465	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-06 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (R15CM)						PKG			
27.460	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-07 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (R3DX)						PKG			
27.470	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-08 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (R16CM)						PKG			
27.475	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
+ 27-80-17-720-802-09 (s)	FUNCTIONAL TEST OF THE SLAT / FLAP POSITION MICROSWITCHES - FLAP POSITION MICROSWITCH (7CM)						PKG			
27.477	PKG 22 REF: AMM 27-80-17-720-802	MOS HRS/MSC AFL	3200	+40			27-APR-2009 5771.6 2919			
27-80-17-900-801-01	LH INBOARD SLAT EXTENDED MICROSWITCH 602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27-80-17-900-801-02	LH INBOARD SLAT RETRACTED MICROSWITCH 402EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-17-900-801-03	LH OUTBOARD SLAT RETRACTED MICROSWITCH 402EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.470										
27-80-17-900-801-04	LH OUTBOARD SLAT EXTENDED MICROSWITCH 602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.475										
27-80-17-900-801-05	RH INBOARD SLAT EXTENDED MICROSWITCH 602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.465										
27-80-17-900-801-06	RH INBOARD SLAT RETRACTED MICROSWITCH 402EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.460										
27-80-17-900-801-07	RH OUTBOARD SLAT RETRACTED MICROSWITCH 402EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.470										
27-80-17-900-801-08	RH OUTBOARD SLAT EXTENDED MICROSWITCH 602EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
27.475										
27-80-17-900-803-01	FLAP POSITION MICROSWITCH 402EN1-6 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:5771.6 N:0			27-APR-2009 5771.6 2919			
27.477										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-17-960-801-01	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT EXTENDED MICROSWITCH (L2DX)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
27-80-17-960-801-02	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH INBOARD SLAT RETRACTED MICROSWITCH (L15CM)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
27-80-17-960-801-03	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT RETRACTED MICROSWITCH (L3DX)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
27-80-17-960-801-04	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - LH OUTBOARD SLAT EXTENDED MICROSWITCH (L16CM)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
27-80-17-960-801-05	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT EXTENDED MICROSWITCH (R2DX)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
27-80-17-960-801-06	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH INBOARD SLAT RETRACTED MICROSWITCH (R15CM)	MOS						11-JAN-1988		
	REF: AMM 27-80-17-960-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-80-17-960-801-07	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT RETRACTED MICROSWITCH (R3DX)	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
	REF: AMM 27-80-17-960-801									
27-80-17-960-801-08	REPLACEMENT / ADJUSTMENT OF THE SLAT POSITION MICROSWITCHES - RH OUTBOARD SLAT EXTENDED MICROSWITCH (R16CM)	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
	REF: AMM 27-80-17-960-801									
27-80-17-960-803-01	REPLACEMENT / ADJUSTMENT OF THE FLAP POSITION MICROSWITCH - FLAP POSITION MICROSWITCH (7CM)	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
	REF: AMM 27-80-17-960-803									
+ 27-80-23-720-801-01	FUNCTIONAL TEST OF THE INBOARD SLAT VALVE BOX - INBOARD SLAT VALVE BOX (507CM)	MOS HRS/MSC AFL	144	+3%				27-JUN-2023 8049.2 3853	27-JUN-2035	05-NOV-2035 4362 d (+131)
27.425	108117-02 137 REF: AMM 27-80-23-720-801									
+ 27-80-23-720-802-01	FUNCTIONAL TEST OF THE OUTBOARD SLAT VALVE BOX - OUTBOARD SLAT VALVE BOX (517CM)	MOS HRS/MSC AFL	144	+3%				16-JUL-2012 6985.1 3525	16-JUL-2024	25-NOV-2024 364 d (+132)
27.425	108117-01 130 REF: AMM 27-80-23-720-802									
27-80-23-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD SLAT VALVE BOX - INBOARD SLAT VALVE BOX (507CM)	MOS HRS/MSC AFL	O/C		R:2 N:6985.1 R:0 R:0			16-JUL-2012 6985.1 3525		
27.425	108117-02 137 REF: AMM 27-80-23-900-801									
27-80-23-900-802-01	REMOVAL/INSTALLATION OF THE OUTBOARD SLAT VALVE BOX - OUTBOARD SLAT VALVE BOX (517CM)	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0			11-JAN-1988 0 0		
	PN SN-UNKNOWN REF: GENERIC NO REF									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
270101	PILOT CONTROL COLUMN									
27.025	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
270121	COPILOT CONTROL COLUMN									
27.030	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
270221	TRIPLE TRIM INDICATOR									
27.035	4863-557-80-13 159 REF: AMM 21-30-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
271251	AILERON TRIM BOX									
27.085	F10A641812A1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
271351	LH AILERON NEUTRAL RETURN UNIT									
27.095	105045-06 3065 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			16-JUL-2012 6985.1 3525			
271381	RH AILERON NEUTRAL RETURN UNIT									
27.095	105045-06 3064 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			16-JUL-2012 6985.1 3525			
271401	LH ROLL CONTROL SEALED BOX									
27.097	FGFB271111A1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
271421	RH ROLL CONTROL SEALED BOX									
27.097	FGFB271211A1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
271601	RUDDER PRESSURE SEALED BOX									
27.155	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
271621	ELEVATOR PRESSURE SEALED BOX									
27.252	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
272071	PILOT RUDDER BAR PEDAL ASSEMBLY									
27.123	0CV299-01 85 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
272081	COPILOT RUDDER BAR PEDAL ASSEMBLY									
27.123	0CV299-02 80 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
272091	PILOT PEDALS ADJUSTMENT ROD BOX									
27.124	4505-1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
272096	COPILOT PEDALS ADJUSTMENT ROD BOX									
27.124	4505-1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
272163	YAW TRIM RELAY BOX									
27.150	FGFB600271010A2 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
273161	ARTHUR Q-UNIT PITCH SERVO VALVE									
27.215	108019-13 1616 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
273171	PITCH ARTHUR BOX									
27.220	062175-02 93 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-OCT-1991 911 616			
274161	HORIZONTAL STABILIZER STANDBY ELECTRIC MOTOR									
27.260	993 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
274201	HORIZONTAL STABILIZER RELAY BOX									
27.265	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
274251	HORIZONTAL STABILIZER STANDBY CONTROL BOX									
27.270	FGFB641810A2 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275121	LH FLAP DUAL BEVEL GEAR									
27.305	021068-06 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
275141	RH FLAP DUAL BEVEL GEAR 021068-07 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275161	LH FLAP BEVEL GEAR 021063-01 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275181	RH FLAP BEVEL GEAR 021063-01 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275351	LH FLAP POSITION TRANSMITTER 1-4414-2 373 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275361	RH FLAP POSITION TRANSMITTER 2-4414-2 208 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275371	FLAP ASYMMETRY DETECTOR J2201-2-10MEB SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
275401	CONFIGURATION PANEL 205TS04Y01AB 400 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
276101	INBOARD/OUTBOARD AIRBRAKE SELECTOR VALVE 65670-1 712A REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276141	MIDDLE AIRBRAKE SELECTOR VALVE 65670-1 776A REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276191	AIRBRAKE HOLD VALVE GAUGE 18040100 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276401	LH OUTBOARD AIRBRAKE RESTRICTOR C24370-202 B2336 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276411	LH MIDDLE AIRBRAKE RESISTOR C24370-402 B2409 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276421	LH INBOARD AIRBRAKE RESISTOR C24370-302 B2375 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276431	RH INBOARD AIRBRAKE RESTRICTOR C24370-302 B2378 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
276441	RH MIDDLE AIRBRAKE RESTRICTOR									
27.403	C24370-402 B2410 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
276451	RH OUTBOARD AIRBRAKE RESTRICTOR									
27.403	C24370-202 B2338 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278101	OUTBOARD SLAT AUTOMATIC DISTRIBUTOR									
27.415	108103-04 487 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278121	OUTBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR									
27.420	65670-1 698A REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278131	INBOARD SLAT ELECTRIC DISTRIBUTOR									
27.420	65670-1 826A REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278171	OUTBOARD SLAT VALVE BOX									
27.425	108117-01 130 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			16-JUL-2012 6985.1 3525			
278401	LH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR									
27.445	C24346-102 B1084 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
278411	RH INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR									
27.445	C24346-102 B1063 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278421	LH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE									
27.450	C24370-102 B2314 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278431	RH OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE									
27.450	C24370-102 B2315 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278441	LH ACTUATOR STANDBY RESTRICTOR VALVE									
27.455	FCFA1875150D 67 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278451	RH ACTUATOR STANDBY RESTRICTOR VALVE									
27.455	FCFA1875150D 80 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
278461	SLATS ACTUATOR RETRACTION RESTRICTOR VALVE									
27.455	C24346-302 B1125 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-41-13-640-801-01 (s)	LUBRICATION OF THE SLAT MECHANISMS						PKG			
27.405	PKG 16 REF: AMM 57-41-13-640-801	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			

CHAPTER 28 FUEL



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-00-00-280-801-01 (s) 28.560	FUEL CONTAMINATION DETECTION TEST PKG 5 REF: AMM 28-00-00-280-801	MOS HRS/MSC AFL	12 800	+1m			PKG 21-JUN-2023 8047.2 3851			
28-00-00-290-801-01 (s)	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH FEEDER TANK PKG 7 REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	36 2400	+1m +40			PKG 21-JUN-2023 8047.2 3851			
28-00-00-290-801-02 (s)	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH FEEDER TANK PKG 7 REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	36 2400	+1m +40			PKG 21-JUN-2023 8047.2 3851			
28-00-00-290-801-03 (s)	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE CTR FEEDER TANK PKG 7 REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	36 2400	+1m +40			PKG 21-JUN-2023 8047.2 3851			
28-00-00-290-801-04	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH CENTER-WING TANK REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-00-00-290-801-05	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH CENTER-WING TANK REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-00-00-290-801-06	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE REAR TANK REF: AMM 28-00-00-290-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-00-00-290-801-07 (s)	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE LH WING TANK PKG 7	MOS	36	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 28-00-00-290-801	HRS/MSC AFL	2400	+40						
28-00-00-290-801-08 (s)	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE RH WING TANK PKG 7	MOS	36	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 28-00-00-290-801	HRS/MSC AFL	2400	+40						
28-00-00-290-801-09	BORESCOPE INSPECTION OF THE FUEL TANKS - BORESCOPE INSPECTION OF THE FRONT TANK	MOS					11-JAN-1988 0 0			
	REF: AMM 28-00-00-290-801	HRS/MSC AFL	O/C							
28-00-00-910-801-01	FUEL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS	MOS					11-JAN-1988 0 0			
	REF: AMM 28-00-00-910-801	HRS/MSC AFL	O/C							
28-00-00-910-802-01	ACCEPTANCE CRITERIA FOR FUEL LEAKS	MOS					11-JAN-1988 0 0			
	REF: AMM 28-00-00-910-802	HRS/MSC AFL	O/C							
28-00-00-910-803-01	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - FUEL INJECTION METHOD	MOS					11-JAN-1988 0 0			
	REF: See Workcard	HRS/MSC AFL	O/C							
28-00-00-910-803-02	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A MINIMUM FUEL LOAD - GRAVITY POURING METHOD	MOS					11-JAN-1988 0 0			
	REF: See Workcard	HRS/MSC AFL	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-00-00-910-803-03	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - FUEL INJECTION METHOD	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
28-00-00-910-803-04	DECONTAMINATION OF THE FUEL SYSTEMS - TREATMENT WITH A FULL FUEL LOAD - GRAVITY POURING METHOD	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
28-00-00-910-803-06	DECONTAMINATION OF THE FUEL SYSTEMS - CLEANING / REPLACEMENT OF FILTERS	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS	MOS					17-DEC-2021			
28.570	REF: AMM 28-00-00-910-804	HRS/MSC	A/R				7940.3			
		AFL					3817			
28-10-00-210-801-01	GENERAL VISUAL INSPECTION OF THE EXTERNAL STRUCTURE TO DETECT FUEL LEAKS	MOS					11-JAN-1988			
	REF: AMM 28-10-00-210-801	HRS/MSC	O/C				0			
		AFL					0			
+ 28-10-00-280-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES						PKG			
28.030	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 28-10-00-280-801	HRS/MSC					8047.2			
		AFL	3750				3851			
28-21-01-900-801-01	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 1 (3QN1)	MOS					24-NOV-2004			
28.370	226-650-51	HRS/MSC	O/C	O:0			4535.8			
	791	AFL		O:0			2438			
	REF: AMM 28-21-01-900-801			O:0						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-21-01-900-801-02	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 2 (3QN2)									
28.380	226-650-2 276 REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C							
28-21-01-900-801-03	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - BOOSTER PUMP 3 (3QN3)									
28.370	226-650-3 113 REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C	R:0 N:10206 R:0 R:0			20-OCT-2005 4747.1 2504			
28-21-01-900-801-04	REMOVAL / INSTALLATION OF THE BOOSTER PUMPS - STAND-BY BOOSTER PUMP 2 (13QN)									
28.380	P99C31-604 513 REF: AMM 28-21-01-900-801	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-NOV-2011 6796.2 3433			
28-21-05-900-801-01	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 1 MANIFOLD (32WB1)									
28.280	L88A31-662A-C 20085 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-21-05-900-801-02	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 2 MANIFOLD (32WB2)									
28.290	L88A31-695 20080 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	R:12 R:0 R:0			26-DEC-2020 7883.1 3800			
28-21-05-900-801-03	REMOVAL / INSTALLATION OF THE BP MANIFOLDS - BP 3 MANIFOLD (32WB3)									
28.300	L88A31-664A-C 20084 REF: AMM 28-21-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
+ 28-21-11-710-801-01 (s)	OPERATIONAL TEST OF THE BP MANIFOLD CROSSFEED ELECTRICAL VALVES - BP 1 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB1)									
28.350	PKG 7 REF: AMM 28-21-11-710-801	MOS HRS/MSC AFL	36 2400	+1m +40			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 28-21-11-710-801-02 (s)	OPERATIONAL TEST OF THE BP MANIFOLD CROSSFEED ELECTRICAL VALVES - BP 3 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB3)						PKG			
28.350	PKG 7	MOS	36	+1m			21-JUN-2023			
		HRS/MSC	2400	+40			8047.2			
	REF: AMM 28-21-11-710-801	AFL					3851			
+ 28-21-13-710-801-01 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (321WB1)						PKG			
76.100	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 28-21-13-710-801	AFL	3750				3851			
+ 28-21-13-710-801-01A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (321WB1) (MANDATORY 5-40)									
76.100		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 28-21-13-710-801	HRS/MSC	11600				8047.2	19647.2		11598
		AFL					3851			
+ 28-21-13-710-801-02 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (321WB2)						PKG			
76.110	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 28-21-13-710-801	AFL	3750				3851			
+ 28-21-13-710-801-02A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (321WB2) (MANDATORY 5-40)									
76.110		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 28-21-13-710-801	HRS/MSC	11600				8047.2	19647.2		11598
		AFL					3851			
+ 28-21-13-710-801-03 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (321WB3)						PKG			
76.120	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 28-21-13-710-801	AFL	3750				3851			
+ 28-21-13-710-801-03A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (321WB3) (MANDATORY 5-40)									
76.120		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 28-21-13-710-801	HRS/MSC	11600				8047.2	19647.2		11598
		AFL					3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-21-13-710-801-04 (s) 76.100	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV CLOSING PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750				PKG 21-JUN-2023 8047.2 3851			
28-21-13-710-801-05 (s) 76.110	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV CLOSING PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750				PKG 21-JUN-2023 8047.2 3851			
28-21-13-710-801-06 (s) 76.120	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV CLOSING PKG 31 REF: AMM 28-21-13-710-801	MOS HRS/MSC AFL	72 3750				PKG 21-JUN-2023 8047.2 3851			
28-21-13-900-802-01	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 1 MANIFOLD ENGINE SOV ELECTRICAL ACTUATOR (3211WB1) PN SN-UNKNOWN REF: AMM 28-21-13-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
28-21-13-900-802-02	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 2 MANIFOLD ENGINE SOV ELECTRICAL ACTUATOR (3211WB2) PN SN-UNKNOWN REF: AMM 28-21-13-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
28-21-13-900-802-03	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 3 MANIFOLD ENGINE SOV ELECTRICAL ACTUATOR (3211WB3) PN SN-UNKNOWN REF: AMM 28-21-13-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
28-21-13-900-802-04	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 1 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB1) PN SN-UNKNOWN REF: AMM 28-21-13-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-21-13-900-802-05	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 2 MANIFOLD DEFUELING VALVE ELECTRICAL ACTUATOR (3231WB2)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 28-21-13-900-802	AFL		N:0			0			
28-21-13-900-802-06	REMOVAL / INSTALLATION OF THE BP MANIFOLD ACTUATORS - BP 3 MANIFOLD CROSSFEED VALVE ELECTRICAL ACTUATOR (3221WB3)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 28-21-13-900-802	AFL		N:0			0			
+ 28-21-14-720-801-01	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 1 MANIFOLD (32WB1)									
	L88A31-662A-C	MOS					11-JAN-1988			
28.280	20085	HRS/MSC	10000	+3%			0	10000	10300	1950.8 (+300)
	REF: AMM 28-21-14-720-801	AFL					0			
+ 28-21-14-720-801-02	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 2 MANIFOLD (32WB2)									
	L88A31-695	MOS					26-DEC-2020			
28.290	20080	HRS/MSC	10000	+3%			7883.1	17883.1	18183.1	9833.9 (+300)
	REF: AMM 28-21-14-720-801	AFL					3800			
+ 28-21-14-720-801-03	FUNCTIONAL TEST OF THE BP MANIFOLD THERMAL EXPANSION SYSTEMS - BP 3 MANIFOLD (32WB3)									
	L88A31-664A-C	MOS					11-JAN-1988			
28.300	20084	HRS/MSC	10000	+3%			0	10000	10300	1950.8 (+300)
	REF: AMM 28-21-14-720-801	AFL					0			
28-21-17-790-801-01	SEALING TEST OF THE APU FUEL SHUT-OFF VALVE									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 28-21-17-790-801	AFL					0			
28-21-17-900-801-01	REMOVAL / INSTALLATION OF THE APU FUEL SHUT-OFF VALVE - APU FUEL SHUT-OFF VALVE (20HT)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 28-21-17-900-801	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 28-21-25-710-801-01 (s)	OPERATIONAL TEST OF THE CROSSFEED UNITS						PKG			
28.160	PKG 7	MOS	36	+1m			21-JUN-2023			
		HRS/MSC	2400	+40			8047.2			
	REF: AMM 28-21-25-710-801	AFL					3851			
28-21-25-900-801-01	REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - LH CROSSFEED UNIT (L500QA)									
28.270	L88A31-665-1	MOS					11-JAN-1988			
	20101	HRS/MSC	O/C		N:0		0			
	REF: AMM 28-21-25-900-801	AFL					0			
28-21-25-900-801-02	REMOVAL / INSTALLATION OF THE LH AND RH CROSSFEED UNITS - RH CROSSFEED UNIT (R500QA)									
28.270	L88A31-665-1	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 28-21-25-900-801	AFL					0			
28-21-27-900-801-01	REMOVAL / INSTALLATION OF THE CROSSFEED VALVE ACTUATORS - LH CROSSFEED VALVE ACTUATOR (L30QA)									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 28-21-27-900-801	AFL			N:0		0			
28-21-27-900-801-02	REMOVAL / INSTALLATION OF THE CROSSFEED VALVE ACTUATORS - RH CROSSFEED VALVE ACTUATOR (R30QA)									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 28-21-27-900-801	AFL			N:0		0			
+ 28-21-29-100-801-01	CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - LH CROSSFEED UNIT FILTER									
28.270	PKG 5	MOS				-215	21-JUN-2023			
		HRS/MSC	25	+50			8047.2	8072.2	8122.2	23 (+50)
	REF: AMM 28-21-29-100-801	AFL					3851			
+ 28-21-29-100-801-02	CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - RH CROSSFEED UNIT FILTER									
28.270	PKG 5	MOS				-215	21-JUN-2023			
		HRS/MSC	25	+50			8047.2	8072.2	8122.2	23 (+50)
	REF: AMM 28-21-29-100-801	AFL					3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 28-21-29-100-801-03	CLEANING OF THE CROSSFEED UNIT FILTERS AND BOOSTER PUMP 2 UNIT FILTER - BOOSTER PUMP 2 UNIT FILTER									
28.330	PKG 5	MOS				-215	21-JUN-2023			
	REF: AMM 28-21-29-100-801	HRS/MSC	25	+50			8047.2	8072.2	8122.2	23 (+50)
		AFL					3851			
28-21-33-870-802-01	BLEEDING OF THE ENGINE FUEL SUPPLY LINES									
		MOS					11-JAN-1988			
	REF: AMM 28-21-33-870-802	HRS/MSC	O/C				0			
		AFL					0			
28-21-33-870-803-01	BLEEDING OF THE APU FUEL SUPPLY LINES									
		MOS					11-JAN-1988			
	REF: AMM 28-21-33-870-803	HRS/MSC	O/C				0			
		AFL					0			
28-21-41-900-801-01	REMOVAL / INSTALLATION OF THE SIDE TANK GROUP INTERCONNECTION VALVE ACTUATOR									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 28-21-41-900-801	AFL					0			
28-22-00-610-801-01	SERVICING OF THE TRANSFER SOLENOID VALVE STAND-BY MANUAL CONTROL									
28.250		MOS								
	REF: AMM 28-22-00-610-801	HRS/MSC	N/A							
		AFL								
28-22-00-650-801-01	QUICK TRANSFER OF FUEL BETWEEN TANK GROUPS									
		MOS					11-JAN-1988			
	REF: AMM 28-22-00-650-801	HRS/MSC	O/C				0			
		AFL					0			
28-22-01-710-801-01	OPERATIONAL TEST OF THE XTK2 VALVE - XTK2 VALVE (34QA)									
28.260		MOS								
	REF: AMM 28-22-01-710-801	HRS/MSC	N/A							
		AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-22-01-900-801-01	REMOVAL / INSTALLATION OF THE TANK INTERCONNECTION VALVE - TANK INTERCONNECTION VALVE (28QA)									
28.150	L87B63-653 20037 REF: AMM 28-22-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-30-00-650-801-01	SUCTION DEFUELING									
	REF: AMM 28-30-00-650-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-30-00-680-801-01	GRAVITY DEFUELING									
	REF: AMM 28-30-00-680-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP									
	REF: AMM 28-30-00-680-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP									
	REF: AMM 28-30-00-680-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE CENTER TANK GROUP									
	REF: AMM 28-30-00-680-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-30-00-680-802-04	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING									
	REF: AMM 28-30-00-680-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-30-00-680-802-06	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY	MOS HRS/MSC AFL	O/C				29-NOV-2014 7252.5 3622			
REF: AMM 28-30-00-680-802										
+ 28-30-00-680-803-01	DRAINING OF THE GRAVITY DEFUELING LINE	MOS HRS/MSC AFL	O/C			-39	20-JUL-2012 6985.1 3525			
28.340										
REF: AMM 28-30-00-680-803										
28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS	MOS HRS/MSC AFL	2	+5d			27-JUN-2023 8049.2 3853	27-AUG-2023	01-SEP-2023	40 d (+5)
REF: AMM 28-30-00-680-804										
28-30-11-900-801-01	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - FRONT TANK SUMP DRAIN VALVE (505QS)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28.060	142G12-31 SN-UNKNOWN			N:0						
REF: AMM 28-30-11-900-801										
28-30-11-900-801-02	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK REAR SUMP DRAIN VALVE (507QS)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28.070	142G12-31 SN-UNKNOWN			N:0						
REF: AMM 28-30-11-900-801										
28-30-11-900-801-03	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH WING INBOARD TANK SUMP DRAIN VALVE (508QS)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28.060	142G12-31 SN-UNKNOWN			N:0						
REF: AMM 28-30-11-900-801										
28-30-11-900-801-04	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH WING INBOARD TANK SUMP DRAIN VALVE (509QS)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28.060	142G12-31 SN-UNKNOWN			N:0						
REF: AMM 28-30-11-900-801										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-30-11-900-801-05	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - REAR TANK SUMP DRAIN VALVE (510QS)									
28.080	142G12-31 SN-UNKNOWN REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-30-11-900-801-06	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK SUMP DRAIN VALVE (512QS)									
28.080	142G12-31 SN-UNKNOWN REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-30-11-900-801-07	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - CENTER FEEDER TANK SUMP DRAIN VALVE (513QS)									
28.080	142G12-32 M09875 REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-NOV-2018 7675 3744			
28-30-11-900-801-08	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH CENTERWING TANK FRONT SUMP DRAIN VALVE (514QS)									
28.070	142G12-32 M09903 REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-NOV-2018 7675 3744			
28-30-11-900-801-09	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - RH FEEDER TANK SUMP DRAIN VALVE (515QS)									
28.070	142G12-31 SN-UNKNOWN REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-30-11-900-801-10	REMOVAL / INSTALLATION OF THE SUMP DRAIN VALVES - LH FEEDER TANK FRONT SUMP DRAIN VALVE (901QS)									
	PN SN-UNKNOWN REF: AMM 28-30-11-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
28-30-11-960-801-01	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - FRONT TANK SUMP DRAIN VALVE (505QS)									
	REF: AMM 28-30-11-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-30-11-960-801-02	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH CENTERWING TANK REAR SUMP DRAIN VALVE (507QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-03	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH WING INBOARD TANK SUMP DRAIN VALVE (508QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-04	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH WING INBOARD TANK SUMP DRAIN VALVE (509QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-05	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - REAR TANK SUMP DRAIN VALVE (510QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-06	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH FEEDER TANK SUMP DRAIN VALVE (512QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-07	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - CENTER FEEDER TANK SUMP DRAIN VALVE (513QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			
28-30-11-960-801-08	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH CENTERWING TANK FRONT SUMP DRAIN VALVE (514QS)	MOS					11-JAN-1988			
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-30-11-960-801-09	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - RH FEEDER TANK SUMP DRAIN VALVE (515QS)	MOS						11-JAN-1988		
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C					0		
		AFL						0		
28-30-11-960-801-10	REPLACEMENT OF THE SUMP DRAIN VALVE SEALS - LH FEEDER TANK FRONT SUMP DRAIN VALVE (901QS)	MOS						11-JAN-1988		
	REF: AMM 28-30-11-960-801	HRS/MSC	O/C					0		
		AFL						0		
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS	MOS						11-JAN-1988		
	REF: AMM 28-30-11-960-802	HRS/MSC	O/C					0		
		AFL						0		
28-40-00-820-801-01	ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM AND PARTIAL REFUELING QUANTITY SELECTOR - FUEL QUANTITY INDICATING SYSTEM	MOS						11-JAN-1988		
	REF: AMM 28-40-00-820-801	HRS/MSC	O/C					0		
		AFL						0		
28-40-00-820-801-02	ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM AND PARTIAL REFUELING QUANTITY SELECTOR - PARTIAL REFUELING QUANTITY SELECTOR (32QS)	MOS						11-JAN-1988		
	REF: AMM 28-40-00-820-801	HRS/MSC	O/C					0		
		AFL						0		
28-41-00-700-802-01	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - LH TANK GROUP	MOS						11-JAN-1988		
	REF: AMM 28-41-00-700-802	HRS/MSC	O/C					0		
		AFL						0		
28-41-00-700-802-02	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - CENTER TANK GROUP	MOS						11-JAN-1988		
	REF: AMM 28-41-00-700-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-00-700-802-03	CHECK / ADJUSTMENT OF THE FUEL QUANTITY INDICATING SYSTEM USING TEST SET - RH TANK GROUP	MOS						11-JAN-1988		
	REF: AMM 28-41-00-700-802	HRS/MSC AFL	O/C					0 0		
+ 28-41-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM	MOS						PKG		
28.385	PKG 22	HRS/MSC AFL APH	3200	+40				04-DEC-2017 7593.7 3722 3592		
28-41-05-900-801-01	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH WING CENTER TANK GAUGE (L6EJ)	MOS								
28.430	766189-4 1259	HRS/MSC AFL	O/C		N:22 N:0 N:0			10-NOV-2021 7940.3 3817		
28-41-05-900-801-02	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH WING CENTER TANK GAUGE (R6EJ)	MOS								
28.430	766-189-4 330	HRS/MSC AFL	O/C					14-NOV-1995 1882 1325		
28-41-05-900-801-03	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - LH FEEDER TANK GAUGE (L7EJ)	MOS								
28.440	766-190-1A 193	HRS/MSC AFL	O/C		N:0			11-JAN-1988 0 0		
28-41-05-900-801-04	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - CENTER FEEDER TANK GAUGE (25EJ)	MOS								
28.460	766-195-2A 140	HRS/MSC AFL	O/C		N:0			11-JAN-1988 0 0		
28-41-05-900-801-05	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - RH FEEDER TANK GAUGE (R7EJ)	MOS								
28.440	766-190-1 1018	HRS/MSC AFL	O/C		N:66 N:0 N:0			10-NOV-2021 7940.3 3817		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-05-900-801-06	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - FRONT TANK REAR GAUGE (23EJ)									
28.450	766-193-3AC 162 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-05-900-801-07	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - FRONT TANK FRONT GAUGE (24EJ)									
28.450	766-192-4A 151 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-05-900-801-08	REMOVAL / INSTALLATION OF THE FUSELAGE FUEL GAUGES - REAR TANK GAUGE (26EJ)									
28.460	766-608-1AB 148 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-09-900-801-01	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING INBOARD TANK GAUGE (L3EJ)									
28.400	792-366-1A 580 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-09-900-801-02	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING INBOARD TANK GAUGE (R3EJ)									
28.410	792-366-1A 581 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-09-900-801-03	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING CENTER TANK GAUGE (L4EJ)									
28.400	792-367-2AB 646 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-09-900-801-04	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING CENTER TANK GAUGE (R4EJ)									
28.410	792-367-2AB 647 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-09-900-801-05	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - LH WING OUTBOARD TANK GAUGE (L5EJ)									
28.400	792-368-2A 683 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-09-900-801-06	REMOVAL / INSTALLATION OF THE WING FUEL GAUGES - RH WING OUTBOARD TANK GAUGE (R5EJ)									
28.410	792-368-2A 684 REF: AMM 28-41-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-13-900-801-04	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - LH TANK GROUP FUEL QUANTITY INDICATOR (L8EJ)									
28.420	748-326-2 206 REF: AMM 28-41-13-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-13-900-801-05	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - CENTER TANK GROUP FUEL QUANTITY INDICATOR (27EJ)									
28.420	748-469-1 159 REF: AMM 28-41-13-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-13-900-801-06	REMOVAL/INSTALLATION OF FUEL QUANTITY INDICATORS - RH TANK GROUP FUEL QUANTITY INDICATOR (R8EJ)									
28.420	748-326-2 210 REF: AMM 28-41-13-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-17-900-801-01	REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - LH TANK GROUP GAUGES AMPLIFIER (L2EJ)									
28.390	736-327-1A 181 REF: AMM 28-41-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-41-17-900-801-02	REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - RH TANK GROUP GAUGES AMPLIFIER (R2EJ)									
28.390	736-327-1A 190 REF: AMM 28-41-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-17-900-801-03 28.390	REMOVAL / INSTALLATION OF THE FUEL GAUGE AMPLIFIERS - CENTER TANK GROUP GAUGES AMPLIFIER (22EJ) 736-328-2 280 REF: AMM 28-41-17-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
28-43-01-720-801	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR REF: AMM 28-43-01-720-801	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
+ 28-43-01-720-801-01 28.490	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE SENSOR (3ER) REF: AMM 28-43-01-720-801	MOS HRS/MSC AFL	N/A				28-NOV-2018 7675 3744			
28-43-01-900-801-01 28.490	REMOVAL / INSTALLATION OF THE FUEL TEMPERATURE SENSOR - FUEL TEMPERATURE SENSOR (3ER) 1122505 00064 REF: AMM 28-43-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-50-00-650-801-01	PRESSURE REFUELING REF: AMM 28-50-00-650-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-50-00-650-802-01	GRAVITY REFUELING REF: AMM 28-50-00-650-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-50-05-700-801-01 28.590	INTEGRITY CHECK OF HIGH-LEVEL SENSORS REF: AMM 28-50-05-700-801	MOS HRS/MSC AFL	O/C				17-JUN-2010 6282.8 3188			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-50-05-900-801-01	REMOVAL / INSTALLATION OF THE HIGH-LEVEL SENSORS - LH HIGH LEVEL SENSOR (L12QS)									
28.470	722105-3 1508 REF: AMM 28-50-05-900-801	MOS HRS/MSC AFL	O/C	N:18 N:0 N:0			26-DEC-2020 7883.1 3800			
28-50-05-900-801-02	REMOVAL / INSTALLATION OF THE HIGH-LEVEL SENSORS - RH HIGH LEVEL SENSOR (R12QS)									
28.470	722105-3 1121 REF: AMM 28-50-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0			29-MAR-2011 6615.8 3344			
28-70-00-860-801-01	DE-PRESSURIZATION / PRESSURIZATION OF THE FUEL TANKS									
	REF: AMM 28-70-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 28-70-01-780-801-01 (s)	CHECK FOR CORRECT CALIBRATION OF THE PRESSURE GAUGE - PRESSURE GAUGE (506QD)									
28.240	PKG 31 REF: AMM 28-70-01-780-801	MOS HRS/MSC AFL	72	+2m 3750			PKG 21-JUN-2023 8047.2 3851			
28-70-05-900-801-01	REMOVAL / INSTALLATION OF THE PRESSURE REDUCING VALVE - PRESSURE REDUCING VALVE (500QD)									
28.170	B14DE2080 134 REF: AMM 28-70-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
28-70-09-350-801-01	RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - LH VALVE BOX (L507QD)									
	B04BA1005 318 REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			17-JUN-2008 5417.7 2752	10417.7	10567.7	2368.5 (+150)
28-70-09-350-801-02	RESTORATION OF THE VALVE BOXES (FILTER CLEANING AND CALIBRATION CHECK) - RH VALVE BOX (R507QD)									
	B04BA1004 925 REF: AMM 28-70-09-350-801	MOS HRS/MSC AFL	5000	+3%			24-MAY-2002 3773.6 2200	8773.6	8923.6	724.4 (+150)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-70-09-900-801-01	REMOVAL / INSTALLATION OF THE VALVE BOXES - LH VALVE BOX (L507QD)									
28.210	B04BA1005 318 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				17-JUN-2008 5417.7 2752			
28-70-09-900-801-02	REMOVAL / INSTALLATION OF THE VALVE BOXES - RH VALVE BOX (R507QD)									
28.210	B04BA1004 925 REF: AMM 28-70-09-900-801	MOS HRS/MSC AFL	O/C				17-JUN-2008 5417.7 2752			
28-70-13-350-801-01	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)									
	B06GA1052-1 7810 REF: AMM 28-70-13-350-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
28-70-13-350-801-02	RESTORATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST) - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)									
	B06GA1052 4548 REF: AMM 28-70-13-350-801	MOS HRS/MSC AFL	O/C				(EBT)			
28-70-13-720-802-01	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)									
	B06GA1052-1 7810 REF: AMM 28-70-13-720-802	MOS HRS/MSC AFL	5000				27-JUN-2023 8049.2 3853	13049.2		5000
28-70-13-720-802-02	FUNCTIONAL TEST OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)									
	B06GA1052 4548 REF: AMM 28-70-13-720-802	MOS HRS/MSC AFL	5000				16-JUL-2012 6985.1 3525	11985.1		3935.9
28-70-13-900-801-01	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (L509QD)									
28.230	B06GA1052-1 7810 REF: AMM 28-70-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2023 8049.2 3853			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-70-13-900-801-02	REMOVAL / INSTALLATION OF THE WING TANK NEGATIVE PRESSURE RELIEF VALVES - RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (R509QD)									
28.230	B06GA1052 4548 REF: AMM 28-70-13-900-801	MOS HRS/MSC AFL	O/C	N:1 N:0 N:0			16-JUL-2012 6985.1 3525			
28-70-17-130-801-01 (s)	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 1 PRESSURIZATION AIR FILTER (L502QD)						PKG			
28.190	PKG 21 REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
28-70-17-130-801-02 (s)	CLEANING OF FUEL TANK PRESSURIZATION AIR FILTERS - ENGINE 2 PRESSURIZATION AIR FILTER (M502QD)						PKG			
28.190	PKG 21 REF: AMM 28-70-17-130-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
28-70-21-860-801-01	OPENING / CLOSING OF THE VENT VALVES									
	REF: AMM 28-70-21-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
28-70-21-900-801-01	REMOVAL / INSTALLATION OF THE VENT VALVES - LH VENT VALVE (L5QS)									
28.130	B97F38-653 A45025 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			15-MAR-2010 6193.7 3133			
28-70-21-900-801-02	RH WING VENT VALVE									
28.130	B97F38-653 20600 REF: AMM 28-70-21-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			26-APR-2011 6626.3 3348			
28-70-22-900-801-01	REMOVAL / INSTALLATION OF THE VENT VALVE ELECTRIC ACTUATORS - LH VENT VALVE ACTUATOR (L5QS1)									
	PN SN-UNKNOWN REF: AMM 28-70-22-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-70-25-900-801-01	REMOVAL / INSTALLATION OF THE REFUELING COUPLING LEVER MICROSWITCH - VENT VALVE CONTROL LEVER MICROSWITCH (26QS)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 28-70-25-900-801	AFL		N:0			0			
28-70-37-230-801-01	SPECIAL DETAILED INSPECTION OF FRAME 12 PRESSURIZATION LINE BASEPLATES									
28.580		MOS					11-JAN-1988			
		HRS/MSC	N/A				0			
	REF: AMM 28-70-37-230-801	AFL					0			
		APH					0			
281101	PRESSURE FUELING COUPLING									
28.040	K97-63-206A	MOS					11-JAN-1988			
	21283	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
281211	FILLING BLOCK									
28.090	K99-31-007	MOS					11-JAN-1988			
	20050	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
281221	FRONT FUEL TANK FILLING ELECTRIC CHECK VALVE									
28.100	L96Z31-201	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
281231	CENTER FUEL TANK FILLING ELECTRIC VALVE									
28.100	L96Z31-201	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
281241	REAR FUEL TANK FILLING ELECTRIC VALVE									
28.100	L96Z31-201	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281251	FRONT FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
281261	CENTER FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
281271	REAR FUEL TANK FILLING RESTRICTOR VALVE									
28.110	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
281281	REAR FUEL TANK FILLING CHECK VALVE									
28.120	L85D38-001 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
281311	LH WING FUELING ELECTRIC VALVE									
28.140	L94Z31-201A 20778 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
281321	RH WING FUELING ELECTRIC VALVE									
28.140	L94Z31-201A 22335 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:26 R:0 R:0			08-DEC-2021 7940.3 3817			
281331	FRONT/REAR FUEL TANK FUELING ELECTRIC VALVE									
28.140	L94Z31-201A 20846 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281351	LP3-1 ELECTRIC INTERCONNECTION VALVE									
28.150	L92B07-205 SN-UNKNOWN REF: AMM 28-22-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282151	NO. 1 ENGINE PRESSURE BLEED CHECK VALVE									
28.180	L96Z19-003 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282161	NO. 2 ENGINE PRESSURE BLEED CHECK VALVE									
28.180	L96Z19-003 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282201	NO. 1 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT									
28.190	P6742 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282221	NO. 2 ENGINE FUEL TANK PRESSURIZATION SYSTEM FILTER ELEMENT									
28.190	P6742 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282451	FUEL PRESSURE GAGE									
28.240	MPMC50701-01 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
282501	PARTIAL FUEL SELECTOR									
28.550	796-740 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
283121	XTK2 TRANSFER SOLENOID VALVE									
28.260	B97-38-662 NOT INST. REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
284251	NO. 2 ENGINE PUMPS BLOCK									
28.330	L88A31-206AB 20038 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
284321	LOW PRESSURE 1-2 CROSSFEED ELECTRIC VALVE									
28.350	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
284351	LOW PRESSURE 2-3 CROSSFEED ELECTRIC VALVE									
28.350	PN SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285401	LOW LEVEL THERMISTOR RELAY BOX									
28.480	722087-3 536 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:8 R:0 R:0			01-JUL-2021 7907.8 3809			
285421	1000 LBS LEVEL DETECTION BOX									
28.480	722-087-2A 174 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285461	FUEL TEMPERATURE INDICATOR									
28.490	5318-201-80-10 159 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				16-NOV-1994 1660 1144			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
285471	REAR TANK LEVEL RELAY BOX									
28.500	722-233-1 150 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285501	NO. 1 ENGINE LOW PRESSURE PRESSURE SWITCH									
28.510	8G1256-1 154 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285511	NO. 2 ENGINE LOW PRESSURE SWITCH									
28.510	8G1256 867 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285521	NO. 3 ENGINE LOW PRESSURE SWITCH									
28.510	8G1256-1 379 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285531	HIGH LEVEL RELAY BOX									
28.520	722-087-2A 223 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
285701	FUELING PANEL									
28.540	19-54-6A 144 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 29 HYDRAULIC POWER										
29-00-00-280-801-01	SAMPLING OF THE HYDRAULIC FLUID									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 29-00-00-280-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-00-00-610-801-01	REPLACEMENT OF THE HYDRAULIC FLUID IN CASE OF CONTAMINATION	MOS						11-JAN-1988		
	REF: AMM 29-00-00-610-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-790-801-01	LEAK CHECK OF THE HYDRAULIC SYSTEMS	MOS						11-JAN-1988		
	REF: AMM 29-00-00-790-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-860-801-01	PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH STAND-BY ELECTRICAL PUMP	MOS						11-JAN-1988		
	REF: AMM 29-00-00-860-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-860-801-02	PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH HYDRAULIC GROUND POWER UNIT	MOS						11-JAN-1988		
	REF: AMM 29-00-00-860-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-860-801-03	PRESSURIZATION / DE-PRESSURIZATION OF THE HYDRAULIC SYSTEMS - WITH THE ENGINES	MOS						11-JAN-1988		
	REF: AMM 29-00-00-860-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-870-801-01	BLEEDING OF THE HYDRAULIC SYSTEMS	MOS						11-JAN-1988		
	REF: AMM 29-00-00-870-801	HRS/MSC	O/C					0		
		AFL						0		
29-00-00-870-802-01	DEGASSING OF THE HYDRAULIC SYSTEMS	MOS						11-JAN-1988		
	REF: AMM 29-00-00-870-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-00-00-910-801-01	HYDRAULIC SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS	MOS					11-JAN-1988			
	REF: AMM 29-00-00-910-801	HRS/MSC O/C AFL					0 0			
29-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 1	MOS	72	+2m			21-JUN-2023			
	PKG 31	HRS/MSC					8047.2			
	REF: AMM 29-10-00-720-801	AFL	3750				3851			
29-10-00-720-801-02 (s)	FUNCTIONAL TEST OF THE MAIN HYDRAULIC SYSTEMS - SYSTEM 2	MOS	72	+2m			21-JUN-2023			
	PKG 31	HRS/MSC					8047.2			
	REF: AMM 29-10-00-720-801	AFL	3750				3851			
29-11-01-350-801-01	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 1 (L500ML)	MOS		I:0			05-OCT-2009			
29.050	4204501	HRS/MSC	3240	+3%			6001.5	9241.5	9338.7	1192.3 (+97.2)
OVERHAUL	REF: AMM 29-11-01-350-801	AFL		I:0			3018			
29-11-01-350-801-02	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 2 (M500ML)	MOS		I:0			05-OCT-2009			
29.050	4204501	HRS/MSC	3240	+3%			6001.5	9241.5	9338.7	1192.3 (+97.2)
OVERHAUL	REF: AMM 29-11-01-350-801	AFL		I:0			3018			
29-11-01-350-801-03	RESTORATION OF THE HYDRAULIC PUMPS (OVERHAUL) - HYDRAULIC PUMP 3 (R500ML)	MOS		I:0			05-OCT-2009			
29.050	4204501	HRS/MSC	3240	+3%			6001.5	9241.5	9338.7	1192.3 (+97.2)
OVERHAUL	REF: AMM 29-11-01-350-801	AFL		I:0			3018			
29-11-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 1 (L500ML)	MOS		O:0			05-OCT-2009			
29.050	4204501	HRS/MSC	H/T	O:0			6001.5			
	REF: AMM 29-11-01-900-801	AFL		O:0			3018			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-11-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 2 (M500ML)									
29.050	4204501 D047 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	O:0 O:0 O:0			05-OCT-2009 6001.5 3018			
29-11-01-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMPS - HYDRAULIC PUMP 3 (R500ML)									
29.050	4204501 0026 REF: AMM 29-11-01-900-801	MOS HRS/MSC AFL	H/T	O:0 O:0 O:0			05-OCT-2009 6001.5 3018			
29-11-07-870-801-01	BLEEDING OF THE HYDRAULIC PUMP SUCTION LINES									
	REF: AMM 29-11-07-870-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
29-11-21-230-801-01	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)									
29.070	A24518001 FM619 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C							
29-11-21-230-801-02	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)									
29.070	A24518001 FM2808 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C							
29-11-21-230-801-03	SPECIAL DETAILED INSPECTION OF THE INTERNAL PART OF THE BODY OF THE PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)									
29.075	A24518001 FM2790 REF: AMM 29-11-21-230-801	MOS HRS/MSC AFL	O/C							
29-11-21-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 1 PRESSURE RELIEF VALVE (L100ML)									
29.070	A24518001 FM619 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-11-21-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 2 PRESSURE RELIEF VALVE (M100ML)									
29.070	A24518001 FM2808 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
29-11-21-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PRESSURE RELIEF VALVES - HYDRAULIC PUMP 3 PRESSURE RELIEF VALVE (R100ML)									
29.075	A24518001 FM2790 REF: AMM 29-11-21-900-801	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
29-11-25-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (2DW1)									
29.190	90G229 023 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-JAN-1992 966 670			
29-11-25-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (2DW2)									
29.190	90G229 140 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-11-25-900-801-03	REMOVAL / INSTALLATION OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (2DW3)									
29.190	90G229 147 REF: AMM 29-11-25-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-11-25-960-801-01	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 1 PRESSURE SWITCH (2DW1)									
29.190	90G229 023 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C	I:0 I:0 I:0			06-JAN-1992 966 670			
29-11-25-960-801-02	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 2 PRESSURE SWITCH (2DW2)									
29.190	90G229 140 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-11-25-960-801-03 29.190	DISCARD OF THE HYDRAULIC PUMP PRESSURE SWITCHES - HYDRAULIC PUMP 3 PRESSURE SWITCH (2DW3) 90G229 147 REF: AMM 29-11-25-960-801	MOS HRS/MSC AFL	O/C	I:0			11-JAN-1988 0 0			
29-13-09-900-801-01 29.110	NO. 1 SYSTEM HYDRAULIC FILTER AC-9607F-10Y4 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				07-APR-2010 6208.2 3145			
29-13-09-900-801-02 29.110	NO. 2 SYSTEM HYDRAULIC FILTER AD3258-8Y54 0042 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-13-09-960-801-01 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - STANDBY PUMP FILTER (14ML) PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			
29-13-09-960-801-02 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 1 RETURN FILTER (L200ML) PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			
29-13-09-960-801-03 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 2 RETURN FILTER (M200ML) PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			
29-13-09-960-801-04 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 3 RETURN FILTER (R200ML) PKG 31 REF: AMM 29-13-09-960-801	MOS HRS/MSC AFL	72 3750	+2m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-13-09-960-801-05 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - SYSTEM 1 GENERAL RETURN FILTER (L300ML) PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 29-13-09-960-801	AFL	3750							
29-13-09-960-801-06 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - SYSTEM 2 GENERAL RETURN FILTER (R300ML) PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 29-13-09-960-801	AFL	3750							
29-13-09-960-801-07 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 1 DELIVERY FILTER (L350ML) PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 29-13-09-960-801	AFL	3750							
29-13-09-960-801-08 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 2 DELIVERY FILTER (M350ML) PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 29-13-09-960-801	AFL	3750							
29-13-09-960-801-09 (s)	REPLACEMENT OF THE HYDRAULIC FILTERS - HYDRAULIC PUMP 3 DELIVERY FILTER (R350ML) PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 29-13-09-960-801	AFL	3750							
29-14-01-610-801-01	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)	MOS HRS/MSC	O/C				11-JAN-1988 0 0			
	REF: AMM 29-14-01-610-801	AFL								
29-14-01-610-801-02	FILLING AND REPLENISHING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)	MOS HRS/MSC	O/C				11-JAN-1988 0 0			
	REF: AMM 29-14-01-610-801	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-14-01-680-801-01	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									
29.030	REF: AMM 29-14-01-680-801	MOS HRS/MSC AFL	O/C				19-JUL-2012 6985.1 3525			
29-14-01-680-801-02	DRAINING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)									
29.030	REF: AMM 29-14-01-680-801	MOS HRS/MSC AFL	O/C				19-JUL-2012 6985.1 3525			
29-14-01-870-801-01	BLEEDING OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									
	REF: AMM 29-14-01-870-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
29-14-01-870-801-02	BLEEDING OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)									
	REF: AMM 29-14-01-870-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
29-14-01-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									
29.030	029029-06 128 REF: AMM 29-14-01-900-801	MOS HRS/MSC AFL	O/C	N:21			07-JAN-1989 205 124			
29-14-01-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC RESERVOIRS - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)									
29.030	029029-05 74 REF: AMM 29-14-01-900-801	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			16-JUL-2012 6985.1 3525			
29-14-01-960-801-01	REPLACEMENT OF THE HYDRAULIC RESERVOIR INDICATOR WINDOW - SYSTEM 1 HYDRAULIC RESERVOIR (L501ML)									
	REF: AMM 29-14-01-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-14-01-960-801-02	REPLACEMENT OF THE HYDRAULIC RESERVOIR INDICATOR WINDOW - SYSTEM 2 HYDRAULIC RESERVOIR (R501ML)	MOS						11-JAN-1988		
	REF: AMM 29-14-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
29-14-09-610-801-01	CHARGING OF THE PRESSURE HOLDING VALVE ACCUMULATORS - SYSTEM 1 PRESSURE HOLDING VALVE ACCUMULATOR (L525ML1)	MOS						11-JAN-1988		
	REF: AMM 29-14-09-610-801	HRS/MSC	O/C					0		
		AFL						0		
29-14-09-610-801-02	CHARGING OF THE PRESSURE HOLDING VALVE ACCUMULATORS - SYSTEM 2 PRESSURE HOLDING VALVE ACCUMULATOR (R525ML1)	MOS						11-JAN-1988		
	REF: AMM 29-14-09-610-801	HRS/MSC	O/C					0		
		AFL						0		
29-14-09-900-802-01	REMOVAL / INSTALLATION OF HYDRAULIC SYSTEM PRESSURE- HOLDING VALVES - SYSTEM 1 PRESSURE-HOLDING VALVE (L525ML)	MOS						11-JAN-1988		
29.090	70073	HRS/MSC	O/C	N:0				0		
	106	AFL						0		
	REF: AMM 29-14-09-900-802							0		
29-14-09-900-802-02	REMOVAL / INSTALLATION OF HYDRAULIC SYSTEM PRESSURE- HOLDING VALVES - SYSTEM 2 PRESSURE-HOLDING VALVE (R525ML)	MOS						11-JAN-1988		
29.090	70073	HRS/MSC	O/C	N:0				0		
	74	AFL						0		
	REF: AMM 29-14-09-900-802							0		
29-14-11-610-801-01	CHARGING OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)	MOS						11-JAN-1988		
	REF: AMM 29-14-11-610-801	HRS/MSC	O/C					0		
		AFL						0		
29-14-11-610-801-02	CHARGING OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)	MOS						11-JAN-1988		
	REF: AMM 29-14-11-610-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-14-11-900-801-01	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 1 ACCUMULATOR (L515ML)									
29.060	60833-2 267 REF: AMM 29-14-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-14-11-900-801-02	REMOVAL / INSTALLATION OF THE HYDRAULIC SYSTEM ACCUMULATORS - SYSTEM 2 ACCUMULATOR (R515ML)									
29.060	60833-2 273 REF: AMM 29-14-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-20-00-720-801-01	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 1									
	REF: AMM 29-20-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
29-20-00-720-801-02	FUNCTIONAL TEST OF THE AUXILIARY HYDRAULIC SYSTEM - SYSTEM 2									
	REF: AMM 29-20-00-720-801	MOS HRS/MSC AFL	5000				25-JUL-2007 5151.9 2642	10151.9		2102.7
29-20-01-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY ELECTRIC PUMP - STANDBY ELECTRIC PUMP (3ML)									
29.240	42032 AG257 REF: AMM 29-20-01-900-801	MOS HRS/MSC AFL	O/C				25-JUL-2007 5151.9 2642			
+ 29-20-03-220-801-01	CHECK OF THE STANDBY ELECTRIC PUMP MOTOR BRUSHES - STANDBY ELECTRIC PUMP (3ML)									
29.240	42032 AG257 REF: AMM 29-20-03-220-801	MOS HRS/MSC AFL	5000	+3%			25-JUL-2007 5151.9 2642	10151.9	10301.9	2102.7 (+150)
29-20-03-720-801-01	FUNCTIONAL TEST OF THE STANDBY ELECTRIC PUMP MOTOR - STANDBY ELECTRIC PUMP (3ML)									
29.240	42032 AG257 REF: AMM 29-20-03-720-801	MOS HRS/MSC AFL	O/C				25-JUL-2007 5151.9 2642			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-20-05-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP SELECTOR VALVE - STANDBY PUMP SELECTOR VALVE (5ML)									
29.260	B94A13-205 20149 REF: AMM 29-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
29-20-07-900-801-01	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L4ML)									
29.200	15H0092PH 0682 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	N:37 N:0 N:0			09-DEC-2021 7940.3 3817			
29-20-07-900-801-02	REMOVAL / INSTALLATION OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R4ML)									
29.200	90G196-2 2938 REF: AMM 29-20-07-900-801	MOS HRS/MSC AFL	O/C	N:210 N:0 N:0			09-DEC-2021 7940.3 3817			
29-20-07-960-801-01	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 1 STANDBY PUMP PRESSURE SWITCH (L4ML)									
29.200	15H0092PH 0682 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				09-DEC-2021 7940.3 3817			
29-20-07-960-801-02	DISCARD OF THE STANDBY PUMP PRESSURE SWITCHES - SYSTEM 2 STANDBY PUMP PRESSURE SWITCH (R4ML)									
29.200	90G196-2 2938 REF: AMM 29-20-07-960-801	MOS HRS/MSC AFL	O/C				09-DEC-2021 7940.3 3817			
291091	NO. 1 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE									
29.040	034001 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291141	NO. 2 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR VALVE									
29.040	034001 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291311	NO. 1 HYDRAULIC PUMP DISCHARGE FILTER AD3255-8Y60 0121 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291321	NO. 2 HYDRAULIC PUMP DISCHARGE FILTER AD3255-8Y60 0049 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
291331	NO. 3 HYDRAULIC PUMP DISCHARGE FILTER AD3255-8Y60 0331 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
291346	NO. 1 HYDRAULIC SYSTEM PRESSURE GAUGE 18040100 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291356	NO. 2 HYDRAULIC SYSTEM PRESSURE GAUGE 18040100 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291361	NO. 1 PUMP REGULATION RETURN FILTER ADB296-5Y3 0106 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291381	NO. 2 PUMP REGULATION RETURN FILTER ADB296-5Y3 0113 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291401	NO. 3 PUMP REGULATION RETURN FILTER ADB296-5Y3 0133 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291461	NO. 1 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION B3005-S4-12D SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291471	NO. 2 SUCTION SYSTEM HYDRAULIC GROUND CONNECTION B3005-S4-12D SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291481	NO. 1 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION TB3005-S4-8D SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291491	NO. 2 DISCHARGE SYSTEM HYDRAULIC GROUND CONNECTION TB3005-S4-8D SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291501	NO. 1 DISCHARGE PUMP QUICK DISCHARGE VALVE 405-20403-13200 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291511	NO. 2 DISCHARGE PUMP QUICK DISCHARGE VALVE 405-20403-13200 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291521	NO. 3 DISCHARGE PUMP QUICK DISCHARGE VALVE 405-20403-13200 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291531	NO. 1 SUCTION PUMP QUICK DISCHARGE VALVE 405-20402-13300 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291541	NO. 2 SUCTION PUMP QUICK DISCHARGE VALVE 405-20402-13300 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291551	NO. 3 SUCTION PUMP QUICK DISCHARGE VALVE 405-20402-13300 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291561	NO. 1 RETURN REGULATION PUMP CHECK VALVE A24515-1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291571	NO. 2 AFT RETURN REGULATION PUMP CHECK VALVE A24515-1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291581	NO. 3 RETURN REGULATION PUMP CHECK VALVE A24515-1 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291591	NO. 1 FILTER/PUMP PROTECTION CHECK VALVE									
29.170	A24517 FM1377 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291601	NO. 2 PUMP PROTECTION CHECK VALVE									
29.180	A24517 FM1314 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291611	NO. 2 FILTER PROTECTION CHECK VALVE									
29.170	A24517 FM1380 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291621	NO. 3 PUMP PROTECTION CHECK VALVE									
29.180	A24517 FM1381 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291631	NO. 2 SYSTEM EXTERIOR POWER SUPPLY CHECK VALVE									
29.185	A24517 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291701	NO. 1 LEVEL/PRESSURE DUAL INDICATOR									
29.210	5502-380-80-10 892 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			28-NOV-2018 7675 3744			
291711	NO. 2 LEVEL/PRESSURE DUAL INDICATOR									
29.210	5502-380-80-10 949 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	R:26 R:0 R:0			28-NOV-2018 7675 3744			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291721	NO. 1 SYSTEM PRESSURE TRANSMITTER									
29.220	8107-132-00-10A 230 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291731	NO. 2 SYSTEM PRESSURE TRANSMITTER									
29.220	8107-132-00-10A 134 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C				18-JUL-1995 1801 1270			
291751	NO. 1 SYSTEM HYDRAULIC QUANTITY GAUGE									
29.230	18040100 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
291761	NO. 2 SYSTEM HYDRAULIC QUANTITY GAUGE									
29.230	18040100 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
292171	ELECTRIC PUMP DISCHARGE FILTER									
29.260	AD3255-8Y63 0064 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
292201	NO. 1 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE									
29.270	A24516 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
292211	NO. 2 SYSTEM ELECTRIC PUMP PROTECTION CHECK VALVE									
29.270	A24516 SN-UNKNOWN REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
292301	HYDRAULIC CONTROL PANEL									
29.280	380TS06Y03 255 REF: AMM GENERIC 1	MOS HRS/MSC AFL APH	O/C	R:3 N:9069 R:0 N:4658 R:0			05-APR-2018 7631.4 3731 3601			
CHAPTER 30 ICE AND RAIN PROTECTION										
30-00-00-960-801-01 (s)	REPLACEMENT OF THE ANTI-ICING SYSTEM WIGGINS COUPLING SEALS						PKG			
30.040	PKG 32 REF: AMM 30-00-00-960-801	MOS HRS/MSC AFL	144 7500	+2m			21-JUN-2023 8047.2 3851			
30-10-00-710-801	OPERATIONAL TEST OF THE WING ANTI-ICING SYSTEM	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
30-10-00-710-801-01	OPERATIONAL TEST OF THE WING ANTI-ICING SYSTEM	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
30-10-00-790-801	LEAK CHECK OF THE WING ANTI-ICING SYSTEM	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
30-10-00-790-801-01	LEAK CHECK OF THE WING ANTI-ICING SYSTEM	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
30-10-00-810-901	TROUBLESHOOTING OF THE WING ANTI-ICING VALVE	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-11-00-350-801-01	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH INBOARD SLAT TELESCOPIC DUCT (L501HJ)									
30.060	5036-600 296 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C	I:0 I:0 I:0			07-APR-2010 6208.2 3145			
30-11-00-350-801-02	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH INBOARD SLAT TELESCOPIC DUCT (R501HJ)									
30.060	5036-500 141 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C	I:240 I:5417.7 I:2752			17-JUN-2008 5417.7 2752			
30-11-00-350-801-03	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - LH OUTBOARD SLAT TELESCOPIC DUCT (L502HJ)									
30.050	5035-400 290 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				08-AUG-2008 5489.2 2787			
30-11-00-350-801-04	RESTORATION OF THE SLAT TELESCOPIC DUCTS (OVERHAUL) - RH OUTBOARD SLAT TELESCOPIC DUCT (R502HJ)									
30.050	5035-500 215 REF: AMM 30-11-00-350-801	MOS HRS/MSC AFL	O/C				08-AUG-2008 5489.2 2787			
30-11-00-720-801-01	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH INBOARD SLAT TELESCOPIC DUCT (L501HJ)									
30.060	5036-600 296 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	2480 2000	+3% +3%			07-APR-2010 6208.2 3145	8688.2 5145	8762.6 5205	639 1292 (+74.4) (+60)
30-11-00-720-801-02	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH INBOARD SLAT TELESCOPIC DUCT (R501HJ)									
30.060	5036-500 141 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	1240 1000	+3% +3%			26-DEC-2020 7883.1 3800	9123.1 4800	9160.3 4830	1073.9 947 (+37.2) (+30)
30-11-00-720-801-03	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD SLAT TELESCOPIC DUCT (L502HJ)									
30.050	5035-400 290 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	1240 1000	+3% +3%			26-DEC-2020 7883.1 3800	9123.1 4800	9160.3 4830	1073.9 947 (+37.2) (+30)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-11-00-720-801-04	FUNCTIONAL TEST OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD SLAT TELESCOPIC DUCT (R502HJ)									
30.050	5035-500 215 REF: AMM 30-11-00-720-801	MOS HRS/MSC AFL	1240 +3% 1000 +3%				26-DEC-2020 7883.1 3800	9123.1 4800	9160.3 4830	1073.9 (+37.2) 947 (+30)
30-11-00-900-801-01	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC DUCT (L501HJ)									
30.060	5036-600 296 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-APR-2010 6208.2 3145			
30-11-00-900-801-02	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC DUCT (R501HJ)									
30.060	5036-500 141 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	O:240 O:5417.7 O:2752			17-JUN-2008 5417.7 2752			
30-11-00-900-801-03	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - LH OUTBOARD TELESCOPIC DUCT (L502HJ)									
30.050	5035-400 290 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-AUG-2008 5489.2 2787			
30-11-00-900-801-04	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCTS - RH OUTBOARD TELESCOPIC DUCT (R502HJ)									
30.050	5035-500 215 REF: AMM 30-11-00-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-AUG-2008 5489.2 2787			
+ 30-11-01-200-801-01	INSPECTION OF THE INBOARD SLAT TELESCOPIC DUCTS - LH INBOARD TELESCOPIC TUBE (L501HJ)									
30.060	REF: AMM 30-11-01-200-801	MOS HRS/MSC AFL	O/C				19-SEP-2011 6734.2 3397			
+ 30-11-01-200-801-02	INSPECTION OF THE INBOARD SLAT TELESCOPIC DUCTS - RH INBOARD TELESCOPIC TUBE (R501HJ)									
30.060	REF: AMM 30-11-01-200-801	MOS HRS/MSC AFL	O/C				19-SEP-2011 6734.2 3397			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-11-11-280-801	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES	MOS						11-JAN-1988		
	REF: AMM 30-11-11-280-801	HRS/MSC	A/R					0		
		AFL						0		
30-11-11-280-801-01	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE	MOS						11-JAN-1988		
	REF: AMM 30-11-11-280-801	HRS/MSC	O/C					0		
		AFL						0		
30-11-11-280-801-02	SPECIAL DETAILED INSPECTION OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE	MOS						11-JAN-1988		
	REF: AMM 30-11-11-280-801	HRS/MSC	O/C					0		
		AFL						0		
30-11-11-960-801	REPLACEMENT OF THE PICCOLO TUBES	MOS						11-JAN-1988		
	REF: AMM 30-11-11-960-801	HRS/MSC	A/R					0		
		AFL						0		
30-11-11-960-801-01	REPLACEMENT OF THE PICCOLO TUBES - LH OUTBOARD SLAT PICCOLO TUBE	MOS						11-JAN-1988		
	REF: AMM 30-11-11-960-801	HRS/MSC	O/C					0		
		AFL						0		
30-11-11-960-801-02	REPLACEMENT OF THE PICCOLO TUBES - LH INBOARD SLAT PICCOLO TUBE	MOS						11-JAN-1988		
	REF: AMM 30-11-11-960-801	HRS/MSC	O/C					0		
		AFL						0		
30-11-11-960-801-03	REPLACEMENT OF THE PICCOLO TUBES - RH INBOARD SLAT PICCOLO TUBE	MOS						11-JAN-1988		
	REF: AMM 30-11-11-960-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-11-11-960-801-04	REPLACEMENT OF THE PICCOLO TUBES - RH OUTBOARD SLAT PICCOLO TUBE	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
	REF: AMM 30-11-11-960-801									
30-11-13-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PIPES - LH WING INBOARD SLAT ANTI-ICING PIPE	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
	REF: AMM 30-11-13-900-801									
30-11-13-900-801-02	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PIPES - RH WING INBOARD SLAT ANTI-ICING PIPE	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
	REF: AMM 30-11-13-900-801									
30-11-13-900-801-03	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PIPES - LH WING OUTBOARD SLAT ANTI-ICING PIPE	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
	REF: AMM 30-11-13-900-801									
30-11-13-900-801-04	REMOVAL / INSTALLATION OF THE WING ANTI-ICING PIPES - RH WING OUTBOARD SLAT ANTI-ICING PIPE	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
	REF: AMM 30-11-13-900-801									
+ 30-11-17-200-801-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM COUPLINGS LOCATED IN THE REAR COMPARTMENT	MOS HRS/MSC AFL	24	+1m				PKG 21-JUN-2023 8047.2 3851		
30.020	PKG 16									
	REF: AMM 30-11-17-200-801									
+ 30-11-17-200-803-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM GENERAL CONNECTOR COUPLINGS	MOS HRS/MSC AFL	72	+2m				PKG 21-JUN-2023 8047.2 3851		
30.150	PKG 31									
	REF: AMM 30-11-17-200-803			3750						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-12-00-720-801-01	FUNCTIONAL TEST OF THE WING ANTI-ICING CONTROLS AND INDICATIONS	MOS						11-JAN-1988		
	REF: AMM 30-12-00-720-801	HRS/MSC	O/C					0		
		AFL						0		
30-12-01-900-801-01	REMOVAL / INSTALLATION OF THE WING ANTI-ICING VALVE - WING ANTI-ICING VALVE (3HJ)	MOS						11-JAN-1988		
30.070	BYLB51035-1	HRS/MSC	O/C	N:0				0		
	REF: AMM 30-12-01-900-801	AFL						0		
30-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 1	MOS					PKG			
	PKG 21	HRS/MSC	1600	+40				11-NOV-2015		
	REF: AMM 30-20-00-710-801	AFL						7355.5		
								3656		
+ 30-20-00-710-801-02 (s)	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 2	MOS					PKG			
30.100	PKG 21	HRS/MSC	1600	+40				11-NOV-2015		
	REF: AMM 30-20-00-710-801	AFL						7355.5		
								3656		
30-20-00-710-801-03 (s)	OPERATIONAL TEST OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM - ENGINE 3	MOS					PKG			
	PKG 21	HRS/MSC	1600	+40				11-NOV-2015		
	REF: AMM 30-20-00-710-801	AFL						7355.5		
								3656		
30-20-00-720-801	FUNCTIONAL TEST OF THE ENGINE 2 AIR INTAKE AND S-DUCT ANTI-ICING CONTROLS AND INDICATIONS	MOS						11-JAN-1988		
	REF: AMM 30-20-00-720-801	HRS/MSC	A/R					0		
		AFL						0		
30-20-00-720-801-01	FUNCTIONAL TEST OF THE ENGINE 2 AIR INTAKE AND S-DUCT ANTI-ICING CONTROLS AND INDICATIONS	MOS						11-JAN-1988		
	REF: AMM 30-20-00-720-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-20-00-790-801	LEAK CHECK OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM	MOS					11-JAN-1988			
	REF: AMM 30-20-00-790-801	HRS/MSC AFL	A/R				0			
30-20-00-790-801-01	LEAK CHECK OF THE ENGINE AIR INTAKE ANTI-ICING SYSTEM	MOS					11-JAN-1988			
	REF: AMM 30-20-00-790-801	HRS/MSC AFL	O/C				0			
+ 30-20-01-700-801-01	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L3HA)	MOS					25-JAN-2008			
30.110	1818-00-1A 0707 REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%			5308.9 2695	10308.9	10458.9	2259.7 (+150)
+ 30-20-01-700-801-02	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M3HA)	MOS					19-OCT-2006			
30.120	6911B030100 043 REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%			4921.5 2564	9921.5	10071.5	1872.3 (+150)
+ 30-20-01-700-801-03	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R3HA)	MOS					19-OCT-2006			
30.130	6911B030100 140 REF: AMM 30-20-01-700-801	HRS/MSC AFL	5000	+3%			4921.5 2564	9921.5	10071.5	1872.3 (+150)
30-20-01-900-801	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES	MOS					11-JAN-1988			
	PN SN-UNKNOWN REF: AMM 30-20-01-900-801	HRS/MSC AFL	O/C				0			
30-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L3HA)	MOS					11-JAN-1988			
	PN SN-UNKNOWN REF: AMM 30-20-01-900-801	HRS/MSC AFL	O/C				0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M3HA)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 30-20-01-900-801	AFL		N:0				0		
30-20-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R3HA)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 30-20-01-900-801	AFL		N:0				0		
30-20-09-810-901	TROUBLESHOOTING OF THE ENGINE ANTI-ICING PRESSURE SWITCHES									
		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM GENERIC 1	AFL						0		
30-21-00	ENGINES 1 AND 3 AIR INTAKE ANTI-ICING									
		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM 30-21-00	AFL						0		
30-22-00	ENGINE 2 AIR INTAKE AND S-DUCT ANTI-ICING SYSTEMS									
		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM 30-22-00	AFL						0		
30-30-00-710-801	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM									
		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM 30-30-00-710-801	AFL						0		
30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM									
	PKG 21	MOS						PKG		
		HRS/MSC	1600	+40				04-NOV-2015		
	REF: AMM 30-30-00-710-801	AFL						7355.5		
								3656		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 30-41-00-200-801-01 (s)	INSPECTION OF THE WINDSHIELD HEATING SYSTEM CONNECTORS PKG 16	MOS	24	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 30-41-00-200-801	HRS/MSC AFL								
+ 30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM PKG 23	MOS	4800	+40			PKG 03-SEP-2003 4150 2320			
30.230	REF: AMM 30-41-00-710-801	HRS/MSC AFL								
30-41-01-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELD RESISTOR BOXES - LH RESISTOR BOX (L11HH) PN	MOS					11-JAN-1988 0 0			
	SN-UNKNOWN	HRS/MSC	O/C							
	REF: AMM 30-41-01-900-801	AFL								
30-41-01-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELD RESISTOR BOXES - RH RESISTOR BOX (R11HH) PN	MOS					11-JAN-1988 0 0			
	SN-UNKNOWN	HRS/MSC	O/C							
	REF: AMM 30-41-01-900-801	AFL								
30-43-00-710-801-01	OPERATIONAL TEST OF THE WINDSHIELD WIPERS REF: AMM 30-43-00-710-801	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
		AFL								
30-43-00-720-801-01	FUNCTIONAL TEST OF THE WINDSHIELD WIPERS REF: AMM 30-43-00-720-801	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
		AFL								
30-43-01-820-801-01	ADJUSTMENT OF THE WINDSHIELD WIPERS REF: AMM 30-43-01-820-801	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
		AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-43-03-200-801-01	INSPECTION OF THE RUBBER WINDSHIELD WIPER BLADES	MOS					11-JAN-1988			
	REF: AMM 30-43-03-200-801	HRS/MSC O/C					0			
		AFL					0			
30-43-03-960-801-01	REPLACEMENT OF THE WINDSHIELD WIPER BLADES	MOS					11-JAN-1988			
	REF: AMM 30-43-03-960-801	HRS/MSC O/C					0			
		AFL					0			
30-43-05-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - LH WINDSHIELD WIPER ARTICULATED ARM (L500MK)	MOS					11-JAN-1988			
30.270	4218246	HRS/MSC O/C		N:0			0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 30-43-05-900-801						0			
30-43-05-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELD WIPER MOTOR-ACTUATED ANGLE DRIVES - RH WINDSHIELD WIPER ARTICULATED ARM (R500MK)	MOS					11-JAN-1988			
30.270	4218209	HRS/MSC O/C		N:0			0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 30-43-05-900-801						0			
+ 30-43-09-220-801-01	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - LH WINDSHIELD WIPER MOTOR (L5MK)	MOS					11-JAN-1988			
30.260	4267568	HRS/MSC	15000	+3%			0	15000	15450	6950.8 (+450)
	11111	AFL					0			
	REF: AMM 30-43-09-220-801						0			
+ 30-43-09-220-801-02	CHECK OF THE WINDSHIELD WIPER MOTOR BRUSHES - RH WINDSHIELD WIPER MOTOR (R5MK)	MOS					11-JAN-1988			
30.260	4267575	HRS/MSC	15000	+3%			0	15000	15450	6950.8 (+450)
	11108	AFL					0			
	REF: AMM 30-43-09-220-801						0			
30-80-01-900-801-01	REMOVAL / INSTALLATION OF THE ICE DETECTOR - ICE DETECTOR (700HA)	MOS					11-JAN-1988			
	PN	HRS/MSC O/C		N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 30-80-01-900-801			N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-90-00-710-801-01	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM									
30.045		MOS					11-JAN-1988			
	REF: AMM 30-90-00-710-801	HRS/MSC	N/A				0			
		AFL					0			
30-90-00-790-801-01	LEAK CHECK OF THE BRAKE HEATING SYSTEM									
		MOS					11-JAN-1988			
	REF: AMM 30-90-00-790-801	HRS/MSC	O/C				0			
		AFL					0			
30-90-01-900-801-01	REMOVAL / INSTALLATION OF THE BRAKE HEATING VALVES - LH BRAKE HEATING VALVE (L51HC)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 30-90-01-900-801	AFL		N:0			0			
30-90-01-900-801-02	REMOVAL / INSTALLATION OF THE BRAKE HEATING VALVES - RH BRAKE HEATING VALVE (R51HC)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 30-90-01-900-801	AFL		N:0			0			
301351	LH WING ANTI-ICING PRESSURE SWITCH									
30.080	8G1199-2	MOS					11-JAN-1988			
	185	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
301381	RH WING ANTI-ICING PRESSURE SWITCH									
30.080	8G1199-2	MOS					11-JAN-1988			
	186	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 1	AFL					0			
301401	BLEED AIR HIGH PRESSURE MONITOR-									
30.080	EL126-00	MOS					04-FEB-2021			
	300	HRS/MSC	O/C				7893.8			
	REF: AMM GENERIC 1	AFL					3803			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
302101	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 1818-00-1A	MOS		N:0			25-JAN-2008			
30.110	0707 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0 N:0			5308.9 2695			
302121	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 6911B030100	MOS					19-OCT-2006			
30.120	043 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:4921.5			4921.5 2564			
302141	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE 6911B030100	MOS					19-OCT-2006			
30.130	140 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:4921.5			4921.5 2564			
302261	NO. 2 ENGINE DUCT ANTI-ICING VALVE B48CA1121AB	MOS					11-JAN-1988			
30.160	161 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
302301	NO. 1 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					11-JAN-1988			
30.170	116 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
302321	NO. 1 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1	MOS					11-JAN-1988			
30.170	142 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			
302341	NO. 2 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2	MOS					11-JAN-1988			
30.180	277 REF: AMM GENERIC 1	HRS/MSC AFL	O/C	N:0			0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
302361	NO. 2 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1 091 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
302381	NO. 2 ENGINE DUCT ANTI-ICING PRESSURE SWITCH 8G1199-2 152 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
302401	NO. 3 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-2 291 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
302421	NO. 3 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-1 149 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
303101	LH PITOT/STATIC HEAT MONITORING BOX 24-255A 86 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
303131	RH PITOT/STATIC HEAT MONITORING BOX 24-255 36 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			24-NOV-2009 6050.6 3045			
303161	STANDBY PITOT HEAT MONITORING BOX 24-256 42 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
304101	PILOT WINDSHIELD HEATING REGULATOR HYLZ50426-1 630D REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
304121	COPILOT WINDSHIELD HEATING REGULATOR HYLZ50426-1 633D REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
304141	LH SIDE WINDOW HEATING REGULATOR HYLZ50422 794D REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
304161	RH SIDE WINDOW HEATING REGULATOR HYLZ50422 800D REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
304301	PILOT WINDSHIELD WIPER MOTOR 4267568 11111 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
304331	COPILOT WINDSHIELD WIPER MOTOR 4267575 11108 REF: AMM GENERIC 1	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 31 INDICATING/RECORDING SYSTEMS										
25-62-00-900-801-01	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)									
31.070	DK120/90 AT118123 REF: AMM 25-62-00-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-FEB-2020 7825.6 3786			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-62-00-900-801-02	REMOVAL / INSTALLATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)									
31.100	DK120/90	MOS		N:0			30-JAN-2020			
	AT137135	HRS/MSC	O/C	N:0			7825.6			
	REF: AMM 25-62-00-900-801	AFL		N:0			3786			
31-10-00-900-801-01	REMOVAL / INSTALLATION OF AN INDICATOR LIGHT (ECE SQUARE LIGHT)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 31-10-00-900-801	AFL		N:0			0			
31-11-47-960-801-01	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "BAT 1" MAGNETIC SWITCH (L2PE)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 31-11-47-960-801	AFL					0			
31-11-47-960-801-02	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "BAT 2" MAGNETIC SWITCH (R2PE)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 31-11-47-960-801	AFL					0			
31-11-47-960-801-03	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 1" MAGNETIC SWITCH (2PA1)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 31-11-47-960-801	AFL					0			
31-11-47-960-801-04	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 2" MAGNETIC SWITCH (2PA2)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 31-11-47-960-801	AFL					0			
31-11-47-960-801-05	REPLACEMENT OF THE OVERHEAD PANEL MAGNETIC SWITCHES - "GEN 3" MAGNETIC SWITCH (2PA3)									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 31-11-47-960-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-21-05-960-801-01	REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (L1DT) BATTERY 811BATT-1 SN-UNKNOWN REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	25				01-MAR-2022 7961.3 3825	25-JUL-2023 M		7 d
31.080 LIFE LIMIT										
31-21-05-960-801-02	REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (R1DT) BATTERY 811BATT-1 SN-UNKNOWN REF: AMM 31-21-05-960-801	MOS HRS/MSC AFL	25				01-MAR-2022 7961.3 3825	25-JUL-2023 M		7 d
31.080 SCRAP										
31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE FLIGHT DATA RECORDER (FDR) SYSTEM PKG 17 REF: AMM 31-31-00-710-802	MOS HRS/MSC AFL	36	+1m			PKG 21-JUN-2023 8047.2 3851			
31.100										
31-31-00-720-802-01	FUNCTIONAL TEST FLIGHT DATA (FDR) RECORDER 57-PARAMETERS S800-2000-01 00310 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C							
31.100										
31-31-00-720-803-01	FUNCTIONAL TEST OF THE 32-PARAMETER FDR - FDR (14FZ) REF: AMM 31-31-00-720-803	MOS HRS/MSC AFL	O/C							
31.100										
31-31-00-970-801-01	DOWNLOAD OF THE FLIGHT DATA RECORDER (FDR) - FDR (14FZ) REF: AMM 31-31-00-970-801	MOS HRS/MSC AFL	A/R				06-JAN-2012 6879 3476			
31.100										
31-31-09-710-801-01	OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (5RK) 6U0-114 591121 REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	N/A							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-31-09-710-801-02	OPERATIONAL TEST OF THE FDR/CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (15FZ) OR (23FZ) PN NOT INSTALLED REF: AMM 31-31-09-710-801	MOS HRS/MSC AFL	N/A							
31-31-09-900-801-01	REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - CVR ACCELERATION CONTACT (5RK) 6U0-114 591121 REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-MAY-1991 807 560			
31-31-09-900-801-02	REMOVAL / INSTALLATION OF THE FDR / CVR ACCELERATION CONTACTS - FDR ACCELERATION CONTACT (15FZ) OR (23FZ) PN NOT INSTALLED REF: AMM 31-31-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
31-31-31-900-801-01	REMOVAL / INSTALLATION OF THE FLIGHT DATA RECORDER (FDR) - FDR (14FZ) S800-2000-01 00310 REF: AMM 31-31-31-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-JUN-2008 5417.7 2752			
31-31-37-820-801-01	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - PITCH CONTROL POSITION POTENTIOMETER (5FZ) REF: AMM 31-31-37-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
31-31-37-820-801-02	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - YAW CONTROL POSITION POTENTIOMETER (6FZ) REF: AMM 31-31-37-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
31-31-37-820-801-03	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - ROLL CONTROL POSITION POTENTIOMETER (7FZ) REF: AMM 31-31-37-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-31-37-820-801-04	ADJUSTMENT OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - HS POSITION REPEATER BOX (4CF)	MOS						11-JAN-1988		
	REF: AMM 31-31-37-820-801	HRS/MSC	O/C					0		
		AFL						0		
31-31-37-900-801-01	REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - PITCH CONTROL POSITION POTENTIOMETER (5FZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 31-31-37-900-801	AFL		N:0				0		
31-31-37-900-801-02	REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - YAW CONTROL POSITION POTENTIOMETER (6FZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 31-31-37-900-801	AFL		N:0				0		
31-31-37-900-801-03	REMOVAL / INSTALLATION OF THE FDR FLIGHT CONTROL POSITION POTENTIOMETERS - ROLL CONTROL POSITION POTENTIOMETER (7FZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 31-31-37-900-801	AFL		N:0				0		
31-31-38-900-801-01	REMOVAL / INSTALLATION OF THE FDR ACCELEROMETER - ACCELEROMETER (4FZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 31-31-38-900-801	AFL		N:0				0		
+ 31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) SYSTEM						PKG			
31.070	PKG 17	MOS	36	+1m				21-JUN-2023		
	REF: AMM 31-31-50-710-801	HRS/MSC						8047.2		
		AFL						3851		
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)	MOS						11-JAN-1988		
	REF: AMM 31-31-50-970-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-31-51-900-801-01	REMOVAL / INSTALLATION OF THE COCKPIT VOICE RECORDER (CVR) - CVR (2RK)									
31.070	1606-00-01 1955 REF: AMM 31-31-51-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-SEP-2019 7761.7 3770			
31-32-00-710-801-01	OPERATIONAL TEST OF THE QUICK ACCESS RECORDER (QAR)									
	REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
31-32-00-860-801-01	CONFIGURATION OF THE QUICK ACCESS RECORDER (QAR)									
	REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
31-32-00-970-801-01	DOWNLOAD OF THE QUICK ACCESS RECORDER (QAR) - QAR (42FZ)									
31.140	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	O/C				11-JAN-1988 0 0 0			
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER									
31.140	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
31-32-05-350-801-01	RESTORATION OF THE QUICK ACCESS RECORDER (QAR BATTERY REPLACEMENT) - QAR (42FZ)									
	PN NOT INSTALLED REF: AMM 31-32-05-350-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
31-32-05-960-801-01	REPLACEMENT OF THE QUICK ACCESS RECORDER (QAR) BATTERY - QAR (42FZ) BATTERY									
31.140	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	N/A				11-JAN-1988 0 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-40-00-700-801-01	CHECK OF THE AVIONICS STANDARD COMMUNICATION BUS	MOS					11-JAN-1988			
	REF: AMM 31-40-00-700-801	HRS/MSC AFL	O/C				0 0			
31-40-01-900-881-01	NO. 1 INTEGRATED AVIONICS COMPUTER	MOS		N:0			11-JAN-1988			
34.620	PN SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0			
31-40-01-900-881-02	NO. 2 INTEGRATED AVIONICS COMPUTER	MOS		N:0			11-JAN-1988			
34.620	PN SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0			
31-40-01-900-881-03	NO. 3 INTEGRATED AVIONICS COMPUTER	MOS		N:0			11-JAN-1988			
34.620	PN SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0			
+ 31-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WARNING PANEL DUAL POWER SUPPLY	MOS	36	+1m			PKG 21-JUN-2023			
31.010	PKG 7 REF: AMM 31-52-00-710-801	HRS/MSC AFL	2400	+40			8047.2 3851			
+ 31-54-00-720-803-01	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - ALARM TEST	MOS					27-JUN-2023			
31.030	REF: AMM 31-54-00-720-803	HRS/MSC AFL	600	+40			8049.2 3853	8649.2	8689.2	600 (+40)
+ 31-54-00-720-803-02 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - TEST OF INDICATION LOGIC	MOS					PKG 11-NOV-2015			
31.030	PKG 21 REF: AMM 31-54-00-720-803	HRS/MSC AFL	1600	+40			7355.5 3656			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 31-55-00-720-801-01 (s)	FUNCTIONAL TEST OF THE LANDING SAFETIES						PKG			
31.040	PKG 21 REF: AMM 31-55-00-720-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
310101	WARNING PANEL									
31.010	90300-4A 167 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
312001	LH PILOT CLOCK (L1DT)									
31.080	811BATT-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-MAR-2022 7961.3 3825			
312006	RH PILOT CLOCK (R1DT)									
31.080	811BATT-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-MAR-2022 7961.3 3825			
315101	AUDIO WARNING UNIT									
31.050	240ZS01Y05 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
315256	VOICE DATA RECORDER CONTROL									
31.120	1641-110-01 0856 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-SEP-2019 7761.7 3770			
315261	VOICE DATA RECORDER REMOTE MICROPHONE									
31.130	16301-01 6070 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-SEP-2019 7761.7 3770			

CHAPTER 32 LANDING GEAR



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-00-00-220-801-01	CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)	MOS					11-JAN-1988			
	REF: AMM 32-00-00-220-801	HRS/MSC	O/C				0			
		AFL					0			
32-00-00-220-801-02	CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)	MOS					11-JAN-1988			
	REF: AMM 32-00-00-220-801	HRS/MSC	O/C				0			
		AFL					0			
32-00-00-220-801-03	CHECK OF THE MINIMUM HEIGHT OF MLG AND NLG SHOCK ABSORBERS - NLG SHOCK ABSORBER (3GF5)	MOS					11-JAN-1988			
	REF: AMM 32-00-00-220-801	HRS/MSC	O/C				0			
		AFL					0			
32-00-00-610-801-01	CHARGING OF THE MLG OR NLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER	MOS					11-JAN-1988			
	REF: AMM 32-00-00-610-801	HRS/MSC	O/C				0			
		AFL					0			
32-00-00-610-801-02	CHARGING OF THE MLG OR NLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER	MOS					11-JAN-1988			
	REF: AMM 32-00-00-610-801	HRS/MSC	O/C				0			
		AFL					0			
32-00-00-610-801-03	CHARGING OF THE MLG OR NLG SHOCK ABSORBERS - NLG SHOCK ABSORBER	MOS					11-JAN-1988			
	REF: AMM 32-00-00-610-801	HRS/MSC	O/C				0			
		AFL					0			
+ 32-00-00-700-801-01	CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)	MOS	18	+1m			27-JUN-2023	27-DEC-2024	27-JAN-2025	528 d (+31)
32.130	REF: AMM 32-00-00-700-801	HRS/MSC					8049.2			
		AFL					3853			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 32-00-00-700-801-02	CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)									
32.050		MOS	18	+1m			27-JUN-2023 8049.2 3853	27-DEC-2024	27-JAN-2025	528 d (+31)
	REF: AMM 32-00-00-700-801	HRS/MSC AFL								
+ 32-00-00-700-801-03	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)									
32.050		MOS	18	+1m			27-JUN-2023 8049.2 3853	27-DEC-2024	27-JAN-2025	528 d (+31)
	REF: AMM 32-00-00-700-801	HRS/MSC AFL								
32-00-00-780-801-01	CHECK OF LANDING GEAR AND L/G DOOR OPERATING PRESSURES									
		MOS					11-JAN-1988 0 0			
	REF: AMM 32-00-00-780-801	HRS/MSC AFL	O/C							
32-00-00-780-802-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER (L2GF5)						PKG			
	PKG 21	MOS					11-NOV-2015 7355.5 3656			
	REF: AMM 32-00-00-780-802	HRS/MSC AFL	1600	+40						
32-00-00-780-802-02 (s)	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER (R2GF5)						PKG			
	PKG 21	MOS					11-NOV-2015 7355.5 3656			
	REF: AMM 32-00-00-780-802	HRS/MSC AFL	1600	+40						
32-00-00-780-802-03 (s)	CHECK OF THE CHARGING PRESSURE OF THE MLG AND NLG SHOCK ABSORBERS - NLG SHOCK ABSORBER (3GF5)						PKG			
	PKG 21	MOS					11-NOV-2015 7355.5 3656			
	REF: AMM 32-00-00-780-802	HRS/MSC AFL	1600	+40						
32-00-00-820-801-01	REDUCTION OF TORQUE LINK END PLAY ON MAIN AND NOSE LANDING GEARS									
		MOS					11-JAN-1988 0 0			
	REF: AMM 32-00-00-820-801	HRS/MSC AFL	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-00-05-900-801-01	REMOVAL / INSTALLATION OF THE NLG AND MLG SHOCK ABSORBER CHARGING VALVES PN SN-UNKNOWN REF: AMM 32-00-05-900-801	MOS HRS/MSC AFL		N:0 N:0 N:0			11-JAN-1988 0 0			
32-10-00-640-801-01 32.010	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS REF: AMM 32-10-00-640-801	MOS HRS/MSC AFL	8 400	+1m		-119	27-JUN-2023 8049.2 3853	31-OCT-2023 4253	30-NOV-2023	105 d (+30) 400
32-10-00-640-801-02 32.010	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS REF: AMM 32-10-00-640-801	MOS HRS/MSC AFL	8 400	+1m		-119	27-JUN-2023 8049.2 3853	31-OCT-2023 4253	30-NOV-2023	105 d (+30) 400
32-10-00-700-801-01	CHECK OF ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF CAMBER ANGLE REF: AMM 32-10-00-700-801	MOS HRS/MSC AFL		O/C			11-JAN-1988 0 0			
32-10-00-700-801-02	CHECK OF ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF L/G LOCKING IN UP POSITION REF: AMM 32-10-00-700-801	MOS HRS/MSC AFL		O/C			11-JAN-1988 0 0			
32-10-00-700-801-03	CHECK OF ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - CHECK OF L/G MAIN DOOR UPLOCKING REF: AMM 32-10-00-700-801	MOS HRS/MSC AFL		O/C			11-JAN-1988 0 0			
32-10-00-700-802-01	GEOMETRICAL CHECK OF THE MAIN LANDING GEARS (MLG) - LH MLG LEG (L2GF) REF: AMM 32-10-00-700-802	MOS HRS/MSC AFL		O/C			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-10-00-700-802-02	GEOMETRICAL CHECK OF THE MAIN LANDING GEARS (MLG) - RH MLG LEG (R2GF)	MOS						11-JAN-1988		
	REF: AMM 32-10-00-700-802	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-01	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF CAMBER ANGLE	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-02	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF MAIN DOOR UPLOCK BOXES	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-03	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF MAIN DOOR WARP AND OUT-OF-FLUSH	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-04	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF MAIN DOOR ACTUATOR	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-05	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF ?MAIN DOOR OPEN? STOP	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
32-10-00-820-801-06	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF FAIRING DOOR	MOS						11-JAN-1988		
	REF: AMM 32-10-00-820-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-10-00-820-801-07	ADJUSTMENT OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - ADJUSTMENT OF CLEARANCE BETWEEN MAIN L/G DOOR AND STRUT DOOR	MOS						11-JAN-1988		
		HRS/MSC	O/C				0			
	REF: AMM 32-10-00-820-801	AFL					0			
32-10-00-860-801-01	MANUAL OPENING / CLOSING OF THE MLG DOORS	MOS						11-JAN-1988		
		HRS/MSC	O/C				0			
	REF: AMM 32-10-00-860-801	AFL					0			
+ 32-11-00-220-801-01	DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)	MOS	72	+8m						
32.020	D22801100-11-/-13	HRS/MSC					28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	U86	AFL					7675			
	REF: AMM 32-11-00-220-801						3744			
+ 32-11-00-220-801-02	DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)	MOS	72	+8m						
32.030	D22802100-11-/-13	HRS/MSC					28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	U38	AFL					7675			
	REF: AMM 32-11-00-220-801						3744			
32-11-00-350-801-01	RESTORATION OF THE MLG LEGS (OVERHAUL) - LH MLG LEG (L2GF)	MOS	144	+3%						
	D22801100-11-/-13	HRS/MSC					27-JUN-2023	27-JUN-2035	05-NOV-2035	4362 d (+131)
	U86	AFL					8049.2			
OVERHAUL	REF: AMM 32-11-00-350-801		6000				3853	9853		6000
32-11-00-350-801-02	RESTORATION OF THE MLG LEGS (OVERHAUL) - RH MLG LEG (R2GF)	MOS	144	+3%						
	D22802100-11-/-13	HRS/MSC					27-JUN-2023	27-JUN-2035	05-NOV-2035	4362 d (+131)
	U38	AFL					8049.2			
OVERHAUL	REF: AMM 32-11-00-350-801		6000				3853	9853		6000
32-11-00-700-801-01	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - LH MLG LEG (L2GF)	MOS						11-JAN-1988		
		HRS/MSC	O/C				0			
	REF: AMM 32-11-00-700-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-11-00-700-801-02	CHECK OF THE MLG LEG GRAVITY OSCILLATIONS - RH MLG LEG (R2GF)	MOS						11-JAN-1988		
	REF: AMM 32-11-00-700-801	HRS/MSC O/C AFL						0 0		
32-11-00-900-801-01	REMOVAL / INSTALLATION OF THE MLG LEGS - LH MLG LEG (L2GF)	MOS						27-JUN-2023		
32.020	D22801100-11-/-13 U86	HRS/MSC H/T AFL		O:132 N:8049.2 O:1064.1 N:3853 O:328				8049.2 3853		
32-11-00-900-801-02	REMOVAL / INSTALLATION OF THE MLG LEGS - RH MLG LEG (R2GF)	MOS						27-JUN-2023		
32.030	D22802100-11-/-13 U38	HRS/MSC H/T AFL		O:132 N:7959.2 O:1064.1 N:3853 O:328				8049.2 3853		
32-11-00-960-801-01	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - LH MLG LEG (L2GF)	MOS						16-JUL-2012		
32.020	D22801100-11-/-13 U86	HRS/MSC AFL	20000	I:6895.1 I:3525				6985.1 3525	20000	16147
	REF: AMM 32-11-00-960-801									
32-11-00-960-801-01A	REPLACEMENT LH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)	MOS						16-JUL-2012		
	D22801100-11-/-13 U86	HRS/MSC AFL	20000	I:6895.1 I:3525				6985.1 3525	20000	16147
	REF: AMM 32-11-00-960-801									
32-11-00-960-801-02	REPLACEMENT OF THE MLG LEGS (DISCARD OF LIFE LIMITED PARTS) - RH MLG LEG (R2GF)	MOS						16-JUL-2012		
32.030	D22802100-11-/-13 U38	HRS/MSC AFL	20000	I:6895.1 I:3525				6985.1 3525	20000	16147
	REF: AMM 32-11-00-960-801									
32-11-00-960-801-02A	REPLACEMENT RH MAIN LANDING GEAR (MLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)	MOS						16-JUL-2012		
	D22802100-11-/-13 U38	HRS/MSC AFL	20000	I:6895.1 I:3525				6985.1 3525	20000	16147
	REF: AMM 32-11-00-960-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-11-05-610-801-01	SERVICING OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER	MOS						11-JAN-1988		
	REF: AMM 32-11-05-610-801	HRS/MSC	O/C					0		
		AFL						0		
32-11-05-610-801-02	SERVICING OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER	MOS						11-JAN-1988		
	REF: AMM 32-11-05-610-801	HRS/MSC	O/C					0		
		AFL						0		
32-11-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - LH MLG SHOCK ABSORBER	MOS		O:0				16-JUL-2012		
32.020	D22805100-6	HRS/MSC	O/C	O:0				6985.1		
	U88	AFL		O:0				3525		
	REF: AMM 32-11-05-900-801									
32-11-05-900-801-02	REMOVAL / INSTALLATION OF THE MLG SHOCK ABSORBERS - RH MLG SHOCK ABSORBER	MOS		O:0				16-JUL-2012		
32.030	D22806100-6	HRS/MSC	O/C	O:0				6985.1		
	U39	AFL		O:0				3525		
	REF: AMM 32-11-05-900-801									
32-11-05-900-802-01	REMOVAL / INSTALLATION OF THE SHOCK ABSORBER FILLING AND CHARGING TOOLS	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 32-11-05-900-802									
32-11-21-900-801-01	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - LH MLG BRACE STRUT ACTUATOR (L12GA)	MOS		N:0				11-JAN-1988		
32.040	D22791001-1	HRS/MSC	O/C	N:0				0		
	U38	AFL						0		
	REF: AMM 32-11-21-900-801									
32-11-21-900-801-02	REMOVAL / INSTALLATION OF THE MLG BRACE STRUT ACTUATORS - RH MLG BRACE STRUT ACTUATOR (R12GA)	MOS		N:0				11-JAN-1988		
32.040	D22792001-1	HRS/MSC	O/C	N:0				0		
	U47	AFL						0		
	REF: AMM 32-11-21-900-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 32-11-25-220-801-01	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)	MOS HRS/MSC AFL	72	+8m			28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	REF: AMM 32-11-25-220-801									
+ 32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)	MOS HRS/MSC AFL	72	+8m			28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	REF: AMM 32-11-25-220-801									
+ 32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)	MOS HRS/MSC AFL	72	+8m			28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	REF: AMM 32-11-25-220-801									
+ 32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)	MOS HRS/MSC AFL	72	+8m			28-NOV-2018	28-NOV-2024	28-JUL-2025	499 d (+242)
	REF: AMM 32-11-25-220-801									
32-11-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG FRONT BALL-JOINT BEARING (L90GA)	MOS		N:0			27-JUN-2023			
	PN	HRS/MSC	O/C	N:0			8049.2			
	REF: AMM 32-11-25-900-801	AFL		N:0			3853			
32-11-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - LH MLG REAR BALL-JOINT BEARING (L100GA)	MOS		N:0			11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-11-25-900-801	AFL		N:0			0			
32-11-25-900-801-03	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG FRONT BALL-JOINT BEARING (R90GA)	MOS		N:0			27-JUN-2023			
	PN	HRS/MSC	O/C	N:0			8049.2			
	REF: AMM 32-11-25-900-801	AFL		N:0			3853			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-11-25-900-801-04	REMOVAL / INSTALLATION OF THE MLG BALL-JOINT BEARINGS - RH MLG REAR BALL-JOINT BEARING (R100GA) PN SN-UNKNOWN REF: AMM 32-11-25-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-12-00-220-802-01	DETAILED INSPECTION OF THE MLG FAIRING DOOR HINGE PINS AND KNUCKLES PN SN-UNKNOWN REF: AMM 32-12-00-220-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-12-17-900-801-01	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA) C24244007-1 U154 REF: AMM 32-12-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-12-17-900-801-02	REMOVAL / INSTALLATION OF THE MLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA) C24245007-1 U299 REF: AMM 32-12-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-12-25-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - LH MLG MAIN DOOR ACTUATOR (L6GA) VN1031-1 114 REF: AMM 32-12-25-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-12-25-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATORS - RH MLG MAIN DOOR ACTUATOR (R6GA) VN1031-1 112 REF: AMM 32-12-25-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-12-29-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - LH MLG MAIN DOOR UPLOCK BOX (L14GA) C24257002 U500 REF: AMM 32-12-29-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-12-29-900-801-02 32.090	REMOVAL / INSTALLATION OF THE MLG DOOR UPLOCK BOXES - RH MLG MAIN DOOR UPLOCK BOX (R14GA) C24257002 U501 REF: AMM 32-12-29-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-20-00-640-801-01 32.100	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF) REF: AMM 32-20-00-640-801	MOS HRS/MSC AFL	8 400	+1m	-124		27-JUN-2023 8049.2 3853	26-OCT-2023 4253	26-NOV-2023	100 d (+31) 400
32-20-00-700-801-01	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF CASTER ANGLE REF: AMM 32-20-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-20-00-700-801-02	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF NOSE LANDING GEAR UPLOCKING REF: AMM 32-20-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-20-00-700-801-03	CHECK OF ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - CHECK OF DOOR ADJUSTMENT REF: AMM 32-20-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-20-00-700-802-01	GEOMETRICAL CHECK OF THE NOSE LANDING GEAR (NLG) - NLG LEG (3GF) REF: AMM 32-20-00-700-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-20-00-820-801-01	ADJUSTMENT OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS REF: AMM 32-20-00-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 32-21-00-220-801-01	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)									
32.110	D22811200-14-/-16-19 U71 REF: AMM 32-21-00-220-801	MOS HRS/MSC AFL	72	+8m			27-JUN-2023 8049.2 3853	27-JUN-2029	27-FEB-2030	2171 d (+245)
32-21-00-350-801-01	RESTORATION OF THE NLG LEG (OVERHAUL) - NLG LEG (3GF)									
OVERHAUL	D22811200-14-/-16-19 U71 REF: AMM 32-21-00-350-801	MOS HRS/MSC AFL	144	+3%			27-JUN-2023 8049.2 3853	27-JUN-2035	05-NOV-2035	4362 d (+131)
32-21-00-700-801-01	CHECK OF THE NLG LEG GRAVITY OSCILLATIONS - NLG LEG (3GF)									
	REF: AMM 32-21-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-21-00-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG - NLG LEG (3GF)									
32.110	D22811200-14-/-16-19 U71 REF: AMM 32-21-00-900-801	MOS HRS/MSC AFL	H/T	O:1 N:6895.1 O:0 N:3525 O:0			16-JUL-2012 6985.1 3525			
32-21-00-960-801-01	REPLACEMENT OF THE NLG LEG (DISCARD OF LIFE LIMITED PARTS) - NLG LEG (3GF)									
32.110	D22811200-14-/-16-19 U71 REF: AMM 32-21-00-960-801	MOS HRS/MSC AFL	20000	I:6895.1 I:3525			16-JUL-2012 6985.1 3525	20000		16147
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR (NLG) LEG (DISCARD LIFE LIMITED PARTS) (MANDATORY 5-40)									
LIFE LIMIT	D22811200-14-/-16-19 U71 REF: AMM 32-21-00-960-801	MOS HRS/MSC AFL	20000	I:6895.1 I:3525			16-JUL-2012 6985.1 3525	20000		16147
32-21-01-610-801-01	SERVICING OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER									
	REF: AMM 32-21-01-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NLG SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE - NLG SHOCK ABSORBER	MOS HRS/MSC AFL	O/C				03-DEC-2013 7168.1 3589			
REF: AMM 32-21-01-780-802										
32-21-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG SHOCK ABSORBER - NLG SHOCK ABSORBER (3GF5)	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-JUL-2012 6985.1 3525			
32.110	D22813200-8/-10 U73									
REF: AMM 32-21-01-900-801										
32-21-09-220-801-01	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING	MOS HRS/MSC AFL	72	+8m			28-NOV-2018 7675 3744	28-NOV-2024	28-JUL-2025	499 d (+242)
32.135										
REF: AMM 32-21-09-220-801										
+ 32-21-09-220-801-02	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING	MOS HRS/MSC AFL	72	+8m			28-NOV-2018 7675 3744	28-NOV-2024	28-JUL-2025	499 d (+242)
REF: AMM 32-21-09-220-801										
+ 32-21-09-220-801-03	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING	MOS HRS/MSC AFL	72	+8m			28-NOV-2018 7675 3744	28-NOV-2024	28-JUL-2025	499 d (+242)
REF: AMM 32-21-09-220-801										
+ 32-21-09-220-801-04	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING	MOS HRS/MSC AFL	72	+8m			28-NOV-2018 7675 3744	28-NOV-2024	28-JUL-2025	499 d (+242)
REF: AMM 32-21-09-220-801										
32-21-09-900-801-01	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG DRAG BRACE BALL-JOINT BEARING	PN SN-UNKNOWN AFL	MOS HRS/MSC O/C		N:0 N:0 N:0		11-JAN-1988 0 0			
REF: AMM 32-21-09-900-801										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-21-09-900-801-02	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG DRAG BRACE BALL-JOINT BEARING									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-21-09-900-801	AFL		N:0			0			
32-21-09-900-801-03	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - LH NLG LEG BALL-JOINT BEARING									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-21-09-900-801	AFL		N:0			0			
32-21-09-900-801-04	REMOVAL / INSTALLATION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS - RH NLG LEG BALL-JOINT BEARING									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-21-09-900-801	AFL		N:0			0			
32-22-01-350-801-01	RESTORATION OF THE NLG DRAG BRACE YOKE ASSY (OVERHAUL) - NLG DRAG BRACE (11GA)									
32.120	GA62269	MOS	144	+3%			27-JUN-2023	27-JUN-2035	05-NOV-2035	4362 d (+131)
	14U397	HRS/MSC					8049.2			
	REF: AMM 32-22-01-350-801	AFL	6000				3853	9853		6000
32-22-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG DRAG BRACE - NLG DRAG BRACE (11GA)									
32.120	D22796001-1	MOS					11-JAN-1988			
	U48	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-22-01-900-801	AFL					0			
32-22-13-900-801-01	REMOVAL / INSTALLATION OF THE NLG ACTUATOR - NLG LEG ACTUATOR (500GA)									
32.130	D22795001	MOS					11-JAN-1988			
	U29	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-22-13-900-801	AFL					0			
32-22-17-900-801-01	REMOVAL / INSTALLATION OF THE NLG UPLOCK BOX - NLG UPLOCK BOX (13GA)									
32.130	C24245006-1	MOS					11-JAN-1988			
	U261	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-22-17-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 32-30-00-720-801-01 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - NORMAL OPERATION						PKG			
32.160	PKG 21	MOS					11-NOV-2015			
	REF: AMM 32-30-00-720-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
32-30-00-720-801-02 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - HYDRAULIC EMERGENCY OPERATION						PKG			
	PKG 21	MOS					11-NOV-2015			
	REF: AMM 32-30-00-720-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
32-30-00-720-801-03 (s)	FUNCTIONAL TEST OF EXTENSION AND RETRACTION OF LANDING GEARS AND DOORS - MECHANICAL EMERGENCY OPERATION						PKG			
	PKG 21	MOS					11-NOV-2015			
	REF: AMM 32-30-00-720-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
32-30-00-720-802-01	FUNCTIONAL TEST OF EXTENSION AND RETRACTION ON STAND-BY PUMP IN NORMAL AND EMERGENCY MODE									
		MOS					11-JAN-1988			
	REF: AMM 32-30-00-720-802	HRS/MSC	O/C				0			
		AFL					0			
32-30-13-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY SELECTOR VALVE - L/G NORMAL/EMERGENCY SELECTOR VALVE (3GA)									
32.240	B94B09-202-1	MOS					11-JAN-1988			
	20042	HRS/MSC	O/C		N:0		0			
	REF: AMM 32-30-13-900-801	AFL					0			
+ 32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEAR RETRACTION INHIBITION ON THE GROUND						PKG			
32.190	PKG 21	MOS					11-NOV-2015			
	REF: AMM 32-31-00-700-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
32-31-00-860-801-01	RETRACTION / EXTENSION OF THE LANDING GEARS									
		MOS					11-JAN-1988			
	REF: AMM 32-31-00-860-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-31-01-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR CONTROL LEVER - L/G CONTROL LEVER (2GA) PN SN-UNKNOWN REF: AMM 32-31-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-31-17-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR HYDRAULIC SUPPLY UNIT SOLENOID VALVES - L/G RETRACTION SOLENOID VALVE (9GA1R) PN SN-UNKNOWN REF: AMM 32-31-17-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-31-17-900-801-02	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR HYDRAULIC SUPPLY UNIT SOLENOID VALVES - L/G EXTENSION SOLENOID VALVE (9GA1E) PN SN-UNKNOWN REF: AMM 32-31-17-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-31-17-900-801-03	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR HYDRAULIC SUPPLY UNIT SOLENOID VALVES - MLG MAIN DOORS CLOSING SOLENOID VALVE (9GA2C) PN SN-UNKNOWN REF: AMM 32-31-17-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-31-17-900-801-04	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR HYDRAULIC SUPPLY UNIT SOLENOID VALVES - MLG MAIN DOORS OPENING SOLENOID VALVE (9GA2O) PN SN-UNKNOWN REF: AMM 32-31-17-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-32-00-640-801-01 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE NLG CONTROL PKG 16 32.180 REF: AMM 32-32-00-640-801	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
32-32-00-640-801-02 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE NLG CONTROL ACTUATION FORCE PKG 16 REF: AMM 32-32-00-640-801	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-32-00-640-801-03 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - LUBRICATION OF THE MLG CONTROLS						PKG			
	PKG 16	MOS	24	+1m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 32-32-00-640-801	AFL						3851		
32-32-00-640-801-04 (s)	SERVICING OF THE LANDING GEAR MECHANICAL EMERGENCY RELEASE CONTROL - CHECK OF THE MLG CONTROL ACTUATION FORCE						PKG			
	PKG 16	MOS	24	+1m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 32-32-00-640-801	AFL						3851		
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION									
32.830		MOS						11-JAN-1988		
		HRS/MSC	A/R					0		
	REF: AMM 32-32-00-700-801	AFL						0		
		APH						0		
32-32-05-820-801-01	ADJUSTMENT OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - LH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (L515GA)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-32-05-820-801	AFL						0		
32-32-05-820-801-02	ADJUSTMENT OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - RH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (R515GA)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-32-05-820-801	AFL						0		
32-32-05-900-801-01	REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - LH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (L515GA)									
	PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 32-32-05-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-32-05-900-801-02	REMOVAL / INSTALLATION OF THE MLG MECHANICAL EMERGENCY RELEASE CONTROL CABLES - RH MLG MECHANICAL EMERGENCY EXTENSION CONTROL CABLE (R515GA)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-32-05-900-801	AFL		N:0				0		
32-32-09-820-801-01	ADJUSTMENT OF THE NLG MECHANICAL EMERGENCY RELEASE CONTROL CABLE									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-32-09-820-801	AFL						0		
32-32-17-640-801-01 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - LUBRICATION OF THE L/G HYDRAULIC EMERGENCY EXTENSION CONTROL						PKG			
	PKG 16	MOS	24	+1m				21-JUN-2023		
32.170		HRS/MSC						8047.2		
	REF: AMM 32-32-17-640-801	AFL						3851		
32-32-17-640-801-02 (s)	SERVICING OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL - CHECK OF CONTROL ACTUATION LOADS						PKG			
	PKG 16	MOS	24	+1m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 32-32-17-640-801	AFL						3851		
32-32-17-820-801-01	ADJUSTMENT OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-32-17-820-801	AFL						0		
32-32-17-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE - L/G HYDRAULIC EMERGENCY EXTENSION CONTROL CABLE (504GA)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-32-17-900-801	AFL		N:0				0		
32-40-00-780-801-01 (s)	CHECK OF BRAKING PRESSURES - NORMAL BRAKING SYSTEM						PKG			
	PKG 22	MOS						27-APR-2009		
		HRS/MSC	3200	+40				5771.6		
	REF: AMM 32-40-00-780-801	AFL						2919		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-40-00-780-801-02 (s)	CHECK OF BRAKING PRESSURES - EMERGENCY BRAKING SYSTEM PKG 22	MOS					PKG 27-APR-2009 5771.6			
	REF: AMM 32-40-00-780-801	HRS/MSC AFL	3200	+40			2919			
32-40-00-870-801-01	BLEEDING OF THE BRAKE HYDRAULIC SYSTEM	MOS					11-JAN-1988 0			
	REF: AMM 32-40-00-870-801	HRS/MSC AFL	O/C				0			
32-41-00-710-802-01	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - LH MLG OUTBOARD WHEEL	MOS					11-JAN-1988 0			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0			
32-41-00-710-802-02	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - LH MLG INBOARD WHEEL	MOS					11-JAN-1988 0			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0			
32-41-00-710-802-03	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - RH MLG OUTBOARD WHEEL	MOS					11-JAN-1988 0			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0			
32-41-00-710-802-04	OPERATIONAL TEST OF THE BLOCKED WHEEL DETECTION - RH MLG INBOARD WHEEL	MOS					11-JAN-1988 0			
	REF: AMM 32-41-00-710-802	HRS/MSC AFL	O/C				0			
32-41-00-720-802-01	FUNCTIONAL TEST OF THE ANTI-SKID SYSTEM	MOS					11-JAN-1988 0			
	REF: AMM 32-41-00-720-802	HRS/MSC AFL	O/C				0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-00-820-801-01	ADJUSTMENT / TEST OF THE NORMAL AND EMERGENCY MODE BRAKE CONTROL	MOS						11-JAN-1988		
	REF: AMM 32-41-00-820-801	HRS/MSC AFL	O/C					0 0		
32-41-07-610-801-01 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - SERVICING	MOS	72	+2m				PKG 21-JUN-2023		
32.415	PKG 31	HRS/MSC AFL						8047.2 3851		
	REF: AMM 32-41-07-610-801		3750							
32-41-07-610-801-02 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - MEASUREMENT OF SLIDING FORCES	MOS	24	+1m				PKG 21-JUN-2023		
32.415	PKG 16	HRS/MSC AFL						8047.2 3851		
	REF: AMM 32-41-07-610-801									
32-41-07-900-801-01	REMOVAL / INSTALLATION OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - LH BRAKE PEDALS INTERCONNECTION CONTROL CABLE (L500GC)	MOS						11-JAN-1988		
	PN	HRS/MSC AFL	O/C					0 0		
	SN-UNKNOWN									
	REF: AMM 32-41-07-900-801									
32-41-07-900-801-02	REMOVAL / INSTALLATION OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS - RH BRAKE PEDALS INTERCONNECTION CONTROL CABLE (R500GC)	MOS						11-JAN-1988		
	PN	HRS/MSC AFL	O/C					0 0		
	SN-UNKNOWN									
	REF: AMM 32-41-07-900-801									
32-41-23-900-801-01	REMOVAL / INSTALLATION OF THE NORMAL / EMERGENCY BRAKE SELECTOR VALVE - NORMAL/EMERGENCY BRAKE SELECTOR VALVE (501GC)	MOS						11-JAN-1988		
	PN	HRS/MSC AFL	O/C					0 0		
	SN-UNKNOWN									
	REF: AMM 32-41-23-900-801									
32-41-37-960-801-01 (s)	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - LH MLG BRAKE FILTER (L580GC)	MOS	1600	+40				PKG 11-NOV-2015		
32.590	PKG 21	HRS/MSC AFL						7355.5 3656		
	REF: AMM 32-41-37-960-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-37-960-801-02 (s) 32.590	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - RH MLG BRAKE FILTER (R580GC) PKG 21 REF: AMM 32-41-37-960-801	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
32-41-37-960-801-03 (s)	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - UPSTREAM FILTER OF PARK BRAKE SELECTOR VALVE (900GC) PKG 21 REF: AMM 32-41-37-960-801	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
32-41-37-960-801-04 (s)	REPLACEMENT OF THE FILTER ELEMENTS OF BRAKING SYSTEM FILTERS - DOWNSTREAM FILTER OF PARK BRAKE SELECTOR VALVE (901GC) PKG 21 REF: AMM 32-41-37-960-801	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
32-41-45-900-801-01 32.610	REMOVAL / INSTALLATION OF THE ANTI-SKID CONTROL UNIT - ANTISKID CONTROL UNIT (2GC) C20188102 U010 REF: AMM 32-41-45-900-801	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		12-JUL-1990 592 409			
32-41-49-100-801-01	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L560GC) REF: AMM 32-41-49-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-41-49-100-801-02	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L555GC) REF: AMM 32-41-49-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-41-49-100-801-03	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R555GC) REF: AMM 32-41-49-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-49-100-801-04	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R560GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-100-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-100-801-05	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - LH NLG WHEEL TACHOMETER GENERATOR (L575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-100-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-100-801-06	CLEANING OF THE TACHOMETER GENERATOR COLLECTOR - RH NLG WHEEL TACHOMETER GENERATOR (R575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-100-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-210-801-01	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L560GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-210-801-02	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L555GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-210-801-03	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R555GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-210-801-04	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R560GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-49-210-801-05	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - LH NLG WHEEL TACHOMETER GENERATOR (L575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-210-801-06	GENERAL VISUAL INSPECTION OF THE TACHOMETER GENERATOR DRIVES - RH NLG WHEEL TACHOMETER GENERATOR (R575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-210-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-720-801-01	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L560GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-720-801-02	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L555GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-720-801-03	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R555GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-720-801-04	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R560GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC	O/C					0		
		AFL						0		
32-41-49-720-801-05	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - LH NLG WHEEL TACHOMETER GENERATOR (L575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-49-720-801-06	FUNCTIONAL TEST OF THE TACHOMETER GENERATORS - RH NLG WHEEL TACHOMETER GENERATOR (R575GC)	MOS						11-JAN-1988		
	REF: AMM 32-41-49-720-801	HRS/MSC AFL	O/C					0 0		
32-41-49-900-802-01	REMOVAL / INSTALLATION OF THE NLG WHEEL TACHOMETER GENERATORS - LH NLG WHEEL TACHOMETER GENERATOR (L575GC)	MOS						11-JAN-1988		
32.620	00-200-1021 2734 REF: AMM 32-41-49-900-802	HRS/MSC AFL	O/C	N:0				0 0		
32-41-49-900-802-02	REMOVAL / INSTALLATION OF THE NLG WHEEL TACHOMETER GENERATORS - RH NLG WHEEL TACHOMETER GENERATOR (R575GC)	MOS						11-JAN-1988		
32.620	00-200-1021 2742 REF: AMM 32-41-49-900-802	HRS/MSC AFL	O/C	N:0				0 0		
32-41-49-900-803-01	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - LH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (L560GC)	MOS						11-JAN-1988		
32.630	00-200-1021 2726 REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C	N:0				0 0		
32-41-49-900-803-02	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - LH MLG INBOARD WHEEL TACHOMETER GENERATOR (L555GC)	MOS						25-AUG-2005		
32.630	C20260000 2340 REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C	N:0				4694 2489		
32-41-49-900-803-03	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - RH MLG INBOARD WHEEL TACHOMETER GENERATOR (R555GC)	MOS						16-JUL-2012		
32.640	C20260000-1 3256 REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C	N:7 N:0 N:0				6985.1 3525		
32-41-49-900-803-04	REMOVAL / INSTALLATION OF THE MLG WHEEL TACHOMETER GENERATORS - RH MLG OUTBOARD WHEEL TACHOMETER GENERATOR (R560GC)	MOS						16-JUL-2012		
32.640	C20260000-1 3254 REF: AMM 32-41-49-900-803	HRS/MSC AFL	O/C	N:7 N:0 N:0				6985.1 3525		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-41-57-900-801-01	REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - LH MLG BRAKE SERVOVALVE (L5GC)									
32.550	C20103300A 115 REF: AMM 32-41-57-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-41-57-900-801-02	REMOVAL / INSTALLATION OF THE BRAKE SERVOVALVES - RH MLG BRAKE SERVOVALVE (R5GC)									
32.550	C20103300 00604 REF: AMM 32-41-57-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-DEC-2013 7168.1 3589			
32-42-00-610-801-01	SERVICING OF THE PARK BRAKE CONTROL - SERVICING OF THE PARK BRAKE CONTROL CABLE (511GC)									
32.420	REF: AMM 32-42-00-610-801	MOS HRS/MSC AFL APH	O/C				04-DEC-2017 7593.7 3722 3592			
32-42-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PARK BRAKE SYSTEM - PARK BRAKE SYSTEM									
	PKG 22 REF: AMM 32-42-00-720-801	MOS HRS/MSC AFL	3200	+40			PKG 27-APR-2009 5771.6 2919			
32-42-00-820-801-01	ADJUSTMENT OF THE PARK BRAKE CONTROL - ADJUSTMENT OF THE PARK BRAKE CONTROL CABLE (511GC)									
	REF: AMM 32-42-00-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-42-00-820-801-02	ADJUSTMENT OF THE PARK BRAKE CONTROL - TESTS OF THE PARK BRAKE CONTROL CABLE (511GC)									
	REF: AMM 32-42-00-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-42-01-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SELECTOR VALVE - PARK BRAKE SELECTOR VALVE (30GC)									
32.680	70012-1 57 REF: AMM 32-42-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-42-05-610-801-01	CHARGING OF THE PARK BRAKE ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)	MOS						11-JAN-1988		
	REF: AMM 32-42-05-610-801	HRS/MSC	O/C					0		
		AFL						0		
+ 32-42-05-720-801-01	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY - PARK BRAKE ACCUMULATOR (520GC)	MOS						28-NOV-2018		
32.690	REF: GENERIC NO REF	HRS/MSC	O/C					7675		
		AFL						3744		
32-42-05-780-801-01	CHECK OF THE PARK BRAKE ACCUMULATOR PRESSURE	MOS						17-OCT-2017		
	REF: AMM 32-42-05-780-801	HRS/MSC	O/C					7585.5		
		AFL						3720		
+ 32-42-05-780-801-02 (s)	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR (520GC)	MOS	24					PKG		
	PKG 6	HRS/MSC	1600					21-JUN-2023		
	REF: AMM 32-42-05-780-801	AFL						8047.2		
								3851		
32-42-05-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE SYSTEM ACCUMULATOR - PARK BRAKE ACCUMULATOR (520GC)	MOS						11-JAN-1988		
32.690	60833-2	HRS/MSC	O/C	N:0				0		
	275	AFL						0		
	REF: AMM 32-42-05-900-801							0		
32-42-13-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE FLEXIBLE CONTROL - PARK BRAKE CONTROL CABLE (511GC)	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 32-42-13-900-801			N:0				0		
32-42-15-900-801-01	REMOVAL / INSTALLATION OF THE PARK BRAKE CHECK VALVE - PARK BRAKE CHECK VALVE (516GC)	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 32-42-15-900-801			N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-42-17-900-801-01 32.700	REMOVAL/INSTALLATION OF PARK BRAKE PRESSURE SWITCH - PARK BRAKE PRESSURE SWITCH (13GW) 90G198-1 080 REF: AMM 32-42-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES REF: AMM 32-44-00-220-801	MOS HRS/MSC AFL	O/C			-9	09-SEP-2020 7873.7 3797			
32-44-00-250-801-01 32.450	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG OUTBOARD WHEEL (L540GC) C20180120-1 U241 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL		400	+3%		27-JUN-2023 8049.2 3853	4253	4265	400 (+12)
32-44-00-250-801-02 32.460	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH MLG INBOARD WHEEL (L535GC) C20180120-1 U271 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL		400	+3%		27-JUN-2023 8049.2 3853	4253	4265	400 (+12)
32-44-00-250-801-03 32.470	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC) C20180120-1 U228 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL		400	+3%		27-JUN-2023 8049.2 3853	4253	4265	400 (+12)
32-44-00-250-801-04 32.480	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC) C20180400 01499 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL APH		400	+3%		04-DEC-2017 7593.7 3722 3592	4122	4134	269 (+12)
32-44-00-250-801-05 32.490	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC) C20182100 707 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL		500	+3%		27-JUN-2023 8049.2 3853	4353	4368	500 (+15)



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-00-250-801-06	SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC)									
32.500	C20182100 706 REF: AMM 32-44-00-250-801	MOS HRS/MSC AFL					27-JUN-2023 8049.2 3853		4353 4368	500 (+15)
32-44-00-640-801-01	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG OUTBOARD WHEEL (L540GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-640-801-02	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH MLG INBOARD WHEEL (L535GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-640-801-03	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG INBOARD WHEEL (R535GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-640-801-04	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH MLG OUTBOARD WHEEL (R540GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-640-801-05	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - LH NLG WHEEL (L565GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-640-801-06	LUBRICATION OF THE MLG AND NLG WHEEL BEARINGS - RH NLG WHEEL (R565GC)									
	REF: AMM 32-44-00-640-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES REF: AMM 32-44-00-780-801	MOS HRS/MSC AFL	2	+5d			27-JUN-2023 8049.2 3853	27-AUG-2023	01-SEP-2023	40 d (+5)
32-44-00-860-801-01	INCREASE OF WEAR POTENTIAL OF BRAKE HEAT SINK THROUGH INSTALLATION OF A CARBON DISC - LH MLG OUTBOARD BRAKE (L530GC) HEAT SINK REF: AMM 32-44-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-860-801-02	INCREASE OF WEAR POTENTIAL OF BRAKE HEAT SINK THROUGH INSTALLATION OF A CARBON DISC - LH MLG INBOARD BRAKE (L525GC) HEAT SINK REF: AMM 32-44-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-860-801-03	INCREASE OF WEAR POTENTIAL OF BRAKE HEAT SINK THROUGH INSTALLATION OF A CARBON DISC - RH MLG INBOARD BRAKE (R525GC) HEAT SINK REF: AMM 32-44-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-860-801-04	INCREASE OF WEAR POTENTIAL OF BRAKE HEAT SINK THROUGH INSTALLATION OF A CARBON DISC - RH MLG OUTBOARD BRAKE (R530GC) HEAT SINK REF: AMM 32-44-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-910-801-01	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - LH MLG OUTBOARD TIRE (L550GC) REF: AMM 32-44-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-00-910-801-02	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - LH MLG INBOARD TIRE (L545GC) REF: AMM 32-44-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-00-910-801-03	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - RH MLG INBOARD TIRE (R545GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-00-910-801-04	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - RH MLG OUTBOARD TIRE (R550GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-00-910-801-05	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - LH NLG TIRE (L570GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-00-910-801-06	REMOVAL / INSTALLATION OF THE SAME TIRE - AUTHORIZED TIRES - MIXING - INFLATION PRESSURE - RH NLG TIRE (R570GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEELS - LH NLG WHEEL (L565GC)	MOS						27-JUN-2023		
32.490	C20182100	HRS/MSC	O/C					8049.2		
	707	AFL						3853		
	REF: AMM 32-44-01-900-801									
32-44-01-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEELS - RH NLG WHEEL (R565GC)	MOS						27-JUN-2023		
32.500	C20182100	HRS/MSC	O/C					8049.2		
	706	AFL						3853		
	REF: AMM 32-44-01-900-801									
32-44-05-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - LH NLG TIRE (L570GC)	MOS						12-FEB-2018		
32.490	M13301	HRS/MSC	O/C					7616		
	7130S196	AFL						3728		
	REF: AMM 32-44-05-900-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-05-900-801-02	REMOVAL / INSTALLATION OF THE NLG WHEEL TIRES - RH NLG TIRE (R570GC)									
32.500	M13301 7130S184 REF: AMM 32-44-05-900-801	MOS HRS/MSC AFL	O/C				12-FEB-2018 7616 3728			
32-44-09-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG OUTBOARD WHEEL (L540GC)									
32.450	C20180120-1 U241 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
32-44-09-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEELS - LH MLG INBOARD WHEEL (L535GC)									
32.460	C20180120-1 U271 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
32-44-09-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG INBOARD WHEEL (R535GC)									
32.470	C20180120-1 U228 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL	O/C	R:92 R:693.7 R:197			27-JUN-2023 8049.2 3853			
32-44-09-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEELS - RH MLG OUTBOARD WHEEL (R540GC)									
32.480	C20180400 01499 REF: AMM 32-44-09-900-801	MOS HRS/MSC AFL APH	O/C	O:0 O:0 O:0			04-DEC-2017 7593.7 3722 3592			
32-44-10-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEEL HEAT SHIELDS AND DAMAGE ACCEPTANCE CRITERIA - LH MLG OUTBOARD WHEEL (L540GC)									
	PN SN-UNKNOWN REF: AMM 32-44-10-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-44-10-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEEL HEAT SHIELDS AND DAMAGE ACCEPTANCE CRITERIA - LH MLG INBOARD WHEEL (L535GC)									
	PN SN-UNKNOWN REF: AMM 32-44-10-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-10-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEEL HEAT SHIELDS AND DAMAGE ACCEPTANCE CRITERIA - RH MLG INBOARD WHEEL (R535GC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-44-10-900-801	AFL		N:0				0		
32-44-10-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEEL HEAT SHIELDS AND DAMAGE ACCEPTANCE CRITERIA - RH MLG OUTBOARD WHEEL (R540GC)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-44-10-900-801	AFL		N:0				0		
32-44-11-220-801-01	DETAILED INSPECTION OF THE MLG WHEEL KEYS - LH MLG OUTBOARD WHEEL (L540GC)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-44-11-220-801	AFL						0		
32-44-11-220-801-02	DETAILED INSPECTION OF THE MLG WHEEL KEYS - LH MLG INBOARD WHEEL (L535GC)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-44-11-220-801	AFL						0		
32-44-11-220-801-03	DETAILED INSPECTION OF THE MLG WHEEL KEYS - RH MLG INBOARD WHEEL (R535GC)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-44-11-220-801	AFL						0		
32-44-11-220-801-04	DETAILED INSPECTION OF THE MLG WHEEL KEYS - RH MLG OUTBOARD WHEEL (R540GC)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 32-44-11-220-801	AFL						0		
32-44-13-900-801-01	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG OUTBOARD TIRE (L550GC)									
	MO6201IND04	MOS		N:0				12-FEB-2018		
32.450	7122S109	HRS/MSC	O/C	N:0				7616		
	REF: AMM 32-44-13-900-801	AFL		N:0				3728		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-13-900-801-02	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - LH MLG INBOARD TIRE (L545GC)									
32.460	M06201IND04 3204S078 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-SEP-2014 7220.5			
32-44-13-900-801-03	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG INBOARD TIRE (R545GC)									
32.470	M06201 2192T131 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-DEC-2022 8042 3849			
32-44-13-900-801-04	REMOVAL / INSTALLATION OF THE MLG WHEEL TIRES - RH MLG OUTBOARD TIRE (R550GC)									
32.480	M06201 6331S1 REF: AMM 32-44-13-900-801	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0			04-DEC-2017 7593.7 3722 3592			
32-44-17-220-803-01	DETAILED INSPECTION OF THE BRAKE UNIT AFTER WHEEL REMOVAL - LH MLG OUTBOARD BRAKE (L530GC)									
	REF: AMM 32-44-17-220-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-17-220-803-02	DETAILED INSPECTION OF THE BRAKE UNIT AFTER WHEEL REMOVAL - LH MLG INBOARD BRAKE (L525GC)									
	REF: AMM 32-44-17-220-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-17-220-803-03	DETAILED INSPECTION OF THE BRAKE UNIT AFTER WHEEL REMOVAL - RH MLG INBOARD BRAKE (R525GC)									
	REF: AMM 32-44-17-220-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-17-220-803-04	DETAILED INSPECTION OF THE BRAKE UNIT AFTER WHEEL REMOVAL - RH MLG OUTBOARD BRAKE (R530GC)									
	REF: AMM 32-44-17-220-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-17-220-804-01	DETAILED INSPECTION OF THE BRAKE ROTORS - LH MLG OUTBOARD BRAKE (L530GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-17-220-804	HRS/MSC	O/C					0		
		AFL						0		
32-44-17-220-804-02	DETAILED INSPECTION OF THE BRAKE ROTORS - LH MLG INBOARD BRAKE (L525GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-17-220-804	HRS/MSC	O/C					0		
		AFL						0		
32-44-17-220-804-03	DETAILED INSPECTION OF THE BRAKE ROTORS - RH MLG INBOARD BRAKE (R525GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-17-220-804	HRS/MSC	O/C					0		
		AFL						0		
32-44-17-220-804-04	DETAILED INSPECTION OF THE BRAKE ROTORS - RH MLG OUTBOARD BRAKE (R530GC)	MOS						11-JAN-1988		
	REF: AMM 32-44-17-220-804	HRS/MSC	O/C					0		
		AFL						0		
32-44-17-350-801-01	RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG OUTBOARD BRAKE (L530GC)	MOS						20-AUG-2001		
32.510	C20181100-3/-6-7	HRS/MSC	A/R					3592		
OVERHAUL	U487	AFL						2127		
	REF: AMM 32-44-17-350-801									
32-44-17-350-801-02	RESTORATION OF THE BRAKES (OVERHAUL) - LH MLG INBOARD BRAKE (L525GC)	MOS						16-JUL-2012		
32.510	C20181100-7	HRS/MSC	A/R					6985.1		
OVERHAUL	U429	AFL						3525		
	REF: AMM 32-44-17-350-801									
32-44-17-350-801-03	RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG INBOARD BRAKE (R525GC)	MOS						16-JUL-2012		
32.520	C20181100-7	HRS/MSC	A/R					6985.1		
OVERHAUL	U738	AFL						3525		
	REF: AMM 32-44-17-350-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-17-350-801-04	RESTORATION OF THE BRAKES (OVERHAUL) - RH MLG OUTBOARD BRAKE (R530GC)									
32.520	C20181100-3-/6-7	MOS					16-JUL-2012			
OVERHAUL	U78	HRS/MSC	A/R				6985.1			
	REF: AMM 32-44-17-350-801	AFL					3525			
32-44-17-900-801-01	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG OUTBOARD BRAKE (L530GC)									
32.510	C20181100-3-/6-7	MOS					20-AUG-2001			
OVERHAUL	U487	HRS/MSC	A/R				3592			
	REF: AMM 32-44-17-900-801	AFL					2127			
32-44-17-900-801-02	REMOVAL / INSTALLATION OF THE BRAKES - LH MLG INBOARD BRAKE (L525GC)									
32.510	C20181100-7	MOS		O:3			16-JUL-2012			
OVERHAUL	U429	HRS/MSC	A/R	N:432 O:0			6985.1			
	REF: AMM 32-44-17-900-801	AFL		N:271 O:0			3525			
32-44-17-900-801-03	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG INBOARD BRAKE (R525GC)									
32.520	C20181100-7	MOS		O:22			16-JUL-2012			
OVERHAUL	U738	HRS/MSC	A/R	N:3169 O:0			6985.1			
	REF: AMM 32-44-17-900-801	AFL		N:1259 O:0			3525			
32-44-17-900-801-04	REMOVAL / INSTALLATION OF THE BRAKES - RH MLG OUTBOARD BRAKE (R530GC)									
32.520	C20181100-3-/6-7	MOS		O:23			16-JUL-2012			
OVERHAUL	U78	HRS/MSC	A/R	N:2381 O:0			6985.1			
	REF: AMM 32-44-17-900-801	AFL		N:1738 O:0			3525			
32-44-18-960-801-01	REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG OUTBOARD BRAKE (L530GC) SEAL									
32.510	C20181100-3-/6-7	MOS					20-AUG-2001			
	U487	HRS/MSC	C/C				3592			
	REF: AMM 32-44-18-960-801	AFL					2127			
32-44-18-960-801-02	REPLACEMENT OF THE WHEEL BRAKE SEALS - LH MLG INBOARD BRAKE (L525GC) SEAL									
32.510	C20181100-7	MOS					16-JUL-2012			
	U429	HRS/MSC	C/C				6985.1			
	REF: AMM 32-44-18-960-801	AFL					3525			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-18-960-801-03	REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG INBOARD BRAKE (R525GC) SEAL C20181100-7 U738 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C				16-JUL-2012 6985.1 3525			
32-44-18-960-801-04	REPLACEMENT OF THE WHEEL BRAKE SEALS - RH MLG OUTBOARD BRAKE (R530GC) SEAL C20181100-3/-6-7 U78 REF: AMM 32-44-18-960-801	MOS HRS/MSC AFL	C/C				16-JUL-2012 6985.1 3525			
32-44-21-820-801-01	CHECK / ADJUSTMENT OF THE BRAKE SWIVEL COUPLING ALIGNMENT REF: AMM 32-44-21-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-21-900-801-01	REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - UPPER SWIVEL COUPLING (L100GC) / (R100GC) / (L101GC) / (R101GC) PN SN-UNKNOWN REF: AMM 32-44-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-44-21-900-801-02	REMOVAL / INSTALLATION OF THE BRAKE SWIVEL COUPLINGS - LOWER SWIVEL COUPLING (L102GC) / (R102GC) / (L103GC) / (R103GC) PN SN-UNKNOWN REF: AMM 32-44-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-44-25-910-801-01	BRAKE HEAT SINK DAMAGE ACCEPTANCE CRITERIA REF: AMM 32-44-25-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
32-44-25-960-801-01	REPLACEMENT OF THE BRAKE HEAT SINK - LH MLG OUTBOARD BRAKE (L530GC) HEAT SINK REF: AMM 32-44-25-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-25-960-801-02	REPLACEMENT OF THE BRAKE HEAT SINK - LH MLG INBOARD BRAKE (L525GC) HEAT SINK	MOS						11-JAN-1988		
	REF: AMM 32-44-25-960-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-25-960-801-03	REPLACEMENT OF THE BRAKE HEAT SINK - RH MLG INBOARD BRAKE (R525GC) HEAT SINK	MOS						11-JAN-1988		
	REF: AMM 32-44-25-960-801	HRS/MSC	O/C					0		
		AFL						0		
32-44-25-960-801-04	REPLACEMENT OF THE BRAKE HEAT SINK - RH MLG OUTBOARD BRAKE (R530GC) HEAT SINK	MOS						11-JAN-1988		
	REF: AMM 32-44-25-960-801	HRS/MSC	O/C					0		
		AFL						0		
32-50-00-720-801-01	FUNCTIONAL TEST OF THE STEERING CONTROL SYSTEM	MOS						11-JAN-1988		
	REF: AMM 32-50-00-720-801	HRS/MSC	O/C					0		
		AFL						0		
32-50-00-720-802-01	FUNCTIONAL TEST OF THE CENTERING SYSTEM AND ANTI-SHIMMY SYSTEM	MOS						11-JAN-1988		
	REF: AMM 32-50-00-720-802	HRS/MSC	O/C					0		
		AFL						0		
32-50-00-820-801-01	ADJUSTMENT OF THE STEERING CONTROL SYSTEM	MOS						11-JAN-1988		
	REF: AMM 32-50-00-820-801	HRS/MSC	O/C					0		
		AFL						0		
32-50-01-900-801-01	REMOVAL / INSTALLATION OF THE NLG WHEEL STEERING REPEATER BOX - STEERING REPEATER BOX (6GH)	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 32-50-01-900-801			N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-50-05-900-801-01	REMOVAL / INSTALLATION OF THE STEERING HYDRAULIC UNIT - STEERING HYDRAULIC UNIT (505GH)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-50-05-900-801	AFL		N:0			0			
32-50-13-900-801-01	REMOVAL / INSTALLATION OF THE STEERING SERVOVALVE - STEERING SERVOVALVE (5GH)									
32.770	A25455	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-50-13-900-801	AFL					0			
32-50-17-960-801-01 (s)	REPLACEMENT OF THE STEERING SYSTEM FILTERING ELEMENT - STEERING SYSTEM FILTER (511GH)						PKG			
32.740	PKG 22	MOS					27-APR-2009			
		HRS/MSC	3200	+40			5771.6			
	REF: AMM 32-50-17-960-801	AFL					2919			
32-50-25-900-801-01	REMOVAL / INSTALLATION OF THE STEERING CONTROL HANDWHEEL UNIT - STEERING CONTROL HANDWHEEL UNIT (2GH)									
32.710	287837-2	MOS					30-NOV-2022			
	H1370	HRS/MSC	O/C				8031.4			
	REF: AMM 32-50-25-900-801	AFL					3845			
32-60-00-910-801-01	USE OF THE GROUND / FLIGHT BOX									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 32-60-00-910-801	AFL					0			
32-60-00-910-802-01	USE OF THE TARGETS FOR FLIGHT SIMULATION									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 32-60-00-910-802	AFL					0			
32-61-01-900-801-01	REMOVAL / INSTALLATION OF THE MLG HARNESSSES - LH MLG UPPER ELECTRICAL HARNESS (L2GF3)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 32-61-01-900-801	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-01-900-801-02	REMOVAL / INSTALLATION OF THE MLG HARNESSSES - RH MLG UPPER ELECTRICAL HARNESS (R2GF3) PN SN-UNKNOWN REF: AMM 32-61-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-01-900-801-03	REMOVAL / INSTALLATION OF THE MLG HARNESSSES - LH MLG LOWER ELECTRICAL HARNESS (L2GF4) PN SN-UNKNOWN REF: AMM 32-61-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-01-900-801-04	REMOVAL / INSTALLATION OF THE MLG HARNESSSES - RH MLG LOWER ELECTRICAL HARNESS (R2GF4) PN SN-UNKNOWN REF: AMM 32-61-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-05-900-802-01	REMOVAL / INSTALLATION OF THE NLG LOWER HARNESS - NLG LOWER ELECTRICAL HARNESS (3GF4) PN SN-UNKNOWN REF: AMM 32-61-05-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-05-900-803-01	REMOVAL / INSTALLATION OF THE NLG UPPER HARNESS - NLG UPPER ELECTRICAL HARNESS (3GF3) PN SN-UNKNOWN REF: AMM 32-61-05-900-803	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-45-760-801-01 (s)	CHECK OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (L6GA1) PKG 21 REF: AMM 32-61-45-760-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
32-61-45-760-801-02 (s)	CHECK OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (R6GA1) PKG 21 REF: AMM 32-61-45-760-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-45-900-801-01	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - LH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (L6GA1)									
32.350	248022750 145 REF: AMM 32-61-45-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-61-45-900-801-02	REMOVAL / INSTALLATION OF THE MLG DOOR ACTUATOR PROXIMITY SWITCHES - RH MLG MAIN DOOR ACTUATOR PROXIMITY SWITCH (R6GA1)									
32.350	248022750 143 REF: AMM 32-61-45-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
32-61-49-900-801-01	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG OUTBOARD PROXIMITY SWITCH (L2GF1)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-49-900-801-02	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - LH MLG LEG INBOARD PROXIMITY SWITCH (L2GF2)									
	D22884000-1 B2728 REF: AMM 32-61-49-900-801	MOS HRS/MSC AFL	O/C				30-NOV-2022 8031.4 3845			
32-61-49-900-801-03	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG INBOARD PROXIMITY SWITCH (R2GF2)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
32-61-49-900-801-04	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - RH MLG LEG OUTBOARD PROXIMITY SWITCH (R2GF1)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-49-900-801-05	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG LH PROXIMITY SWITCH (3GF1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-801	AFL		N:0				0		
32-61-49-900-801-06	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LEG RH PROXIMITY SWITCH (3GF2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-801	AFL		N:0				0		
32-61-49-900-801-07	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG LH DOOR PROXIMITY SWITCH (L3DG)									
32.390	84738-702	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-801	AFL						0		
32-61-49-900-801-08	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR PROXIMITY SWITCHES - NLG RH DOOR PROXIMITY SWITCH (R3DG)									
32.390	84738-702	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-801	AFL						0		
32-61-49-900-802-01	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - NLG DRAG BRACE LH PROXIMITY SWITCH (11GA1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-802	AFL		N:0				0		
32-61-49-900-802-02	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - NLG DRAG BRACE RH PROXIMITY SWITCH (11GA2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-49-900-802-03	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - LH MLG BRACE ACTUATOR PROXIMITY SWITCH 1 (L12GA1)									
32.410	84738702 2372 REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
32-61-49-900-802-04	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - LH MLG BRACE ACTUATOR PROXIMITY SWITCH 2 (L12GA2)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
32-61-49-900-802-05	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - RH MLG BRACE ACTUATOR PROXIMITY SWITCH 1 (R12GA1)									
32.410	84738702 2372 REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
32-61-49-900-802-06	REMOVAL / INSTALLATION OF THE PROXIMITY SWITCHES INSTALLED ON NLG TELESCOPIC STRUT AND ON MLG BRACE STRUT ACTUATORS - RH MLG BRACE ACTUATOR PROXIMITY SWITCH 2 (R12GA2)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
32-61-49-900-803-01	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - NLG UPLOCK BOX PROXIMITY SWITCH 1 (13GA1)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
32-61-49-900-803-02	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - NLG UPLOCK BOX PROXIMITY SWITCH 2 (13GA2)									
	PN SN-UNKNOWN REF: AMM 32-61-49-900-803	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-61-49-900-803-03	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MLG UPLOCK BOX PROXIMITY SWITCH (L7GA1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
32-61-49-900-803-04	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MLG UPLOCK BOX PROXIMITY SWITCH (R7GA1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
32-61-49-900-803-05	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 1 (L14GA1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
32-61-49-900-803-06	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - LH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 2 (L14GA2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
32-61-49-900-803-07	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 1 (R14GA1)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
32-61-49-900-803-08	REMOVAL / INSTALLATION OF THE LANDING GEAR AND DOOR UPLOCK BOX PROXIMITY SWITCHES - RH MAIN DOOR UPLOCK BOX PROXIMITY SWITCH 2 (R14GA2)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 32-61-49-900-803	AFL		N:0				0		
321111	LH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY									
	D22803100-7	MOS		O:0				16-JUL-2012		
32.020	U86	HRS/MSC	O/C	N:4459 O:0				6985.1		
	REF: AMM GENERIC 2	AFL		N:4558 O:0				3525		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321161	RH MAIN LANDING GEAR (MLG) STRUT ASSEMBLY									
32.030	D22804100 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-JUL-2012 6985.1 3525			
321241	LH MAIN LANDING GEAR STRUT DOOR									
32.060	FGFB191 43 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
321251	RH MAIN LANDING GEAR STRUT DOOR									
32.060	FGFB192 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-DEC-1992 1218 832			
321261	LH MAIN LANDING GEAR DOOR									
32.070	FGFB293100 45BZ REF: AMM 52-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
321271	RH MAIN LANDING GEAR DOOR									
32.070	FGFB293200 45BZ REF: AMM 52-80-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
322111	NOSE LANDING GEAR (NLG) CYLINDER									
32.110	D22812100 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			16-JUL-2012 6985.1 3525			
322155	NOSE LANDING GEAR TELESCOPIC TUBE YOKE ASSEMBLY									
32.120	GA62269 14U397 REF: AMM GENERIC 2	MOS HRS/MSC AFL	H/T	O:132 N:8049.2 O:1064.1 N:3853 O:328			27-JUN-2023 8049.2 3853			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
322211	NOSE LANDING GEAR STRUT MAIN DOOR FGFB291300 40 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
322221	NOSE LANDING GEAR STRUT SECONDARY DOOR FGFB291400 33AG REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
322231	LH NOSE LANDING GEAR DOOR FGFB291100 40BZ REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
322241	RH NOSE LANDING GEAR DOOR FGFB291200 41BZ REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
322A03	STRUT TELESCOPIC NLG YOKE GA62269 144397 REF:	MOS HRS/MSC AFL	O/C	O:0 N:3220 O:0 N:1549 O:0			08-FEB-2000 3067 1929			
323101	GEAR/DOOR CONTROL BHC1031-1 54 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323121	GEAR EXTENSION CONTROL ELECTRIC VALVE PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323131	GEAR RETRACTION CONTROL ELECTRIC VALVE									
32.210	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323141	DOOR OPENING CONTROL ELECTRIC VALVE									
32.220	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323151	DOOR CLOSING CONTROL ELECTRIC VALVE									
32.220	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323161	GEAR ELECTRO DISTRIBUTOR									
32.230	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323181	DOOR ELECTRO DISTRIBUTOR									
32.230	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323201	MAIN LANDING GEAR DOOR ACTUATOR RESTRICTOR VALVE									
32.230	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323231	SHUTTLE VALVE PROTECTION CHECK VALVE									
32.240	C24816000 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323241	LH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE									
32.250	A24508-5220 B12181 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323251	RH MAIN LANDING GEAR ACTUATOR EXTENSION RESTRICTOR VALVE									
32.250	A24508-5220 B12187 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323261	LH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE									
32.260	A24510-5220 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323271	RH MAIN LANDING GEAR ACTUATOR RETRACTION RESTRICTOR VALVE									
32.260	A24510-5220 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323281	LH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE									
32.270	A24506-5200 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323291	RH MAIN LANDING GEAR ACTUATOR DOOR OPENING RESTRICTOR VALVE									
32.270	A24506-5200 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323331	NOSE LANDING GEAR UNLOCKING RESTRICTOR VALVE									
32.290	A24508-5090 B12153 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323341	NOSE LANDING GEAR TELESCOPIC STRUT UNLOCKING RESTRICTOR VALVE									
32.290	A24508-5180 B12138 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323551	NOSE LANDING GEAR SWIVEL COUPLING									
32.320	C24266-1 U90 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				30-MAR-2011 6615.8 3344			
323721	LH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR									
32.380	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
323731	RH MAIN LANDING GEAR WHEEL WELL PROXIMITY DETECTOR									
32.380	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324451	NORMAL/EMERGENCY BRAKE DISTRIBUTOR									
32.530	57530-20 46 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324461	NORMAL BRAKE ELECTRIC DISTRIBUTOR									
32.530	65660-1 191A REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324471	NORMAL BRAKE DISTRIBUTOR RETURN CHECK VALVE									
32.540	A24516 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324501	LH SERVO-VALVE RETURN CHECK VALVE A24516 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324511	RH SERVO-VALVE RETURN CHECK VALVE A24516 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324521	LH BRAKE NORMAL RESTRICTOR VALVE C24758140 B77 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324531	RH BRAKE NORMAL RESTRICTOR VALVE C24758140 B78 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324541	LH BRAKE NORMAL PRESSURE SWITCH 7G663-1 758 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-SEP-1991 902 608			
324551	RH BRAKE NORMAL PRESSURE SWITCH 7G663-1 422 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-MAR-1991 781 533			
324561	LH BRAKING SYSTEM FILTER ADB295-4 121 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324571	RH BRAKING SYSTEM FILTER									
32.590	ADB295-4 122 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324577	PARKING BRAKE SELECTOR VALVE UPSTREAM FILTER									
32.595	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0			11-JAN-1988 0 0 0			
324578	PARKING BRAKE SELECTOR VALVE DOWNSTREAM FILTER									
32.595	PN SN-UNKNOWN REF: AMM GENERIC 2	DAYS HRS/MSC AFL	O/C				0 0			
324581	LH BRAKING SYSTEM SWIVEL COUPLING									
32.600	A100-24660 SN-UNKNOWN REF: AMM 32-44-21-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324591	RH BRAKING SYSTEM SWIVEL COUPLING									
32.600	A101-24660 SN-UNKNOWN REF: AMM 32-44-21-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324701	EMERGENCY BRAKE ELECTRIC DISTRIBUTOR									
32.650	65670-1 744A REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324711	EMERGENCY BRAKE DISTRIBUTOR RETURN CHECK VALVE									
32.650	A24515 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324721	LH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH									
32.660	7G1108 745 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-JUN-2008 5417.7 2752			
324731	RH MAIN GEAR EMERGENCY SYSTEM PRESSURE SWITCH									
32.660	7G1108 744 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-JUN-2008 5417.7 2752			
324741	LH EMERGENCY/PARKING BRAKE SHUTTLE VALVE									
32.670	CN100 24 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-1988 122 84			
324751	RH EMERGENCY/PARKING BRAKE SHUTTLE VALVE									
32.670	CN100 23 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-1988 122 84			
324821	PARKING BRAKE ACCUMULATOR PRESSURE GAUGE									
32.690	18040100 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324831	PARKING BRAKE ACCUMULATOR CHECK VALVE									
32.700	A24515 SN-UNKNOWN REF: AMM 32-42-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
324841	PARKING BRAKE ACCUMULATOR OVERPRESSURE VALVE									
32.700	D25AB1310A 51 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
325111	STEERING AMPLIFIER									
32.710	C24242010 303 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325121	NOSE LANDING GEAR STEERING ACTUATOR									
32.710	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325171	STEERING ACCUMULATOR									
32.730	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325191	STEERING SYSTEM FILTERING ELEMENT									
32.740	ADB295-4 107 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325201	LH NOSE LANDING GEAR STEERING SWIVEL COUPLING									
32.750	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325211	RH NOSE LANDING GEAR STEERING SWIVEL COUPLING									
32.750	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
325251	STEERING SLIDING DISTRIBUTOR VALVE									
32.760	C24166-1 U264 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
325271	STEERING SUPPLY ELECTRODISTRIBUTOR									
32.760	65670-1 697A REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 33 LIGHTS										
33-00-00-710-802-01	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - PILOT READING LIGHT (L3LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									
33-00-00-710-802-02	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - COPILOT READING LIGHT (R3LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									
33-00-00-710-802-03	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - LH CIRCUIT BREAKER PANEL SPOTLIGHT (L5LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									
33-00-00-710-802-04	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - RH CIRCUIT BREAKER PANEL SPOTLIGHT (R5LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									
33-00-00-710-802-05	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - OVERHEAD PANEL LIGHTED FACE (14LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									
33-00-00-710-802-06	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - LH RHEOSTAT SUPPORT PLATE (L15LC)									
		MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 33-00-00-710-802									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-00-00-710-802-07	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - RH RHEOSTAT SUPPORT PLATE (R15LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-08	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - PILOT GLARESHIELD TUBE (L24LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-09	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - COPILOT GLARESHIELD TUBE (R24LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-10	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - LIGHT STRIP (L25LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-11	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - LIGHT STRIP (M25LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-12	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - LIGHT STRIP (R25LC)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-13	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - PILOT DOME LIGHT (L7LH)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-00-00-710-802-14	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - COPILOT DOME LIGHT (R7LH)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-15	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - STEP SPOTLIGHT (175LE)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-16	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - STEP SPOTLIGHT (176LE)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-17	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - STEP SPOTLIGHT (177LE)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-18	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - STEP SPOTLIGHT (178LE)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-00-00-710-802-19	OPERATIONAL TEST OF THE INTERIOR LIGHTING SYSTEMS - STEP SPOTLIGHT (179LE)	MOS						11-JAN-1988		
	REF: AMM 33-00-00-710-802	HRS/MSC	O/C					0		
		AFL						0		
33-10-07-900-801-01	REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - PILOT DOME LIGHT (L7LH)	MOS						11-JAN-1988		
33.020	35-43-1 SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 33-10-07-900-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-10-07-900-801-02	REMOVAL/INSTALLATION OF THE COCKPIT DOME LIGHTS - COPILOT DOME LIGHT (R7LH)									
33.020	35-43-1 SN-UNKNOWN REF: AMM 33-10-07-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33-10-09-960-801-01	REPLACEMENT OF THE GLARESHIELD LIGHTS - PILOT GLARESHIELD TUBE (L24LC)									
	REF: AMM 33-10-09-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-10-09-960-801-02	REPLACEMENT OF THE GLARESHIELD LIGHTS - COPILOT GLARESHIELD TUBE (R24LC)									
	REF: AMM 33-10-09-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-10-17-900-801-01	REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - LH CIRCUIT BREAKER PANEL SPOTLIGHT (L5LC)									
33.030	4X650 SN-UNKNOWN REF: AMM 33-10-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33-10-17-900-801-02	REMOVAL / INSTALLATION OF THE CIRCUIT BREAKER PANEL SPOTLIGHTS - RH CIRCUIT BREAKER PANEL SPOTLIGHT (R5LC)									
33.030	4X650 SN-UNKNOWN REF: AMM 33-10-17-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33-20-00-200-801-01	INSPECTION OF "ALC" LIGHTING TUBES									
33.085	REF: AMM 33-20-00-200-801	MOS HRS/MSC AFL	12 400	+1m +40		-35	30-NOV-2022 8031.4 3845	26-OCT-2023 8431.4	26-NOV-2023 8471.4	100 d (+31) 382.2 (+40)
33-20-00-200-802-01	CHECK OF THE CONNECTION OF "SELA" LIGHTING TUBES									
33.290	REF: AMM 33-20-00-200-802	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-30-01-710-801-01	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - LH REAR COMPARTMENT DOME LIGHT (L4LH)	MOS						11-JAN-1988		
	REF: AMM 33-30-01-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-30-01-710-801-02	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - RH REAR COMPARTMENT DOME LIGHT (R4LH)	MOS						11-JAN-1988		
	REF: AMM 33-30-01-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-30-01-710-801-03	OPERATIONAL TEST OF THE NOSE CONE, BAGGAGE AND REAR COMPARTMENT LIGHTING - BAGGAGE COMPARTMENT DOME LIGHT (5LH)	MOS						11-JAN-1988		
	REF: AMM 33-30-01-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-01	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH NAVIGATION LIGHT (28L)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-02	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH NAVIGATION LIGHT (29L)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-03	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH NAVIGATION LIGHT (L3LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-04	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH NAVIGATION LIGHT (R3LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-00-710-801-05	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - REAR WHITE NAVIGATION/ANTI-COLLISION LIGHT (8LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-06	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH WING WHITE ANTI-COLLISION LIGHT (L23LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-07	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH WING WHITE ANTI-COLLISION LIGHT (R23LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-08	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - UPPER ANTI-COLLISION LIGHT (4LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-09	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - BELLY ANTI-COLLISION LIGHT (6LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-10	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH LANDING LIGHT (L3LM)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-11	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH LANDING LIGHT (R3LM)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-00-710-801-12	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - TAXI LIGHT (4LR)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-13	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH WING ICE DETECTION LIGHT (L33LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-14	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH WING ICE DETECTION LIGHT (R33LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-15	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH LOGO LIGHT (L14LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-16	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH LOGO LIGHT (R14LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-17	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH UPPER LOGO LIGHT (L310LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-18	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH UPPER LOGO LIGHT (R310LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-00-710-801-19	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - LH LOWER LOGO LIGHT (L320LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-710-801-20	OPERATIONAL TEST OF THE EXTERIOR LIGHTING - RH LOWER LOGO LIGHT (R320LX)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
33-40-00-720-801-01	FUNCTIONAL TEST OF THE EXTERIOR LIGHTS WITH LED TECHNOLOGY - TAXI LIGHT (4LR)	MOS						11-JAN-1988		
	REF: AMM 33-40-00-720-801	HRS/MSC	N/A					0		
		AFL						0		
33-40-01-900-801-01	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - LH NAVIGATION LIGHT (L3LJ) OR (L3LJ) / (28L)	MOS						04-DEC-2017		
33.120	30-1205-1	HRS/MSC	O/C					7593.7		
	REF: AMM 33-40-01-900-801	AFL						3722		
		APH						3592		
33-40-01-900-801-02	REMOVAL / INSTALLATION OF THE WING NAVIGATION LIGHTS - RH NAVIGATION LIGHT (R3LJ) OR (R3LJ) / (29L)	MOS						22-FEB-2012		
33.120	A7512-24	HRS/MSC	O/C					6932.9		
	SN-UNKNOWN	AFL						3498		
	REF: AMM 33-40-01-900-801									
33-40-07-900-801-01	REMOVAL / INSTALLATION OF THE WHITE REAR NAVIGATION / ANTI-COLLISION LIGHT - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (8LX)	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 33-40-07-900-801			N:0				0		
33-40-07-960-802-01	REPLACEMENT OF THE WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT BULBS - WHITE REAR NAVIGATION/ANTI-COLLISION LIGHT (8LX) BULB(S)	MOS						11-JAN-1988		
	REF: AMM 33-40-07-960-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-09-900-802-01 33.190	REMOVAL / INSTALLATION OF UPPER ANTI-COLLISION LIGHT - UPPER ANTI-COLLISION LIGHT (4LX) 30-1136-9 1780 REF: AMM 33-40-09-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33-40-09-960-801-01	REPLACEMENT OF UPPER ANTI-COLLISION LIGHT BULB (WHELEN) - UPPER ANTI-COLLISION LIGHT (4LX) BULB REF: AMM 33-40-09-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-09-960-802-01	REPLACEMENT OF UPPER ANTI-COLLISION LIGHT FLASH TUBE (GRIMES) - UPPER ANTI-COLLISION LIGHT (4LX) FLASH TUBE REF: AMM 33-40-09-960-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-09-960-803-01	REPLACEMENT OF LOWER ANTICOLLISION LIGHT FLASH TUBE (LABINAL) - BELLY ANTI-COLLISION LIGHT (6LX) FLASH TUBE REF: AMM 33-40-09-960-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-31-960-801-01	REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - FLASH TUBE OF LH WHITE WING ANTI-COLLISION LIGHT (L23LJ) REF: AMM 33-40-31-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-31-960-801-02	REPLACEMENT OF THE FLASH TUBE OF THE WING WHITE ANTI-COLLISION LIGHT - FLASH TUBE OF RH WHITE WING ANTI-COLLISION LIGHT (R23LJ) REF: AMM 33-40-31-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-31-960-802-01	REPLACEMENT OF THE WING WHITE ANTI-COLLISION LIGHTS - LH WING WHITE ANTI-COLLISION LIGHT (L23LJ) REF: AMM 33-40-31-960-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-31-960-802-02	REPLACEMENT OF THE WING WHITE ANTI-COLLISION LIGHTS - RH WING WHITE ANTI-COLLISION LIGHT (R23LJ)	MOS						11-JAN-1988		
	REF: AMM 33-40-31-960-802	HRS/MSC	O/C					0		
		AFL						0		
33-40-33-900-801-01	REMOVAL / INSTALLATION OF THE LOGO LIGHTS - LH LOGO LIGHT (L14LJ)	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: See Workcard									
33-40-33-900-801-02	REMOVAL / INSTALLATION OF THE LOGO LIGHTS - RH LOGO LIGHT (R14LJ)	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: See Workcard									
33-40-33-960-801-01	REPLACEMENT OF THE LOGO LIGHT BULB - LH LOGO LIGHT (L14LJ) BULB	MOS						11-JAN-1988		
	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
33-40-33-960-801-02	REPLACEMENT OF THE LOGO LIGHT BULB - RH LOGO LIGHT (R14LJ) BULB	MOS						11-JAN-1988		
	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
33-40-33-960-801-03	REPLACEMENT OF THE LOGO LIGHT BULB - LH LOWER LOGO LIGHT (L320LX) BULB	MOS						11-JAN-1988		
	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
33-40-33-960-801-04	REPLACEMENT OF THE LOGO LIGHT BULB - RH LOWER LOGO LIGHT (R320LX) BULB	MOS						11-JAN-1988		
	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-37-900-801-01 33.170	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - LH LANDING LIGHT (L3LM) Q4559X SN-UNKNOWN REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C				14-MAR-2008 5376.6 2726			
33-40-37-900-801-02 33.170	REMOVAL / INSTALLATION OF THE LANDING LIGHTS - RH LANDING LIGHT (R3LM) Q4559X SN-UNKNOWN REF: AMM 33-40-37-900-801	MOS HRS/MSC AFL	O/C	N:32 N:1100.8 N:554			09-NOV-2010 6477.4 3280			
33-40-37-960-801-01	REPLACEMENT OF THE LANDING LIGHT OPTICAL UNITS - LH LANDING LIGHT (L3LM) OPTICAL UNIT REF: AMM 33-40-37-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-37-960-801-02	REPLACEMENT OF THE LANDING LIGHT OPTICAL UNITS - RH LANDING LIGHT (R3LM) OPTICAL UNIT REF: AMM 33-40-37-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-41-820-801-01	ADJUSTMENT OF THE TAXI LIGHT - TAXI LIGHT (4LR) REF: AMM 33-40-41-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
33-40-41-900-801-01 33.180	REMOVAL / INSTALLATION OF THE TAXI LIGHT - TAXI LIGHT (4LR) 4060622A 45214 REF: AMM 33-40-41-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33-40-41-960-801-01	REPLACEMENT OF THE TAXI LIGHT BULB - TAXI LIGHT (4LR) BULB REF: AMM 33-40-41-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-40-49-900-801-01	REMOVAL / INSTALLATION OF THE LANDING LIGHT "PULSE" MODE CONTROL BOX - LANDING LIGHT "PULSE" MODE CONTROL BOX (12LM)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 33-40-49-900-801	AFL		N:0				0		
33-40-53-960-801-01	REPLACEMENT OF THE WHITE REAR ANTI-COLLISION LIGHT POWER SUPPLY BOX - REAR WHITE ANTI-COLLISION LIGHT POWER SUPPLY BOX (7LX)									
33.210	39-44-31	MOS						28-NOV-2018		
	2351	HRS/MSC	O/C					7675		
	REF: AMM 33-40-53-960-801	AFL						3744		
33-40-65-960-801-01	REPLACEMENT OF THE WING ANTI-COLLISION LIGHT POWER SUPPLY BOXES									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 33-40-65-960-801	AFL						0		
+ 33-50-00-710-804-01 (s)	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EMERGENCY LIGHTING SYSTEM							PKG		
	PKG 23	MOS						04-MAY-2019		
		HRS/MSC	4800	+40				7724.9		
	REF: AMM 33-50-00-710-804	AFL						3761		
33-50-05-350-801-01	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)									
	PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 33-50-05-350-801	AFL						0		
		APH						0		
33-50-05-350-801-02	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT)									
	PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 33-50-05-350-801	AFL						0		
		APH						0		
33-50-05-350-803-01	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)									
	PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	N/A					0		
	REF: AMM 33-50-05-350-803	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-05-350-803-02	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A					11-JAN-1988 0 0		
33-50-05-350-820-01	RESTORATION OF THE NON-CHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-820	MOS HRS/MSC AFL	N/A					11-JAN-1988 0 0		
33-50-05-350-820-02	RESTORATION OF THE NON-CHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-820	MOS HRS/MSC AFL	N/A					11-JAN-1988 0 0		
33-50-05-900-801-01	PILOT FLASHLIGHT PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0				11-JAN-1988 0 0 0		
33-50-05-900-801-02	COPILOT FLASHLIGHT PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL APH	O/C	N:0 N:0 N:0 N:0				11-JAN-1988 0 0 0		
33-50-05-960-801-01	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - LH FLASHLIGHT BATTERY (9610ME) PN SN-UNKNOWN REF: AMM 33-50-05-960-801	MOS HRS/MSC AFL	N/A					11-JAN-1988 0 0		
33-50-05-960-801-02	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - RH FLASHLIGHT BATTERY (9620ME) PN SN-UNKNOWN REF: AMM 33-50-05-960-801	MOS HRS/MSC AFL	N/A					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-33-610-801-01	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 1 (L3LW)									
33.240	D734-02-001 2812/07-2006 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-NOV-2019			
33-50-33-610-801-02	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 2 (R3LW)									
33.240	D734-02-001 2820/07-2006 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-NOV-2019			
33-50-33-610-801-03	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 3 (4LW)									
33.250	D734-02-001 1824 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-NOV-2019			
33-50-33-610-801-04	SERVICING OF THE EMERGENCY POWER SUPPLIES - EPS 4 (20LW) (OPTIONAL)									
33.130	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
33-50-33-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 1 (L3LW)									
33.240	D734-02-001 2812/07-2006 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			26-DEC-2020 7883.1 3800			
33-50-33-900-801-02	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 2 (R3LW)									
33.240	D734-02-001 2820/07-2006 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	N:42 R:0 N:334.6 R:0 N:92 R:0			26-DEC-2020 7883.1 3800			
33-50-33-900-801-03	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 3 (4LW)									
33.250	D734-02-001 1824 REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			26-DEC-2020 7883.1 3800			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-33-900-801-04	REMOVAL / INSTALLATION OF THE EMERGENCY POWER SUPPLIES - EPS 4 (20LW) (OPTIONAL)									
33.130	PN NOT INSTALLED REF: AMM 33-50-33-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
33-50-37-900-801-01	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 1 (L3LW) BATTERY PACK									
	C734-01-030 CF34368/02/22 REF: AMM 33-50-37-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
33-50-37-900-801-02	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 2 (R3LW) BATTERY PACK									
	C734-01-030 CF34367/02/22 REF: AMM 33-50-37-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
33-50-37-900-801-03	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 3 (4LW) BATTERY PACK									
	C734-01-030 CF34366/02/22 REF: AMM 33-50-37-900-801	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
33-50-37-900-801-04	REMOVAL / INSTALLATION OF THE EPS BATTERY PACKS (PAGE) - EPS 4 (20LW) (OPTIONAL) BATTERY PACK									
	PN SN-UNKNOWN REF: AMM 33-50-37-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 33-50-37-960-802-01	DISCARD OF THE EPS BATTERY PACKS - EPS 1 (L3LW) BATTERY PACK									
33.240	C734-01-030 CF34368/02/22 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				27-JUN-2023 8049.2 3853	27-JUL-2025		740 d
LIFE LIMIT										
+ 33-50-37-960-802-02	DISCARD OF THE EPS BATTERY PACKS - EPS 2 (R3LW) BATTERY PACK									
33.240	C734-01-030 CF34367/02/22 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				27-JUN-2023 8049.2 3853	27-JUL-2025		740 d
LIFE LIMIT										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-50-37-960-802-03	DISCARD OF THE EPS BATTERY PACKS - EPS 3 (4LW) BATTERY PACK C734-01-030 CF34366/02/22 REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	25				27-JUN-2023 8049.2 3853	27-JUL-2025		740 d
33.250 LIFE LIMIT										
33-50-37-960-802-04	DISCARD OF THE EPS BATTERY PACKS - EPS 4 (20LW) (OPTIONAL) BATTERY PACK PN SN-UNKNOWN REF: AMM 33-50-37-960-802	MOS HRS/MSC AFL	N/A							
33.130										
331101	PILOT LIGHTING BOX 24-01AB 1205 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33.010										
331111	COPILOT LIGHTING BOX 24-01AB 1179 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33.010										
331161	PILOT READING LIGHT 34150-13-305 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33.040										
331171	COPILOT READING LIGHT 34150-13-305 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33.040										
331181	PILOT FLUORESCENT GLARESHIELD TUBE 10-501BA 61 REF: AMM 33-10-09-960-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
33.050										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
331191	COPILOT FLUORESCENT GLARESHIELD TUBE 10-501TA	MOS					11-JAN-1988			
33.050	63 REF: AMM 33-10-09-960-801	HRS/MSC AFL	O/C	N:0			0 0			
331201	GLARESHIELD POWER SUPPLY BOX 55-0520-4	MOS					11-JAN-1988			
33.060	72 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
331211	PILOT LIGHTING INSTRUMENT TRANSFORMER 24-54BD	MOS					11-JAN-1988			
33.070	463 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
331221	COPILOT LIGHTING INSTRUMENT TRANSFORMER 24-54BD	MOS					11-JAN-1988			
33.070	460 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
331231	LIGHTING PEDESTAL TRANSFORMER 24-54BD	MOS					11-JAN-1988			
33.080	461 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
331241	OVERHEAD PANEL LIGHTING TRANSFORMER 24-014	MOS					11-JAN-1988			
33.080	111 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
331251	CENTER INSTRUMENT PANEL LIGHTING TRANSFORMER 24-54BD	MOS					11-JAN-1988			
33.070	462 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
333101	LH REAR COMPARTMENT DOME LIGHT 15-0254-3 33.090 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
333111	RH REAR COMPARTMENT DOME LIGHT 15-0254-3 33.090 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
333121	BAGGAGE COMPARTMENT DOME LIGHT 15-0254-3 33.100 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
333131	BAGGAGE COMPARTMENT SPOT LIGHT 32-24 33.100 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
333141	NOSE CONE INSPECTION LIGHT B8550-1-1385 33.110 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
334131	LH WING STROBE POWER SUPPLY 39-42-1 33.140 238 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			07-SEP-1995 1840 1294			
334141	RH WING STROBE POWER SUPPLY 6480702 33.150 874 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:6 N:0 N:0			26-DEC-2020 7883.1 3800			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
334151	LH WING STROBE LIGHT									
33.140	39-28-21A 231 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			18-AUG-1994 1604 1098			
334161	RH WING STROBE LIGHT									
33.150	39-28-21 227 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JUN-1994 1553 1083			
334171	LH ICE DETECTION SPOT LIGHT									
33.160	30-1361-9 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
334181	RH ICE DETECTION SPOT LIGHT									
33.160	30-1361-10 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
334231	TAXI LIGHT PROXIMITY DETECTOR									
33.180	84739702 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
334251	VERTICAL STABILIZER ANTI-COLLISION POWER SUPPLY									
33.190	60-2667-3 1408 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
334271	FUSELAGE ANTI-COLLISION POWER SUPPLY									
33.200	3944-31 209 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
334281	FUSELAGE ANTI-COLLISION LIGHT										
33.200	39-59-2 SN-UNKNOWN REF: AMM 33-40-09-960-803	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0				
334301	REAR STROBE LIGHT										
33.210	39-54-21R 136 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				07-FEB-1995 1693 1188				
335151	FORWARD PASSENGER DOOR LIGHT										
33.260	306-03 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0				
335161	AFT PASSENGER DOOR LIGHT										
33.260	306-03 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0				
335171	EMERGENCY EXIT EXTERIOR LIGHT										
33.270	32-515M8 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0				
335181	RH WING EVACUATION LIGHT										
33.270	30-1358-17 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0				
CHAPTER 34 NAVIGATION											
+ 34-01-00-720-801-01 (s)	FUNCTIONAL TEST OF THE EFIS SYSTEM						PKG				
34.032	PKG 6	MOS	24	+1m			21-JUN-2023				
	REF: AMM 34-01-00-720-801	HRS/MSC AFL	1600	+40			8047.2 3851				



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-01-13-900-801-01	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EADI 1 (L12FV)									
34.170	7003110-901 86111593 REF: AMM 34-01-13-900-801	MOS HRS/MSC AFL	O/C				26-SEP-1994 1627 1118			
34-01-13-900-801-02	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EHSI 1 (L22FV)									
34.170	7003110-901 88022540 REF: AMM 34-01-13-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-APR-2013 7079.7 3562			
34-01-13-900-801-03	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EADI 2 (R12FV)									
34.180	7003110-901 90024380 REF: AMM 34-01-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-APR-1990 490 349			
34-01-13-900-801-04	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - EHSI 2 (R22FV)									
34.180	7003110-901 92127256 REF: AMM 34-01-13-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-SEP-2011 6734.2 3397			
34-01-13-900-801-05	REMOVAL / INSTALLATION OF THE EFIS DISPLAY UNITS - MFD (62FV)									
34.190	7003110-901 87021860 REF: AMM 34-01-13-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			29-MAR-2011 6615.8 3344			
+ 34-01-25-710-801-01 (s)	OPERATIONAL TEST OF THE EFIS FANS						PKG			
34.020	PKG 21 REF: AMM 34-01-25-710-801	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
34-10-00-700-801-01	OPERATIONS TO BE PERFORMED AFTER REMOVAL / INSTALLATION OF THE AIR DATA SYSTEM PNEUMATIC COMPONENTS - AIR DATA SYSTEM PNEUMATIC COMPONENTS									
	REF: AMM 34-10-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE AIR DATA SYSTEM PKG 16	MOS	24	+1m			PKG 21-JUN-2023 8047.2 3851			
34.045		HRS/MSC								
RVSM	REF: AMM 34-10-00-720-801	AFL								
34-10-00-860-801-01	PREPARATION AND USE OF THE AIR DATA BENCH	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
	REF: AMM 34-10-00-860-801	AFL								
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE TEMPERATURE PROBE (52FL)	MOS					11-JAN-1988 0 0			
34.090	102AU1CK 72161	HRS/MSC	O/C	N:0						
	REF: AMM 34-10-01-900-801	AFL								
+ 34-10-11-720-801-01 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - LH AOA SENSOR (L11CM)	MOS					PKG 19-JUL-2012 6985.1 3525			
27.480	PKG 21	HRS/MSC	1600	+40						
	REF: AMM 34-10-11-720-801	AFL								
+ 34-10-11-720-801-02 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF ANGLE-OF-ATTACK SENSORS - RH AOA SENSOR (R11CM)	MOS					PKG 04-NOV-2015 7355.5 3656			
27.480	PKG 21	HRS/MSC	1600	+40						
	REF: AMM 34-10-11-720-801	AFL								
34-10-11-720-803-01	CHECK OF THE POTENTIOMETER WIPER-CONTACT RESISTANCE ON THE AOA SENSORS - LH AOA SENSOR (L11CM)	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
	REF: AMM 34-10-11-720-803	AFL								
34-10-11-720-803-02	CHECK OF THE POTENTIOMETER WIPER-CONTACT RESISTANCE ON THE AOA SENSORS - RH AOA SENSOR (R11CM)	MOS					11-JAN-1988 0 0			
		HRS/MSC	O/C							
	REF: AMM 34-10-11-720-803	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-10-11-900-801-01 27.480	REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - LH AOA SENSOR (L11CM) 861CAU2 00129 REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
34-10-11-900-801-02 27.480	REMOVAL / INSTALLATION OF THE ANGLE-OF-ATTACK SENSOR - RH AOA SENSOR (R11CM) 861CAU2 1127A REF: AMM 34-10-11-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			04-NOV-2015 7355.5 3656			
34-11-00-200-801-01	CHECK OF THE TOTAL / STATIC PRESSURE SYSTEM FOR CLOGGING REF: AMM 34-11-00-200-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
34-11-00-680-802-01 (s)	DRAINING OF THE STAND-BY PITOT / STATIC PRESSURE SYSTEM PKG 16 REF: AMM 34-11-00-680-802	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
34-11-00-790-801-01	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT STATIC AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL APH	O/C				04-DEC-2017 7593.7 3722 3592			
34-11-00-790-801-02	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - PILOT TOTAL AIR PRESSURE SYSTEM REF: AMM 34-11-00-790-801	MOS HRS/MSC AFL APH	O/C				04-DEC-2017 7593.7 3722 3592			
34-11-00-790-801-03	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT STATIC AIR PRESSURE SYSTEM REF: See Workcard	MOS HRS/MSC AFL APH	O/C				04-DEC-2017 7593.7 3722 3592			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-11-00-790-801-04	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - COPILOT TOTAL AIR PRESSURE SYSTEM	MOS						04-DEC-2017		
	REF: AMM 34-11-00-790-801	HRS/MSC	O/C					7593.7		
		AFL						3722		
		APH						3592		
34-11-00-790-801-05	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY STATIC AIR PRESSURE SYSTEMS	MOS						04-NOV-2015		
	REF: See Workcard	HRS/MSC	O/C					7355.5		
		AFL						3656		
34-11-00-790-801-06	LEAK TEST OF THE TOTAL / STATIC PRESSURE SYSTEM - STAND-BY TOTAL AIR PRESSURE SYSTEMS	MOS						04-NOV-2015		
	REF: AMM 34-11-00-790-801	HRS/MSC	O/C					7355.5		
		AFL						3656		
34-11-01-100-801-01	INSPECTION AND CLEANING OF THE TOTAL PRESSURE PROBES	MOS						11-JAN-1988		
	REF: AMM 34-11-01-100-801	HRS/MSC	O/C					0		
		AFL						0		
34-11-01-200-801-01	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - LH TOTAL PRESSURE PROBE (L4FL)	MOS						17-OCT-2017		
	REF: AMM 34-11-01-200-801	HRS/MSC	O/C					7585.5		
		AFL						3720		
34-11-01-200-801-02	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - RH TOTAL PRESSURE PROBE (R4FL)	MOS						17-OCT-2017		
	REF: AMM 34-11-01-200-801	HRS/MSC	O/C					7585.5		
		AFL						3720		
34-11-01-200-801-03	CHECK OF THE TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING - STAND-BY TOTAL PRESSURE PROBE (24FL)	MOS						17-OCT-2017		
	REF: AMM 34-11-01-200-801	HRS/MSC	O/C					7585.5		
		AFL						3720		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-11-01-900-801-01	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - LH TOTAL PRESSURE PROBE (L4FL)									
34.080	50620-10 493 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
34-11-01-900-801-02	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - RH TOTAL PRESSURE PROBE (R4FL)									
34.080	50620-10 492 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
34-11-01-900-801-03	REMOVAL / INSTALLATION OF THE TOTAL PRESSURE PROBES - STAND-BY TOTAL PRESSURE PROBE (24FL)									
34.080	50620-10 491 REF: AMM 34-11-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUL-1989 311 195			
34-11-05-900-801-01	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - LH STATIC PRESSURE PROBE (L13FL)									
34.060	C16757AA 408 REF: AMM 34-11-05-900-801	MOS HRS/MSC AFL	O/C	N:12 N:0 N:0			16-JUL-2012 6985.1 3525			
34-11-05-900-801-02	REMOVAL / INSTALLATION OF THE STATIC PRESSURE PROBES - RH STATIC PRESSURE PROBE (R13FL)									
34.060	C16757AA 958 REF: AMM 34-11-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-DEC-2020 7883.1 3800			
34-11-05-900-802-01	REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - STAND-BY STATIC PRESSURE PROBE (L501FL)									
34.070	PN SN-UNKNOWN REF: AMM 34-11-05-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
34-11-05-900-802-02	REMOVAL / INSTALLATION OF THE STAND-BY STATIC PRESSURE PROBES - STAND-BY STATIC PRESSURE PROBE (R501FL)									
34.070	PN SN-UNKNOWN REF: AMM 34-11-05-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-13-00-720-801-01	FUNCTIONAL TEST OF THE ANGLE-OF-ATTACK INDICATING SYSTEM	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: See Workcard									
+ 34-14-01-700-881-01	TEST NO. 1 AIR DATA (ADC1) COMPUTER (FAR 91.411)	MOS HRS/MSC AFL	24				05-NOV-2021	05-NOV-2023		110 d
34.050	7000700-947 95086693									
MANDATORY	REF: See Workcard									
+ 34-14-01-700-881-02	TEST NO. 2 AIR DATA (ADC 2) COMPUTER (FAR 91.411)	MOS HRS/MSC AFL	24				05-NOV-2021	05-NOV-2023		110 d
34.055	7000700-647 87032051									
MANDATORY	REF: See Workcard									
34-14-01-710-801-01	OPERATIONAL TEST OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (L2FX)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 34-14-01-710-801									
34-14-01-710-801-02	OPERATIONAL TEST OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (R2FX)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 34-14-01-710-801									
34-14-01-900-801-01	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 1 (L2FX)	MOS HRS/MSC AFL	O/C	R:72 R:346.6 R:95			05-NOV-2021 7940.3 3817			
34.050	7000700-947 95086693									
	REF: AMM 34-14-01-900-801									
34-14-01-900-801-02	REMOVAL / INSTALLATION OF THE AIR DATA COMPUTERS (ADC) - ADC 2 (R2FX)	MOS HRS/MSC AFL	O/C				05-NOV-2021 7940.3 3817			
34.055	7000700-647 87032051									
	REF: AMM 34-14-01-900-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-15-01-700-881-01	TEST PILOT ALTIMETER (FAR 91.411) 4016341-904A-G 87044548 REF: See Workcard	MOS HRS/MSC AFL	24				27-JUN-2023	27-JUN-2025		710 d
34.100 MANDATORY										
+ 34-15-01-700-881-02	TEST COPILOT ALTIMETER (FAR 91.411) 4016341-904A-G 87014417 REF: See Workcard	MOS HRS/MSC AFL	24				27-JUN-2023	27-JUN-2025		710 d
34.100 MANDATORY										
+ 34-15-02-700-881-01	TEST PILOT STAND-BY ALTIMETER (FAR 91.411) 64141-530-1 4739 REF: See Workcard	MOS HRS/MSC AFL	24				27-JUN-2023	27-JUN-2025		710 d
34.110 MANDATORY										
+ 34-16-00-720-801-01	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L2FX) 7000700-947 95086693 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			05-NOV-2021 7940.3 3817	05-NOV-2023	26-NOV-2023	110 d (+21)
34.050										
+ 34-16-00-720-801-02	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R2FX) 7000700-647 87032051 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			05-NOV-2021 7940.3 3817	05-NOV-2023	26-NOV-2023	110 d (+21)
34.055										
+ 34-16-00-720-801-03	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY ALTIMETER (1FK) 64141-530-1 4739 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			17-DEC-2021 7940.3 3817	17-DEC-2023	08-JAN-2024	152 d (+22)
34.110										
+ 34-16-00-720-801-04	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY MACH AIRSPEED INDICATOR (26FL) 64032-229-1 1627 REF: AMM 34-16-00-720-801	MOS HRS/MSC AFL	24	+3%			17-DEC-2021 7940.3 3817	17-DEC-2023	08-JAN-2024	152 d (+22)
34.140										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-21-00-700-801-01 (s)	CHECK OF THE ARINC 429 LINES TO THE INERTIAL REFERENCE SYSTEM (IRS)						PKG			
34.150	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 34-21-00-700-801	HRS/MSC					8047.2			
		AFL	3750				3851			
+ 34-21-00-710-801-01 (s)	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 1 (L2FP)						PKG			
34.310	PKG 21	MOS					11-NOV-2015			
	REF: AMM 34-21-00-710-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
+ 34-21-00-710-801-02 (s)	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 2 (R2FP)						PKG			
34.310	PKG 21	MOS					11-OCT-2022			
	REF: AMM 34-21-00-710-801	HRS/MSC	1600	+40			7998.3			
		AFL					3836			
34-21-00-710-801-03	OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) - IRU 3 (22FP) (OPTION)									
34.312		MOS					11-JAN-1988			
	REF: AMM 34-21-00-710-801	HRS/MSC	N/A				0			
		AFL					0			
34-21-00-820-801-01	IRS ALIGNMENT - IRU 1 (L2FP)									
		MOS					11-JAN-1988			
	REF: AMM 34-21-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
34-21-00-820-801-02	IRS ALIGNMENT - IRU 2 (R2FP)									
		MOS					11-JAN-1988			
	REF: AMM 34-21-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
34-21-00-820-801-03	IRS ALIGNMENT - IRU 3 (22FP)									
		MOS					11-JAN-1988			
	REF: AMM 34-21-00-820-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-21-01-900-801-01	REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 1 (L2FP)									
34.310	HG1075AE03 804 REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C	R:0			26-MAY-2006 4839.6 2528			
34-21-01-900-801-02	REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 2 (R2FP)									
34.310	HG1075AE03 623 REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C				11-OCT-2022 7998.3 3836			
34-21-01-900-801-03	REMOVAL / INSTALLATION OF THE INERTIAL REFERENCE UNITS (IRU) - IRU 3 (22FP)									
34.312	HG1075AE03 NOT INST. REF: AMM 34-21-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
34-21-13-100-801-01 (s)	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 1 (L2FP) FAN FILTER						PKG			
34.380	PKG 22 REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL APH	3200 +40				04-DEC-2017 7593.7 3722 3592			
34-21-13-100-801-02 (s)	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 2 (R2FP) FAN FILTER						PKG			
34.380	PKG 22 REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL APH	3200 +40				04-DEC-2017 7593.7 3722 3592			
34-21-13-100-801-03	CLEANING / REPLACEMENT OF THE IRU FAN FILTERS - IRU 3 (22FP) FAN FILTER (OPTION)									
34.385	REF: AMM 34-21-13-100-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
34-23-00-720-802-01	FUNCTIONAL TEST OF THE STAND-BY HORIZON - STAND-BY HORIZON (6FG)									
	REF: AMM 34-23-00-720-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-23-00-900-801-01	REMOVAL / INSTALLATION OF THE STAND-BY HORIZON - STAND-BY HORIZON (6FG)									
34.250	H200AKM 5530 REF: AMM 34-23-00-900-801	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			06-MAY-2010 6237.1 3162			
34-25-00-820-801-01	COMPENSATION OF STAND-BY COMPASS - STAND-BY COMPASS (42FL)									
	REF: AMM 34-25-00-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
34-41-01-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR RECEIVER / TRANSMITTER / ANTENNA ASSEMBLY - RADAR ANTENNA (3SQ)									
34.290	7012640-922 90010511 REF: AMM 34-41-01-900-801	MOS HRS/MSC AFL	O/C				17-FEB-1993 1255 869			
34-41-03-900-801-01	REMOVAL / INSTALLATION OF THE WEATHER RADAR TRANSCEIVER - RADAR TRANSCEIVER (2SQ)									
34.295	PN SN-UNKNOWN REF: AMM 34-41-03-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
34-42-00-710-801-01	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 1 SYSTEM									
	REF: AMM 34-42-00-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
34-42-00-710-801-02	OPERATIONAL TEST OF THE RADIO ALTIMETER SYSTEM - RADIO ALTIMETER 2 SYSTEM									
	REF: AMM 34-42-00-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 34-42-01-820-801-01	CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (2SA) WITH CABLE									
34.340	7001840-922 86102071 REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	O/C				23-AUG-2017			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-42-01-820-801-02	CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (22SA) WITH CABLE									
34.340	7001840-912 NOT INST. REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
34-42-01-820-801-03	CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (2SA) WITHOUT CABLE									
	REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
34-42-01-820-801-04	CALIBRATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (22SA) WITHOUT CABLE									
	REF: AMM 34-42-01-820-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
34-42-01-900-801-01	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 1 RECEIVER/TRANSMITTER (2SA)									
34.340	7001840-922 86102071 REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			04-DEC-2017 7593.7 3722			
34-42-01-900-801-02	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER RECEIVER / TRANSMITTER - RADIO ALTIMETER 2 RECEIVER/TRANSMITTER (22SA)									
34.340	7001840-912 NOT INST. REF: AMM 34-42-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
34-42-09-900-801-01	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 TRANSMITTER ANTENNA (3SA)									
34.350	S67-2002-13 223 REF: AMM 34-42-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
34-42-09-900-801-02	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 1 RECEIVER ANTENNA (4SA)									
34.350	S67-2002-13 162 REF: AMM 34-42-09-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-42-09-900-801-03	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 TRANSMITTER ANTENNA (23SA)									
34.355	S67-2002-13 NOT INST. REF: AMM 34-42-09-900-801	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
34-42-09-900-801-04	REMOVAL / INSTALLATION OF THE RADIO ALTIMETER ANTENNAS - RADIO ALTIMETER 2 RECEIVER ANTENNA (24SA)									
34.355	S67-2002-13 NOT INST. REF: AMM 34-42-09-900-801	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
34-44-05-900-801-01	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - LOWER TCAS ANTENNA (12SH)									
	PN SN-UNKNOWN REF: AMM 34-44-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
34-44-05-900-801-02	REMOVAL / INSTALLATION OF THE TCAS ANTENNAS - UPPER TCAS ANTENNA (13SH)									
	PN SN-UNKNOWN REF: AMM 34-44-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
34-45-00-720-802-01	FUNCTIONAL TEST OF THE GROUND PROXIMITY WARNING SYSTEM (GPWS)									
	REF: See Workcard	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
34-45-01-900-802-01	REMOVAL / INSTALLATION OF GROUND PROXIMITY WARNING SYSTEM (GPWS) COMPUTER - "GPWS" COMPUTER (12SA)									
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-JAN-1988 0 0		
34-51-00-710-801-01	OPERATIONAL TEST OF THE VOR NAVIGATION SYSTEM									
	REF: AMM 34-51-00-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-51-01-820-801-01	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 1 RECEIVER (L3RS)									
34.430	622-6137-201 4906 REF: AMM 34-51-01-820-801	MOS HRS/MSC AFL	O/C							
+ 34-51-01-820-801-02	CALIBRATION OF THE VOR / ILS / MARKER RECEIVERS - VOR/ILS/MARKER 2 RECEIVER (R3RS)									
34.430	622-6137-201 4987 REF: AMM 34-51-01-820-801	MOS HRS/MSC AFL	O/C							
34-51-05-900-801-01	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - VOR/LOC ANTENNA (5RS) - LH									
34.440	DMN4-45-3 1178 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
34-51-05-900-801-02	REMOVAL / INSTALLATION OF THE VOR / LOC ANTENNAS - VOR/LOC ANTENNA (5RS) - RH									
34.440	DMN4-45-3 1653 REF: AMM 34-51-05-900-801	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
34-51-17-900-801-01	REMOVAL / INSTALLATION OF THE MARKER ANTENNA - MARKER ANTENNA (8RS) .									
34.280	S35-1000-1 1374 REF: AMM 34-51-17-900-801	MOS HRS/MSC AFL	O/C	N:0				11-JAN-1988 0 0		
34-51-20-710-801-01	OPERATIONAL TEST OF THE INSTRUMENT LANDING SYSTEM (ILS)									
	REF: AMM 34-51-20-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		
34-51-40-710-801-01	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 1 SYSTEM									
	REF: AMM 34-51-40-710-801	MOS HRS/MSC AFL	O/C					11-JAN-1988 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-51-40-710-801-02	OPERATIONAL TEST OF THE MARKER SYSTEM - MARKER 2 SYSTEM	MOS						11-JAN-1988		
	REF: AMM 34-51-40-710-801	HRS/MSC	O/C					0		
		AFL						0		
34-52-00-710-801-01	OPERATIONAL TEST OF THE DISTANCE MEASURING EQUIPMENT (DME) SYSTEM	MOS						11-JAN-1988		
	REF: AMM 34-52-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
34-52-05-900-801-01	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 1 ANTENNA (L4RV)	MOS		N:0				28-NOV-2018		
34.460	DMNI50-2-2	HRS/MSC	O/C	N:0				7675		
	142876	AFL		N:0				3744		
	REF: AMM 34-52-05-900-801									
34-52-05-900-801-02	REMOVAL / INSTALLATION OF THE DME ANTENNAS - DME 2 ANTENNA (R4RV)	MOS		N:0				11-JAN-1988		
34.460	DMNI50-2-2	HRS/MSC	O/C	N:0				0		
	33100	AFL						0		
	REF: AMM 34-52-05-900-801									
34-53-00-710-801-01	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 1 SYSTEM	MOS						11-JAN-1988		
	REF: AMM 34-53-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
34-53-00-710-801-02	OPERATIONAL TEST OF THE AUTOMATIC DIRECTION FINDER (ADF) SYSTEM - ADF 2 SYSTEM	MOS						11-JAN-1988		
	REF: AMM 34-53-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
+ 34-54-00-700-881-01	TEST NO. 1 ATC TRANSPONDER (FAR 91.413)	MOS	24					27-JUN-2023	27-JUN-2025	710 d
34.480	7510700-951	HRS/MSC								
	RCE00197	AFL								
	MANDATORY									
	REF: See Workcard									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-54-00-700-881-02	TEST NO. 2 ATC TRANSPONDER (FAR 91.413)									
34.490	75010700-951	MOS	24				27-JUN-2023	27-JUN-2025		710 d
MANDATORY	RCE96772	HRS/MSC								
	REF: See Workcard	AFL								
34-54-00-710-801-01	OPERATIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 34-54-00-710-801	AFL					0			
34-54-00-710-801-02	OPERATIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 34-54-00-710-801	AFL					0			
34-54-00-720-802-01	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS									
34.480	7510700-951	MOS					05-NOV-2021			
	RCE00197	HRS/MSC	O/C				7940.3			
	REF: See Workcard	AFL					3817			
34-54-00-720-802-02	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS									
34.490	75010700-951	MOS					05-NOV-2021			
	RCE96772	HRS/MSC	O/C				7940.3			
	REF: See Workcard	AFL					3817			
34-54-00-720-802-03	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM COMPLEMENTARY TESTS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: See Workcard	AFL					0			
34-54-00-720-802-04	FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM COMPLEMENTARY TESTS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: See Workcard	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-54-05-900-801-01	REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 LOWER ANTENNA (L5SH)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 34-54-05-900-801	AFL		N:0			0			
34-54-05-900-801-02	REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 1 UPPER ANTENNA (L9SH)									
34.500	DMNI50-2-2	MOS		N:0			28-NOV-2018			
	142874	HRS/MSC	O/C	N:0			7675			
	REF: AMM 34-54-05-900-801	AFL		N:0			3744			
34-54-05-900-801-03	REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 LOWER ANTENNA (R5SH)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 34-54-05-900-801	AFL		N:0			0			
34-54-05-900-801-04	REMOVAL / INSTALLATION OF THE ATC ANTENNAS - ATC 2 UPPER ANTENNA (R9SH)									
34.500	DMNI50-2-2	MOS		N:0			28-NOV-2018			
	142875	HRS/MSC	O/C	N:0			7675			
	REF: AMM 34-54-05-900-801	AFL		N:0			3744			
+ 34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)									
34.445		DAYS	30				27-JUN-2023	27-JUL-2023		9 d
MANDATORY	REF: See Workcard	HRS/MSC					8049.2			
		AFL					3853			
+ 34-61-00-710-801-01	OPERATIONAL TEST OF THE FLIGHT MANAGEMENT SYSTEM (FMS) - PILOT FMS									
34.240		MOS					04-DEC-2017			
		HRS/MSC	O/C				7593.7			
	REF: AMM 34-61-00-710-801	AFL					3722			
		APH					3592			
+ 34-61-00-710-801-02	OPERATIONAL TEST OF THE FLIGHT MANAGEMENT SYSTEM (FMS) - COPILOT FMS									
34.240		MOS					04-DEC-2017			
		HRS/MSC	O/C				7593.7			
	REF: AMM 34-61-00-710-801	AFL					3722			
		APH					3592			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-61-01-900-803-01	REMOVAL / INSTALLATION OF THE DATA MANAGEMENT UNIT (DMU) - DMU COMPUTER (22RJ) PN NOT INSTALLED REF: AMM 34-61-01-900-803	MOS HRS/MSC AFL	O/C							
34-61-05-960-801-01	REPLACEMENT OF THE BATTERY MODULE FOR HONEYWELL NZ 2000 TYPE FLIGHT MANAGEMENT COMPUTER REF: AMM 34-61-05-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 34-61-05-960-802-01	REPLACEMENT OF THE DMU INTERNAL BATTERY PN NOT INSTALLED REF: AMM 34-61-05-960-802	MOS HRS/MSC AFL	N/A							
34-61-07-900-801-01	REMOVAL / INSTALLATION OF THE FMS CDU - CDU 1 (L12RJ) PN NOT INSTALLED REF: AMM 34-61-07-900-801	MOS HRS/MSC AFL	O/C							
34-61-07-900-801-02	REMOVAL / INSTALLATION OF THE FMS CDU - CDU 2 (R12RJ) PN NOT INSTALLED REF: AMM 34-61-07-900-801	MOS HRS/MSC AFL	O/C							
34-61-09-960-801-01	REPLACEMENT OF THE CONTROL DISPLAY UNIT BATTERY - CDU 1 (L12RJ) PN NOT INSTALLED REF: AMM 34-61-09-960-801	MOS HRS/MSC AFL APH	N/A				0			
34-61-09-960-801-02	REPLACEMENT OF THE CONTROL DISPLAY UNIT BATTERY - CDU 2 (R12RJ) PN NOT INSTALLED REF: AMM 34-61-09-960-801	MOS HRS/MSC AFL	N/A							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 34-61-09-960-801-04	REPLACEMENT OF THE CONTROL DISPLAY UNIT BATTERY - FMS 3 CDU (701RJ)	MOS								
	REF: AMM 34-61-09-960-801	HRS/MSC AFL	O/C							
34-90-10-900-801-01	CONTROL DISPLY UNIT (CDU) (GNS-XLS BATTERY ONLY) BATTERY	MOS								
	PN NOT INSTALLED	HRS/MSC AFL	O/C							
	REF: GENERIC NO REF	APH					0			
341021	ANGLE OF ATTACK METER COMPUTER	MOS						11-JAN-1988		
34.520	910000-543 SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0			
	REF: AMM GENERIC 2						0			
341026	ANGLE OF ATTACK METER PROBE	MOS						11-JAN-1988		
34.530	SLZ9164 SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0			
	REF: AMM GENERIC 2						0			
341031	ANGLE OF ATTACK METER INDICATOR	MOS						11-JAN-1988		
34.550	SLZ7725 SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0			
	REF: AMM GENERIC 2						0			
341036	ANGLE OF ATTACK METER CONTROL	MOS						11-JAN-1988		
34.550	911001 SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0			
	REF: AMM GENERIC 2						0			
341301	PILOT ALTIMETER	MOS						05-NOV-2021		
34.100	4016341-904A-G 87044548	HRS/MSC AFL	O/C	N:7940.3			7940.3			
	REF: AMM GENERIC 2						3817			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
341321	COPILOT ALTIMETER 4016341-904A-G 87014417 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:7940.3			05-NOV-2021 7940.3 3817			
341341	PILOT STAND-BY ALTIMETER 64141-530-1 4739 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-DEC-2021 7940.3 3817			
341401	PILOT VERTICAL SPEED INDICATOR 4067241-890 94035725 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-NOV-2004 4535.8 2438			
341421	COPILOT VERTICAL SPEED INDICATOR 4013013-907 87044417 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
341441	PILOT MACH-AIRSPEED INDICATOR 4018366-902AB 87030571 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
341461	COPILOT MACH-AIRSPEED INDICATOR 4018366-902AB 87030562 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
341481	STAND-BY MACH-AIRSPEED INDICATOR 64032-229-1 1627 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			17-DEC-2021 7940.3 3817			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
341A15	LIGHTNING SNSR PROCESSOR 7011822-903 87120127 REF:	MOS HRS/MSC AFL	O/C	N:233 R:0 N:5284.1 R:0 N:2642 R:0			15-DEC-2008 5595.1 2837			
341A16	LIGHTNING SNSR ANTENNA 7014062-901 89070141 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-OCT-1989 382 236			
342101 34.160	PILOT DDRMI INDICATOR 63540-250-2 153 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JUN-2013 7126.1 3576			
342121 34.160	COPILOT DDRMI INDICATOR 63540-250-2A-D 883 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
342301 34.200	PILOT PROCESSOR DISPLAY UNIT 7007356-905 87020178 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				30-NOV-2012 7034.4 3543			
342321 34.200	COPILOT PROCESSOR DISPLAY UNIT 7007356-906 91080407 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			26-SEP-2011 6744.2 3403			
342341 34.210	PILOT CONTROL DISPLAY PANEL 7007277-901A 87040187 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
342361	COPILOT CONTROL DISPLAY PANEL 7007277-901A	MOS					21-JAN-1999			
34.210	86080126 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:2696 N:1777			2696 1777			
342381	PILOT SWITCH REVERSION PANEL 7007280-901	MOS					11-JAN-1988			
34.220	86110161 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
342391	COPILOT SWITCH REVERSION PANEL 7007280-901	MOS					11-JAN-1988			
34.220	87040189 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
342451	REMOTE CONTROL DISPLAY PANEL 7008703-903	MOS					28-AUG-1989			
34.245	86020102 REF: AMM GENERIC 2	HRS/MSC AFL	O/C				360 212			
342541	STAND-BY COMPASS KCA0105W	MOS					11-JAN-1988			
34.270	SAV20/884 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
342601	EFIS 1 BLOWER 030002	MOS					11-JAN-1988			
34.275	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
342611	EFIS 2 BLOWER 030002	MOS					11-JAN-1988			
34.275	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
342701	PILOT PFD DISPLAY SCREEN									
34.030	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
342711	PILOT MFD DISPLAY SCREEN									
34.031	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
342721	COPILOT PFD DISPLAY SCREEN									
34.030	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			27-JUN-2023 8049.2 3853			
342731	COPILOT MFD DISPLAY SCREEN									
34.031	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
342741	ENGINE INSTRUMENT DISPLAY SCREEN									
34.700	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
342751	EFIS CONTROL									
34.590	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
343101	GLIDE NO. 1/ NO. 2 ANTENNA									
34.280	DMN25-2 2019 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344051	MULTIFUNCTION DISPLAY PROCESSOR UNIT									
34.285	7009289-803 87100161 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				15-JAN-2002 3702 2174			
344061	MULTIFUNCTION DISPLAY CONTROL									
34.285	7007062-803 85080143 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-JAN-2007 5011.8 2596			
344121	RADAR ANTENNA									
34.295	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
344131	RADAR WAVE GUIDE									
34.295	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
344141	PILOT RADAR CONTROL									
34.300	7008471-801 88030349 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				14-JUL-1989 311 195			
344151	COPILOT RADAR CONTROL									
34.300	7006921-301 NOT INST. REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344156	MLS ANTENNA									
34.410	810001-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344241	INTERTIAL SYSTEM DISPLAY UNIT									
34.315	CG1230AC10 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344261	NO. 1 MODE SELECTOR UNIT									
34.320	CG1042AB03 433 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344281	NO. 2 MODE SELECTOR UNIT									
34.320	CG1042AB03 419 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344301	NO. 3 MODE SELECTOR UNIT									
34.320	CG1042AB03 NOT INST. REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344441	NO. 1 IRU BLOWER									
34.380	10089782-105 DW3901 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344461	NO. 2 IRU BLOWER									
34.380	10089782-105 PK6737 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
344481	NO. 3 IRU BLOWER									
34.385	10089782-105 NOT INST. REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344A16	CHECKLIST MODULE 7990056-132 86060196 REF:	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
345101 34.390	NO. 1 ADF CONTROL 622-6522-005 2967 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345111 34.390	NO. 2 ADF CONTROL 622-6522-005 2962 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345121 34.400	NO. 1 ADF RECEIVER 622-2873-001 555 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345131 34.400	NO. 2 ADF RECEIVER 622-2873-001 556 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345141 34.410	NO. 1 ADF LOOP ANTENNA 622-2363-001 20183 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345151 34.410	NO. 2 ADF LOOP ANTENNA 622-2363-001 20187 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345201	NO. 1 VOR/DME CONTROL									
34.420	622-6521-013 14507 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JAN-2003 3998.2 2279			
345211	NO. 2 VOR/DME CONTROL									
34.420	622-6521-013 9360 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:34			30-DEC-2021 7948.3 3821			
345221	NO. 1 VOR/ILS/MARKER RECEIVER									
34.430	622-6137-201 4906 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				17-JUN-2008 5417.7 2752			
345231	NO. 2 VOR/ILS/MARKER RECEIVER									
34.430	622-6137-201 4987 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				17-JUN-2008 5417.7 2752			
345301	NO. 1 DME TRANSCEIVER									
34.450	622-6263-001 4607 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:7675			28-NOV-2018 7675 3744			
345311	NO. 2 DME TRANSCEIVER									
34.450	622-6263-001 4603 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:178 R:3439.1 R:1392			28-NOV-2018 7675 3744			
345401	NO. 1 ATC CONTROL									
34.470	G7624-121 75 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-NOV-2004 4535.8 2438			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345411	NO. 2 ATC CONTROL									
34.470	PN NOT INSTALLED REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				24-NOV-2004 4535.8 2438			
345421	NO. 1 ATC TRANSPONDER									
34.480	7510700-951 RCE00197 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:70 N:542.1 N:146			05-NOV-2021 7940.3 3817			
345431	NO. 2 ATC TRANSPONDER									
34.490	75010700-951 RCE96772 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:204 N:3404.5 N:1379			05-NOV-2021 7940.3 3817			
345461	NO. 1 ADF ADAPTER									
34.600	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
345471	NO. 2 ADF ADAPTER									
34.600	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
345501	VLF/OMEGA RECEIVER/ PROCESSOR UNIT									
34.510	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
345511	VLF/OMEGA ANTENNA									
34.510	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345A03	GPS SENSOR HG2021GB01 94030283 REF:	MOS HRS/MSC AFL	O/C				13-MAR-1995 1718 1207			
345A04	GPS ANTENNA 013-00244-00 23061 REF:	MOS HRS/MSC AFL	O/C				27-JUN-2023 8049.2 3853			
345A30	TCAS COMPUTER 7517900-55020 97100166 REF:	MOS HRS/MSC AFL APH	O/C	R:1 R:0 R:0			29-AUG-2016 7448.9 3681			
346101 34.230	PILOT FMS CONTROL DISPLAY 7007549-901 89040537 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			17-MAR-2009 5740.7 2903			
346121 34.230	COPILOT FMS CONTROL DISPLAY 7007549-901 88100465 REF:	MOS HRS/MSC AFL	O/C				09-SEP-1998 2580 1723			
346141 34.240	PILOT FMS COMPUTER 7018879-03014 97011303 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:71 R:1827.9 R:704			11-DEC-2009 6063.8 3056			
346161 34.240	COPILOT FMS COMPUTER 7018879-03014 96061063 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:71 R:1827.9 R:704			11-DEC-2009 6063.8 3056			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
346181	FMS DATA LOADER									
34.230	G7226-01 1401 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-APR-2018 7633.9 3730			
346211	NO. 1 FMS CONFIGURATION MODULE									
34.610	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
346221	NO. 2 FMS CONFIGURATION MODULE									
34.610	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
346231	NO. 3 FMS CONFIGURATION MODULE									
34.610	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
346741	NO. 1 DATA ACQUISITION UNIT									
34.630	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
346751	NO. 2 DATA ACQUISITION UNIT									
34.630	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
349101	HEADS UP DISPLAY OVERHEAD UNIT									
34.640	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
349106	HEADS UP DISPLAY COMBINER									
34.650	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
349111	HEADS UP DISPLAY CONTROL									
34.660	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
349116	HEADS UP DISPLAY FAN									
34.670	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
349121	HEADS UP DISPLAY COMPUTER									
34.680	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
349126	HEADS UP DISPLAY LOW SPEED DETECTOR									
34.690	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
CHAPTER 35 OXYGEN										
35-00-00-360-801-01	LOCALIZATION AND REPAIR OF LEAKS ON THE OXYGEN SYSTEM									
	REF: AMM 35-00-00-360-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
35-00-00-910-801-01	OXYGEN SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS									
	REF: AMM 35-00-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-10-00-790-801-01	LEAK CHECK OF THE CREW OXYGEN SYSTEM	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-10-00-790-801									
35-10-05-100-801-01	CLEANING OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-10-05-100-801									
35-10-05-100-801-02	CLEANING OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-10-05-100-801									
35-10-05-100-801-03	CLEANING OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-10-05-100-801									
35-10-05-350-801-01	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - LH PILOT OXYGEN MASK (L502WH)	MOS HRS/MSC AFL	72	+3%			27-JUN-2023 8049.2 3853	27-JUN-2029	31-AUG-2029	2171 d (+65)
35.060 OVERHAUL	MC10-12-152 110221 REF: AMM 35-10-05-350-801									
35-10-05-350-801-02	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - RH PILOT OXYGEN MASK (R502WH)	MOS HRS/MSC AFL	72	+3%			27-JUN-2023 8049.2 3853	27-JUN-2029	31-AUG-2029	2171 d (+65)
35.060 OVERHAUL	MC10-12-152 88642 REF: AMM 35-10-05-350-801									
+ 35-10-05-350-801-03	RESTORATION OF THE CREW OXYGEN MASKS (OVERHAUL) - THIRD CREW MEMBER OXYGEN MASK (524WH)	MOS HRS/MSC AFL	O/C							
	289-601-228 SN-UNKNOWN REF: AMM 35-10-05-350-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-10-05-710-801-01 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH) PKG 15	MOS	12	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 35-10-05-710-801	HRS/MSC AFL								
35-10-05-710-801-02 (s)	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH) PKG 15	MOS	12	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 35-10-05-710-801	HRS/MSC AFL								
+ 35-10-05-710-801-03	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)	MOS					11-JAN-1988 0 0			
	REF: AMM 35-10-05-710-801	HRS/MSC AFL	O/C							
35-10-05-900-801-01	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH) MC10-12-152 110221	MOS		O:0			27-JUN-2023 8049.2 3853			
35.060	REF: AMM 35-10-05-900-801	HRS/MSC AFL	H/T	O:0 O:0						
35-10-05-900-801-02	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH) MC10-12-152 88642	MOS		O:0			27-JUN-2023 8049.2 3853			
35.060	REF: AMM 35-10-05-900-801	HRS/MSC AFL	H/T	O:0 O:0						
35-10-05-900-801-03	REMOVAL / INSTALLATION OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH) 289-601-228 SN-UNKNOWN	MOS		N:0			05-OCT-2009 6001.5 3018			
35.160	REF: AMM 35-10-05-900-801	HRS/MSC AFL	O/C	N:0 N:0						
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS PKG 16	MOS	24	+1m			PKG 21-JUN-2023 8047.2 3851			
35.250	REF: AMM 35-20-00-210-801	HRS/MSC AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG			
35.090	PKG 21	MOS					11-NOV-2015			
	REF: AMM 35-20-00-720-801	HRS/MSC	1600	+40			7355.5			
		AFL					3656			
35-20-00-790-801-01	LEAK CHECK OF THE PASSENGERS OXYGEN SYSTEM									
		MOS					11-JAN-1988			
	REF: AMM 35-20-00-790-801	HRS/MSC	O/C				0			
		AFL					0			
35-20-01-350-801-01	RESTORATION OF THE PASSENGER OXYGEN CONTROLLER (OVERHAUL) - PASSENGER OXYGEN CONTROLLER (1WH)									
35.110	RCA74-03	MOS	72	+3%			19-NOV-2019	19-NOV-2025	23-JAN-2026	855 d (+65)
OVERHAUL	1363	HRS/MSC					7805.2			
	REF: AMM 35-20-01-350-801	AFL					3779			
35-20-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN CONTROLLER - PASSENGER OXYGEN CONTROLLER (1WH)									
35.110	RCA74-03	MOS					17-JUN-2008			
	1363	HRS/MSC	H/T				5417.7			
	REF: AMM 35-20-01-900-801	AFL					2752			
35-20-05-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DROP-OUT BOXES									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 35-20-05-900-801	AFL					0			
35-20-09-860-801-01	PACKING OF THE PASSENGER OXYGEN MASKS									
		MOS					11-JAN-1988			
	REF: AMM 35-20-09-860-801	HRS/MSC	O/C				0			
		AFL					0			
35-20-09-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER OXYGEN MASKS									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 35-20-09-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-20-09-960-802-01	REPLACEMENT OF THE FLEXIBLE TUBE SLEEVE ON PASSENGER OXYGEN MASKS	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-20-09-960-802									
35-21-05-160-801-01	CLEANING OF THE RILSAN TUBE ASSEMBLIES	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 35-21-05-160-801									
35-21-05-210-801-01	INSPECTION OF THE RILSAN TUBE ASSEMBLY	MOS HRS/MSC AFL APH	N/A				11-JAN-1988 0 0 0			
	REF: AMM 35-21-05-210-801									
35-21-05-900-801-01	REMOVAL / INSTALLATION OF THE RILSAN TUBE ASSEMBLIES	PN SN-UNKNOWN REF: AMM 35-21-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		11-JAN-1988 0 0			
35-21-20-900-801-01	FIRST AID OXYGEN CYLINDER	6350-894-20330 588203 REF: AMM 35-40-01-900-801	MOS HRS/MSC AFL	O/C			04-DEC-2017 7593.7 3722			
35-30-01-960-801-01	DISCARD OF THE SMOKE HOOD - SMOKE HOOD (508WH)	802300-14 E18120361 REF: AMM 35-30-01-960-801	MOS HRS/MSC AFL	120			01-JUN-2020 7851.7 3788	01-JUN-2030		2510 d
	35.230 LIFE LIMIT									
35-30-01-960-801-02	DISCARD NO. 2 PROTECTIVE BREATHING EQUIPMENT HOOD	802300-14 E18120362 REF:	MOS HRS/MSC AFL	120			01-JUN-2020 7851.7 3788	01-JUN-2030		2510 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 35-30-05-210-801-01	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									
35.240	894-20330 588203 REF: AMM 35-30-05-210-801	MOS HRS/MSC AFL	12	+3%			27-JUN-2023 8049.2 3853	27-JUN-2024	07-JUL-2024	345 d (+10)
+ 35-30-05-350-801-01	RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									
35.050 OVERHAUL	894-20330 588203 REF: AMM 35-30-05-350-801	MOS HRS/MSC AFL	60	+3%			01-APR-2023	01-APR-2028	25-MAY-2028	1719 d (+54)
35-30-05-610-801-01	REFILLING OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									
	REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
35-30-05-960-801-01	DISCARD OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									
	894-20330 588203 REF: AMM 35-30-05-960-801	MOS HRS/MSC AFL	O/C							
+ 35-30-09-100-801-01	CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)									
35.050	894-20330 588203 REF: AMM 35-30-09-100-801	MOS HRS/MSC AFL	12	+3%			27-JUN-2023 8049.2 3853	27-JUN-2024	07-JUL-2024	345 d (+10)
35-40-01-610-801-01	REFILLING OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									
	REF: AMM 35-40-01-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 35-40-01-720-801-01	FUNCTIONAL TEST OF THE OXYGEN CYLINDER AND REGULATOR ASSEMBLY - OXYGEN CYLINDER (500WH)									
	176220 964312101 REF: AMM 35-40-01-720-801	MOS HRS/MSC AFL	60				10-JUN-2021	10-JUN-2026		1058 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-40-01-790-801-01	HYDROSTATIC TEST OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									
35.010	176220 964312101 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				10-JUN-2021			
35-40-01-900-801-01	REMOVAL / INSTALLATION OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									
35.010	176220 964312101 REF: AMM 35-40-01-900-801	MOS HRS/MSC AFL	H/T	O:6 O:0 O:0			17-DEC-2021 7940.3 3817			
35-40-01-960-801-01	DISCARD OF THE OXYGEN CYLINDER - OXYGEN CYLINDER (500WH)									
35.010	176220 964312101 REF: AMM 35-40-01-960-801	MOS HRS/MSC AFL	180				01-MAY-2018	01-MAY-2033		3575 d
LIFE LIMIT										
35-40-05-720-801-01	FUNCTIONAL TEST OF THE OXYGEN CYLINDER PRESSURE REDUCING VALVE									
35.010	172203 0335 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				29-OCT-2015 7355.5 3656			
350121	OXYGEN PRESSURE REDUCER VALVE									
35.010	172203 0335 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			17-DEC-2010 6512.1 3296			
350141	HP OXYGEN PRESSURE BOTTLE GAGE									
35.030	CMT150 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
350161	OXYGEN FILLER VALVE									
35.040	DKR131 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
350201	PORTABLE OXYGEN BOTTLE									
35.050	894-20330 588203 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	O:66 O:455.5 O:131			27-JUN-2023 8049.2 3853			
351121	PILOT OXYGEN MASK HOSE									
35.070	DTF44A435 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:10			11-JAN-1988 0 0			
351131	PILOT OXYGEN CONNECTOR									
35.080	DPB179 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0			11-JAN-1988 0 0			
351171	COPILOT OXYGEN MASK HOSE									
35.070	DTF55A350 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:11			11-JAN-1988 0 0			
351181	COPILOT OXYGEN CONNECTOR									
35.080	DPB179 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
352111	NO. 1 PASSENGER OXYGEN MASK									
35.120	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352121	NO. 2 PASSENGER OXYGEN MASK									
35.120	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
352131	NO. 3 PASSENGER OXYGEN MASK									
35.120	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352141	NO. 4 PASSENGER OXYGEN MASK									
35.130	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352151	NO. 5 PASSENGER OXYGEN MASK									
35.130	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352161	NO. 6 PASSENGER OXYGEN MASK									
35.130	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352171	NO. 7 PASSENGER OXYGEN MASK									
35.140	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352181	NO. 8 PASSENGER OXYGEN MASK									
35.140	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352191	NO. 9 PASSENGER OXYGEN MASK									
35.140	289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
352201	NO. 10 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352211	NO. 11 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352221	NO. 12 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM 35-20-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352261	NO. 1 FIRST AID MASK 289-601-228 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352271	NO. 2 FIRST AID MASK 289-601-228 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352281	NO. 1 LAVATORY OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352291	NO. 2 LAVATORY OXYGEN MASK 289-601-228 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
352A21	OXYGEN PASSENGER #13 MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
352A22	OXYGEN PASSENGER #14 MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-OCT-2009 6001.5 3018			
353101 35.230	PROTECTIVE BREATHING EQUIPMENT HOOD 802300-14 E18120361 REF: AMM GENERIC 2	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			01-JUN-2020 7851.7 3788			
353102	NO. 2 PROTECTIVE BREATHING EQUIPMENT HOOD 802300-14 E18120362 REF:	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			01-JUN-2020 7851.7 3788			
CHAPTER 36 PNEUMATIC										
21-71-01-900-801-01 36.030	REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - LH OZONE CONVERTER (L517HN) D20425-1 0166 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
21-71-01-900-801-02 36.030	REMOVAL / INSTALLATION OF THE OZONE CONVERTERS - RH OZONE CONVERTER (R517HN) D20425-1 0145 REF: AMM 21-71-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
36-10-00-790-801	LEAK CHECK OF THE BLEED AIR SYSTEM AFTER COMPONENT INSTALLATION REF: AMM 36-10-00-790-801	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
36-10-00-790-801-01	LEAK CHECK OF THE BLEED AIR SYSTEM AFTER COMPONENT INSTALLATION	MOS					11-JAN-1988			
	REF: AMM 36-10-00-790-801	HRS/MSC O/C					0			
		AFL					0			
36-10-21-710-801-01	OPERATIONAL TEST OF THE BLEED AIR ISOLATION VALVE - BLEED AIR ISOLATION ELECTRIC VALVE (23HU)	MOS					11-JAN-1988			
	REF: AMM 36-10-21-710-801	HRS/MSC O/C					0			
		AFL					0			
36-10-29-280-801	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 HP BLEED AIR PIPE	MOS					11-JAN-1988			
	REF: AMM 36-10-29-280-801	HRS/MSC A/R					0			
		AFL					0			
36-10-29-280-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 HP BLEED AIR PIPE	MOS					22-OCT-2015			
36.010	REF: AMM 36-10-29-280-801	HRS/MSC O/C					7355.5			
		AFL					3656			
36-10-33-350-801-01	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (OVERHAUL) - ENGINE 1 ARTICULATED PIPE (L510HU)	MOS					21-OCT-2011			
36.040	B45CB1120	HRS/MSC	5000/E/C	+150			6781.4	11781.4	11931.4	3732.2 (+150)
OVERHAUL	REF: AMM 36-10-33-350-801	AFL					3423			
36-10-33-350-801-02	RESTORATION OF THE BLEED AIR ARTICULATED PIPES (OVERHAUL) - ENGINE 3 ARTICULATED PIPE (R510HU)	MOS					07-DEC-2005			
36.040	B45CB1120	HRS/MSC	5000/E/C	+150	I:0		4794	9794	9944	1744.8 (+150)
OVERHAUL	REF: AMM 36-10-33-350-801	AFL			I:0		2516			
36-10-33-900-801-01	REMOVAL / INSTALLATION OF THE BLEED AIR ARTICULATED PIPES - ENGINE 1 ARTICULATED PIPE (L510HU)	MOS					07-DEC-2005			
36.040	B45CB1120	HRS/MSC	H/T		O:0		4794			
	REF: AMM 36-10-33-900-801	AFL			O:0		2516			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
36-10-33-900-801-02	REMOVAL / INSTALLATION OF THE BLEED AIR ARTICULATED PIPES - ENGINE 3 ARTICULATED PIPE (R510HU)									
36.040	B45CB1120 T797 REF: AMM 36-10-33-900-801	MOS HRS/MSC AFL	H/T	O:0 O:0 O:0			07-DEC-2005 4794 2516			
36-21-00-720-801-01	FUNCTIONAL TEST OF THE BLEED AIR OVERHEATING WARNING SYSTEM									
	REF: AMM 36-21-00-720-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
36-21-17-900-801-01	REMOVAL / INSTALLATION OF THE OVERHEATING DETECTION BOX									
36.120	EL137-00 184 REF: AMM 36-21-17-900-801	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			10-DEC-2004 4545.5 2444			
361101	NO. 1 ENGINE LOW PRESSURE BLEED CHECK VALVE									
36.020	CYLB51161-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361111	NO. 2 ENGINE LOW PRESSURE BLEED CHECK VALVE									
36.020	CYLB51161-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361121	NO. 3 ENGINE LOW PRESSURE BLEED CHECK VALVE									
36.020	CYLB51161-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361191	NO. 1 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE									
36.050	CYLB51161-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361201	NO. 3 ENGINE LOW PRESSURE INTERCOMMUNICATION CHECK VALVE CYLB51161-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361211	NO. 2 ENGINE HIGH PRESSURE CHECK VALVE CYLB50713-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361221	APU BLEED AIR CHECK VALVE CYLB50713-1 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361241	NO. 2 ENGINE PRESSURE REGULATING (PRV2) VALVE 3214730-2 188 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361251	NO. 3 ENGINE PRESSURE REGULATING (PRV3) VALVE 3214730-2 210 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361261	NO. 2 ENGINE PRV2 3 WAYS ELECTRIC VALVE L92A07-501A 20099 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361271	NO. 3 PRV2 3 WAYS ELECTRIC VALVE L92A07-501A 20072 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361281	NO. 1 HIGH PRESSURE AIR BLEED VALVE B48CB1041A-C 141 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
361291	BLEED AIR ISOLATION ELECTRIC VALVE B48CA1121 T518 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				25-SEP-1995 1855 1308			
362101	AIR BLEED INDICATING CONTROL EL125-02 101 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				04-FEB-2011 6561.2 3315			
362151	NO. 1 ENGINE THERMOCOUPLE SENSOR RP161-00 373 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-NOV-1992 1213 825			
362161	NO. 2 ENGINE THERMOCOUPLE SENSOR RP161-00 374 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-NOV-1992 1213 825			
362171	NO. 3 ENGINE THERMOCOUPLE SENSOR RP161-00 375 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-NOV-1992 1213 825			
362181	NO. 1 ENGINE THERMOCOUPLE SENSOR RP129-00 413 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
362191	NO. 2 THERMOCOUPLE SENSOR									
36.140	RP129-02 5822 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			13-FEB-2007 5022.8 2602			
362201	NO. 3 ENGINE THERMOCOUPLE SENSOR									
36.140	RP129-02 2371 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUN-1992 1095 758			
CHAPTER 38 WATER/WASTE										
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SYSTEM						PKG			
38.080	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
38-00-00-910-801-01	WATER SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS									
	REF: AMM 38-00-00-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
38-10-00-210-801-01 (s)	DETAILED INSPECTION OF WATER SYSTEM COMPONENTS						PKG			
	PKG 31 REF: AMM 38-10-00-210-801	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
38-10-00-610-801-01	PRESSURE REFILLING OF THE POTABLE WATER SYSTEM									
	REF: AMM 38-10-00-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
38-10-00-610-802-01	GRAVITY REFILLING OF THE POTABLE WATER SYSTEM									
	REF: AMM 38-10-00-610-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION									
38.010		MOS	6	+1m		-61	27-JUN-2023 8049.2 3853	27-OCT-2023	27-NOV-2023	101 d (+31)
	REF: AMM 38-10-00-670-801	HRS/MSC AFL								
38-10-00-670-801-02	STERILIZATION OF THE POTABLE WATER SYSTEM - SHOCK TREATMENT									
		MOS					11-JAN-1988 0 0			
	REF: AMM 38-10-00-670-801	HRS/MSC AFL	O/C							
38-10-00-680-801-01	DRAINING OF THE POTABLE WATER SYSTEM									
		MOS					11-JAN-1988 0 0			
	REF: See Workcard	HRS/MSC AFL	O/C							
38-10-00-720-801-01	FUNCTIONAL TEST OF THE WATER SUPPLY SYSTEM									
		MOS					11-JAN-1988 0 0			
	REF: See Workcard	HRS/MSC AFL	O/C							
38-10-00-860-801-01	PRESSURIZATION OF THE POTABLE WATER SYSTEM									
		MOS					11-JAN-1988 0 0			
	REF: AMM 38-10-00-860-801	HRS/MSC AFL	O/C							
38-11-01-900-801-01	REMOVAL / INSTALLATION OF THE POTABLE WATER TANK - POTABLE WATER TANK (620JT)									
	PN	MOS					11-JAN-1988 0 0			
	SN-UNKNOWN	HRS/MSC	O/C							
	REF: AMM 38-11-01-900-801	AFL								
38-13-01-960-801-01	REPLACEMENT OF THE MAIN FILTER CARTRIDGE									
38.020		MOS					02-MAY-2018 7638.1 3733			
	REF: AMM 38-13-01-960-801	HRS/MSC AFL APH	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-13-09-710-801-01	OPERATIONAL TEST OF THE WATER HEATING MONITORING SYSTEM									
38.070		MOS					11-JAN-1988			
	REF: AMM 38-13-09-710-801	HRS/MSC	O/C				0			
		AFL					0			
38-13-09-710-802-01	OPERATIONAL TEST OF THE WATER HEATER SAFETY THERMOSTATS - TEST OF THE WATER HEATER SAFETY THERMOSTATS									
		MOS					11-JAN-1988			
	REF: AMM 38-13-09-710-802	HRS/MSC	O/C				0			
		AFL					0			
38-13-09-900-801-01	REMOVAL / INSTALLATION OF THE REAR WATER HEATER - REAR WATER HEATER (33HR)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 38-13-09-900-801	AFL		N:0			0			
38-13-09-900-802-01	REMOVAL / INSTALLATION OF THE FORWARD WATER HEATER - FWD WATER HEATER (63HR)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 38-13-09-900-802	AFL		N:0			0			
		APH		N:0			0			
38-15-01-680-801-01	DRAINING OF THE UV STERILIZER - AFT VANITY UV STERILIZER (7442MT)									
		MOS					11-JAN-1988			
	REF: AMM 38-15-01-680-801	HRS/MSC	O/C				0			
		AFL					0			
38-15-01-710-801-01	OPERATIONAL TEST OF THE UV STERILIZER - AFT VANITY UV STERILIZER (7442MT)									
		MOS					11-JAN-1988			
	REF: AMM 38-15-01-710-801	HRS/MSC	O/C				0			
		AFL					0			
		APH					0			
38-15-01-900-802-01	REMOVAL / INSTALLATION OF THE AFT LAVATORY UV STERILIZER - AFT VANITY UV STERILIZER (7442MT)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 38-15-01-900-802	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-15-01-910-801-01	DISABLING / ENABLING THE UV STERILIZER(S) FOR COLD WEATHER OPERATION - DISABLING THE UV STERILIZER(S)	MOS						11-JAN-1988		
	REF: AMM 38-15-01-910-801	HRS/MSC	O/C					0		
		AFL						0		
38-15-01-910-801-02	DISABLING / ENABLING THE UV STERILIZER(S) FOR COLD WEATHER OPERATION - ENABLING THE UV STERILIZER(S)	MOS						11-JAN-1988		
	REF: AMM 38-15-01-910-801	HRS/MSC	O/C					0		
		AFL						0		
38-15-09-900-801-01	REMOVAL / INSTALLATION OF THE UV LAMP - UV LAMP (9870MT)	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 38-15-09-900-801							0		
38-15-09-960-801-01	REPLACEMENT OF THE UV LAMP - UV LAMP (9870MT)	MOS						11-JAN-1988		
	PN	HRS/MSC	N/A					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 38-15-09-960-801	APH						0		
38-15-17-100-801-01	CLEANING OF THE UV STERILIZER QUARTZ SLEEVE - QUARTZ SLEEVE (9890MT)	MOS						11-JAN-1988		
	REF: AMM 38-15-17-100-801	HRS/MSC	N/A					0		
		AFL						0		
		APH						0		
38-15-17-900-801-01	REMOVAL / INSTALLATION OF THE UV STERILIZER QUARTZ SLEEVE - QUARTZ SLEEVE (9890MT)	MOS		N:0				11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 38-15-17-900-801							0		
38-30-00-100-801-01	CLEANING OF THE WATER TRAP FILTER IN WASH HANDBASIN DRAINAGE SYSTEM	MOS						15-MAY-2006		
38.060	REF: AMM 38-30-00-100-801	HRS/MSC	O/C					4812.3		
		AFL						2521		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-30-00-710-801-01	OPERATIONAL TEST OF THE DRAIN MAST ANTI-ICING SYSTEMS	MOS						11-JAN-1988		
	REF: AMM 38-30-00-710-801	HRS/MSC	O/C					0		
		AFL						0		
38-30-05-960-801-01	REPLACEMENT OF THE WATER DRAIN MAST THERMOSTATS - THERMOSTAT (17HA)	MOS						11-JAN-1988		
	REF: AMM 38-30-05-960-801	HRS/MSC	O/C					0		
		AFL						0		
38-30-05-960-801-02	REPLACEMENT OF THE WATER DRAIN MAST THERMOSTATS - THERMOSTAT (19HA)	MOS						11-JAN-1988		
	REF: AMM 38-30-05-960-801	HRS/MSC	O/C					0		
		AFL						0		
38-31-01-900-801-01	REMOVAL / INSTALLATION OF THE FRONT DRAIN MAST - FRONT DRAIN MAST (25HA)	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: See Workcard			N:0				0		
38-31-13-160-801-01	CLEANING OF THE STRAINER	MOS						11-JAN-1988		
	REF: AMM 38-31-13-160-801	HRS/MSC	O/C					0		
		AFL						0		
38-31-13-960-801-01	REPLACEMENT OF THE GALLEY WATER FILTER	MOS						11-JAN-1988		
	REF: See Workcard	HRS/MSC	O/C					0		
		AFL						0		
38-31-17-200-801-01	INSPECTION OF THE DRAIN BOX - DRAIN BOX (905MD)	MOS						11-JAN-1988		
38.090	REF: AMM 38-31-17-200-801	HRS/MSC	O/C					0		
		AFL						0		
		APH						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-32-01-900-801-01	REMOVAL / INSTALLATION OF THE REAR DRAIN MAST - REAR DRAIN MAST (23HA) PN SN-UNKNOWN REF: AMM 38-32-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
38-34-00-600-801-01	DRAINING AND FILLING OF THE TOILETS REF: See Workcard	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
38-34-01-900-801-01	REMOVAL / INSTALLATION OF THE FORWARD TOILET ASSEMBLY - FORWARD TOILET ASSEMBLY (700MX) PN SN-UNKNOWN REF: AMM 38-34-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
38-34-09-900-801-01	REMOVAL / INSTALLATION OF THE AFT TOILET ASSEMBLY - AFT TOILET ASSEMBLY (2MX) PN SN-UNKNOWN REF: AMM 38-34-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
38-34-17-210-801-01	GENERAL VISUAL INSPECTION OF THE FORWARD TOILET DRAIN CONTROL - FORWARD TOILET DRAIN CONTROL (525MD) REF: AMM 38-34-17-210-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
38-34-21-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL - AFT TOILET DRAIN CONTROL (516MD) PKG 17 REF: AMM 38-34-21-210-801	MOS HRS/MSC AFL	36	+1m			PKG 21-JUN-2023 8047.2 3851			
38-34-21-900-801-01	REMOVAL / INSTALLATION OF THE AFT TOILET DRAIN CONTROL - AFT TOILET DRAIN CONTROL (516MD) PN SN-UNKNOWN REF: AMM 38-34-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-40-17-900-801-01	REMOVAL / INSTALLATION OF THE HIGH PRESSURE REGULATOR AIR FILTER ASSEMBLY - HIGH-PRESSURE REGULATOR / AIR FILTER ASSEMBLY (600HU)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 38-40-17-900-801	AFL		N:0			0			
38-40-21-900-801-01	REMOVAL / INSTALLATION OF THE LOW PRESSURE REGULATOR AIR FILTER ASSEMBLY - LOW PRESSURE REGULATOR / AIR FILTER ASSEMBLY (607HU)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 38-40-21-900-801	AFL		N:0			0			
381151	POTABLE WATER PRESSURE REGULATOR									
	B07-235-AIKA	MOS		N:0			02-JAN-2002			
38.030	SN-UNKNOWN	HRS/MSC	O/C	N:0			3702			
	REF: AMM GENERIC 2	AFL		N:0			2174			
381171	POTABLE WATER TWO WAYS VALVE									
	879B14-13	MOS		N:0			11-JAN-1988			
38.040	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 2	AFL		N:0			0			
381201	POTABLE WATER FILLING PLUG									
	FGFB838001210A1	MOS		N:0			11-JAN-1988			
38.040	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM GENERIC 2	AFL		N:0			0			
381A31	HEATER DRAIN ELEMENT									
	115855-4	MOS		N:0			27-APR-2009			
	848	HRS/MSC	O/C	N:0			5771.6			
	REF:	AFL		N:0			2919			
		APH								

CHAPTER 45 CENTRAL MAINT SYSTEM

45-00-00-700-801-01	RS-232 OR SSH CONNECTION USING A TERMINAL EMULATOR TOOL									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 45-00-00-700-801	AFL					0			

CHAPTER 46 INFORMATION SYSTEMS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
46-20-02-720-801-01	FUNCTIONAL TEST OF THE EDU BATTERIES - LH EDU (L7101NS) PN NOT INSTALLED REF: AMM 46-20-02-720-801	MOS HRS/MSC AFL	N/A							
46-20-02-720-801-02	FUNCTIONAL TEST OF THE EDU BATTERIES - RH EDU (R7101NS) PN NOT INSTALLED REF: AMM 46-20-02-720-801	MOS HRS/MSC AFL	N/A							
46-90-03-900-801-01	PILOT ELECTRONIC FLIGHT BAG (EFB) UNIT PN NOT INSTALLED REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				16-NOV-2016 7448.9 3681			
46-90-03-900-801-02	COPILOT ELECTRONIC FLIGHT BAG (EFB) UNIT PN NOT INSTALLED REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				16-NOV-2016 7448.9 3681			
CHAPTER 49 AIRBORNE AUXILIARY POWER										
49-00-00-860-801-01	PREPARATION FOR FLIGHT WITHOUT APU REF: AMM 49-00-00-860-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
49-10-01-900-801-01	REMOVAL / INSTALLATION OF THE APU CUSTOMIZATION PN SN-UNKNOWN REF: AMM 49-10-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
49-10-01-900-802-01	REMOVAL / INSTALLATION OF THE APU - APU (500HT) PN SN-UNKNOWN REF: AMM 49-10-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
49-10-01-900-803-01	REMOVAL / INSTALLATION OF THE APU ECU - APU ECU (12HT)									
49.030	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
49-91-00-610-801-01	SERVICING OF THE APU OIL									
	REF: AMM 49-91-00-610-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
496101	APU T5 INDICATOR									
49.155	2396-507-00-10 172 REF: AMM GENERIC 2	MOS HRS/MSC AFL APH APS	O/C	N:0			11-JAN-1988 0 0			
496201	APU TACHOMETER									
49.155	2396-506-00-10 170 REF: AMM GENERIC 2	MOS HRS/MSC AFL APH APS	O/C	N:0			11-JAN-1988 0 0			
49APU1	APU									
	3800188-1 P-139 REF: AMM GENERIC 2	MOS HRS/MSC AFL	E/C							
APU Model : GTCP36-150(F) Serial # P-139 Part # 3800188-1										
49-10-01-900-803-01	APU - REMOVAL / INSTALLATION OF THE APU ECU - APU ECU (12HT)									
49.030	3882730-2 A303 REF: AMM GENERIC 2	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
491010	APU - TURBINE ROTOR									
LIFE LIMIT	3615880-1 5-0145-4555 REF: GENERIC NO REF	MOS HRS/MSC APUS	10000	N:0			27-SEP-1995 926 0	10926		7170



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
491020	APU - COMPRESSOR ROTOR 3822101-1 8-03501-4891 REF: GENERIC NO REF	MOS HRS/MSC APUS	100000	N:0			27-SEP-1995 926 0	100926		97170
LIFE LIMIT										
491025	APU - VISUAL CHECK COMPRESSOR ROTOR 3822101-1 8-03501-4891 REF: MM 49-20-00	MOS HRS/MSC APUS	4500				03-OCT-1995 926 0	5426		1670
493020	APU - REMOVE AND REPLACE FUEL CONTROL FUEL FILTER ELEMENT 3882730-2 A303 REF: MM 49-30-52	MOS HRS/MSC APUS	1000				27-JUN-2023 3756	4756		1000
493030	APU - ORIFICE FITTING 3606721-1 SN-UNKNOWN REF: MM 49-30-56	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
493040	APU - FUEL SHUTOFF VALVE 692545-17 SN-UNKNOWN REF: MM 49-30-54	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
+ 493050	APU - CHECK FUEL NOZZLE FLOW RATE REF: MM 49-20-00	MOS HRS/MSC APUS	4500				03-OCT-1995 926 0	5426		1670
493060	APU - CONTROLLER 2118306-2 88-244 REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	N:0 N:0			24-OCT-1988 76 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
493070	APU - LOAD CONTROL VALVE 109812-3-1 703 REF: MM 49-50-33	MOS HRS/MSC APUS	O/C	O:0 O:0 O:0			27-SEP-2005			
494010	APU - IGNITION UNIT 3888000-2 87046510 REF: MM 49-40-32	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
494020	APU - IGNITOR PLUG 3888002-2 SN-UNKNOWN REF: MM 49-40-33	MOS HRS/MSC APUS	O/C	N:0 N:0			03-OCT-1995 926 0			
+ 494030	APU - INSPECT/CLEAN IGNITOR PLUG 3888002-2 SN-UNKNOWN REF: MM 49-40-33	MOS HRS/MSC APUS	750				19-SEP-2011 3223	3973		217
497010	APU - MOTION PICK UP TRANSDUCER 3876104-1 55386 REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			17-MAR-2008 247			
497020	APU - IMMERSION THERMOCOUPLE 3876003-3 SN-UNKNOWN REF: MM 49-60-45	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
497030	APU - HOURMETER 3888126-1 SN-UNKNOWN REF: MM 49-70-41	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
499010	APU - ROTARY OIL PUMP 3880225-2 SN-UNKNOWN REF: MM 49-90-51	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
+ 499020	APU - REMOVE AND INSPECT MAGNETIC DRAIN PLUG REF: MM 49-90-46	MOS HRS/MSC APUS	17 750				27-JUN-2023 3756	27-NOV-2024 4506		498 d 750
499030	APU - DRAIN AND REFILL OIL REF: MM 49-20-00	MOS HRS/MSC APUS	17 750				27-JUN-2023 3756	27-NOV-2024 4506		498 d 750
499040	APU - REMOVE AND REPLACE OIL FILTER ELEMENT REF: MM 49-90-47	MOS HRS/MSC APUS	17 750				27-JUN-2023 3756	27-NOV-2024 4506		498 d 750
499050	APU - PRESSURE REGULATING VALVE 3880021-13 SN-UNKNOWN REF: MM 49-90-52	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
499060	APU - HIGH OIL TEMPERATURE SWITCH 3888030-1 SN-UNKNOWN REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	N:0			11-JAN-1988 0 0			
499070	APU - LOW OIL PRESSURE SWITCH 3876001-6 0054 REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	N:0 N:0			11-APR-1991 388 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
499110	APU - SOAP CHECK OIL	MOS						22-MAR-2017		
	REF: SIL SIL APU-49	HRS/MSC	O/C					3560		
		APUS						5865		
CHAPTER 51 STD PRACTICES AND STRUCT-GENRL										
+ 51-00-00-200-801-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 12 M OR 800 FH INSPECTION						PKG			
	PKG 5	MOS	12					21-JUN-2023		
	REF: AMM 51-00-00-200-801	HRS/MSC	800					8047.2		
		AFL						3851		
+ 51-00-00-200-802-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 24 M OR 1600 FH INSPECTION						PKG			
	PKG 6	MOS	24					21-JUN-2023		
	REF: AMM 51-00-00-200-802	HRS/MSC	1600					8047.2		
		AFL						3851		
+ 51-00-00-200-803-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 1C INSPECTION						PKG			
	PKG 31	MOS	72					21-JUN-2023		
	REF: AMM 51-00-00-200-803	HRS/MSC						8047.2		
		AFL	3750					3851		
+ 51-00-00-200-804-01 (s)	INSPECTION OF CORROSION INHIBITOR COMPOUND DURING 2C INSPECTION						PKG			
	PKG 32	MOS	144					21-JUN-2023		
	REF: AMM 51-00-00-200-804	HRS/MSC						8047.2		
		AFL	7500					3851		
51-30-00-220-802-01	DETAILED INSPECTION OF THE INTERNAL COMPOSITE MATERIAL COMPONENTS									
51.040		MOS						19-JUL-2012		
	REF: GENERIC NO REF	HRS/MSC	O/C					6985.1		
		AFL						3525		
CHAPTER 52 DOORS										
+ 52-00-00-200-802-01 (s)	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - MAIN ENTRANCE DOOR FRAME SEAL						PKG			
53.100	PKG 31	MOS	72	+2m				21-JUN-2023		
	REF: AMM 52-00-00-200-802	HRS/MSC						8047.2		
		AFL	3750					3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-00-00-200-802-02 (s)	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - BAGGAGE COMPARTMENT DOOR FRAME SEAL PKG 31	MOS	72	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 52-00-00-200-802	AFL	3750							
52-00-00-200-802-03 (s)	INSPECTION / CHECK OF THE MAIN ENTRANCE, BAGGAGE COMPARTMENT AND REAR COMPARTMENT DOOR FRAME SEALS - REAR COMPARTMENT DOOR FRAME SEAL PKG 31	MOS	72	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 52-00-00-200-802	AFL	3750							
52-00-00-640-801-01 (s)	LUBRICATION OF SERVICE DOORS PKG 15	MOS	12	+1m			21-JUN-2023 8047.2 3851			
52.010	REF: AMM 52-00-00-640-801	AFL								
52-00-00-700-801-01	CHECK / ADJUSTMENT OF THE HARTWELL LATCHES PN	MOS			N:0		11-JAN-1988 0 0			
	SN-UNKNOWN	HRS/MSC	O/C		N:0					
	REF: AMM 52-00-00-700-801	AFL			N:0					
+ 52-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR COUNTERBALANCING SYSTEM PKG 31	MOS	72	+2m			21-JUN-2023 8047.2 3851			
52.040	REF: AMM 52-10-00-220-801	AFL	3750							
52-10-00-610-801-01 (s)	SERVICING OF THE PASSENGER DOOR PKG 17	MOS	36	+1m			21-JUN-2023 8047.2 3851			
52.030	REF: AMM 52-10-00-610-801	AFL								
52-10-00-610-802-01 (s)	SERVICING OF THE PASSENGER DOOR SAFETY CATCH PKG 17	MOS	36	+1m			21-JUN-2023 8047.2 3851			
	REF: AMM 52-10-00-610-802	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-00-640-801-01 (s)	LUBRICATION OF THE ROLLERS OF THE PASSENGER DOOR LOWER MECHANISM						PKG			
52.120	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 52-10-00-640-801	AFL	7500				3851			
+ 52-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER DOOR						PKG			
52.020	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 52-10-00-720-801	AFL	3750				3851			
52-10-00-820-801-01	ADJUSTMENT OF THE PASSENGER DOOR									
		MOS					11-JAN-1988	0	0	
	REF: AMM 52-10-00-820-801	AFL					0			
52-10-00-820-802-01	ADJUSTMENT OF THE PASSENGER DOOR COUNTERBALANCING SYSTEM									
		MOS					11-JAN-1988	0	0	
	REF: AMM 52-10-00-820-802	AFL					0			
52-10-00-860-801-01	OPENING / CLOSING OF THE PASSENGER DOOR									
		MOS					11-JAN-1988	0	0	
	REF: See Workcard	AFL					0			
52-10-01-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR									
52.030	FGFB295	MOS					11-JAN-1988	0	0	
	37HP	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-10-01-900-801	AFL					0			
52-10-03-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)									
52.045	222900M02	MOS					11-JAN-1988	0	0	
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 52-10-03-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-03-960-801-01	DISCARD OF THE PASSENGER DOOR PNEUMATIC ACTUATOR - PASSENGER DOOR PNEUMATIC ACTUATOR (902MC)									
52.045	222900M02 SN-UNKNOWN REF: AMM 52-10-03-960-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
52-10-05-710-801-01	OPERATIONAL TEST OF THE PASSENGER DOOR ELECTRICAL LIFTING SYSTEM									
	REF: AMM 52-10-05-710-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
52-10-05-900-801-01	REMOVAL / INSTALLATION OF THE PRESSURIZING FLAP SEAL									
	PN SN-UNKNOWN REF: AMM 52-10-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
52-10-09-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR REDUCING GEAR MOTOR - PASSENGER DOOR REDUCING GEAR MOTOR (13MC)									
	PN SN-UNKNOWN REF: AMM 52-10-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
52-10-09-900-802-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR REDUCING GEAR MOTOR PCB - PASSENGER DOOR REDUCING GEAR MOTOR (13MC)									
	PN SN-UNKNOWN REF: AMM 52-10-09-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
52-10-11-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR COUNTERBALANCING LEAF-SPRING ACTUATOR - PASSENGER DOOR COUNTERBALANCING ACTUATOR (500MA)									
52.040	AE40142Z 328514 REF: AMM 52-10-11-900-801	MOS HRS/MSC AFL	H/T	N:0			11-JAN-1988 0 0			
52-10-11-960-801-01	DISCARD OF THE PASSENGER DOOR COUNTERBALANCING LEAF-SPRING ACTUATOR - PASSENGER DOOR COUNTERBALANCING ACTUATOR (500MA)									
52.040	AE40142Z 328514 REF: AMM 52-10-11-960-801	MOS HRS/MSC AFL	8800				11-JAN-1988 0 0		8800	4947
LIFE LIMIT										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-13-960-801-01	REPLACEMENT OF THE PASSENGER DOOR SEAL	MOS						11-JAN-1988		
	REF: AMM 52-10-13-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-10-15-960-801-01	REPLACEMENT OF THE BUSHES ON PASSENGER DOOR TELESCOPIC RODS	MOS						11-JAN-1988		
	REF: AMM 52-10-15-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-10-17-960-801-01	REPLACEMENT OF THE PASSENGER DOOR SAFETY CATCH SPRING	MOS						11-JAN-1988		
	REF: AMM 52-10-17-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-10-19-900-801-01	REMOVAL / INSTALLATION OF THE PASSENGER DOOR HANDRAIL	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 52-10-19-900-801			N:0				0		
52-10-19-900-803-01	REMOVAL / INSTALLATION OF THE SECOND PASSENGER DOOR HANDRAIL - REMOVAL/INSTALLATION OF THE SECOND PASSENGER DOOR HANDRAIL	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	AFL		N:0				0		
	REF: AMM 52-10-19-900-803			N:0				0		
52-10-19-960-801-01	REPLACEMENT OF THE PASSENGER DOOR HANDRAIL SHIMS AND RUBBING RINGS	MOS						11-JAN-1988		
	REF: AMM 52-10-19-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-10-19-960-802-01	REPLACEMENT OF THE SHIMS AND ROLLERS ON PASSENGER DOOR HANDRAIL CARRIAGE	MOS						11-JAN-1988		
	REF: AMM 52-10-19-960-802	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-21-960-801-01	REPLACEMENT / ADJUSTMENT OF THE PASSENGER DOOR STOPS	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 52-10-21-960-801									
52-10-29-300-801-01	REPAIR OF THE AIR STAIR TREAD	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 52-10-29-300-801									
52-10-29-960-801-01	REPLACEMENT OF THE AIR STAIR TREAD	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: AMM 52-10-29-960-801									
52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN	MOS HRS/MSC AFL	24				PKG 21-JUN-2023 8047.2 3851			
52.050	REF: AMM 52-20-00-610-801									
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)	MOS HRS/MSC AFL	24				21-JUN-2023 8047.2 3851	21-JUN-2025		704 d
52.050 MANDATORY 5-40	REF: AMM 52-20-00-610-801									
52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT DOOR	MOS HRS/MSC AFL	24	+1d			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 52-20-00-610-801									
+ 52-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM OUTSIDE	MOS HRS/MSC AFL	1600	+40			PKG 11-NOV-2015 7355.5 3656			
52.050	REF: AMM 52-20-00-710-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-20-00-720-801-01	FUNCTIONAL TEST OF THE EMERGENCY EXIT DOOR UNLOCKING LOADS	MOS						11-JAN-1988		
	REF: AMM 52-20-00-720-801	HRS/MSC	O/C					0		
		AFL						0		
52-20-01-900-801-01	REMOVAL / INSTALLATION OF THE EMERGENCY EXIT DOOR	MOS						11-JAN-1988		
52.050	FGFB296001	HRS/MSC	O/C	N:0				0		
	55HP	AFL						0		
	REF: AMM 52-20-01-900-801							0		
52-20-05-960-801-01	REPLACEMENT OF THE EMERGENCY EXIT DOOR SEAL	MOS						11-JAN-1988		
	REF: AMM 52-20-05-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-20-07-960-801-01	REPLACEMENT OF THE EMERGENCY EXIT DOOR UNLOCKING HANDLE	MOS						11-JAN-1988		
	REF: AMM 52-20-07-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-20-11-960-801-01	REPLACEMENT OF THE EMERGENCY EXIT DOOR ELECTRICAL CONNECTORS	MOS						11-JAN-1988		
	REF: AMM 52-20-11-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-20-13-960-801-01	REPLACEMENT / ADJUSTMENT OF THE EMERGENCY EXIT DOOR STOPS	MOS						11-JAN-1988		
	REF: AMM 52-20-13-960-801	HRS/MSC	O/C					0		
		AFL						0		
+ 52-30-00-270-801-01 (s)	ULTRASONIC TEST OF THE BAGGAGE COMPARTMENT DOOR OUTER SKIN	MOS	72	+2m				PKG		
52.060	PKG 31	HRS/MSC						21-JUN-2023		
	REF: AMM 52-30-00-270-801	AFL	3750					8047.2		
								3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR						PKG			
52.060	PKG 17	MOS	36				21-JUN-2023			
	REF: AMM 52-30-00-610-801	HRS/MSC					8047.2			
		AFL					3851			
+ 52-30-00-710-801-01 (s)	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR MECHANISM						PKG			
52.060	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 52-30-00-710-801	HRS/MSC					8047.2			
		AFL	3750				3851			
+ 52-30-00-710-801-02 (s)	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR SLIDING BOLTS						PKG			
52.060	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 52-30-00-710-801	HRS/MSC					8047.2			
		AFL	3750				3851			
+ 52-30-00-710-801-02A	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM - TEST OF DOOR SLIDING BOLTS (MANDATORY 5-40)									
52.060		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 52-30-00-710-801	HRS/MSC	8000				8047.2	16047.2		7998
		AFL					3851			
52-30-00-820-801-01	ADJUSTMENT OF THE BAGGAGE COMPARTMENT DOOR									
		MOS					11-JAN-1988			
	REF: AMM 52-30-00-820-801	HRS/MSC	O/C				0			
		AFL					0			
52-30-00-860-801-01	OPENING / CLOSING OF THE BAGGAGE COMPARTMENT DOOR									
		MOS					11-JAN-1988			
	REF: AMM 52-30-00-860-801	HRS/MSC	O/C				0			
		AFL					0			
52-30-01-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR									
52.060	FGFB299	MOS					11-JAN-1988			
	BZ30	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-30-01-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-30-03-960-801-01	REPLACEMENT OF THE BAGGAGE COMPARTMENT DOOR LOCKING MECHANISM CABLES	MOS						11-JAN-1988		
	REF: AMM 52-30-03-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-30-09-960-801-01	REPLACEMENT OF THE BAGGAGE COMPARTMENT DOOR SEAL	MOS						11-JAN-1988		
	REF: AMM 52-30-09-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-30-19-900-801-01	REMOVAL / INSTALLATION OF THE BAGGAGE COMPARTMENT DOOR REDUCING GEAR MOTOR ASSEMBLY - BAGGAGE COMPARTMENT DOOR REDUCING GEAR MOTOR (3MC)	MOS						29-MAR-2011		
52.060	4220-5	HRS/MSC	O/C	R:0				6615.8		
	274	AFL		R:0				3344		
	REF: AMM 52-30-19-900-801			R:0						
52-30-20-960-801-01	REPLACEMENT OF THE BAGGAGE COMPARTMENT DOOR LIFTING CABLE	MOS						11-JAN-1988		
	REF: AMM 52-30-20-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ACCESS PANELS AND DOORS	MOS	24	+1m				21-JUN-2023		
52.090	PKG 16	HRS/MSC						8047.2		
	REF: AMM 52-40-00-210-801	AFL						3851		
52-41-07-610-801-01 (s)	SERVICING OF THE NLG WELL CEILING DOOR	MOS	24	+1m				21-JUN-2023		
52.110	PKG 16	HRS/MSC						8047.2		
	REF: AMM 52-41-07-610-801	AFL						3851		
52-50-00-710-801-01 (s)	INSPECTION / TEST OF THE BLOWOUT DOORS / PANELS	MOS	72	+2m				21-JUN-2023		
	PKG 31	HRS/MSC						8047.2		
	REF: AMM 52-50-00-710-801	AFL	3750					3851		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-51-05-900-801-01	REMOVAL / INSTALLATION OF THE REAR FUEL TANK ACCESS DOORS AND PANEL - REMOVAL/ INSTALLATION OF CENTER FEEDER TANK ACCESS DOOR (160AZ)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-51-05-900-801	AFL		N:0			0			
52-51-05-900-801-02	REMOVAL / INSTALLATION OF THE REAR FUEL TANK ACCESS DOORS AND PANEL - REMOVAL/ INSTALLATION OF REAR TANK ACCESS DOOR (180AZ)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-51-05-900-801	AFL		N:0			0			
52-51-05-900-802-01	REMOVAL / INSTALLATION OF THE REAR FUEL TANK ACCESS PANEL									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-51-05-900-802	AFL		N:0			0			
52-53-00-610-801-01 (s)	SERVICING OF THE CABIN / BAGGAGE COMPARTMENT DOOR						PKG			
52.100	PKG 17	MOS	36	+1m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 52-53-00-610-801	AFL					3851			
52-53-02-900-801-01	REMOVAL / INSTALLATION OF THE CABIN / BAGGAGE COMPARTMENT DOOR LOCKING MECHANISM									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 52-53-02-900-801	AFL		N:0			0			
52-54-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVIDERS AND BULKHEADS						PKG			
	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 52-54-00-210-801	AFL	3750				3851			
52-54-05-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM						PKG			
	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 52-54-05-210-801	AFL	3750				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-54-05-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER - INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER						PKG			
	PKG 6	MOS	24	+1m				21-JUN-2023		
		HRS/MSC	1600	+40				8047.2		
	REF: AMM 52-54-05-210-802	AFL						3851		
52-55-00-610-801-01 (s)	SERVICING OF THE S-DUCT DOOR						PKG			
52.080	PKG 16	MOS	24	+1m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 52-55-00-610-801	AFL						3851		
52-60-00-860-801-01	OPENING / CLOSING OF THE SERVICING COMPARTMENT DOOR - SERVICING COMPARTMENT DOOR (MSD)									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 52-60-00-860-801	AFL						0		
52-60-09-610-801-01 (s)	SERVICING OF THE REAR COMPARTMENT DOOR						PKG			
52.070	PKG 17	MOS	36	+1m				21-JUN-2023		
		HRS/MSC						8047.2		
	REF: AMM 52-60-09-610-801	AFL						3851		
52-60-13-960-801-01	REPLACEMENT OF THE REAR COMPARTMENT DOOR SEALS									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 52-60-13-960-801	AFL						0		
52-60-15-900-801-01	REMOVAL / INSTALLATION OF THE MECHANIC'S SERVICING COMPARTMENT DOOR RETAINING CABLES									
	PN	MOS						11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C					0		
	REF: AMM 52-60-15-900-801	AFL						0		
52-70-01-960-801-01	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - PASSENGER DOOR									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 52-70-01-960-801	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-70-01-960-801-02	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - FORWARD TOILET SERVICING DOOR	MOS						11-JAN-1988		
	REF: AMM 52-70-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-70-01-960-801-03	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - CABIN/BAGGAGE COMPARTMENT COMMUNICATION DOOR	MOS						11-JAN-1988		
	REF: AMM 52-70-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-70-01-960-801-04	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - BAGGAGE COMPARTMENT DOOR	MOS						11-JAN-1988		
	REF: AMM 52-70-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-70-01-960-801-05	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - MECHANIC'S SERVICING COMPARTMENT DOOR	MOS						11-JAN-1988		
	REF: AMM 52-70-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-70-01-960-801-06	REPLACEMENT / ADJUSTMENT OF THE DOOR MICROSWITCHES AND PROXIMITY SWITCHES - ENGINE 2 S-DUCT INSPECTION DOOR	MOS						11-JAN-1988		
	REF: AMM 52-70-01-960-801	HRS/MSC	O/C					0		
		AFL						0		
52-80-05-900-801-01	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR DOORS - LH MLG DOOR	MOS						11-JAN-1988		
	PN			N:0						
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 52-80-05-900-801	AFL		N:0				0		
52-80-05-900-801-02	REMOVAL / INSTALLATION OF THE MAIN LANDING GEAR DOORS - RH MLG DOOR	MOS						11-JAN-1988		
	PN			N:0						
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 52-80-05-900-801	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
523A11	BAGGAGE DOOR CABLE 4220-250 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-NOV-2018 7675 3744			
524101 52.070	REAR COMPARTMENT DOOR FGFB297 34HP REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
525301 52.080	S-DUCT DOOR FGFB241025510 34BZ REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 53 FUSELAGE										
53-00-00-100-801-01	PRESSURE CLEANING OF THE LH AND RH FEEDER TANKS - LH FEEDER TANK	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
53-00-00-100-801-02	PRESSURE CLEANING OF THE LH AND RH FEEDER TANKS - RH FEEDER TANK	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
53-00-00-100-802-01	PRESSURE CLEANING OF THE REAR FUEL TANK	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
53-00-00-100-803-01	PRESSURE CLEANING OF LH AND RH CENTER WING TANK - LH CENTER WING TANK	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-00-00-100-803-02	PRESSURE CLEANING OF LH AND RH CENTER WING TANK - RH CENTER WING TANK	MOS					11-JAN-1988			
	REF: AMM 53-00-00-100-803	HRS/MSC	O/C				0			
		AFL					0			
53-00-00-100-804-01	PRESSURE CLEANING OF THE CTR FEEDER TANK	MOS					11-JAN-1988			
	REF: AMM 53-00-00-100-804	HRS/MSC	O/C				0			
		AFL					0			
+ 53-00-00-200-803-01	INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 - GENERAL VISUAL INSPECTION	MOS					15-MAY-2006			
53.140	REF: AMM 53-00-00-200-803	HRS/MSC					4812.3			
		AFL	11250				2521	11250		7397
+ 53-00-00-200-803-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40)	MOS					15-MAY-2006			
53.140	REF: AMM 53-00-00-200-803	HRS/MSC					4812.3			
MANDATORY 5-40		AFL	11250				2521	11250		7397
53-00-00-200-803-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 - DETAILED INSPECTION IN SPECIFIC AREAS	MOS					11-JAN-1988			
	REF: AMM 53-00-00-200-803	HRS/MSC					0			
		AFL	11250				0	11250		7397
		APH					0			
53-00-00-200-803-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 4 TO FRAME 30 (MANDATORY 5-40)	MOS					11-JAN-1988			
	REF: AMM 53-00-00-200-803	HRS/MSC					0			
MANDATORY 5-40		AFL	11250				0	11250		7397
		APH					0			
53-00-00-200-810-01	INSPECTIONS SPECIFIC TO A/C 1	MOS					11-JAN-1988			
53.305	REF: AMM 53-00-00-200-810	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-00-00-200-811-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 155)									
53.300		MOS					11-JAN-1988			
	REF: AMM 53-00-00-200-811	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			
53-00-00-200-812-01	SPECIFIC INSPECTION OF THE REPAIRED AREAS (S/N 67)									
		MOS					11-JAN-1988			
	REF: AMM 53-00-00-200-812	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			
+ 53-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION									
53.010	PKG 16	MOS	24	+1m			21-JUN-2023			
	REF: AMM 53-00-00-210-801	HRS/MSC					8047.2			
		AFL					3851			
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)									
		MOS	25				21-JUN-2023	21-JUL-2025		734 d
CPCP	REF: AMM 53-00-00-210-801	HRS/MSC					8047.2			
		AFL					3851			
53-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION									
	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 53-00-00-220-801	HRS/MSC					8047.2			
		AFL	3750				3851			
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)									
		MOS	74				21-JUN-2023	21-AUG-2029		2226 d
CPCP	REF: AMM 53-00-00-220-801	HRS/MSC					8047.2			
		AFL					3851			
53-00-00-220-810-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 67)									
		MOS					11-JAN-1988			
	REF: AMM 53-00-00-220-810	HRS/MSC	N/A				0			
		AFL					0			
		APH					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-00-00-220-811-01	SPECIFIC DETAILED INSPECTION OF THE REPAIRED AREAS (S/N 155)									
53.300		MOS						11-JAN-1988		
	REF: AMM 53-00-00-220-811	HRS/MSC	N/A					0		
		AFL						0		
		APH						0		
53-00-00-220-812-01	DETAILED INSPECTION OF THE RIVETS AT FRAMES 05 AND 07 (S/N 2)									
53.315		MOS						11-JAN-1988		
	REF: AMM 53-00-00-220-812	HRS/MSC	N/A					0		
		AFL						0		
		APH						0		
53-00-00-370-801-01	APPLICATION OF CORROSION INHIBITOR COMPOUND IN FUSELAGE AREAS									
		MOS						11-JAN-1988		
	REF: AMM 53-00-00-370-801	HRS/MSC	O/C					0		
		AFL						0		
53-04-01-900-802-02	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-03	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-04	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113CZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-05	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113DZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-04-01-900-802-06	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113EZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-07	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113FZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-08	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (113GZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-09	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-10	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-11	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114CZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-12	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114DZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-04-01-900-802-13	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114EZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-14	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - COCKPIT FLOOR (114FZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-15	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (121AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-16	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (121BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-17	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (121CZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-18	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (123AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-19	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (123BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-04-01-900-802-20	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (123CZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-21	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (124AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-22	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (124BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-23	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (124CZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-24	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (131AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-25	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (145AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-26	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (145BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-04-01-900-802-27	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (146AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-28	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (155AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-29	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (155BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-30	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (156AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-31	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (161AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-32	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (161BZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		
53-04-01-900-802-33	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (162AZ)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 53-04-01-900-802	AFL		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-04-01-900-802-34	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (181AZ) PN SN-UNKNOWN REF: AMM 53-04-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-04-01-900-802-35	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (183AZ) PN SN-UNKNOWN REF: AMM 53-04-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-04-01-900-802-36	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - CABIN FLOOR (184AZ) PN SN-UNKNOWN REF: AMM 53-04-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-04-01-900-802-37	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - BAGGAGE COMPARTMENT FLOOR (191AZ) PN SN-UNKNOWN REF: AMM 53-04-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-04-01-900-802-38	REMOVAL / INSTALLATION OF THE CABIN FLOOR PANELS - BAGGAGE COMPARTMENT FLOOR (191BZ) PN SN-UNKNOWN REF: AMM 53-04-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-04-10-900-801-01	REMOVAL / INSTALLATION OF THE CABIN SEAT TRACKS PN SN-UNKNOWN REF: AMM 53-04-10-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 53-10-00-200-808-01 (s)	INSPECTION OF THE NLG BAY PKG 15 REF: AMM 53-10-00-200-808	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-10-00-200-808-01C	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY (CPCP)	MOS	13				21-JUN-2023 8047.2 3851	21-JUL-2024		369 d
CPCP	REF: AMM 53-10-00-200-808	HRS/MSC AFL								
+ 53-10-00-200-810-01	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - GENERAL VISUAL INSPECTION	MOS					15-MAY-2006 4812.3 2521		7500	3647
53.120	REF: AMM 53-10-00-200-810	HRS/MSC AFL	7500							
+ 53-10-00-200-810-01A	GENERAL VISUAL INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)	MOS					15-MAY-2006 4812.3 2521		7500	3647
53.120	REF: AMM 53-10-00-200-810	HRS/MSC AFL	7500							
MANDATORY 5-40										
53-10-00-200-810-02	INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 - DETAILED INSPECTION IN SPECIFIC AREAS	MOS					11-JAN-1988 0 0 0		11250	7397
	REF: AMM 53-10-00-200-810	HRS/MSC AFL APH	11250							
53-10-00-200-810-02A	DETAILED INSPECTION OF THE FUSELAGE SKIN - FRAME 0 TO FRAME 4 (MANDATORY 5-40)	MOS					11-JAN-1988 0 0 0		11250	7397
	REF: AMM 53-10-00-200-810	HRS/MSC AFL APH	11250							
MANDATORY 5-40										
+ 53-10-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT	MOS	24	+1m			21-JUN-2023 8047.2 3851	21-JUN-2025 12047.2	21-JUL-2025	704 d (+30) 3998
53.0301	REF: AMM 53-10-00-210-802	HRS/MSC AFL	4000							
53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN THE PROBE AREAS	MOS	24	+1m			PKG 21-JUN-2023 8047.2 3851			
53.260	REF: AMM 53-10-00-220-801	HRS/MSC AFL								
RVSM										



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT						PKG			
53.0302	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 53-10-00-220-802	HRS/MSC					8047.2			
		AFL	3750				3851			
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)									
		MOS	74				21-JUN-2023	21-AUG-2029		2226 d
		HRS/MSC					8047.2			
CPCP	REF: AMM 53-10-00-220-802	AFL					3851			
53-10-00-220-804-01	DIMENSIONAL CHECK OF NLG BALL-JOINT BEARING BORES									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 53-10-00-220-804	AFL					0			
+ 53-10-01-250-801-01	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP									
53.170		MOS					28-NOV-2018			
		HRS/MSC					7675			
	REF: AMM 53-10-01-250-801	AFL	3750				3744	7494		3641
53-10-03-220-801-03 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS.						PKG			
	PKG 32	MOS	144	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 53-10-03-220-801	AFL	7500				3851			
53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS - DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)									
		MOS	148				21-JUN-2023	21-OCT-2035		4478 d
		HRS/MSC					8047.2			
CPCP	REF: AMM 53-10-03-220-801	AFL					3851			
+ 53-10-03-250-801-01	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING									
53.130		MOS					28-NOV-2018			
		HRS/MSC					7675			
	REF: AMM 53-10-03-250-801	AFL	3750				3744	7494		3641



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE PASSENGER DOOR FRAME EDGING (MANDATORY 5-40)									
53.130		MOS					28-NOV-2018			
MANDATORY 5-40	REF: AMM 53-10-03-250-801	HRS/MSC					7675			
		AFL	3750				3744	7494		3641
53-10-33-220-802-01	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS									
53.230		MOS					11-JAN-1988			
	REF: AMM 53-10-33-220-802	HRS/MSC	O/C				0			
		AFL					0			
53-10-33-220-802-01C	INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)									
		MOS					11-JAN-1988			
CPCP	REF: AMM 53-10-33-220-802	HRS/MSC	O/C				0			
		AFL					0			
53-10-33-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELD RETAINERS									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 53-10-33-900-801	AFL		N:0			0			
+ 53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG			
53.220	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 53-10-39-220-801	HRS/MSC					8047.2			
		AFL	3750				3851			
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)									
		MOS	74				21-JUN-2023	21-AUG-2029		2226 d
CPCP	REF: AMM 53-10-39-220-801	HRS/MSC					8047.2			
		AFL					3851			
+ 53-10-39-220-802-01 (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						PKG			
53.240	PKG 32	MOS	144	+2m			21-JUN-2023			
	REF: AMM 53-10-39-220-802	HRS/MSC					8047.2			
		AFL	7500				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)	MOS	148				21-JUN-2023 8047.2 3851	21-OCT-2035		4478 d
CPCP	REF: AMM 53-10-39-220-802	HRS/MSC AFL								
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR	MOS					08-FEB-2000 3067 1929			
53.200	REF: AMM 53-10-41-220-801	HRS/MSC AFL	O/C							
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NLG ACTUATOR (MANDATORY 5-40)	MOS					11-JAN-1988 0 0			
53.200	REF: AMM 53-10-41-220-801	HRS/MSC AFL	O/C							
MANDATORY 5-40										
+ 53-10-43-220-801-01	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NLG WELL LH WALL	MOS					28-NOV-2018 7675 3744	7494		3641
53.097	REF: AMM 53-10-43-220-801	HRS/MSC AFL	3750							
+ 53-10-43-220-801-01A	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LH WALL (MANDATORY 5-40)	MOS					28-NOV-2018 7675 3744	7494		3641
53.097	REF: AMM 53-10-43-220-801	HRS/MSC AFL	3750							
MANDATORY 5-40										
53-11-00-210-801-01	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA	MOS					20-OCT-2016 7448.9 3681			
53.0201	REF: AMM 53-11-00-210-801	HRS/MSC AFL	O/C							
+ 53-11-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA	MOS	24				21-JUN-2023 8047.2 3851			
PKG 16	REF: AMM 53-11-00-210-801	HRS/MSC AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-11-00-760-801-01 (s)	CHECK OF THE NOSE CONE ELECTRICAL BONDING						PKG			
53.250	PKG 16	MOS	24	+1m			21-JUN-2023			
	REF: AMM 53-11-00-760-801	HRS/MSC					8047.2			
		AFL					3851			
53-11-00-860-801-01	OPENING / CLOSING OF THE NOSE CONE									
		MOS					11-JAN-1988			
	REF: AMM 53-11-00-860-801	HRS/MSC	O/C				0			
		AFL					0			
53-11-01-900-801-01	REMOVAL / INSTALLATION OF THE NOSE CONE									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 53-11-01-900-801	AFL					0			
53-11-05-960-801-01	REPLACEMENT OF THE METALLIZED RADAR PARTITION SEAL									
		MOS					11-JAN-1988			
	REF: AMM 53-11-05-960-801	HRS/MSC	O/C				0			
		AFL					0			
53-11-09-900-801-01	REMOVAL / INSTALLATION OF THE RADOME									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 53-11-09-900-801	AFL					0			
53-11-13-960-801-01	REPLACEMENT OF THE RADAR WALL BONDING SEAL									
		MOS					11-JAN-1988			
	REF: AMM 53-11-13-960-801	HRS/MSC	O/C				0			
		AFL					0			
53-11-17-960-801-01	REPLACEMENT OF THE NOSE CONE COUNTERBALANCING ACTUATOR									
		MOS					11-JAN-1988			
	REF: AMM 53-11-17-960-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL PKG 31	MOS					21-JUN-2023 8047.2			
53.270	REF: AMM 53-11-21-960-801	HRS/MSC AFL	7500				3851	11351		7498
53-11-25-820-801-01	ADJUSTMENT OF THE NOSE CONE LOCKS	MOS					11-JAN-1988			
	REF: AMM 53-11-25-820-801	HRS/MSC AFL	O/C				0	0		
53-11-25-960-801-01	REPLACEMENT OF THE NOSE CONE LOCKING CLEVIS - LH UPPER CLEVIS (L9940MT)	MOS					11-JAN-1988			
	REF: AMM 53-11-25-960-801	HRS/MSC AFL	O/C				0	0		
53-11-25-960-801-02	REPLACEMENT OF THE NOSE CONE LOCKING CLEVIS - RH UPPER CLEVIS (R9940MT)	MOS					11-JAN-1988			
	REF: AMM 53-11-25-960-801	HRS/MSC AFL	O/C				0	0		
53-11-25-960-801-03	REPLACEMENT OF THE NOSE CONE LOCKING CLEVIS - LH MEDIAN CLEVIS (L9950MT)	MOS					11-JAN-1988			
	REF: AMM 53-11-25-960-801	HRS/MSC AFL	O/C				0	0		
53-11-25-960-801-04	REPLACEMENT OF THE NOSE CONE LOCKING CLEVIS - RH MEDIAN CLEVIS (R9950MT)	MOS					11-JAN-1988			
	REF: AMM 53-11-25-960-801	HRS/MSC AFL	O/C				0	0		
53-11-25-960-801-05	REPLACEMENT OF THE NOSE CONE LOCKING CLEVIS - LOWER CLEVIS (9960MT)	MOS					11-JAN-1988			
	REF: AMM 53-11-25-960-801	HRS/MSC AFL	O/C				0	0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-11-33-960-801-01	REPLACEMENT / REPAIR OF THE LIGHTNING ARRESTER STRIPS	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
	REF: See Workcard									
+ 53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG			
53.0401	PKG 16	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
	REF: AMM 53-30-00-210-802									
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR						PKG			
53.0402	PKG 31	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 53-30-00-220-801									
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)	MOS HRS/MSC AFL	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
	CPCP									
	REF: AMM 53-30-00-220-801									
53-30-00-220-807-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR						PKG			
53.0402	PKG 32	MOS HRS/MSC AFL	144	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 53-30-00-220-807									
+ 53-30-00-250-801-01	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES	MOS HRS/MSC AFL	3750				28-NOV-2018 7675 3744	7494		3641
53.160										
	REF: AMM 53-30-00-250-801									
+ 53-30-00-250-801-01A	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES (MANDATORY 5-40)	MOS HRS/MSC AFL	3750				28-NOV-2018 7675 3744	7494		3641
53.160										
	MANDATORY 5-40									
	REF: AMM 53-30-00-250-801									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-30-00-250-802-01	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS									
53.150		MOS					28-NOV-2018			
	REF: AMM 53-30-00-250-802	HRS/MSC					7675			
		AFL	3750				3744	7494		3641
<hr/>										
+ 53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY 5-40)									
53.150		MOS					28-NOV-2018			
MANDATORY 5-40	REF: AMM 53-30-00-250-802	HRS/MSC					7675			
		AFL	3750				3744	7494		3641
<hr/>										
53-30-03-200-804-01	INSPECTION CHECK OF THE LIGHTNING DIVERTER STRIPS ON REAR TANK									
		MOS					11-JAN-1988			
	REF: AMM 53-30-03-200-804	HRS/MSC	O/C				0			
		AFL					0			
<hr/>										
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK									
53.290		MOS					11-JAN-1988			
	REF: AMM 53-30-03-960-801	HRS/MSC	A/R				0			
		AFL					0			
		APH					0			
<hr/>										
+ 53-40-00-200-804-01 (s)	INSPECTION OF THE MLG BAYS - LH MLG BAY						PKG			
53.090	PKG 15	MOS	12	+1m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 53-40-00-200-804	AFL					3851			
<hr/>										
53-40-00-200-804-01C	INSPECTION OF THE LH MLG BAY (CPCP)									
		MOS	13				21-JUN-2023	21-JUL-2024		369 d
		HRS/MSC					8047.2			
CPCP	REF: AMM 53-40-00-200-804	AFL					3851			
<hr/>										
+ 53-40-00-200-804-02 (s)	INSPECTION OF THE MLG BAYS - RH MLG BAY						PKG			
53.090	PKG 15	MOS	12	+1m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 53-40-00-200-804	AFL					3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-40-00-200-804-02C	INSPECTION OF THE RH MLG BAY (CPCP)	MOS	13				21-JUN-2023 8047.2 3851	21-JUL-2024		369 d
CPCP	REF: AMM 53-40-00-200-804	HRS/MSC AFL								
+ 53-40-00-200-810-01	INSPECTION OF THE CENTER WING LOWER PANEL FROM FR15 TO FR19	MOS					11-JAN-1988 0 0			
	REF: AMM 53-40-00-200-810	HRS/MSC AFL	N/A							
53-40-00-200-810-01A	INSPECTION OF THE CENTER WING LOWER PANEL FROM FR15 TO FR19 (MANDATORY 5-40)	MOS					11-JAN-1988 0 0			
	REF: AMM 53-40-00-200-810	HRS/MSC AFL	N/A							
+ 53-40-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS	MOS	24	+1m			21-JUN-2023 8047.2 3851	21-JUN-2025 12047.2	21-JUL-2025	704 d (+30) 3998
53.0601	PKG 16	HRS/MSC AFL	4000							
	REF: AMM 53-40-00-210-802									
+ 53-40-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS	MOS	72	+2m			21-JUN-2023 8047.2 3851			
53.0602	PKG 31	HRS/MSC AFL	3750							
	REF: AMM 53-40-00-220-801									
53-40-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)	MOS	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
CPCP	REF: AMM 53-40-00-220-801	HRS/MSC AFL								
+ 53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS	MOS	72	+2m			21-JUN-2023 8047.2 3851			
53.050	PKG 31	HRS/MSC AFL	3750							
	REF: AMM 53-40-00-220-802									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)	MOS	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
CPCP	REF: AMM 53-40-00-220-802	HRS/MSC AFL								
+ 53-40-00-270-801-01 (s)	ULTRASONIC INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10						PKG			
53.280	PKG 31	MOS	72	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 53-40-00-270-801	HRS/MSC AFL	3750							
53-40-00-270-801-01C	ULTRASONIC-INSPECTION FOR CORROSION AROUND THE FASTENERS OF THE FRONT CENTER PANEL AHEAD OF FRAME 10 (CPCP)	MOS	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
CPCP	REF: AMM 53-40-00-270-801	HRS/MSC AFL								
53-40-06-220-801-01	DETAILED INSPECTION OF THE CORROSION ON CENTERWING REAR SPAR	MOS					11-JAN-1988 0 0 0			
53.310		HRS/MSC	N/A							
	REF: AMM 53-40-06-220-801	AFL APH								
+ 53-40-07-280-802-01	SPECIFIC DETAILED INSPECTION (SDI) OF THE REPAIRED AREA ON CENTERWING LOWER PANEL	MOS					11-JAN-1988 0 0			
		HRS/MSC	N/A							
	REF: AMM 53-40-07-280-802	AFL								
53-40-07-280-803-01A	SPECIAL DETAILED INSPECTION OF THE REPAIRED AREAS ON CENTERWING LOWER PANEL	MOS					11-JAN-1988 0 0			
		HRS/MSC	N/A							
	REF: AMM 53-40-07-280-802	AFL								
53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - LH WING						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023 8047.2 3851			
	REF: See Workcard	HRS/MSC AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d
CPCP	REF: See Workcard									
53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE UPPER WING ROOT BOLT RECESSES - RH WING PKG 16	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
	REF: See Workcard									
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)	MOS HRS/MSC AFL	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d
CPCP	REF: See Workcard									
+ 53-41-00-220-802-01 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING PKG 31	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
53.110	REF: AMM 53-41-00-220-802		3750							
+ 53-41-00-220-802-01A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)	MOS HRS/MSC AFL	7500				21-JUN-2023 8047.2 3851	11351		7498
53.110	REF: AMM 53-41-00-220-802									
MANDATORY 5-40										
+ 53-41-00-220-802-02 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING PKG 31	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
	REF: AMM 53-41-00-220-802		3750							
+ 53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)	MOS HRS/MSC AFL	7500				21-JUN-2023 8047.2 3851	11351		7498
MANDATORY 5-40	REF: AMM 53-41-00-220-802									



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-41-00-620-802-01	RENEWAL OF THE TEMPORARY PROTECTION OF THE LH WING ROOT UPPER BOLT RECESSES									
57.240	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
53-41-00-620-802-02	RENEWAL OF THE TEMPORARY PROTECTION OF THE RH WING ROOT UPPER BOLT RECESSES									
57.250	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
53-41-01-640-801-01 (s)	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - LH LINK ROD						PKG			
57.030	PKG 31 REF: AMM 53-41-01-640-801	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
53-41-01-640-801-02 (s)	LUBRICATION OF THE WING TO FUSELAGE CONNECTING ROD - RH LINK ROD						PKG			
57.030	PKG 31 REF: AMM 53-41-01-640-801	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			
+ 53-50-00-210-804-02 (s)	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT						PKG			
53.080	PKG 15 REF: AMM 53-50-00-210-804	MOS HRS/MSC AFL	12	+1m			21-JUN-2023 8047.2 3851			
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)									
CPCP	REF: AMM 53-50-00-210-804	MOS HRS/MSC AFL	13				21-JUN-2023 8047.2 3851	21-JUL-2024		369 d
+ 53-50-00-210-806-01 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						PKG			
53.0701	PKG 16 REF: AMM 53-50-00-210-806	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d
CPCP	REF: AMM 53-50-00-210-806	HRS/MSC AFL								
53-50-00-210-807-01	GENERAL VISUAL INSPECTION APU OF THE APU AREA	MOS					04-DEC-2017 7593.7 3722 3592			
49.005	REF: AMM 53-50-00-210-807	HRS/MSC AFL APH	O/C							
+ 53-50-00-210-807-02 (s)	GENERAL VISUAL INSPECTION OF THE APU AREA	MOS	12				21-JUN-2023 8047.2 3851			
	PKG 15	HRS/MSC AFL								
	REF: AMM 53-50-00-210-807									
+ 53-50-00-220-803-01 (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT	MOS	72	+2m			21-JUN-2023 8047.2 3851			
53.0702	PKG 31	HRS/MSC AFL								
	REF: AMM 53-50-00-220-803		3750							
53-50-00-220-803-01A	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT	MOS					21-JUN-2023 8047.2 3851	7601		3748
MANDATORY 5-40	REF: AMM 53-50-00-220-803	HRS/MSC AFL	3750							
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
CPCP	REF: AMM 53-50-00-220-803	HRS/MSC AFL								
53-50-00-220-805-01	DETAILED INSPECTION OF THE REAR COMPARTMENT	MOS					20-OCT-2016 7448.9 3681			
53.082	REF: AMM 53-50-00-220-805	HRS/MSC AFL	O/C							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-50-00-220-805-02 (s)	DETAILED INSPECTION OF THE REAR COMPARTMENT PKG 16	MOS	24				PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 53-50-00-220-805	HRS/MSC AFL								
+ 53-50-00-220-805-02C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)	MOS	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d
	REF: AMM 53-50-00-220-805	HRS/MSC AFL								
53-50-00-220-807-01	DETAILED INSPECTION OF THE FRAME 30 UPPER PART	MOS					11-JAN-1988 0			
	REF: AMM 53-50-00-220-807	HRS/MSC AFL	5000				0	5000		1147
53-50-00-220-807-01A	DETAILED INSPECTION OF THE FRAME 30 UPPER PART	MOS					11-JAN-1988 0			
MANDATORY 5-40	REF: AMM 53-50-00-220-807	HRS/MSC AFL	5000				0	5000		1147
53-50-07-900-801-01	REMOVAL / INSTALLATION OF THE FIN STUB REAR CONE	PN					11-JAN-1988 0			
	SN-UNKNOWN	MOS			N:0		0			
	REF: AMM 53-50-07-900-801	HRS/MSC AFL	O/C		N:0		0			
+ 53-50-30-250-802-01	EDDY-CURRENT INSPECTION OF THE REAR EDGE OF BEAMS AT FRAME 30	MOS					28-NOV-2018 7675			
53.180	REF: AMM 53-50-30-250-802	HRS/MSC AFL	3750				3744	7494		3641
+ 53-60-00-760-801-01 (s)	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING - FUSELAGE CENTER LOWER FAIRING (150A)	MOS	36	+1m			PKG 21-JUN-2023 8047.2 3851			
53.255	REF: AMM 53-60-00-760-801	HRS/MSC AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-60-01-900-801-01	REMOVAL / INSTALLATION OF THE FUSELAGE FAIRINGS PN SN-UNKNOWN REF: AMM 53-60-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-60-05-900-801-01	REMOVAL / INSTALLATION OF A LANDING LIGHT TRANSPARENCY PN SN-UNKNOWN REF: AMM 53-60-05-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
53-70-01-900-801-01	REMOVAL / INSTALLATION OF THE FUSELAGE LATERAL FAIRING 193AL PN SN-UNKNOWN REF: AMM 53-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 53-80-00-200-801-01 (s)	CHECK OF THE CONDENSATION AND STREAM WATER DRAINS PKG 16 51.020 REF: AMM 53-80-00-200-801	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
53-80-01-710-801-01	OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - "AFT WATER LEAK" PCB (53MD) REF: AMM 53-80-01-710-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
53-80-01-710-801-02	OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - "AFT WATER LEAK" SENSOR (55MD) REF: AMM 53-80-01-710-801	MOS HRS/MSC AFL	N/A				11-JAN-1988 0 0			
53-80-01-900-801-01	REMOVAL / INSTALLATION OF THE WATER DETECTION SENSOR - "AFT WATER LEAK" SENSOR (55MD) PN SN-UNKNOWN REF: AMM 53-80-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						PKG			
51.050	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 53-80-09-710-801	HRS/MSC					8047.2			
		AFL	3750				3851			
CHAPTER 54 NACELLES/PYLONS										
+ 54-00-00-210-810-01	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)									
54.0101		MOS					27-JUN-2023			
	REF: AMM 54-00-00-210-810	HRS/MSC	300	+100			8049.2	8349.2	8449.2	300 (+100)
		AFL					3853			
+ 54-00-00-210-810-02	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)									
54.0101		MOS					27-JUN-2023			
	REF: AMM 54-00-00-210-810	HRS/MSC	300	+100			8049.2	8349.2	8449.2	300 (+100)
		AFL					3853			
+ 54-00-00-210-811-01	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE									
54.0201		MOS					27-JUN-2023			
	REF: AMM 54-00-00-210-811	HRS/MSC	300	+100			8049.2	8349.2	8449.2	300 (+100)
		AFL					3853			
54-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)						PKG			
54.0102	PKG 32	MOS	144	+2m			21-JUN-2023			
	REF: AMM 54-00-00-220-801	HRS/MSC					8047.2			
		AFL	7500				3851			
54-00-00-220-801-01C	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON (CPCP)									
		MOS	148				21-JUN-2023	21-OCT-2035		4478 d
CPCP	REF: AMM 54-00-00-220-801	HRS/MSC					8047.2			
		AFL					3851			
54-00-00-220-801-02 (s)	DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)						PKG			
54.0102	PKG 32	MOS	144	+2m			21-JUN-2023			
	REF: AMM 54-00-00-220-801	HRS/MSC					8047.2			
		AFL	7500				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-00-00-220-801-02C	DETAILED INSPECTION OF THE NO. 3 ENGINE NACELLE AND PYLON (CPCP)									
		MOS	148				21-JUN-2023	21-OCT-2035		4478 d
CPCP	REF: AMM 54-00-00-220-801	HRS/MSC AFL					8047.2 3851			
54-11-00-610-801-01 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 COWLINGS						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023			
54.060	REF: AMM 54-11-00-610-801	HRS/MSC AFL					8047.2 3851			
54-11-00-610-801-02 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 COWLINGS						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023			
54.060	REF: AMM 54-11-00-610-801	HRS/MSC AFL					8047.2 3851			
54-11-00-610-801-03 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 3 COWLINGS						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023			
54.060	REF: AMM 54-11-00-610-801	HRS/MSC AFL					8047.2 3851			
+ 54-11-00-760-801-01 (s)	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023			
54.125	REF: AMM 54-11-00-760-801	HRS/MSC AFL					8047.2 3851			
54-11-01-900-802-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 1 LOWER COWLING									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 54-11-01-900-802	AFL					0			
54-11-01-900-802-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 3 LOWER COWLING									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 54-11-01-900-802	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-11-01-900-802-03	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 1 UPPER COWLING PN SN-UNKNOWN REF: AMM 54-11-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
54-11-01-900-802-04	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 UPPER AND LOWER COWLINGS - ENGINE 3 UPPER COWLING PN SN-UNKNOWN REF: AMM 54-11-01-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
54-11-09-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 COWLINGS - OPENING / CLOSING OF COWLINGS (455AL) / (456AR) PN SN-UNKNOWN REF: AMM 54-11-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
54-11-09-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 2 COWLINGS - REMOVAL / INSTALLATION OF COWLINGS (455AL) / (456AR) PN SN-UNKNOWN REF: AMM 54-11-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
54-11-13-960-801-01	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 1 UPPER COWLING REF: AMM 54-11-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
54-11-13-960-801-02	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 3 UPPER COWLING REF: AMM 54-11-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
54-11-13-960-801-03	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 1 LOWER COWLING REF: AMM 54-11-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-11-13-960-801-04	REPLACEMENT OF THE ENGINE 1 AND 3 COWLING SEALS - ENGINE 3 LOWER COWLING	MOS						11-JAN-1988		
	REF: AMM 54-11-13-960-801	HRS/MSC	O/C					0		
		AFL						0		
54-12-01-900-801-01	REMOVAL / INSTALLATION OF THE INNER FAN DUCTS OF THE LATERAL ENGINES - INNER FAN DUCT OF ENGINE 1 (L4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-01-900-801	AFL		N:0				0		
54-12-01-900-801-02	REMOVAL / INSTALLATION OF THE INNER FAN DUCTS OF THE LATERAL ENGINES - INNER FAN DUCT OF ENGINE 3 (R4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-01-900-801	AFL		N:0				0		
54-12-01-900-802-01	REMOVAL / INSTALLATION OF THE SPOKE FAIRINGS OF THE LATERAL ENGINES - SPOKE FAIRING ASSEMBLY OF ENGINE 1 (L4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-01-900-802	AFL		N:0				0		
54-12-01-900-802-02	REMOVAL / INSTALLATION OF THE SPOKE FAIRINGS OF THE LATERAL ENGINES - SPOKE FAIRING ASSEMBLY OF ENGINE 3 (R4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-01-900-802	AFL		N:0				0		
54-12-05-900-801-01	REMOVAL / INSTALLATION OF THE INNER FAN DUCT OF THE CENTRAL ENGINE - INNER FAN DUCT OF ENGINE 2 (M4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-05-900-801	AFL		N:0				0		
54-12-05-900-802-01	REMOVAL / INSTALLATION OF THE SPOKE FAIRINGS OF THE CENTRAL ENGINE - SPOKE FAIRING ASSEMBLY OF ENGINE 2 (M4EZ)	PN		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 54-12-05-900-802	AFL		N:0				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-13-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AFTERBODIES - ENGINE 1 AFTERBODY									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-13-01-900-801	AFL		N:0			0			
54-13-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AFTERBODIES - ENGINE 3 AFTERBODY									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-13-01-900-801	AFL		N:0			0			
+ 54-13-05-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ENGINE 2 AFTERBODY						PKG			
78.015	PKG 5	MOS	12	+1m			21-JUN-2023			
		HRS/MSC	800	+40			8047.2			
	REF: AMM 54-13-05-210-801	AFL					3851			
54-13-05-220-801-01	DETAILED INSPECTION OF THE NO. 2 ENGINE AFTERBODY									
		MOS					28-NOV-2018			
		HRS/MSC	O/C				7675			
	REF: AMM 54-13-05-220-801	AFL					3744			
+ 54-13-05-220-801-02 (s)	DETAILED INSPECTION OF THE ENGINE 2 AFTERBODY						PKG			
	PKG 31	MOS	72				21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 54-13-05-220-801	AFL	3750				3851			
54-13-05-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 AFTERBODY									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-13-05-900-801	AFL		N:0			0			
54-13-09-960-801-01	REPLACEMENT OF THE ENGINE 2 AFTERBODY METALLIC SEALS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 54-13-09-960-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-14-01-280-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLE FAN INNER DUCTS - ENGINE 1 (L4EZ)									
54.120	REF: AMM 54-14-01-280-801	MOS HRS/MSC AFL	O/C				16-MAY-1991 807 560			
54-14-01-280-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 NACELLE FAN INNER DUCTS - ENGINE 3 (R4EZ)									
54.120	REF: AMM 54-14-01-280-801	MOS HRS/MSC AFL	O/C				16-MAY-1991 807 560			
54-14-01-280-802-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 NACELLE FAN INNER COWLINGS									
	REF: AMM 54-14-01-280-802	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
54-41-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AIR INTAKES - ENGINE 1 AIR INTAKE									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-41-01-900-801	AFL		N:0			0			
54-41-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 AIR INTAKES - ENGINE 3 AIR INTAKE									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-41-01-900-801	AFL		N:0			0			
54-42-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 2 AIR INTAKE									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-42-01-900-801	AFL		N:0			0			
54-42-05-900-801-01	REMOVAL / INSTALLATION OF THE S-DUCT SECTION 1 AND 2									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 54-42-05-900-801	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-42-09-900-801-01	REMOVAL / INSTALLATION OF THE S-DUCT SECTION 3 AND 4 PN SN-UNKNOWN REF: AMM 54-42-09-900-801	MOS HRS/MSC AFL						11-JAN-1988 0 0		
CHAPTER 55 STABILIZERS										
+ 55-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT									
55.0101	PKG 16 REF: AMM 55-00-00-210-801	MOS HRS/MSC AFL	24 4000	+1m		-244	21-JUN-2023 8047.2 3851	20-OCT-2024 12047.2	20-NOV-2024	460 d (+31) 3998
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT (CPCP)									
CPCP	REF: AMM 55-00-00-210-801	MOS HRS/MSC AFL	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d
+ 55-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT						PKG			
55.0102	PKG 31 REF: AMM 55-00-00-220-801	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT (CPCP)									
CPCP	REF: AMM 55-00-00-220-801	MOS HRS/MSC AFL	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
55-00-00-370-801-01	APPLICATION OF CORROSION INHIBITOR COMPOUND IN STABILIZER AREAS									
	REF: AMM 55-00-00-370-801	MOS HRS/MSC AFL		O/C			11-JAN-1988 0 0			
+ 55-00-00-760-801-01 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RUDDER						PKG			
55.110	PKG 16 REF: AMM 55-00-00-760-801	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-00-00-760-801-02 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - LH ELEVATOR PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 55-00-00-760-801									
55-00-00-760-801-03 (s)	CHECK OF THE STABILIZER MOVABLE SURFACE ELECTRICAL BONDING - RH ELEVATOR PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 55-00-00-760-801									
55-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE PKG 32	MOS HRS/MSC AFL	144	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 55-10-00-220-801		7500							
55-10-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE	MOS HRS/MSC AFL	148				21-JUN-2023 8047.2 3851	21-OCT-2035		4478 d
CPCP	REF: AMM 55-10-00-220-801									
55-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS PKG 32	MOS HRS/MSC AFL	144	+2m			PKG 21-JUN-2023 8047.2 3851			
	REF: AMM 55-10-00-220-802		7500							
55-10-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS	MOS HRS/MSC AFL	148				21-JUN-2023 8047.2 3851	21-OCT-2035		4478 d
CPCP	REF: AMM 55-10-00-220-802									
55-10-00-270-801-01 (s)	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
55.030	REF: AMM 55-10-00-270-801		3750							



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY 5-40)									
55.030		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 55-10-00-270-801	HRS/MSC					8047.2			
		AFL	3750				3851	7601		3748
55-10-00-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER FRONT TORQUE LINK AND ACTUATOR UPPER HINGE - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)						PKG			
27.237	PKG 16	MOS	24	+1m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 55-10-00-640-802	AFL					3851			
55-10-01-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER									
55.065	FGFB331	MOS			R:2		28-NOV-2018			
	6/176HD	HRS/MSC	O/C		R:0		7675			
	REF: AMM 55-10-01-900-801	AFL			R:0		3744			
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						PKG			
	PKG 16	MOS	24	+1m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 55-10-03-640-801	AFL					3851			
55-10-03-820-801-01	ADJUSTMENT OF THE SPRING-LOADED FAIRINGS - LH SPRING LOADED FAIRINGS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 55-10-03-820-801	AFL					0			
55-10-03-820-801-02	ADJUSTMENT OF THE SPRING-LOADED FAIRINGS - RH SPRING LOADED FAIRINGS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 55-10-03-820-801	AFL					0			
55-10-03-900-801-01	REMOVAL / INSTALLATION OF THE SPRING-LOADED FAIRINGS - LH SPRING LOADED FAIRINGS									
	PN	MOS			N:0		11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 55-10-03-900-801	AFL			N:0		0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-03-900-801-02	REMOVAL / INSTALLATION OF THE SPRING-LOADED FAIRINGS - RH SPRING LOADED FAIRINGS									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 55-10-03-900-801	AFL		N:0			0			
55-10-05-960-802-01	REPLACEMENT OF THE SPRING-LOADED FAIRING FRICTION STRIPS									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 55-10-05-960-802	AFL					0			
55-10-29-900-801-01	REMOVAL / INSTALLATION OF THE HORIZONTAL STABILIZER TORQUE LINK									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 55-10-29-900-801	AFL		N:0			0			
+ 55-10-31-220-801-01 (s)	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS						PKG			
55.090	PKG 31	MOS	72	+2m			21-JUN-2023			
		HRS/MSC					8047.2			
	REF: AMM 55-10-31-220-801	AFL	3750				3851			
+ 55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY 5-40)									
55.090		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 55-10-31-220-801	HRS/MSC					8047.2			
		AFL	3750				3851	7601		3748
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS									
27.235		MOS	36	+1m			27-JUN-2023	27-JUN-2026	27-JUL-2026	1075 d (+30)
		HRS/MSC	600	+40			8049.2	8649.2	8689.2	600 (+40)
	REF: AMM 55-10-33-640-801	AFL					3853			
55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE									
55.040		MOS					28-NOV-2018			
	REF: AMM 55-10-39-220-801	HRS/MSC					7675			
		AFL	3750				3744	7494		3641



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-39-220-801-01A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS (MANDATORY 5-40)									
55.040		MOS					28-NOV-2018			
MANDATORY 5-40	REF: AMM 55-10-39-220-801	HRS/MSC AFL	3750				7675 3744		7494	3641
55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE									
		MOS					11-JAN-1988			
	REF: AMM 55-10-39-220-801	HRS/MSC AFL	11250				0 0		7494 M	3641
55-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ELEVATORS - LH ELEVATOR									
55.070	FGFB341	MOS					11-JAN-1988			
	31-229HD	HRS/MSC	O/C	N:0			0			
	REF: AMM 55-20-01-900-801	AFL					0			
55-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ELEVATORS - RH ELEVATOR									
55.070	FGFB342	MOS					11-JAN-1988			
	52-231HD	HRS/MSC	O/C	N:0			0			
	REF: AMM 55-20-01-900-801	AFL					0			
55-20-03-640-801-01 (s)	LUBRICATION OF THE ELEVATOR BEARINGS - LH ELEVATOR									
55.070	PKG 32	MOS	144	+2m			PKG			
	REF: AMM 55-20-03-640-801	HRS/MSC AFL	7500				21-JUN-2023 8047.2 3851			
55-20-03-640-801-02 (s)	LUBRICATION OF THE ELEVATOR BEARINGS - RH ELEVATOR									
55.070	PKG 32	MOS	144	+2m			PKG			
	REF: AMM 55-20-03-640-801	HRS/MSC AFL	7500				21-JUN-2023 8047.2 3851			
55-20-03-640-802-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES									
27.170	PKG 15	MOS	12	+1m			PKG			
	REF: AMM 55-20-03-640-802	HRS/MSC AFL					21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-20-05-640-801-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND U-JOINTS						PKG			
27.240	PKG 5	MOS	12	+1m			21-JUN-2023			
	REF: AMM 55-20-05-640-801	HRS/MSC	800	+40			8047.2			
		AFL					3851			
55-20-05-960-801-01	REPLACEMENT OF THE ELEVATOR INBOARD BEARING ROLLER BEARINGS									
		MOS					11-JAN-1988			
	REF: AMM 55-20-05-960-801	HRS/MSC	O/C				0			
		AFL					0			
55-30-00-270-801-01 (s)	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS						PKG			
55.050	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 55-30-00-270-801	HRS/MSC					8047.2			
		AFL	3750				3851			
55-30-00-270-801-01A	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY 5-40)									
55.050		MOS					21-JUN-2023			
MANDATORY 5-40	REF: AMM 55-30-00-270-801	HRS/MSC					8047.2			
		AFL	3750				3851	7601		3748
55-30-01-900-801-01	REMOVAL / INSTALLATION OF THE VERTICAL STABILIZER									
55.075	FGFB310	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 55-30-01-900-801	AFL					0			
55-30-05-960-801-01	REPLACEMENT OF THE FIN TIP FAIRING LIGHTNING-ARRESTER STRIP									
		MOS					11-JAN-1988			
	REF: AMM 55-30-05-960-801	HRS/MSC	O/C				0			
		AFL					0			
55-30-07-900-801-01	REMOVAL / INSTALLATION OF THE FIN TIP FAIRING									
	PN	MOS					11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0			
	REF: AMM 55-30-07-900-801	AFL			N:0		0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-40-01-900-801-01	REMOVAL / INSTALLATION OF THE RUDDER									
55.080	FGFB321 47-239 REF: AMM 55-40-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
55-40-05-640-801-01 (s)	LUBRICATION OF THE RUDDER BEARINGS						PKG			
55.080	PKG 32 REF: AMM 55-40-05-640-801	MOS HRS/MSC AFL	144 7500	+2m			21-JUN-2023 8047.2 3851			
55-40-05-640-802-01 (s)	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES						PKG			
27.100	PKG 15 REF: AMM 55-40-05-640-802	MOS HRS/MSC AFL	12	+1m			21-JUN-2023 8047.2 3851			
551101	LH SPRING LOADED RIB									
55.060	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
551121	RH SPRING LOADED RIB									
55.060	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 56		WINDOWS								
56-00-00-100-801-01	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - COCKPIT WINDSHIELDS/WINDOWS									
	REF: AMM 56-00-00-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
56-00-00-100-801-02	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - CABIN WINDOWS									
	REF: AMM 56-00-00-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-00-00-100-801-03	CLEANING OF WINDSHIELD, WINDOWS AND TRANSPARENT FAIRINGS - TRANSPARENT FAIRINGS	MOS						11-JAN-1988		
	REF: AMM 56-00-00-100-801	HRS/MSC	O/C					0		
		AFL						0		
56-00-00-350-801-01	SMOOTHING OF SCRATCHES ON WINDSHIELDS, WINDOWS AND TRANSPARENT FAIRINGS	MOS						11-JAN-1988		
	REF: AMM 56-00-00-350-801	HRS/MSC	O/C					0		
		AFL						0		
56-00-00-910-801-01	ACCEPTANCE CRITERIA FOR DAMAGE TO WINDSHIELDS, WINDOWS AND TRANSPARENT FAIRINGS	MOS						11-JAN-1988		
	REF: AMM 56-00-00-910-801	HRS/MSC	O/C					0		
		AFL						0		
56-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WINDSHIELDS - PILOT WINDSHIELD (L4HH)	MOS						16-JUL-2012		
56.010	SPSF900-2-8-3	HRS/MSC	O/C	N:9				6985.1		
	2875	AFL		N:0				3525		
	REF: AMM 56-10-01-900-801			N:0						
56-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WINDSHIELDS - COPILOT WINDSHIELD (R4HH)	MOS						16-JUL-2012		
56.010	SPSF900-3-8-3	HRS/MSC	O/C	N:20				6985.1		
	2878	AFL		N:0				3525		
	REF: AMM 56-10-01-900-801			N:0						
56-10-01-900-801-03	REMOVAL / INSTALLATION OF THE WINDSHIELDS - FRONT WINDSHIELD (5HH)	MOS						16-JUL-2012		
56.010	SPSF900-1-7-3	HRS/MSC	O/C	N:7				6985.1		
	1032	AFL		N:0				3525		
	REF: AMM 56-10-01-900-801			N:0						
56-10-07-900-801-01	REMOVAL / INSTALLATION OF THE RH LATERAL WINDOW - RH LATERAL WINDOW (R35HH)	MOS						20-APR-1994		
56.035	SPSF900-5-7-2	HRS/MSC	O/C	N:0				1513		
	615	AFL		N:0				1054		
	REF: AMM 56-10-07-900-801			N:0						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 56-10-09-640-801-01 (s)	LUBRICATION OF THE OPENING WINDOW MECHANISM - LH SLIDING WINDOW (L35HH)						PKG			
56.020	PKG 16	MOS	24	+1m			21-JUN-2023			
	REF: AMM 56-10-09-640-801	HRS/MSC					8047.2			
		AFL					3851			
56-10-09-900-801-01	REMOVAL / INSTALLATION OF THE OPENING WINDOW - LH SLIDING WINDOW (L35HH)									
56.020	SPSF900-4-2-1	MOS					11-JAN-1988			
	48	HRS/MSC	O/C	N:0			0			
	REF: AMM 56-10-09-900-801	AFL					0			
56-10-09-960-801-01	REPLACEMENT OF THE OPENING WINDOW PANE AND SEAL - REPLACEMENT OF WINDOW PANE									
		MOS					11-JAN-1988			
	REF: AMM 56-10-09-960-801	HRS/MSC	O/C				0			
		AFL					0			
56-10-09-960-801-02	REPLACEMENT OF THE OPENING WINDOW PANE AND SEAL - REPLACEMENT OF SEAL									
		MOS					11-JAN-1988			
	REF: AMM 56-10-09-960-801	HRS/MSC	O/C				0			
		AFL					0			
56-10-11-900-801-01	REMOVAL / INSTALLATION OF THE REAR WINDOWS - LH REAR WINDOW (L44HH)									
56.030	SPSF900-6-9-3	MOS		R:0			25-AUG-2008			
	3123	HRS/MSC	O/C	R:0			5492.6			
	REF: AMM 56-10-11-900-801	AFL		R:0			2792			
56-10-11-900-801-02	REMOVAL / INSTALLATION OF THE REAR WINDOWS - RH REAR WINDOW (R44HH)									
56.030	SPSF900-7-4-2	MOS					11-JAN-1988			
	200	HRS/MSC	O/C	N:0			0			
	REF: AMM 56-10-11-900-801	AFL					0			
56-20-05-900-801-01	NO. 1 LEFT CABIN WINDOW									
56.040	SPSF900-8-6-0	MOS					11-JAN-1988			
	2560	HRS/MSC	O/C	N:0			0			
	REF: AMM 56-20-05-900-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-01 56.080	NO. 1 RIGHT CABIN WINDOW SPSF900-8-6-0 2552 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.070	NO. 10 LEFT CABIN WINDOW SPSF900-8-6-0 2530 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.110	NO. 10 RIGHT CABIN WINDOW SPSF900-8-6-0 2598 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.070	NO. 11 LEFT CABIN WINDOW SPSF900-8-6-0 2601 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.110	NO. 11 RIGHT CABIN WINDOW SPSF900-8-6-0 2607 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.070	NO. 12 LEFT CABIN WINDOW SPSF900-8-6-0 2555 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.110	NO. 12 RIGHT CABIN WINDOW SPSF900-8-6-0 2606 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-01 56.040	NO. 2 LEFT CABIN WINDOW SPSF900-8-6-0 2610 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.080	NO. 2 RIGHT CABIN WINDOW SPSF900-8-6-0 2094 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-JUL-2012 6985.1 3525			
56-20-05-900-801-01 56.040	NO. 3 LEFT CABIN WINDOW SPSF900-8-3-0 372 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			03-JUN-1988 30 13			
56-20-05-900-801-01 56.080	NO. 3 RIGHT CABIN WINDOW SPSF900-8-6-0 2599 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.050	NO. 4 LEFT CABIN WINDOW SPSF900-8-6-0 2604 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.090	NO. 4 RIGHT CABIN WINDOW SPSF900-8-6-0 2026 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.050	NO. 5 LEFT CABIN WINDOW SPSF900-8-6-0 2318 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-01 56.090	NO. 5 RIGHT CABIN WINDOW SPSF900-8-6-0 2596 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.050	NO. 6 LEFT CABIN WINDOW SPSF900-8-6-0 2600 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.090	NO. 6 RIGHT CABIN WINDOW SPSF900-8-6-0 2608 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.060	NO. 7 LEFT CABIN WINDOW SPSF900-8-6-0 2562 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.100	NO. 7 RIGHT CABIN WINDOW SPSF900-8-6-0 2603 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.060	NO. 8 LEFT CABIN WINDOW SPSF900-8-6-0 2553 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01 56.100	NO. 8 RIGHT CABIN WINDOW SPSF900-8-6-0 2026 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-JUL-2012 6985.1 3525			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-20-05-900-801-01	NO. 9 LEFT CABIN WINDOW									
56.060	SPSF900-8-6-0 2561 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-801-01	NO. 9 RIGHT CABIN WINDOW									
56.100	SPSF900-8-6-0 2602 REF: AMM 56-20-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
56-20-05-900-802-01	REMOVAL / INSTALLATION OF THE INNER PANE OF A CABIN WINDOW									
	PN SN-UNKNOWN REF: AMM 56-20-05-900-802	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
CHAPTER 57 WINGS										
57-00-00-100-801-01	PRESSURE CLEANING OF WING TANKS - LH WING TANKS									
	REF: AMM 57-00-00-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
57-00-00-100-801-02	PRESSURE CLEANING OF WING TANKS - RH WING TANKS									
	REF: AMM 57-00-00-100-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 57-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING									
57.0101	PKG 16 REF: AMM 57-00-00-210-801	MOS HRS/MSC AFL	24 4000	+1m	-244		21-JUN-2023 8047.2 3851	20-OCT-2024 12047.2	20-NOV-2024	460 d (+31) 3998
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)									
CPCP	REF: AMM 57-00-00-210-801	MOS HRS/MSC AFL	25				21-JUN-2023 8047.2 3851	21-JUL-2025		734 d



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-00-00-210-801-02	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING									
57.0101	PKG 16	MOS	24	+1m			21-JUN-2023	20-OCT-2024	20-NOV-2024	460 d (+31)
	REF: AMM 57-00-00-210-801	HRS/MSC	4000				8047.2	12047.2		3998
		AFL					3851			
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)									
		MOS	25				21-JUN-2023	21-JUL-2025		734 d
CPCP	REF: AMM 57-00-00-210-801	HRS/MSC					8047.2			
		AFL					3851			
+ 57-00-00-220-802-01 (s)	DETAILED INSPECTION OF THE WINGS - LH WING						PKG			
57.0102	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 57-00-00-220-802	HRS/MSC					8047.2			
		AFL	3750				3851			
57-00-00-220-802-01C	DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)									
		MOS	74				21-JUN-2023	21-AUG-2029		2226 d
CPCP	REF: AMM 57-00-00-220-802	HRS/MSC					8047.2			
		AFL					3851			
+ 57-00-00-220-802-02 (s)	DETAILED INSPECTION OF THE WINGS - RH WING						PKG			
57.0102	PKG 31	MOS	72	+2m			21-JUN-2023			
	REF: AMM 57-00-00-220-802	HRS/MSC					8047.2			
		AFL	3750				3851			
57-00-00-220-802-02C	DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)									
		MOS	74				21-JUN-2023	21-AUG-2029		2226 d
CPCP	REF: AMM 57-00-00-220-802	HRS/MSC					8047.2			
		AFL					3851			
57-00-00-370-801-01	APPLICATION OF CORROSION INHIBITOR COMPOUND IN WING AREAS									
		MOS					11-JAN-1988			
	REF: AMM 57-00-00-370-801	HRS/MSC	O/C				0			
		AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-00-00-760-801-01 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHAILERON						PKG			
57.265	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-02 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHAILERON						PKG			
57.265	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-03 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHFLAPS						PKG			
57.270	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-04 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHFLAPS						PKG			
57.270	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-05 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHSLATS						PKG			
57.280	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-06 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHSLATS						PKG			
57.280	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								
+ 57-00-00-760-801-07 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES						PKG			
57.275	PKG 16	MOS	24	+1m			21-JUN-2023	8047.2	3851	
	REF: AMM 57-00-00-760-801	HRS/MSC								
		AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-00-00-760-801-08 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES						PKG			
57.275	PKG 16 REF: AMM 57-00-00-760-801	MOS HRS/MSC AFL	24	+1m			21-JUN-2023 8047.2 3851			
57-00-01-900-800-01	LH WING FGFB101 38-223 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-00-01-900-800-02	RH WING FGFB102 38-223 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-00-01-900-801-01	REMOVAL / INSTALLATION OF THE WINGS - LH WING PN SN-UNKNOWN REF: AMM 57-00-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-00-01-900-801-02	REMOVAL / INSTALLATION OF THE WINGS - RH WING PN SN-UNKNOWN REF: AMM 57-00-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-10-00-220-803-01	DIMENSIONAL CHECK OF MLG BALL-JOINT BEARING BORES REF: AMM 57-10-00-220-803	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
+ 57-10-00-290-801-01 (s)	BORESCOPE INSPECTION OF THE WING TANKS						PKG			
57.130	PKG 31 REF: AMM 57-10-00-290-801	MOS HRS/MSC AFL	72	+2m			21-JUN-2023 8047.2 3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)	MOS HRS/MSC AFL	74				21-JUN-2023 8047.2 3851	21-AUG-2029		2226 d
CPCP	REF: AMM 57-10-00-290-801									
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING	MOS HRS/MSC AFL APH	11250				11-JAN-1988 0 0 0	11250		7397
REF: AMM 57-10-01-210-801										
57-10-01-210-801-01A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - LH WING (MANDATORY 5-40)	MOS HRS/MSC AFL APH	11250				11-JAN-1988 0 0 0	11250		7397
MANDATORY 5-40	REF: AMM 57-10-01-210-801									
+ 57-10-01-210-801-02	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING	MOS HRS/MSC AFL	11250				11-JAN-1988 0 0	11250 M		7397
REF: AMM 57-10-01-210-801										
+ 57-10-01-210-801-02A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS - RH WING (MANDATORY 5-40)	MOS HRS/MSC AFL	11250				11-JAN-1988 0 0	11250 M		7397
MANDATORY 5-40	REF: AMM 57-10-01-210-801									
57-10-01-900-801-01	REMOVAL / INSTALLATION OF THE WING STRUCTURAL FUEL TANK REMOVABLE PANELS - LH WING	PN SN-UNKNOWN REF: AMM 57-10-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		11-JAN-1988 0 0			
57-10-01-900-801-02	REMOVAL / INSTALLATION OF THE WING STRUCTURAL FUEL TANK REMOVABLE PANELS - RH WING	PN SN-UNKNOWN REF: AMM 57-10-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-11-900-801-01	REMOVAL / INSTALLATION OF THE WING TIP FAIRINGS - LH WING TIP FAIRING PN SN-UNKNOWN REF: AMM 57-10-11-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-10-11-900-801-02	REMOVAL / INSTALLATION OF THE WING TIP FAIRINGS - RH WING TIP FAIRING PN SN-UNKNOWN REF: AMM 57-10-11-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING REF: AMM 57-10-14-220-801	MOS HRS/MSC AFL APH	11250				11-JAN-1988 0 0 0	11250		7397
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40) REF: AMM 57-10-14-220-801	MOS HRS/MSC AFL APH	11250				11-JAN-1988 0 0 0	11250		7397
+ 57-10-14-220-801-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING REF: AMM 57-10-14-220-801	MOS HRS/MSC AFL	11250				11-JAN-1988 0 0	11250 M		7397
+ 57-10-14-220-801-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40) REF: AMM 57-10-14-220-801	MOS HRS/MSC AFL	11250				11-JAN-1988 0 0	11250 M		7397
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING REF: AMM 57-10-14-220-802	MOS HRS/MSC AFL APH	11250				11-JAN-1988 0 0 0	11250		7397



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-14-220-802	HRS/MSC					0			
		AFL	11250				0	11250		7397
		APH					0			
+ 57-10-14-220-802-02	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-14-220-802	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-14-220-802-02A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-14-220-802	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-14-250-801-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-14-250-801	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-14-250-801-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - LH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-14-250-801	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-14-250-801-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-14-250-801	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-14-250-801-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO 9 - RH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-14-250-801	HRS/MSC					0			
		AFL	11250				0	11250 M		7397



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-10-14-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING	MOS HRS/MSC REF: AMM 57-10-14-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-14-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - LH WING (MANDATORY 5-40)	MOS HRS/MSC MANDATORY 5-40 REF: AMM 57-10-14-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-14-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING	MOS HRS/MSC REF: AMM 57-10-14-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-14-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 - RH WING (MANDATORY 5-40)	MOS HRS/MSC MANDATORY 5-40 REF: AMM 57-10-14-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING	MOS HRS/MSC REF: AMM 57-10-15-220-801	AFL	11250			11-JAN-1988 0 0		11250	7397
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)	MOS HRS/MSC MANDATORY 5-40 REF: AMM 57-10-15-220-801	AFL	11250			11-JAN-1988 0 0		11250	7397
+ 57-10-15-220-801-02	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING	MOS HRS/MSC REF: AMM 57-10-15-220-801	AFL	11250			11-JAN-1988 0 0		11250 M	7397



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-10-15-220-801-02A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-15-220-801	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-15-220-802	HRS/MSC					0			
		AFL	11250				0	11250		7397
		APH					0			
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-15-220-802	HRS/MSC					0			
		AFL	11250				0	11250		7397
		APH					0			
+ 57-10-15-220-802-02	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-15-220-802	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-15-220-802-02A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-15-220-802	HRS/MSC					0			
		AFL	11250				0	11250 M		7397
+ 57-10-15-250-801-01	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - LH WING	MOS					07-JUN-1988			
57.120	REF: AMM 57-10-15-250-801	HRS/MSC					0			
		AFL	11250				0	11250		7397
+ 57-10-15-250-801-01A	SPECIAL DETAILED INSPECTION OF RIB 8 REAR WING SPAR SPLICE PLATE - LH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
57.120	REF: AMM 57-10-15-250-801	HRS/MSC					0			
MANDATORY 5-40		AFL	11250				0	11250		7397



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-10-15-250-801-02	SPECIAL DETAILED INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE - RH WING	MOS HRS/MSC REF: AMM 57-10-15-250-801	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-15-250-801-02A	SPECIAL DETAILED INSPECTION OF RIB 8 REAR WING SPAR SPLICE PLATE - RH WING (MANDATORY 5-40)	MOS HRS/MSC REF: AMM 57-10-15-250-801	AFL	11250			11-JAN-1988 0 0		11250 M	7397
	MANDATORY 5-40									
+ 57-10-15-250-802-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING	MOS HRS/MSC REF: AMM 57-10-15-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-15-250-802-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - LH WING (MANDATORY 5-40)	MOS HRS/MSC REF: AMM 57-10-15-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
	MANDATORY 5-40									
+ 57-10-15-250-802-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING	MOS HRS/MSC REF: AMM 57-10-15-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
+ 57-10-15-250-802-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 - RH WING (MANDATORY 5-40)	MOS HRS/MSC REF: AMM 57-10-15-250-802	AFL	11250			11-JAN-1988 0 0		11250 M	7397
	MANDATORY 5-40									
+ 57-10-15-250-803-01	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING	MOS HRS/MSC REF: AMM 57-10-15-250-803	AFL	11250			11-JAN-1988 0 0		11250 M	7397



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-10-15-250-803-01A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - LH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-15-250-803	HRS/MSC AFL	11250				0 0		11250 M	7397
+ 57-10-15-250-803-02	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING	MOS					11-JAN-1988			
	REF: AMM 57-10-15-250-803	HRS/MSC AFL	11250				0 0		11250 M	7397
+ 57-10-15-250-803-02A	SPECIAL DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 - RH WING (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 57-10-15-250-803	HRS/MSC AFL	11250				0 0		11250 M	7397
57-41-05-900-801-01	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCT CLOSING MECHANISMS - LH OUTBOARD SLAT TELESCOPIC DUCT (L502HJ) CLOSING MECHANISM	PN					11-JAN-1988			
		MOS		N:0			0			
		HRS/MSC	O/C	N:0			0			
	REF: AMM 57-41-05-900-801	AFL		N:0			0			
57-41-05-900-801-02	REMOVAL / INSTALLATION OF THE SLAT TELESCOPIC DUCT CLOSING MECHANISMS - RH OUTBOARD SLAT TELESCOPIC DUCT (R502HJ) CLOSING MECHANISM	PN					11-JAN-1988			
		MOS		N:0			0			
		HRS/MSC	O/C	N:0			0			
	REF: AMM 57-41-05-900-801	AFL		N:0			0			
57-45-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD SLATS - LH INBOARD SLAT	FGFB133					11-JAN-1988			
57.160		MOS					0			
		HRS/MSC	O/C	N:0			0			
	REF: AMM 57-45-01-900-801	AFL					0			
57-45-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD SLATS - RH INBOARD SLAT	FGFB143A2					23-DEC-1992			
57.170		MOS					1226			
		HRS/MSC	O/C	N:0			845			
	REF: AMM 57-45-01-900-801	AFL		N:0						



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-45-01-960-801-01	REPLACEMENT OF THE INBOARD SLATS - LH INBOARD SLAT	MOS					11-JAN-1988			
	REF: AMM 57-45-01-960-801	HRS/MSC	O/C				0			
		AFL					0			
57-45-01-960-801-02	REPLACEMENT OF THE INBOARD SLATS - RH INBOARD SLAT	MOS					11-JAN-1988			
	REF: AMM 57-45-01-960-801	HRS/MSC	O/C				0			
		AFL					0			
57-45-13-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - LH OUTBOARD SLAT	MOS					11-JAN-1988			
57.160	FGFB134	HRS/MSC	O/C	N:0			0			
	38-234	AFL					0			
	REF: AMM 57-45-13-900-801						0			
57-45-13-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD SLATS - RH OUTBOARD SLAT	MOS					11-JAN-1988			
57.170	FGFB144	HRS/MSC	O/C	N:0			0			
	38-235	AFL					0			
	REF: AMM 57-45-13-900-801						0			
57-45-13-960-801-01	REPLACEMENT OF THE OUTBOARD SLATS - LH OUTBOARD SLAT	MOS					11-JAN-1988			
	REF: AMM 57-45-13-960-801	HRS/MSC	O/C				0			
		AFL					0			
57-45-13-960-801-02	REPLACEMENT OF THE OUTBOARD SLATS - RH OUTBOARD SLAT	MOS					11-JAN-1988			
	REF: AMM 57-45-13-960-801	HRS/MSC	O/C				0			
		AFL					0			
57-45-21-900-801-01	REMOVAL / INSTALLATION OF THE SLAT ANTI-VIBRATION SYSTEM - LH SIDE	MOS					11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 57-45-21-900-801			N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-45-21-900-801-02	REMOVAL / INSTALLATION OF THE SLAT ANTI-VIBRATION SYSTEM - RH SIDE PN SN-UNKNOWN REF: AMM 57-45-21-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-45-21-910-801-01	WEAR ACCEPTANCE CRITERIA OF THE SLAT ROLLER SLIDING CONTACTS REF: AMM 57-45-21-910-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
57-45-23-900-801-01	REMOVAL / INSTALLATION OF THE SLAT SEALS - LH INBOARD SLAT SEAL PN SN-UNKNOWN REF: AMM 57-45-23-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-45-23-900-801-02	REMOVAL / INSTALLATION OF THE SLAT SEALS - RH INBOARD SLAT SEAL PN SN-UNKNOWN REF: AMM 57-45-23-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-45-23-900-801-03	REMOVAL / INSTALLATION OF THE SLAT SEALS - LH OUTBOARD SLAT SEAL PN SN-UNKNOWN REF: AMM 57-45-23-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-45-23-900-801-04	REMOVAL / INSTALLATION OF THE SLAT SEALS - RH OUTBOARD SLAT SEAL PN SN-UNKNOWN REF: AMM 57-45-23-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 57-45-25-250-801-01	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 5 AND 10 REF: AMM 57-45-25-250-801	MOS HRS/MSC AFL	7500				19-JUL-2012 6985.1 3525	11025		7172



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-45-25-250-801-02	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 1 AND 4	MOS HRS/MSC REF: AMM 57-45-25-250-801	AFL	11250			11-JAN-1988 0 0	11250		7397
57-51-01-960-801-01	REPLACEMENT OF THE WING FIXED TRAILING EDGE SEALS - LH SEALING STRIPS	MOS HRS/MSC REF: AMM 57-51-01-960-801	O/C AFL				11-JAN-1988 0 0			
57-51-01-960-801-02	REPLACEMENT OF THE WING FIXED TRAILING EDGE SEALS - RH SEALING STRIPS	MOS HRS/MSC REF: AMM 57-51-01-960-801	O/C AFL				11-JAN-1988 0 0			
+ 57-55-00-700-801-01 (s)	CHECK OF THE FLAP LATERAL CLEARANCE - LH WING	PKG 31 MOS HRS/MSC REF: AMM 57-55-00-700-801	72 AFL	+2m			PKG 21-JUN-2023 8047.2 3851			
+ 57-55-00-700-801-02 (s)	CHECK OF THE FLAP LATERAL CLEARANCE - RH WING	PKG 31 MOS HRS/MSC REF: AMM 57-55-00-700-801	72 AFL	+2m			PKG 21-JUN-2023 8047.2 3851			
57-55-01-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - LH INBOARD FLAP	FGFB161 38-227 REF: AMM 57-55-01-900-801	MOS HRS/MSC AFL	O/C	N:0		11-JAN-1988 0 0			
57-55-01-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD FLAPS - RH INBOARD FLAP	FGFB162A2 R6 REF: AMM 57-55-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0		02-DEC-1992 1218 832			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-55-05-900-801-01	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - LH OUTBOARD FLAP									
57.190	FGFB163 38-228 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-55-05-900-801-02	REMOVAL / INSTALLATION OF THE OUTBOARD FLAPS - RH OUTBOARD FLAP									
57.190	FGFB164 38-229 REF: AMM 57-55-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
+ 57-55-07-220-801-01 (s)	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - LH WING						PKG			
57.150	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
+ 57-55-07-220-801-02 (s)	DETAILED INSPECTION OF THE PROTECTION ON INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS - RH WING						PKG			
57.150	PKG 31 REF: AMM 57-55-07-220-801	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
57-55-07-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP JUNCTION FAIRINGS - LH FLAP JUNCTION FAIRING									
	PN SN-UNKNOWN REF: AMM 57-55-07-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-07-900-801-02	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP JUNCTION FAIRINGS - RH FLAP JUNCTION FAIRING									
	PN SN-UNKNOWN REF: AMM 57-55-07-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-01	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 1									
	PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-55-09-900-801-02	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 2 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-03	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH INBOARD FORE FLAP 3 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-04	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH OUTBOARD FORE FLAP 1 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-05	REMOVAL / INSTALLATION OF THE FORE FLAPS - LH OUTBOARD FORE FLAP 2 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-06	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 1 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-07	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 2 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-08	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH INBOARD FORE FLAP 3 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-55-09-900-801-09	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH OUTBOARD FORE FLAP 1 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-09-900-801-10	REMOVAL / INSTALLATION OF THE FORE FLAPS - RH OUTBOARD FORE FLAP 2 PN SN-UNKNOWN REF: AMM 57-55-09-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS PKG 31 57.210 REF: AMM 57-55-11-210-801	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
57-55-13-640-801-01 (s)	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - LH WING PKG 5 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	12 800	+1m +40			PKG 21-JUN-2023 8047.2 3851			
57-55-13-640-801-02 (s)	GREASING / LUBRICATION OF FLAP ROLLERS AND TRACKS - RH WING PKG 5 REF: AMM 57-55-13-640-801	MOS HRS/MSC AFL	12 800	+1m +40			PKG 21-JUN-2023 8047.2 3851			
57-55-13-900-801-01	REMOVAL / INSTALLATION OF THE INBOARD / OUTBOARD FLAP ROLLERS PN SN-UNKNOWN REF: AMM 57-55-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
57-55-13-960-801-01	REPLACEMENT OF THE FLAP ROLLER SLIDING PEG REF: AMM 57-55-13-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 57-55-21-250-801-01	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5									
57.200		MOS HRS/MSC					28-NOV-2018 7675			
	REF: AMM 57-55-21-250-801	AFL	3750				3744	7494		3641
+ 57-55-21-250-801-01A	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5 (MANDATORY 5-40)									
FD		MOS HRS/MSC					28-NOV-2018 7675			
	REF: AMM 57-55-21-250-801	AFL	4770				3744	8514		4661
57-60-01-900-801-01	REMOVAL / INSTALLATION OF THE AILERONS - LH AILERON									
57.140	F50B153 52-225	MOS HRS/MSC	O/C	N:0			11-JAN-1988 0			
	REF: AMM 57-60-01-900-801	AFL					0			
57-60-01-900-801-02	REMOVAL / INSTALLATION OF THE AILERONS - RH AILERON									
57.140	F50B154 52-225	MOS HRS/MSC	O/C	N:0			11-JAN-1988 0			
	REF: AMM 57-60-01-900-801	AFL					0			
57-60-03-960-801-01	REPLACEMENT OF THE AILERON BRUSHES - LH AILERON									
		MOS HRS/MSC	O/C				11-JAN-1988 0			
	REF: AMM 57-60-03-960-801	AFL					0			
57-60-03-960-801-02	REPLACEMENT OF THE AILERON BRUSHES - RH AILERON									
		MOS HRS/MSC	O/C				11-JAN-1988 0			
	REF: AMM 57-60-03-960-801	AFL					0			
57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE AILERON BEARINGS - LH AILERON BEARINGS									
57.140	PKG 31	MOS HRS/MSC	72	+2m			PKG 21-JUN-2023 8047.2			
	REF: AMM 57-60-05-640-801	AFL	3750				3851			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-60-05-640-801-02 (s) 57.140	PRESSURE LUBRICATION OF THE AILERON BEARINGS - RH AILERON BEARINGS PKG 31 REF: AMM 57-60-05-640-801	MOS HRS/MSC AFL	72	+2m			PKG 21-JUN-2023 8047.2 3851			
57-60-05-640-802-01 (s)	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - LH AILERON PKG 15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
57-60-05-640-802-02 (s)	LUBRICATION OF THE AILERON CONTROL SURFACE HINGES - RH AILERON PKG 15 REF: AMM 57-60-05-640-802	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
57-70-01-900-801-01 57.220	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH OUTBOARD AIRBRAKE FGFB165 43-234 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-70-01-900-801-02 57.220	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH MIDDLE AIRBRAKE FGFB169 43-458 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-70-01-900-801-03 57.220	REMOVAL / INSTALLATION OF THE AIRBRAKES - LH INBOARD AIRBRAKE FGFB167 43-226 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-70-01-900-801-04 57.230	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH INBOARD AIRBRAKE FGFB168 43-230 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-70-01-900-801-05	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH MIDDLE AIRBRAKE									
57.230	FGFB169 40-451 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-70-01-900-801-06	REMOVAL / INSTALLATION OF THE AIRBRAKES - RH OUTBOARD AIRBRAKE									
57.230	FGFB166 40-224 REF: AMM 57-70-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES									
	PKG 15 REF: AMM 57-70-03-640-801	MOS HRS/MSC AFL	12	+1m			PKG 21-JUN-2023 8047.2 3851			
570201	LH WING/FUSELAGE CONNECTING ROD									
57.030	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
570221	RH WING/FUSELAGE CONNECTING ROD									
57.030	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
CHAPTER 71	POWER PLANT									
71-00-00-100-801	ENGINE CLEANING									
	REF: AMM 71-00-00-100-801	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
71-00-00-700-801-01	ENGINE STARTING AND SHUTDOWN - ENGINE 1 (L4EZ)									
	REF: AMM 71-00-00-700-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
71-00-00-700-801-02	ENGINE STARTING AND SHUTDOWN - ENGINE 2 (M4EZ)	MOS						11-JAN-1988		
	REF: AMM 71-00-00-700-801	HRS/MSC	O/C					0		
		AFL						0		
71-00-00-700-801-03	ENGINE STARTING AND SHUTDOWN - ENGINE 3 (R4EZ)	MOS						11-JAN-1988		
	REF: AMM 71-00-00-700-801	HRS/MSC	O/C					0		
		AFL						0		
71-00-00-910-802-01	ENGINE INSPECTION RUN-UP - ENGINE 1 (L4EZ)	MOS						21-OCT-2011		
71.050	REF: AMM 71-00-00-910-802	HRS/MSC	O/C					6781.4		
		AFL						3423		
71-00-00-910-802-02	ENGINE INSPECTION RUN-UP - ENGINE 2 (M4EZ)	MOS						14-JAN-2016		
71.050	REF: AMM 71-00-00-910-802	HRS/MSC	O/C					7386.3		
		AFL						3666		
71-00-00-910-802-03	ENGINE INSPECTION RUN-UP - ENGINE 3 (R4EZ)	MOS						11-DEC-2009		
71.050	REF: AMM 71-00-00-910-802	HRS/MSC	O/C					6063.8		
		AFL						3056		
71-00-00-910-803	END OF INSPECTION RUN-UP	MOS						11-JAN-1988		
	REF: AMM 71-00-00-910-803	HRS/MSC	A/R					0		
		AFL						0		
71-00-00-910-805-01	WET AND DRY MOTORING	MOS						11-JAN-1988		
	REF: AMM 71-00-00-910-805	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
71-00-01-860-801-01	ENGINE 1 CUSTOMIZATION - ENGINE 1 (L4EZ)	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
71-00-01-860-802-01	ENGINE 3 CUSTOMIZATION - ENGINE 3 (R4EZ)	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
71-00-01-900-801-01	REMOVAL / INSTALLATION OF ENGINES 1 AND 3 - ENGINE 1 (L4EZ)	MOS					11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 71-00-01-900-801			N:0			0			
71-00-01-900-801-02	REMOVAL / INSTALLATION OF ENGINES 1 AND 3 - ENGINE 3 (R4EZ)	MOS					11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 71-00-01-900-801			N:0			0			
71-00-05-860-801-01	ENGINE 2 CUSTOMIZATION - ENGINE 2 (M4EZ)	MOS					11-JAN-1988			
	REF: See Workcard	HRS/MSC	O/C				0			
		AFL					0			
71-00-05-900-801-01	REMOVAL / INSTALLATION OF ENGINE 2 - ENGINE 2 (M4EZ)	MOS					11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 71-00-05-900-801			N:0			0			
71-00-09-900-801-01	REMOVAL / INSTALLATION OF THE FAN SPINNER	MOS					11-JAN-1988			
	PN	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL		N:0			0			
	REF: AMM 71-00-09-900-801			N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
71-20-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 MOUNTS - ENGINE 1 FRONT MOUNT PN SN-UNKNOWN REF: AMM 71-20-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
71-20-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 MOUNTS - ENGINE 1 AFT MOUNT PN SN-UNKNOWN REF: AMM 71-20-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
71-20-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 MOUNTS - ENGINE 3 FRONT MOUNT PN SN-UNKNOWN REF: AMM 71-20-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
71-20-01-900-801-04	REMOVAL / INSTALLATION OF THE ENGINE 1 AND 3 MOUNTS - ENGINE 3 AFT MOUNT PN SN-UNKNOWN REF: AMM 71-20-01-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
+ 71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT 54.030 REF: AMM 71-20-02-250-801	MOS HRS/MSC AFL	10000				11-JAN-1988 0 0	10000		6147
71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 1 ENGINE FRONT MOUNT (MANDATORY 5-40) MANDATORY 5-40 REF: AMM 71-20-02-250-801	MOS HRS/MSC AFL	10000				11-JAN-1988 0 0	10000		6147
+ 71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT 54.030 REF: AMM 71-20-02-250-801	MOS HRS/MSC AFL	10000				11-JAN-1988 0 0	10000		6147



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURENT) OF THE NO. 3 ENGINE FRONT MOUNT (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 71-20-02-250-801	HRS/MSC AFL	10000				0 0		10000	6147
+ 71-20-02-250-802-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 FRONT MOUNT SHACKLES - ENGINE 1 FRONT MOUNT SHACKLE	MOS					11-JAN-1988			
54.050	REF: AMM 71-20-02-250-802	HRS/MSC AFL	10000				0 0		10000	6147
+ 71-20-02-250-802-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 1 AND 3 FRONT MOUNT SHACKLES - ENGINE 3 FRONT MOUNT SHACKLE	MOS					11-JAN-1988			
54.050	REF: AMM 71-20-02-250-802	HRS/MSC AFL	10000				0 0		10000	6147
+ 71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT	MOS					11-JAN-1988			
54.040	REF: AMM 71-20-07-250-801	HRS/MSC AFL	10000				0 0		10000	6147
71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION NO. 1 ENGINE REAR MOUNT (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 71-20-07-250-801	HRS/MSC AFL	10000				0 0		10000	6147
+ 71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT	MOS					11-JAN-1988			
54.040	REF: AMM 71-20-07-250-801	HRS/MSC AFL	10000				0 0		10000	6147
71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION NO. 3 ENGINE REAR MOUNT (MANDATORY 5-40)	MOS					11-JAN-1988			
MANDATORY 5-40	REF: AMM 71-20-07-250-801	HRS/MSC AFL	10000				0 0		10000	6147



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 LH FRONT VIBRATION ISOLATOR (M900EZ1)									
71.070	LM833SA13 N/A REF: AMM 71-20-17-230-801	MOS HRS/MSC AFL	5000	+3%			14-JAN-2016 7386.3 3666	12386.3	12536.3	4337.1 (+150)
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 FRONT VIBRATION ISOLATORS / REPLACEMENT OF RUBBER CORES - ENGINE 2 RH FRONT VIBRATION ISOLATOR (M900EZ2)									
71.070	LM833SA13 N/A REF: AMM 71-20-17-230-801	MOS HRS/MSC AFL	5000	+3%			14-JAN-2016 7386.3 3666	12386.3	12536.3	4337.1 (+150)
712001	NO. 1 ENGINE FRONT UPPER SHOCK MOUNT									
71.075	3071070-4 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:6781.4 N:3423			21-OCT-2011 6781.4 3423			
712002	NO. 1 ENGINE FRONT LOWER SHOCK MOUNT									
71.075	3071070-4 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:6781.4 N:3423			21-OCT-2011 6781.4 3423			
712003	NO. 2 ENGINE LH FRONT SHOCK MOUNT									
71.070	LM833SA13 N/A REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-FEB-2004 4235.9 2352			
712004	NO. 2 ENGINE RH FRONT SHOCK MOUNT									
71.070	LM833SA13 N/A REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-FEB-2004 4235.9 2352			
712005	NO. 3 ENGINE FRONT UPPER SHOCK MOUNT									
71.080	3071070-4 SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:6063.8			09-DEC-2009 6063.8 3056			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
712006	NO. 3 ENGINE FRONT LOWER SHOCK MOUNT 3071070-4	MOS					09-DEC-2009			
71.080	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:6063.8			6063.8 3056			
712251	NO. 2 ENGINE HOIST 4219-1	MOS					11-JAN-1988			
71.040	143 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
71EN1	NO. 1 ENGINE PN NOT INSTALLED	MOS HRS/MSC AFL	E/C				14-JAN-2016 7386.3 3850			
71EN2	NO. 2 ENGINE 3075330-3	MOS					11-DEC-2009			
	P-97161C REF: AMM 71-00-05-900-801	HRS/MSC AFL	E/C	N:7039			6063.8 3666			
71EN3	NO. 3 ENGINE 3075330-3	MOS					01-JAN-2005			
	P-97149C REF: AMM 71-00-01-900-801	HRS/MSC AFL	E/C	N:5863.4			0 3056			

ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3

+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						PKG			
71.030	PKG 4	MOS					14-JAN-2016			
	REF: GENERIC NO REF	HRS/MSC ENC	800				7039 3533			
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						PKG			
71.040	PKG 4	MOS					14-JAN-2016			
	REF: GENERIC NO REF	HRS/MSC ENC	800				7039 3533			

ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						PKG			
71.030	PKG 4	MOS					19-NOV-2019			
		HRS/MSC	800				7604.8			
	REF: GENERIC NO REF	ENC					3661			
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						PKG			
71.040	PKG 4	MOS					19-NOV-2019			
		HRS/MSC	800				7604.8			
	REF: GENERIC NO REF	ENC					3661			

ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3

+ 714010 (s)	NO. 3 ENGINE - CHECK ELECTRICAL WIRING AND CONNECTIONS						PKG			
71.030	PKG 4	MOS					28-NOV-2018			
		HRS/MSC	800				7303.1			
	REF: GENERIC NO REF	ENC					3595			
+ 715010 (s)	NO. 3 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS						PKG			
71.040	PKG 4	MOS					28-NOV-2018			
		HRS/MSC	800				7303.1			
	REF: GENERIC NO REF	ENC					3595			

CHAPTER 72 ENGINE

ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3

+ 72-00-00.10	NO. 1 ENGINE - HOT START							28-MAR-1987		
		MOS					0			
		HRS/MSC	A/R				0			
	REF: LMM 72-00-00	ENC					0			
+ 72-00-00.11	NO. 1 ENGINE - SURGE BLEED VALVE OPERATION CHECK							28-MAR-1987		
		MOS					0			
		HRS/MSC	A/R				0			
	REF: LMM 72-00-00	ENC					0			
+ 72-00-00.12	NO. 1 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS							28-MAR-1987		
		MOS					0			
		HRS/MSC	A/R				0			
	REF: LMM 72-00-00	ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.13 INSP	NO. 1 ENGINE - ROUTINE PERIODIC INSPECTION	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.13 ITT	NO. 1 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 BINDING	NO. 1 ENGINE - ENGINE INTERNAL BINDING CHECKS	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 STALL	NO. 1 ENGINE - COMPRESSOR STALL	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.15 MEDRA	NO. 1 ENGINE - ENGINE PERFORMANCE EVALUATION RUN USING MANUAL ENGINE DATA REDUCTION AND ANALYSIS (MEDRA)	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 COMBUSTION	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 P3	NO. 1 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST	MOS					28-MAR-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.17	NO. 1 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.19	NO. 1 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.2	NO. 1 ENGINE - NO N2 INDICATION	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.5	NO. 1 ENGINE - NO OR LOW FUEL FLOW	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6B	NO. 1 ENGINE - N1 TRANSDUCER CIRCUIT CHECK	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6C	NO. 1 ENGINE - N2 TRANSDUCER CIRCUIT CHECK	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6D	NO. 1 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.6H	NO. 1 ENGINE - SURGE CONTROL VALVE SOLENOID CIRCUIT CHECK	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.7	NO. 1 ENGINE - FUEL LEAKAGE CHECKS	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.8	NO. 1 ENGINE - NO N1 INDICATION	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.9	NO. 1 ENGINE - HUNG START (NO OR SLOW ACCELERATION)	MOS						28-MAR-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-20-01.4A	NO. 1 ENGINE - REPAIR OF DAMAGED ABRADABLE MATERIAL	MOS						28-MAR-1987		
	REF: LMM 72-20-01	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.2	NO. 1 ENGINE - LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY INSPECTION	MOS						28-MAR-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.4	NO. 1 ENGINE - REPAIR OF LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY	MOS						28-MAR-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-40-01.1	NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER PN SN-UNKNOWN REF: LMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 72-40-01.2	NO. 1 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER TEST REF: LMM 72-40-01	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
72-40-02.1	NO. 1 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: LMM 72-40-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 72-40-02.2	NO. 1 ENGINE - COMBUSTION CHAMBER LINER INSPECTION/CHECK REF: LMM 72-40-02	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 72-40-03.1	NO. 1 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 72-40-03.2	NO. 1 ENGINE - OUTER TRANSITION LINER INSPECTION/CHECK REF: LMM 72-40-03	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
720007	NO. 1 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 720120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI)									
71.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	2500	+100			14-JAN-2016 7039 3533	(9539) 9886.3	9639	1837.1 (+100)
+ 720130 (s)	NO. 1 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES									
71.020	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	800				14-JAN-2016 7039 3533			
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				28-MAR-1987 0 0			
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				28-MAR-1987 0 0			
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				28-MAR-1987 0 0			
+ 723110	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)									
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			14-JAN-2016 7039 3533	(12039) 12386.3	12239	4337.1 (+200)
724110	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-5 7-22151-2424 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:3667 N:1455			09-OCT-1997 2083.6 1544			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 724120	NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE 3072443-5 7-22151-2424 REF: LMM 72-40-04	MOS HRS/MSC ENC	2500	+100			29-SEP-2009 5690.5 2901	(8190.5) 8537.8	8290.5	488.6 (+100)
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 70080020-1 14-156103-00762 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				14-DEC-2015 7039 3533	(13533) 13666		9813
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3074752 960322903340 REF: GENERIC NO REF	MOS HRS/MSC ENC (AFL)	10000				09-OCT-1997 2083.6 1544	(11544) 11677		7824
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3074756 961217200256 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				09-OCT-1997 2083.6 1544	(11544) 11677		7824
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC 3075227 5-18040-6609 REF: LMM 72-50-06	MOS HRS/MSC ENC	10000				28-MAR-1987 0 0	(10000) 10133		6280
725050	NO. 1 ENGINE - FAN DISC 3074641-4 5-12172-644 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				14-DEC-2015 7039 3533	(10000) 10133		6280
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395 6-03160-358 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				28-MAR-1987 0 0	(10000) 10133		6280



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396	MOS					28-MAR-1987			
72.100	5-12112-437	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10133		6280
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397	MOS					28-MAR-1987			
72.110	6-03160-683	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10133		6280
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398	MOS					09-OCT-1997			
72.120	960350102362	HRS/MSC		N:0			2083.6			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			1544	(21544) 21677		17824
725091	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS					14-DEC-2015			
72.130	7P-6333	HRS/MSC	O/C	N:11189			7039			
	REF: LMM 72-30-10	ENC		N:7965			3533			
725110	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					28-MAR-1987			
72.140	6-12172-367	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10133		6280
725130	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					28-MAR-1987			
72.150	7P-3454	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000) 12133		8280
725140	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					28-MAR-1987			
72.160	5-18040-5777	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	N:0			0	(30000) 30133		26280



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725150	NO. 1 ENGINE - FAN DRIVE SHAFT									
72.170	3074641-3 7P-8997 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
725160	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									
72.180	3077063-1 6P-28238 REF: LMM 72-50-05	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
725180	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE									
72.190	3077125-2 15-3300-02419 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			02-DEC-2015			
725190	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL									
72.200	3073765-9 96P19532 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			09-OCT-1997 2083.6 1544			
725191	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT									
72.210	3074052-2 96P19237 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			09-OCT-1997 2083.6 1544			
725230	NO. 1 ENGINE - FAN SPINNER									
72.220	3074623-3 2388 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0			09-OCT-1997 2083.6 1544			
726110	NO. 1 ENGINE - ACCESSORY GEARBOX									
72.230	3070003-31 P-4610 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 726120	NO. 1 ENGINE - INSPECT ACCESSORY GEARBOX 3070003-31 P-4610 REF: LMM 72-60-02	MOS HRS/MSC ENC	5000	+200			14-JAN-2016 7039 3533	(12039) 12386.3	12239	4337.1 (+200)
726130	NO. 1 ENGINE - TRANSFER GEARBOX 3070093-32 P-5856 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
726140	NO. 1 ENGINE - INSPECT TRANSFER GEARBOX 3070093-32 P-5856 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				14-JAN-2016 7039 3533			
+ 727110	NO. 1 ENGINE - INSPECT FAN SUPPORT ASSEMBLY REF: LMM 72-70-06	MOS HRS/MSC ENC	5000	+200			14-JAN-2016 7039 3533	(12039) 12386.3	12239	4337.1 (+200)
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3										
+ 72-00-00.10	NO. 2 ENGINE - HOT START REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				29-JAN-1987 0 0			
+ 72-00-00.11	NO. 2 ENGINE - SURGE BLEED VALVE OPERATION CHECK REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				29-JAN-1987 0 0			
+ 72-00-00.12	NO. 2 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				29-JAN-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.13 INSP	NO. 2 ENGINE - ROUTINE PERIODIC INSPECTION	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.13 ITT	NO. 2 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 BINDING	NO. 2 ENGINE - ENGINE INTERNAL BINDING CHECKS	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 STALL	NO. 2 ENGINE - COMPRESSOR STALL	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.15 MEDRA	NO. 2 ENGINE - ENGINE PERFORMANCE EVALUATION RUN USING MANUAL ENGINE DATA REDUCTION AND ANALYSIS (MEDRA)	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 COMBUSTION	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 P3	NO. 2 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST	MOS					29-JAN-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.17	NO. 2 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.19	NO. 2 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.2	NO. 2 ENGINE - NO N2 INDICATION	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.5	NO. 2 ENGINE - NO OR LOW FUEL FLOW	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6B	NO. 2 ENGINE - N1 TRANSDUCER CIRCUIT CHECK	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6C	NO. 2 ENGINE - N2 TRANSDUCER CIRCUIT CHECK	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6D	NO. 2 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.6H	NO. 2 ENGINE - SURGE CONTROL VALVE SOLENOID CIRCUIT CHECK	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.7	NO. 2 ENGINE - FUEL LEAKAGE CHECKS	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.8	NO. 2 ENGINE - NO N1 INDICATION	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.9	NO. 2 ENGINE - HUNG START (NO OR SLOW ACCELERATION)	MOS						29-JAN-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-20-01.4A	NO. 2 ENGINE - REPAIR OF DAMAGED ABRADABLE MATERIAL	MOS						29-JAN-1987		
	REF: LMM 72-20-01	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.2	NO. 2 ENGINE - LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY INSPECTION	MOS						29-JAN-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.4	NO. 2 ENGINE - REPAIR OF LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY	MOS						29-JAN-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-40-01.1	NO. 2 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER PN SN-UNKNOWN REF: LMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				29-JAN-1987 0 0		
+ 72-40-01.2	NO. 2 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER TEST REF: LMM 72-40-01	MOS HRS/MSC ENC	A/R					29-JAN-1987 0 0		
72-40-02.1	NO. 2 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: LMM 72-40-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				29-JAN-1987 0 0		
+ 72-40-02.2	NO. 2 ENGINE - COMBUSTION CHAMBER LINER INSPECTION/CHECK REF: LMM 72-40-02	MOS HRS/MSC ENC	A/R					29-JAN-1987 0 0		
+ 72-40-03.1	NO. 2 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				29-JAN-1987 0 0		
+ 72-40-03.2	NO. 2 ENGINE - OUTER TRANSITION LINER INSPECTION/CHECK REF: LMM 72-40-03	MOS HRS/MSC ENC	A/R					29-JAN-1987 0 0		
720007	NO. 2 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R					29-JAN-1987 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 720120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI)									
71.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	2500	+100			11-DEC-2009 5886.7 2938	(8386.7) 8587.1	8486.7	537.9 (+100)
+ 720130 (s)	NO. 2 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES									
71.020	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	800				19-NOV-2019 7604.8 3661			
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				29-JAN-1987 0 0 0			
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				29-JAN-1987 0 0 0			
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				29-JAN-1987 0 0 0			
+ 723110	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)									
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			11-DEC-2009 5886.7 2938	(10886.7) 11087.1	11086.7	3037.9 (+200)
724110	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-5 8P-16197 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:6335 N:6766			02-JAN-1998 2135.3 1546			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 724120	NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE 3072443-5 8P-16197 REF: LMM 72-40-04	MOS HRS/MSC ENC	2500	+100			11-DEC-2009 5886.7 2938	(8386.7) 8587.1	8486.7	537.9 (+100)
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3074747 6-23315-505 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				29-JAN-1987 0 0	(10000) 10118		6265
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3074752 960322905259 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				02-JAN-1998 2135.3 1546	(11546) 11664		7811
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3074756 961217200277 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				02-JAN-1998 2135.3 1546	(11546) 11664		7811
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3075227 5-18040-6603 REF: LMM 72-50-06	MOS HRS/MSC ENC	10000				29-JAN-1987 0 0	(10000) 10118		6265
725050	NO. 2 ENGINE - FAN DISC 3074621 5-12172-684 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				29-JAN-1987 0 0	(10000) 10118		6265
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395 6-03501-2529 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				29-JAN-1987 0 0	(10000) 10118		6265



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396	MOS					29-JAN-1987			
72.100	5-12112-377	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10118		6265
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397	MOS					29-JAN-1987			
72.110	5-03160-638	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10118		6265
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398	MOS					02-JAN-1998			
72.120	960350104259	HRS/MSC		N:0			2135.3			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			1546	(21546) 21664		17811
725091	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS					29-JAN-1987			
72.130	6P-22332	HRS/MSC	O/C	N:0			0			
	REF: LMM 72-30-10	ENC		N:0			0			
725110	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					29-JAN-1987			
72.140	6-12112-787	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10118		6265
725130	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					29-JAN-1987			
72.150	6P-30013	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000) 12118		8265
725140	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					29-JAN-1987			
72.160	6-18040-510	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	N:0			0	(30000) 30118		26265



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725150	NO. 2 ENGINE - FAN DRIVE SHAFT									
72.170	3074641-3 7P-932 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
725160	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT									
72.180	3072592-3 96P20197 REF: LMM 72-50-05	MOS HRS/MSC ENC	O/C	N:0 N:0			02-JAN-1998 2135.3 1546			
725180	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE									
72.190	3075715-2 97P-05004 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			02-JAN-1998 2135.3 1546			
725190	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL									
72.200	3073765-9 97P05904 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			02-JAN-1998 2135.3 1546			
725191	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT									
72.210	3074052-2 97P05768 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			02-JAN-1998 2135.3 1546			
725230	NO. 2 ENGINE - FAN SPINNER									
72.220	3074623-3 2387 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0			02-JAN-1998 2135.3 1546			
726110	NO. 2 ENGINE - ACCESSORY GEARBOX									
72.230	3070003-31 P4562 REF: LMM 72-60-02	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 726120	NO. 2 ENGINE - INSPECT ACCESSORY GEARBOX 3070003-31 P4562 REF: LMM 72-60-02	MOS HRS/MSC ENC	5000	+200			11-DEC-2009 5886.7 2938	(10886.7) 11087.1	11086.7	3037.9 (+200)
726130	NO. 2 ENGINE - TRANSFER GEARBOX 3070093-12 P5810 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
726140	NO. 2 ENGINE - INSPECT TRANSFER GEARBOX 3070093-12 P5810 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				29-JAN-1987 0 0			
+ 727110	NO. 2 ENGINE - INSPECT FAN SUPPORT ASSEMBLY REF: LMM 72-70-06	MOS HRS/MSC ENC	5000	+200			11-DEC-2009 5886.7 2938	(10886.7) 11087.1	11086.7	3037.9 (+200)
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3										
+ 72-00-00.10	NO. 3 ENGINE - HOT START REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
+ 72-00-00.11	NO. 3 ENGINE - SURGE BLEED VALVE OPERATION CHECK REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
+ 72-00-00.12	NO. 3 ENGINE - SURGE BLEED VALVE AND SOLENOID CONTROLLER CHECKS REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.13 INSP	NO. 3 ENGINE - ROUTINE PERIODIC INSPECTION	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.13 ITT	NO. 3 ENGINE - INTERSTAGE TURBINE TEMPERATURE (ITT) CIRCUITRY CHECKS	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 BINDING	NO. 3 ENGINE - ENGINE INTERNAL BINDING CHECKS	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.14 STALL	NO. 3 ENGINE - COMPRESSOR STALL	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.15 MEDRA	NO. 3 ENGINE - ENGINE PERFORMANCE EVALUATION RUN USING MANUAL ENGINE DATA REDUCTION AND ANALYSIS (MEDRA)	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 COMBUSTION	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE PERIODIC INSPECTION	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			
+ 72-00-00.16 P3	NO. 3 ENGINE - COMPRESSOR DISCHARGE PRESSURE (P3) LIMITER VALVE FUNCTIONAL TEST	MOS					17-FEB-1987			
	REF: LMM 72-00-00	HRS/MSC	A/R				0			
		ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.17	NO. 3 ENGINE - COMPRESSOR ZONE PERIODIC INSPECTION	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.19	NO. 3 ENGINE - COMBUSTION CHAMBER LINER BORESCOPE INSPECTION	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.2	NO. 3 ENGINE - NO N2 INDICATION	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.5	NO. 3 ENGINE - NO OR LOW FUEL FLOW	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6B	NO. 3 ENGINE - N1 TRANSDUCER CIRCUIT CHECK	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6C	NO. 3 ENGINE - N2 TRANSDUCER CIRCUIT CHECK	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.6D	NO. 3 ENGINE - INLET TEMPERATURE (T2) SENSOR CIRCUIT CHECK	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-00-00.6H	NO. 3 ENGINE - SURGE CONTROL VALVE SOLENOID CIRCUIT CHECK	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.7	NO. 3 ENGINE - FUEL LEAKAGE CHECKS	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.8	NO. 3 ENGINE - NO N1 INDICATION	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-00-00.9	NO. 3 ENGINE - HUNG START (NO OR SLOW ACCELERATION)	MOS						17-FEB-1987		
	REF: LMM 72-00-00	HRS/MSC	A/R					0		
		ENC						0		
+ 72-20-01.4A	NO. 3 ENGINE - REPAIR OF DAMAGED ABRADABLE MATERIAL	MOS						17-FEB-1987		
	REF: LMM 72-20-01	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.2	NO. 3 ENGINE - LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY INSPECTION	MOS						17-FEB-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		
+ 72-30-04.4	NO. 3 ENGINE - REPAIR OF LOW PRESSURE FIRST STAGE COMPRESSOR ROTOR ASSEMBLY	MOS						17-FEB-1987		
	REF: LMM 72-30-04	HRS/MSC	A/R					0		
		ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 72-40-01.1	NO. 3 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER PN SN-UNKNOWN REF: LMM 72-40-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-FEB-1987 0 0			
+ 72-40-01.2	NO. 3 ENGINE - PLENUM CASE DRAIN VALVE AND HP BLEED AIR PORT COVER TEST REF: LMM 72-40-01	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
72-40-02.1	NO. 3 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: LMM 72-40-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-FEB-1987 0 0			
+ 72-40-02.2	NO. 3 ENGINE - COMBUSTION CHAMBER LINER INSPECTION/CHECK REF: LMM 72-40-02	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
+ 72-40-03.1	NO. 3 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			17-FEB-1987 0 0			
+ 72-40-03.2	NO. 3 ENGINE - OUTER TRANSITION LINER INSPECTION/CHECK REF: LMM 72-40-03	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
720007	NO. 3 ENGINE - SPECIAL INSPECTION - HP IMPELLER BORESCOPE INSPECTION REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 720120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI)									
71.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	2500	+100			21-OCT-2011 6419.5 3274	(8919.5) 9291.4	9019.5	1242.2 (+100)
+ 720130 (s)	NO. 3 ENGINE - INSPECT FAN ROTOR ASSEMBLY BLADES									
71.020	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	800				PKG 28-NOV-2018 7303.1 3595			
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				17-FEB-1987 0 0 0			
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				17-FEB-1987 0 0 0			
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE									
72.001	REF: LMM 72-00-00	MOS HRS/MSC ENC (AFL)	O/C				17-FEB-1987 0 0 0			
+ 723110	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)									
72.010	REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			21-OCT-2011 6419.5 3274	(11419.5) 11791.4	11619.5	3742.2 (+200)
724110	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE									
72.020	3072443-5 6P-15465 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 724120	NO. 3 ENGINE - INSPECT COMBUSTION CHAMBER PLENUM CASE 3072443-5 6P-15465 REF: LMM 72-40-04	MOS HRS/MSC ENC	2500	+100			21-OCT-2011 6419.5 3274	(8919.5) 9291.4	9019.5	1242.2 (+100)
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3074747 6-23315-470 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0			17-FEB-1987 0 0	(10000) 10149		6296
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3074752-1 960322905257 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0			02-JAN-1998 2010.6 1537	(11537) 11686		7833
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3074756-1 951217201540 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0			02-JAN-1998 2010.6 1537	(11537) 11686		7833
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC 3075227 5-18040-6700 REF: LMM 72-50-06	MOS HRS/MSC ENC	10000	N:0 N:0			17-FEB-1987 0 0	(10000) 10149		6296
725050	NO. 3 ENGINE - FAN DISC 3074621-3 6-12112-1770 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:3723 N:1517			02-JAN-1998 2010.6 1537	(10020) 10169		6316
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395 5-03160-477 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0			17-FEB-1987 0 0	(10000) 10149		6296



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3072396	MOS					17-FEB-1987			
72.100	5-12112-433	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10149		6296
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3072397	MOS					17-FEB-1987			
72.110	5-03160-574	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10149		6296
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3072398	MOS					02-JAN-1998			
72.120	960350102360	HRS/MSC		N:0			2010.6			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			1537	(21537) 21686		17833
725091	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1	MOS					17-FEB-1987			
72.130	6P-22355	HRS/MSC	O/C	N:0			0			
	REF: LMM 72-30-10	ENC		N:0			0			
725110	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3073398-1	MOS					17-FEB-1987			
72.140	6-12112-1770	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10149		6296
725130	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3072545-1	MOS					17-FEB-1987			
72.150	6P-30002	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000) 12149		8296
725140	NO. 3 ENGINE - HIGH PRESSURE TURBINE ROTOR SEAL PLATE 3077065-1	MOS					17-FEB-1987			
72.160	6-18040-507	HRS/MSC		N:0			0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	30000	N:0			0	(30000) 30149		26296



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725150	NO. 3 ENGINE - FAN DRIVE SHAFT 3074641-3	MOS						17-FEB-1987		
72.170	7P-2297 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			0 0			
725160	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3077063-1	MOS						17-FEB-1987		
72.180	6P-28242 REF: LMM 72-50-05	HRS/MSC ENC	O/C	N:0 N:0			0 0			
725180	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE NOZZLE 3075715-1	MOS						02-JAN-1998		
72.190	97P01941 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
725190	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL 3073765-9	MOS						02-JAN-1998		
72.200	97P03051 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
725191	NO. 3 ENGINE - LOW PRESSURE TURBINE ROTATING AIR SEAL SUPPORT 3074052-2	MOS						02-JAN-1998		
72.210	97P04726 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
725230	NO. 3 ENGINE - FAN SPINNER 3074623-3	MOS						02-JAN-1998		
72.220	971326200712 REF: See Workcard	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
726110	NO. 3 ENGINE - ACCESSORY GEARBOX 3070003-31	MOS						17-FEB-1987		
72.230	P4564 REF: LMM 72-60-02	HRS/MSC ENC	O/C	N:0 N:0			0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 726120	NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX									
72.240	3070003-31 P4564 REF: LMM 72-60-02	MOS HRS/MSC ENC	5000	+200			21-OCT-2011 6419.5 3274	(11419.5) 11791.4	11619.5	3742.2 (+200)
726130	NO. 3 ENGINE - TRANSFER GEARBOX									
72.250	3070093-12 P5819 REF: LMM 72-60-01	MOS HRS/MSC ENC	O/C	N:0 N:0			17-FEB-1987 0 0			
726140	NO. 3 ENGINE - INSPECT TRANSFER GEARBOX									
72.250	3070093-12 P5819 REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				17-FEB-1987 0 0			
+ 727110	NO. 3 ENGINE - INSPECT FAN SUPPORT ASSEMBLY									
72.270	REF: LMM 72-70-06	MOS HRS/MSC ENC	5000	+200			21-OCT-2011 6419.5 3274	(11419.5) 11791.4	11619.5	3742.2 (+200)
CHAPTER 73	ENGINE FUEL AND CONTROL									
+ 73-20-01-710-802-01 (s)	OPERATIONAL TEST OF THE ENGINE 1 COMPUTER STAND-BY POWER SUPPLY						PKG			
73.075	PKG 21 REF: AMM 73-20-01-710-802	MOS HRS/MSC AFL	1600	+40			11-NOV-2015 7355.5 3656			
+ 73-20-01-710-802-01A	OPERATIONAL TEST OF THE NO. 1 ENGINE COMPUTER STAND-BY POWER SUPPLY (MANDATORY 5-40)									
73.075 MANDATORY 5-40	REF: AMM 73-20-01-710-802	MOS HRS/MSC AFL	1640				11-NOV-2015 7355.5 3656	8995.5		946.3
73-30-12-900-801-04	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 1/TOTAL FUEL USED INDICATOR (2EH1)									
73.080	9-464-30 811 REF: AMM 73-30-12-900-801	MOS HRS/MSC AFL	O/C				14-MAR-1990 482 336			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
73-30-12-900-801-05	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 2/TOTAL FUEL USED INDICATOR (2EH2)									
73.080	9-464-30A 966 REF: AMM 73-30-12-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
73-30-12-900-801-06	REMOVAL / INSTALLATION OF THE FUEL FLOW INDICATORS - FLOWMETER 3/TOTAL FUEL USED INDICATOR (2EH3)									
73.080	9-464-30 707 REF: AMM 73-30-12-900-801	MOS HRS/MSC AFL	O/C				11-OCT-1989 382 236			
732101	NO. 1 ENGINE FUEL COMPUTER									
73.070	2118002-60 108-117 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				09-OCT-1997 2185 1589			
732102	NO. 2 ENGINE FUEL COMPUTER									
73.070	2118002-60 78-1142 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				09-OCT-1997 2185 1589			
732103	NO. 3 ENGINE FUEL COMPUTER									
73.070	2118002-60 70-1594 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				09-OCT-1997 2185 1589			
733151	NO. 1 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 1639 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1445 N:993			10-FEB-1994 1495 1038			
733152	NO. 2 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 1635 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1329 N:921			23-JUL-1993 1370 940			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
733153	NO. 3 ENGINE FUEL FLOW TRANSMITTER									
73.090	9-231-14 1815 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1370 N:941			05-NOV-1993 1445 993			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3										
+ 73-10-01.1	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY									
	PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 73-10-01.2	NO. 1 ENGINE - FUEL MANIFOLD ASSEMBLY INSPECTION/CHECK									
	REF: LMM 73-10-01	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 73-10-04.2	NO. 1 ENGINE - FUEL HEATER AND CHECK VALVE INSPECTION/CHECK									
	REF: LMM 73-10-04	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 73-10-2.1	NO. 1 ENGINE - FUEL AND P3 SENSING LINES INSTALLATION									
	REF: LMM 73-10-02	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 73-10-3.1	NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES									
	PN SN-UNKNOWN REF: LMM 73-10-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 73-10-3.2	NO. 1 ENGINE - SERVICE TUBES CLAMP AND TUBES INSPECTION/CHECK									
	REF: LMM 73-10-03	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 73-20-01.2	NO. 1 ENGINE - FUEL SYSTEMS INSPECTION/CHECK REF: LMM 73-20-01	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 73-21-01.1	NO. 1 ENGINE - FUEL CONTROL COMPONENTS REF: LMM 73-21-01	PN SN-UNKNOWN ENC	MOS HRS/MSC O/C		N:0 N:0 N:0		28-MAR-1987 0 0			
+ 73-21-01.2	NO. 1 ENGINE - FUEL CONTROL COMPONENTS INSPECTION/CHECK REF: LMM 73-21-01	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
731110 73.010	NO. 1 ENGINE - FUEL PUMP 3070850-57 MX445830 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0		28-MAR-1987 0 0			
731120 (s) 73.010	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: See Workcard	MOS HRS/MSC ENC	300	+100			PKG 31-MAY-2022			
731130 73.030	NO. 1 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1 6759 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0		28-MAR-1987 0 0			
731140 73.040	NO. 1 ENGINE - FUEL HEATER 158670-5 36-4451 REF: LMM 73-10-04	MOS HRS/MSC ENC	O/C		N:0 N:0		28-MAR-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 731150 (s)	NO. 1 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE)						PKG			
73.050	PKG 4	MOS					14-JAN-2016			
	REF: LMM 79-20-06	HRS/MSC	800				7039			
		ENC					3533			
731160	NO. 1 ENGINE - FUEL HEATER CHECK VALVE									
73.060	3073932-4	MOS					28-MAR-1987			
	6-20404-177	HRS/MSC	O/C	N:0			0			
	REF: LMM 73-10-04	ENC		N:0			0			
732110	NO. 1 ENGINE - FUEL CONTROL UNIT									
73.070	3070800-26	MOS		O:0			17-DEC-2010			
	A10866	HRS/MSC	O/C	O:0			6195.6			
	REF: LMM 73-20-01	ENC		O:0			3173			
732120	NO. 1 ENGINE - PRESSURE LIMITER VALVE									
73.080	3070685-6	MOS					09-OCT-1997			
	A9106	HRS/MSC	O/C				2083.6			
	REF: GENERIC NO REF	ENC					1544			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3										
+ 73-10-01.1	NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY									
	PN	MOS		N:0			29-JAN-1987			
	SN-UNKNOWN	HRS/MSC	A/R	N:0			0			
	REF: LMM 73-10-01	ENC		N:0			0			
+ 73-10-01.2	NO. 2 ENGINE - FUEL MANIFOLD ASSEMBLY INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 73-10-01	ENC					0			
+ 73-10-04.2	NO. 2 ENGINE - FUEL HEATER AND CHECK VALVE INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 73-10-04	ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 73-10-2.1	NO. 2 ENGINE - FUEL AND P3 SENSING LINES INSTALLATION	MOS						29-JAN-1987		
	REF: LMM 73-10-02	HRS/MSC A/R						0		
		ENC						0		
+ 73-10-3.1	NO. 2 ENGINE - SERVICE TUBES CLAMP AND TUBES	MOS						29-JAN-1987		
	PN	HRS/MSC O/C		N:0				0		
	SN-UNKNOWN	ENC		N:0				0		
	REF: LMM 73-10-03			N:0				0		
+ 73-10-3.2	NO. 2 ENGINE - SERVICE TUBES CLAMP AND TUBES INSPECTION/CHECK	MOS						29-JAN-1987		
	REF: LMM 73-10-03	HRS/MSC A/R						0		
		ENC						0		
+ 73-20-01.2	NO. 2 ENGINE - FUEL SYSTEMS INSPECTION/CHECK	MOS						29-JAN-1987		
	REF: LMM 73-20-01	HRS/MSC A/R						0		
		ENC						0		
+ 73-21-01.1	NO. 2 ENGINE - FUEL CONTROL COMPONENTS	MOS						29-JAN-1987		
	PN	HRS/MSC O/C		N:0				0		
	SN-UNKNOWN	ENC		N:0				0		
	REF: LMM 73-21-01			N:0				0		
+ 73-21-01.2	NO. 2 ENGINE - FUEL CONTROL COMPONENTS INSPECTION/CHECK	MOS						29-JAN-1987		
	REF: LMM 73-21-01	HRS/MSC A/R						0		
		ENC						0		
731110	NO. 2 ENGINE - FUEL PUMP	MOS						29-JAN-1987		
	3070850-57	HRS/MSC O/C		N:0				0		
73.010	MX-444256	ENC		N:0				0		
	REF: See Workcard			N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2	MOS					PKG			
73.010	REF: See Workcard	HRS/MSC ENC	300	+100			31-MAY-2022			
731130	NO. 2 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1	MOS					29-JAN-1987			
73.030	6573 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			0 0			
731140	NO. 2 ENGINE - FUEL HEATER 158670-5	MOS					29-JAN-1987			
73.040	36-4414 REF: LMM 73-10-04	HRS/MSC ENC	O/C	N:0 N:0			0 0			
+ 731150 (s)	NO. 2 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) PKG 4	MOS					PKG			
73.050	REF: LMM 79-20-06	HRS/MSC ENC	800				19-NOV-2019 7604.8 3661			
731160	NO. 2 ENGINE - FUEL HEATER CHECK VALVE 3073932-4	MOS					29-JAN-1987			
73.060	6-20404-153 REF: LMM 73-10-04	HRS/MSC ENC	O/C	N:0 N:0			0 0			
732110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-26	MOS					02-JAN-1998			
73.070	A8256C REF: LMM 73-20-01	HRS/MSC ENC	O/C				2135.3 1546			
732120	NO. 2 ENGINE - PRESSURE LIMITER VALVE 3070685-6	MOS					29-JAN-1987			
73.080	A9082 REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			0 0			

ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 73-10-01.1	NO. 3 ENGINE - FUEL MANIFOLD ASSEMBLY PN SN-UNKNOWN REF: LMM 73-10-01	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0				17-FEB-1987 0 0		
+ 73-10-01.2	NO. 3 ENGINE - FUEL MANIFOLD ASSEMBLY INSPECTION/CHECK REF: LMM 73-10-01	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		
+ 73-10-04.2	NO. 3 ENGINE - FUEL HEATER AND CHECK VALVE INSPECTION/CHECK REF: LMM 73-10-04	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		
+ 73-10-2.1	NO. 3 ENGINE - FUEL AND P3 SENSING LINES INSTALLATION REF: LMM 73-10-02	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		
+ 73-10-3.1	NO. 3 ENGINE - SERVICE TUBES CLAMP AND TUBES PN SN-UNKNOWN REF: LMM 73-10-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				17-FEB-1987 0 0		
+ 73-10-3.2	NO. 3 ENGINE - SERVICE TUBES CLAMP AND TUBES INSPECTION/CHECK REF: LMM 73-10-03	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		
+ 73-20-01.2	NO. 3 ENGINE - FUEL SYSTEMS INSPECTION/CHECK REF: LMM 73-20-01	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 73-21-01.1	NO. 3 ENGINE - FUEL CONTROL COMPONENTS PN SN-UNKNOWN REF: LMM 73-21-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				17-FEB-1987 0 0		
+ 73-21-01.2	NO. 3 ENGINE - FUEL CONTROL COMPONENTS INSPECTION/CHECK REF: LMM 73-21-01	MOS HRS/MSC ENC	A/R					17-FEB-1987 0 0		
731110 73.010	NO. 3 ENGINE - FUEL PUMP 3070850-57 MX444252 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0				17-FEB-1987 0 0		
731120 (s) 73.010	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: See Workcard	MOS HRS/MSC ENC	300	+100				PKG 31-MAY-2022 7595.1 3678		
731130 73.030	NO. 3 ENGINE - FLOW DIVIDER/DRAIN VALVE 394396-2-1 6569 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0				17-FEB-1987 0 0		
731140 73.040	NO. 3 ENGINE - FUEL HEATER 158670-3 36-4413 REF: LMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0				17-FEB-1987 0 0		
+ 731150 (s) 73.050	NO. 3 ENGINE - CHECK FUEL HEATER OIL TUBES (FLUID TRANSFER TUBE) PKG 4 REF: LMM 79-20-06	MOS HRS/MSC ENC	800					PKG 28-NOV-2018 7303.1 3595		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731160	NO. 3 ENGINE - FUEL HEATER CHECK VALVE									
73.060	3073932-4 6-20404-152 REF: LMM 73-10-04	MOS HRS/MSC ENC	O/C	N:0 N:0			17-FEB-1987 0 0			
732110	NO. 3 ENGINE - FUEL CONTROL UNIT									
73.070	3070800-26 A10614C REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	R:1 R:0 R:0			08-FEB-2015 6907.1 3480			
732120	NO. 3 ENGINE - PRESSURE LIMITER VALVE									
73.080	3070685-6 A-9066 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			17-FEB-1987 0 0			
CHAPTER 74 IGNITION										
74-00-00	IGNITION									
	REF: See Workcard	MOS HRS/MSC AFL	A/R				11-JAN-1988 0 0			
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3										
+ 74-00-01.2	NO. 1 ENGINE - IGNITION UNIT AND IGNITER PLUG INSPECTION/CHECK									
	REF: LMM 74-00-01	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
741110	NO. 1 ENGINE - IGNITION UNIT									
74.010	3073914 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				09-OCT-1997 2083.6 1544			
+ 741120 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM									
74.010	PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1200	+200			PKG 14-JAN-2016 7039 3533			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
742110	NO. 1 ENGINE - 6 O'CLOCK IGNITOR PLUG 3074541-1 9773996 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				09-OCT-1997 2083.6 1544		
+ 742120 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				PKG			
742130	NO. 1 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-1 9774017 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				09-OCT-1997 2083.6 1544		
+ 742140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				PKG 14-JAN-2016 7039 3533			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3										
+ 74-00-01.2	NO. 2 ENGINE - IGNITION UNIT AND IGNITER PLUG INSPECTION/CHECK REF: LMM 74-00-01	MOS HRS/MSC ENC	A/R					29-JAN-1987 0 0		
741110	NO. 2 ENGINE - IGNITION UNIT 3073914 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0				29-JAN-1987 0 0		
+ 741120 (s)	NO. 2 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1200	+200			PKG 16-JUL-2012 6784.7 3407			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
742110	NO. 2 ENGINE - 6 O'CLOCK IGNITOR PLUG 3074541-1 9774007 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			02-JAN-1998 2135.3 1546			
+ 742120 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				PKG 28-NOV-2018 7474.6 3626			
742130	NO. 2 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-1 9774018 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			02-JAN-1998 2135.3 1546			
+ 742140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600				PKG 28-NOV-2018 7474.6 3626			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3										
+ 74-00-01.2	NO. 3 ENGINE - IGNITION UNIT AND IGNITER PLUG INSPECTION/CHECK REF: LMM 74-00-01	MOS HRS/MSC ENC	A/R				17-FEB-1987 0 0			
741110	NO. 3 ENGINE - IGNITION UNIT 3073914-4 92392789 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C				02-JAN-1998 2010.6 1537			
+ 741120 (s)	NO. 3 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1200	+200			PKG 21-OCT-2011 6419.5 3274			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
742110	NO. 3 ENGINE - 6 O'CLOCK IGNITOR PLUG 3074541-1	MOS		N:0			02-JAN-1998			
74.030	9782116 REF: LMM 74-00-01	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
+ 742120 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 6 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG 21-OCT-2011			
74.030	REF: LMM 74-00-01	HRS/MSC ENC	1600				6419.5 3274			
742130	NO. 3 ENGINE - 7 O'CLOCK IGNITOR PLUG 3074541-1	MOS					02-JAN-1998			
74.050	9782116 REF: LMM 74-00-01	HRS/MSC ENC	O/C	N:0 N:0			2010.6 1537			
+ 742140 (s)	NO. 3 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEADS IN PLACE PKG 5	MOS					PKG 21-OCT-2011			
74.050	REF: LMM 74-00-01	HRS/MSC ENC	1600				6419.5 3274			
CHAPTER 75 AIR										
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3										
+ 75-10-05.1	NO. 1 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT PN	MOS		N:0			28-MAR-1987			
	SN-UNKNOWN REF: LMM 75-10-05	HRS/MSC ENC	O/C	N:0 N:0			0 0			
+ 75-10-05.2	NO. 1 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT INSPECTION/CHECK	MOS					28-MAR-1987			
	REF: LMM 75-10-05	HRS/MSC ENC	A/R				0 0			
+ 75-40-01.2	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR INSPECTION/CHECK	MOS					28-MAR-1987			
	REF: LMM 75-40-01	HRS/MSC ENC	A/R				0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
750130	NO. 1 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR									
	3070816-12	MOS					09-OCT-1997			
75.010	53809	HRS/MSC	O/C	N:147			2083.6			
	REF: LMM 75-40-01	ENC		N:138			1544			

ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3

+ 75-10-05.1	NO. 2 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT									
	PN	MOS		N:0			29-JAN-1987			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: LMM 75-10-05	ENC		N:0			0			

+ 75-10-05.2	NO. 2 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 75-10-05	ENC					0			

+ 75-40-01.2	NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 75-40-01	ENC					0			

750130	NO. 2 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR									
	3070816-4	MOS					29-JAN-1987			
75.010	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: LMM 75-40-01	ENC		N:0			0			

ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3

+ 75-10-05.1	NO. 3 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT									
	PN	MOS		N:0			17-FEB-1987			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: LMM 75-10-05	ENC		N:0			0			

+ 75-10-05.2	NO. 3 ENGINE - ENGINE ANTI-ICING BLEED AIR DUCT INSPECTION/CHECK									
		MOS					17-FEB-1987			
		HRS/MSC	A/R				0			
	REF: LMM 75-10-05	ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 75-40-01.2	NO. 3 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR INSPECTION/CHECK							17-FEB-1987		
		MOS						0		
	REF: LMM 75-40-01	HRS/MSC A/R						0		
		ENC						0		
750130	NO. 3 ENGINE - INLET PRESSURE/TEMPERATURE SENSOR									
	3070816-12	MOS		N:0				15-MAR-2010		
75.010	091789319666	HRS/MSC	O/C	N:0				5869		
	REF: LMM 75-40-01	ENC		N:0				3010		
CHAPTER 76 ENGINE CONTROLS										
+ 76-10-00-220-801-01	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 1									
		MOS						17-OCT-2017		
76.030		HRS/MSC	O/C					7585.5		
	REF: AMM 76-10-00-220-801	AFL						3720		
+ 76-10-00-220-801-02	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 2									
		MOS						17-OCT-2017		
76.030		HRS/MSC	O/C					7585.5		
	REF: AMM 76-10-00-220-801	AFL						3720		
+ 76-10-00-220-801-03	CHECK OF THE THROTTLE LEVERS FOR FRICTION POINTS - ENGINE 3									
		MOS						17-OCT-2017		
76.030		HRS/MSC	O/C					7585.5		
	REF: AMM 76-10-00-220-801	AFL						3720		
76-10-00-220-802-01	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 1									
		MOS						21-OCT-2011		
76.060		HRS/MSC	O/C					6781.4		
	REF: AMM 76-10-00-220-802	AFL						3423		
76-10-00-220-802-02	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 2									
		MOS						14-JAN-2016		
76.060		HRS/MSC	O/C					7386.3		
	REF: AMM 76-10-00-220-802	AFL						3666		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-00-220-802-03	MEASUREMENT OF THE THROTTLE LEVER OPERATING FORCES - ENGINE 3									
76.060		MOS						11-DEC-2009		
	REF: AMM 76-10-00-220-802	HRS/MSC	O/C					6063.8		
		AFL						3056		
76-10-00-700-802-01	CHECK OF THE ADJUSTMENT OF THE THROTTLE CONTROL									
		MOS						11-JAN-1988		
	REF: AMM 76-10-00-700-802	HRS/MSC	O/C					0		
		AFL						0		
76-10-00-820-802-01	ADJUSTMENT OF THE THROTTLE CONTROLS - CHECK AND ADJUSTMENT OF ENGINE 1 THROTTLE CONTROL AT THE TORQUE TUBE									
		MOS						11-JAN-1988		
	REF: AMM 76-10-00-820-802	HRS/MSC	O/C					0		
		AFL						0		
76-10-00-820-802-02	ADJUSTMENT OF THE THROTTLE CONTROLS - CHECK AND ADJUSTMENT OF ENGINE 3 THROTTLE CONTROL AT THE TORQUE TUBE									
		MOS						11-JAN-1988		
	REF: AMM 76-10-00-820-802	HRS/MSC	O/C					0		
		AFL						0		
76-10-00-820-802-03	ADJUSTMENT OF THE THROTTLE CONTROLS - CHECK AND ADJUSTMENT OF ENGINE 1, 2 AND 3 THROTTLE LEVERS FOR TRAVEL EQUALIZATION									
		MOS						11-JAN-1988		
	REF: AMM 76-10-00-820-802	HRS/MSC	O/C					0		
		AFL						0		
76-10-01-820-801-01	CHECK / ADJUSTMENT OF THE THROTTLE CONTROL UNIT "STOP" AND "FULL POWER" STOPS - ADJUSTMENT OF THE THROTTLE CONTROL UNIT ?STOP? STOP									
		MOS						11-JAN-1988		
	REF: AMM 76-10-01-820-801	HRS/MSC	O/C					0		
		AFL						0		
76-10-01-820-801-02	CHECK / ADJUSTMENT OF THE THROTTLE CONTROL UNIT "STOP" AND "FULL POWER" STOPS - ADJUSTMENT OF THE THROTTLE CONTROL UNIT ?FULL POWER? STOP									
		MOS						11-JAN-1988		
	REF: AMM 76-10-01-820-801	HRS/MSC	O/C					0		
		AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-01-900-801-01	REMOVAL / INSTALLATION OF THE THROTTLE CONTROL UNIT - THROTTLE CONTROL UNIT (500EC)									
76.070	FGFB771100A4 47 REF: AMM 76-10-01-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
76-10-21-640-802-01 (s)	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 1)						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
76-10-21-640-802-02 (s)	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 2)						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
76-10-21-640-802-03 (s)	LUBRICATION OF THE TELEFLEX CONTROL CABLE BALL-JOINTS - LUBRICATION OF TELEFLEX CABLE BALL-JOINTS (ENGINE 3)						PKG			
76.050	PKG 31 REF: AMM 76-10-21-640-802	MOS HRS/MSC AFL	72 3750	+2m			21-JUN-2023 8047.2 3851			
76-10-21-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - LH ENGINE TELEFLEX CONTROL CABLE (L502EC)									
76.090	4234476A 1108 REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
76-10-21-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 1 AND 3 TELEFLEX CONTROL CABLES - RH ENGINE TELEFLEX CONTROL CABLE (R502EC)									
76.090	4234499A 1117 REF: AMM 76-10-21-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
76-10-21-900-802-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 2 TELEFLEX CONTROL CABLE - CENTER ENGINE TELEFLEX CONTROL CABLE (M502EC)									
76.095	4234483A 976 REF: AMM 76-10-21-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-25-640-801-01 (s)	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 1						PKG			
76.040	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-25-640-801	AFL	7500							
76-10-25-640-801-02 (s)	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 2						PKG			
76.040	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-25-640-801	AFL	7500							
76-10-25-640-801-03 (s)	GREASING OF THE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS - ENGINE 3						PKG			
76.040	PKG 32	MOS	144	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-25-640-801	AFL	7500							
+ 76-10-33-820-801-01 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 1 CONTROL CABLE (L501EC)						PKG			
76.065	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-33-820-801	AFL	3750							
+ 76-10-33-820-801-02 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 2 CONTROL CABLE (M501EC)						PKG			
76.065	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-33-820-801	AFL	3750							
+ 76-10-33-820-801-03 (s)	CHECK OF THE THROTTLE CONTROL CABLE TENSION - ENGINE 3 CONTROL CABLE (R501EC)						PKG			
76.065	PKG 31	MOS	72	+2m			21-JUN-2023	8047.2	3851	
	REF: AMM 76-10-33-820-801	AFL	3750							
76-10-33-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 1 THROTTLE CONTROL CABLE									
76.080	FGFB771000040	MOS					11-JAN-1988	0	0	
	SN-UNKNOWN	HRS/MSC	O/C	N:0						
	REF: AMM 76-10-33-900-801	AFL								



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-33-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 2 THROTTLE CONTROL CABLE									
76.080	FGFB771000050 SN-UNKNOWN REF: AMM 76-10-33-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
76-10-33-900-801-03	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE CONTROL CABLES - ENGINE 3 THROTTLE CONTROL CABLE									
76.080	FGFB771000060 SN-UNKNOWN REF: AMM 76-10-33-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
76-10-37-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - LH THROTTLE LEVER TAKE-OFF PROXIMITY SWITCH (3EW1)									
	PN SN-UNKNOWN REF: AMM 76-10-37-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
76-10-37-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - CENTER THROTTLE LEVER TAKE-OFF PROXIMITY SWITCH (3EW2)									
	PN SN-UNKNOWN REF: AMM 76-10-37-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
76-10-37-900-801-03	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - RH THROTTLE LEVER TAKE-OFF PROXIMITY SWITCH (3EW3)									
	PN SN-UNKNOWN REF: AMM 76-10-37-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
76-10-37-900-801-04	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - LH THROTTLE LEVER L/G PROXIMITY SWITCH (2GW1)									
	PN SN-UNKNOWN REF: AMM 76-10-37-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-37-900-801-05	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - CENTER THROTTLE LEVER L/G PROXIMITY SWITCH (2GW2)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-06	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - RH THROTTLE LEVER L/G PROXIMITY SWITCH (2GW3)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-07	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - LH THROTTLE LEVER PROXIMITY SWITCH (8HN1)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-08	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - CENTER THROTTLE LEVER PROXIMITY SWITCH (8HN2)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-09	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - RH THROTTLE LEVER PROXIMITY SWITCH (8HN3)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-10	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - LH THROTTLE LEVER PROXIMITY SENSOR (4KK1)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-37-900-801-11	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - CENTER THROTTLE LEVER PROXIMITY SENSOR (4KK2)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-12	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - RH THROTTLE LEVER PROXIMITY SENSOR (4KK3)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-13	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - TR ARMING PROXIMITY SWITCH (4KR)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-37-900-801-14	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THROTTLE LEVER PROXIMITY SWITCHES - TR CONTROL LEVER PROXIMITY SWITCH (6KR)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-37-900-801	AFL		N:0			0			
76-10-41-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER CONTROL LEVER LOCKING SOLENOID - TR CONTROL LEVER LOCKING SOLENOID (9KR)									
	PN	MOS		N:0			11-JAN-1988			
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: AMM 76-10-41-900-801	AFL		N:0			0			
76-10-43-700-801-01	MEASUREMENT OF THE ENGINE 2 THROTTLE LEVER LOCKING FORCES IF THRUST REVERSER CLAMHELL DOORS ARE NOT STOWED									
		MOS					11-JAN-1988			
		HRS/MSC	O/C				0			
	REF: AMM 76-10-43-700-801	AFL					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
76-10-43-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE ENGINE 2 THROTTLE LEVER "IDLE" POSITION LOCKING SOLENOID - CENTER THROTTLE LEVER IDLE POSITION LOCKING SOLENOID (10KR)									
	PN	MOS		N:0				11-JAN-1988		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM 76-10-43-900-801	AFL		N:0				0		
76-10-45-820-801-01	ADJUSTMENT OF THE TR FULL POWER STOP									
		MOS						11-JAN-1988		
		HRS/MSC	O/C					0		
	REF: AMM 76-10-45-820-801	AFL						0		
762111	NO. 1 ENGINE FUEL SHUTOFF VALVE									
	L88A31662	MOS						11-JAN-1988		
76.100	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM GENERIC 2	AFL						0		
762112	NO. 2 ENGINE FUEL SHUTOFF VALVE									
	L88A31663	MOS						11-JAN-1988		
76.110	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM GENERIC 2	AFL						0		
762113	NO. 3 ENGINE FUEL SHUTOFF VALVE									
	L88A31664	MOS						11-JAN-1988		
76.120	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: AMM GENERIC 2	AFL						0		
ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3										
+ 76-10-02.1	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS									
	PN	MOS		N:0				28-MAR-1987		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: LMM 76-10-02	ENC		N:0				0		
+ 76-10-02.2	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS INSPECTION/CHECK									
		MOS						28-MAR-1987		
		HRS/MSC	A/R					0		
	REF: LMM 76-10-02	ENC						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 76-10-03.1	NO. 1 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS PN SN-UNKNOWN REF: LMM 76-10-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-MAR-1987 0 0			
+ 76-10-03.2	NO. 1 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS INSPECTION/CHECK REF: LMM 76-10-03	MOS HRS/MSC ENC	A/R				28-MAR-1987 0 0			
+ 760120 (s) 76.020	NO. 1 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL PKG 2 REF: See Workcard	MOS HRS/MSC ENC	300	+100			PKG 31-MAY-2022			
760130 76.050	NO. 1 ENGINE - DOWNLOAD ECTM REF: See Workcard	MOS HRS/MSC ENC	O/C				09-APR-2018 7286.6 3597			
761310 76.030	NO. 1 ENGINE - SURGE BLEED VALVE 978812-7-1 15059 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			02-DEC-2015			
761320 76.040	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE 109696-4-1 8478 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			09-OCT-1997 2083.6 1544			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3										
+ 76-10-02.1	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS PN SN-UNKNOWN REF: LMM 76-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			29-JAN-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 76-10-02.2	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS INSPECTION/CHECK	MOS						29-JAN-1987		
	REF: LMM 76-10-02	HRS/MSC	A/R					0		
		ENC						0		
+ 76-10-03.1	NO. 2 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS	MOS		N:0				29-JAN-1987		
	PN	HRS/MSC	O/C	N:0				0		
	SN-UNKNOWN	ENC		N:0				0		
	REF: LMM 76-10-03									
+ 76-10-03.2	NO. 2 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS INSPECTION/CHECK	MOS						29-JAN-1987		
	REF: LMM 76-10-03	HRS/MSC	A/R					0		
		ENC						0		
+ 760120 (s)	NO. 2 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL	MOS					PKG			
	PKG 2	HRS/MSC	300	+100				31-MAY-2022		
	76.020	ENC								
	REF: See Workcard									
760130	NO. 2 ENGINE - DOWNLOAD ECTM	MOS						09-APR-2018		
	76.050	HRS/MSC	O/C					7433.5		
	REF: See Workcard	ENC						3612		
761310	NO. 2 ENGINE - SURGE BLEED VALVE	MOS						29-JAN-1987		
	978812-5-1	HRS/MSC	O/C	N:0				0		
	76.030	ENC		N:0				0		
	REF: LMM 76-10-01									
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE	MOS						29-JAN-1987		
	109696-4-1	HRS/MSC	O/C	N:0				0		
	76.040	ENC		N:0				0		
	REF: LMM 76-10-01									

ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 76-10-02.1	NO. 3 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS									
	PN	MOS		N:0				17-FEB-1987		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: LMM 76-10-02	ENC		N:0				0		
+ 76-10-02.2	NO. 3 ENGINE - DIGITAL ELECTRONIC ENGINE CONTROL (DEEC) AND DEEC WIRING HARNESS INSPECTION/CHECK									
		MOS						17-FEB-1987		
		HRS/MSC	A/R					0		
	REF: LMM 76-10-02	ENC						0		
+ 76-10-03.1	NO. 3 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS									
	PN	MOS		N:0				17-FEB-1987		
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: LMM 76-10-03	ENC		N:0				0		
+ 76-10-03.2	NO. 3 ENGINE - N1 DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC) AND N1 DEEC WIRING HARNESS INSPECTION/CHECK									
		MOS						17-FEB-1987		
		HRS/MSC	A/R					0		
	REF: LMM 76-10-03	ENC						0		
+ 760120 (s)	NO. 3 ENGINE - BITE CHECK DIGITAL ELECTRONIC ENGINE CONTROL									
	PKG 2	MOS						PKG		
76.020		HRS/MSC	300	+100				31-MAY-2022		
	REF: See Workcard	ENC						7595.1		
								3678		
760130	NO. 3 ENGINE - DOWNLOAD ECTM									
		MOS						09-APR-2018		
76.050		HRS/MSC	O/C					7262		
	REF: See Workcard	ENC						3581		
761310	NO. 3 ENGINE - SURGE BLEED VALVE									
	978812-5-1	MOS						17-FEB-1987		
76.030	6255	HRS/MSC	O/C	N:0				0		
	REF: LMM 76-10-01	ENC		N:0				0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
761320	NO. 3 ENGINE - SOLENOID CONTROLLER VALVE									
	109696-4-1	MOS					17-FEB-1987			
76.040	5659	HRS/MSC	O/C	N:0			0			
	REF: LMM 76-10-01	ENC		N:0			0			
CHAPTER 77 ENGINE INDICATING										
77-10-05-900-801-07	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 "N1" INDICATOR (2EU1)									
	5428-701-80-10	MOS					11-FEB-2009			
77.020	115M	HRS/MSC	O/C				5698.4			
	REF: AMM 77-10-05-900-801	AFL					2880			
77-10-05-900-801-08	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 "N1" INDICATOR (2EU2)									
	5428-701-80-10	MOS		R:0			06-JUN-2006			
77.020	528	HRS/MSC	O/C				4699.3			
	REF: AMM 77-10-05-900-801	AFL					2444			
77-10-05-900-801-09	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 "N1" INDICATOR (2EU3)									
	5428-701-80-10	MOS		R:0			13-FEB-2009			
77.020	131	HRS/MSC	O/C	R:0			5699			
	REF: AMM 77-10-05-900-801	AFL		R:0			2881			
77-10-05-900-801-10	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 1 "N2" INDICATOR (3EU1)									
	5423-713-80-10	MOS					04-MAR-1999			
77.040	209A	HRS/MSC	O/C				2752			
	REF: AMM 77-10-05-900-801	AFL					1799			
77-10-05-900-801-11	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 2 "N2" INDICATOR (3EU2)									
	5423-713-80-10	MOS		R:0			17-JUN-2008			
77.040	331A	HRS/MSC	O/C	R:0			5417.7			
	REF: AMM 77-10-05-900-801	AFL		R:0			2752			
77-10-05-900-801-12	REMOVAL/INSTALLATION OF ENGINE N1/N2 INDICATORS - ENGINE 3 "N2" INDICATOR (3EU3)									
	5423-713-80-10	MOS		R:0			26-APR-2011			
77.040	491A	HRS/MSC	O/C	R:0			6626.3			
	REF: AMM 77-10-05-900-801	AFL		R:0			3348			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
77-20-00-700-801	CHECK OF THE ITT LINE INSULATION AND CONTINUITY REF: AMM 77-20-00-700-801	MOS HRS/MSC AFL	A/R					11-JAN-1988 0 0		
77-20-09-900-801	REMOVAL / INSTALLATION OF THE ENGINE PT2 - TT2 SENSOR REF: AMM 77-20-09-900-801	PN SN-UNKNOWN AFL	MOS HRS/MSC O/C		N:0 N:0 N:0			11-JAN-1988 0 0		
77-20-13-200-801	CHECK AND DRAINING OF THE PT2 LINE DRAINING BOWLS REF: AMM 77-20-13-200-801	MOS HRS/MSC AFL	A/R					11-JAN-1988 0 0		
77-20-13-790-801	LEAK TEST OF THE PT2 LINES REF: AMM 77-20-13-790-801	MOS HRS/MSC AFL	A/R					11-JAN-1988 0 0		
77-20-17-900-801-04 77.050	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 1 ITT INDICATOR (2EC1) 5428-559-80-10 134A REF: AMM 77-20-17-900-801	MOS HRS/MSC AFL	O/C					21-JAN-1999 2696 1777		
77-20-17-900-801-05 77.050	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 2 ITT INDICATOR (2EC2) 5428-559-80-10 360 REF: AMM 77-20-17-900-801	MOS HRS/MSC AFL	O/C					09-OCT-1997 2185 1589		
77-20-17-900-801-06 77.050	REMOVAL/INSTALLATION OF ENGINE ITT INDICATORS - ENGINE 3 ITT INDICATOR (2EC3) 5428-559-80-10 141A REF: AMM 77-20-17-900-801	MOS HRS/MSC AFL	O/C					09-OCT-1997 2185 1589		

ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 77-10-03.2	NO. 1 ENGINE - N1 TRANSDUCER AND N1 COMPENSATOR INSPECTION/CHECK	MOS					28-MAR-1987			
	REF: LMM 77-10-03	HRS/MSC A/R					0			
		ENC					0			
+ 77-10-05.2	NO. 1 ENGINE - N2 TRANSDUCER INSPECTION/CHECK	MOS					28-MAR-1987			
	REF: LMM 77-10-05	HRS/MSC A/R					0			
		ENC					0			
+ 77-20-01.2	NO. 1 ENGINE - THERMOCOUPLE HARNESS INSPECTION/CHECK	MOS					28-MAR-1987			
	REF: LMM 77-20-01	HRS/MSC A/R					0			
		ENC					0			
771110	NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER	MOS					28-MAR-1987			
77.010	3073827-3	HRS/MSC O/C		N:0			0			
	REF: LMM 77-10-03	ENC		N:0			0			
771120	NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER	MOS					28-MAR-1987			
77.020	3070722-3	HRS/MSC O/C		N:0			0			
	REF: LMM 77-10-05	ENC		N:0			0			
772110	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS	MOS					09-OCT-1997			
77.030	3073605-1	HRS/MSC O/C					2083.6			
	REF: LMM 77-20-01	ENC					1544			

ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3

+ 77-10-03.2	NO. 2 ENGINE - N1 TRANSDUCER AND N1 COMPENSATOR INSPECTION/CHECK	MOS					29-JAN-1987			
	REF: LMM 77-10-03	HRS/MSC A/R					0			
		ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 77-10-05.2	NO. 2 ENGINE - N2 TRANSDUCER INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 77-10-05	ENC					0			
+ 77-20-01.2	NO. 2 ENGINE - THERMOCOUPLE HARNESS INSPECTION/CHECK									
		MOS					29-JAN-1987			
		HRS/MSC	A/R				0			
	REF: LMM 77-20-01	ENC					0			
771110	NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER									
	3073827-3	MOS					29-JAN-1987			
77.010	SN-UNKNOWN	HRS/MSC	O/C	N:0			0			
	REF: LMM 77-10-03	ENC		N:0			0			
771120	NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER									
	3070722-10	MOS		N:0			14-SEP-2010			
77.020	64467	HRS/MSC	O/C	N:0			6218.7			
	REF: LMM 77-10-05	ENC		N:0			3136			
772110	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS									
	3073605-1	MOS		N:0			02-JAN-1998			
77.030	972021900268	HRS/MSC	O/C	N:0			2135.3			
	REF: LMM 77-20-01	ENC		N:0			1546			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3										
+ 77-10-03.2	NO. 3 ENGINE - N1 TRANSDUCER AND N1 COMPENSATOR INSPECTION/CHECK									
		MOS					17-FEB-1987			
		HRS/MSC	A/R				0			
	REF: LMM 77-10-03	ENC					0			
+ 77-10-05.2	NO. 3 ENGINE - N2 TRANSDUCER INSPECTION/CHECK									
		MOS					17-FEB-1987			
		HRS/MSC	A/R				0			
	REF: LMM 77-10-05	ENC					0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 77-20-01.2	NO. 3 ENGINE - THERMOCOUPLE HARNESS INSPECTION/CHECK							17-FEB-1987		
		MOS						0		
	REF: LMM 77-20-01	HRS/MSC A/R						0		
		ENC						0		
771110	NO. 3 ENGINE - LOW PRESSURE (N1) TRANSDUCER							02-JAN-1998		
	3073827-3	MOS						2010.6		
77.010	1800	HRS/MSC	O/C	N:570				1537		
	REF: LMM 77-10-03	ENC		N:481						
771120	NO. 3 ENGINE - HIGH PRESSURE (N2) TRANSDUCER							17-FEB-1987		
	3070722-3	MOS						0		
77.020	SN-UNKNOWN	HRS/MSC	O/C	N:0				0		
	REF: LMM 77-10-05	ENC		N:0				0		
772110	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS							02-JAN-1998		
	3073605-1	MOS						2010.6		
77.030	2-20219-188	HRS/MSC	O/C					1537		
	REF: LMM 77-20-01	ENC								
CHAPTER 78 EXHAUST										
78-30-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER							PKG		
	PKG 7	MOS	36					21-JUN-2023		
78.010		HRS/MSC	2400					8047.2		
	REF: AMM 78-30-00-210-801	AFL						3851		
+ 78-30-00-720-801-01 (s)	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN							PKG		
	PKG 31	MOS	72	+2m				21-JUN-2023		
78.020		HRS/MSC						8047.2		
	REF: AMM 78-30-00-720-801	AFL	3750					3851		
78-30-00-910-802-01	DEPLOYMENT / STOWING OF THE THRUST REVERSER - DEPLOYMENT/STOWING OF THRUST REVERSER (WITH HYDRAULIC GROUND POWER UNIT)							11-JAN-1988		
		MOS						0		
		HRS/MSC	O/C					0		
	REF: AMM 78-30-00-910-802	AFL						0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-30-00-910-802-02	DEPLOYMENT / STOWING OF THE THRUST REVERSER - DEPRESSURIZATION OF THRUST REVERSER ACCUMULATOR	MOS						11-JAN-1988		
	REF: AMM 78-30-00-910-802	HRS/MSC	O/C					0		
		AFL						0		
78-30-00-910-802-03	DEPLOYMENT / STOWING OF THE THRUST REVERSER - THRUST REVERSER STOWING AFTER DEPRESSURIZATION OF THRUST REVERSER ACCUMULATOR	MOS						11-JAN-1988		
	REF: AMM 78-30-00-910-802	HRS/MSC	O/C					0		
		AFL						0		
78-30-00-910-807-01	INHIBITION OF THE THRUST REVERSER	MOS						11-JAN-1988		
78.170	REF: AMM 78-30-00-910-807	HRS/MSC	O/C					0		
		AFL						0		
		APH						0		
78-31-00-640-802-01	GREASING OF THE THRUST REVERSER DOOR HINGE PINS	MOS	12	+1m				11-JAN-1988		
78.145	REF: AMM 78-31-00-640-802	HRS/MSC	400	+40			27-JUN-2023	27-JUN-2024	27-JUL-2024	345 d (+30)
		AFL					8049.2	8449.2	8489.2	400 (+40)
							3853			
78-31-00-640-804-01 (s)	GREASING OF THE THRUST REVERSER CONTROL AND UNLOCKING LINKAGE	MOS	24	+1m				11-JAN-1988		
78.100	REF: AMM 78-31-00-640-804	HRS/MSC					21-JUN-2023			
		AFL					8047.2			
							3851			
78-31-01-900-801-01	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - LH THRUST-REVERSER DOOR	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 78-31-01-900-801							0		
78-31-01-900-801-02	REMOVAL / INSTALLATION / ADJUSTMENT OF THE THRUST REVERSER DOORS - RH THRUST-REVERSER DOOR	MOS						11-JAN-1988		
	PN	HRS/MSC	O/C					0		
	SN-UNKNOWN	AFL						0		
	REF: AMM 78-31-01-900-801							0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-31-05-900-801-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR UPPER LATCH									
78.140	A861TS4RF900 721 REF: AMM 78-31-05-900-801	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
78-31-05-900-802-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR LOWER LATCH									
78.140	A861TS4RF50 715 REF: AMM 78-31-05-900-802	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
78-31-09-960-801-01	REPLACEMENT OF THE THRUST REVERSER DOOR SEALS - LH THRUST REVERSER DOOR SEAL									
	REF: AMM 78-31-09-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
78-31-09-960-801-02	REPLACEMENT OF THE THRUST REVERSER DOOR SEALS - RH THRUST REVERSER DOOR SEAL									
	REF: AMM 78-31-09-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			
78-31-13-900-801-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER DOOR ACTUATOR AND CONTROL RODS									
	PN SN-UNKNOWN REF: AMM 78-31-13-900-801	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-JAN-1988 0 0			
78-31-15-960-801-01	REPLACEMENT OF THE BALL-JOINT END-FITTING OF THE THRUST REVERSER DOOR ACTUATOR - TR ACTUATOR (202KR)									
78.100	106124-01 12 REF: AMM 78-31-15-960-801	MOS HRS/MSC AFL	O/C							
78-31-33-960-801-01	REPLACEMENT OF THE THRUST REVERSER DOOR BALL JOINTS - THRUST-REVERSER CLAMSHELL DOOR (454FL)									
	REF: AMM 78-31-33-960-801	MOS HRS/MSC AFL	O/C				11-JAN-1988 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-31-33-960-801-02	REPLACEMENT OF THE THRUST REVERSER DOOR BALL JOINTS - THRUST-REVERSER CLAMSHELL DOOR (454FR)	MOS					11-JAN-1988			
	REF: AMM 78-31-33-960-801	HRS/MSC	O/C				0			
		AFL					0			
78-32-03-870-802-01	BLEEDING OF THE THRUST REVERSER HYDRAULIC SYSTEM	MOS					11-JAN-1988			
	REF: AMM 78-32-03-870-802	HRS/MSC	O/C				0			
		AFL					0			
78-32-09-610-801-01	CHARGING OF THE THRUST REVERSER ACCUMULATOR - TR ACCUMULATOR (190KR)	MOS					11-JAN-1988			
	REF: AMM 78-32-09-610-801	HRS/MSC	O/C				0			
		AFL					0			
78-32-09-900-801-01	REMOVAL / INSTALLATION OF THE THRUST REVERSER HYDRAULIC ACCUMULATOR - TR ACCUMULATOR (190KR)	MOS					11-JAN-1988			
78.050	60909-1	HRS/MSC	O/C	N:0			0			
	7781	AFL					0			
	REF: AMM 78-32-09-900-801						0			
783101	THRUST REVERSER SYSTEM PRESSURE GAGE	MOS					11-JAN-1988			
78.030	18040100	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL					0			
	REF: AMM GENERIC 2						0			
783106	THRUST REVERSER SYSTEM CHARGING VALVE	MOS					11-JAN-1988			
78.040	MS26889-2	HRS/MSC	O/C	N:0			0			
	SN-UNKNOWN	AFL					0			
	REF: AMM GENERIC 2						0			
783221	THRUST REVERSER ELECTRODISTRIBUTION CONTROL	MOS					11-JAN-1988			
78.060	108131-02AB	HRS/MSC	O/C	N:0			0			
	41	AFL					0			
	REF: AMM GENERIC 2						0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783301	THRUST REVERSER SYSTEM CHECK SUPPLY VALVE A24515	MOS					11-JAN-1988			
78.070	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
783311	THRUST REVERSER SYSTEM CHECK RETURN VALVE C24816000	MOS					11-JAN-1988			
78.070	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
783321	THRUST REVERSER RETRACTION JACK ISOLATION VALVE AE99113E	MOS					11-JAN-1988			
78.080	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
783331	THRUST REVERSER EXTENSION JACK ISOLATION VALVE AE99113E	MOS					11-JAN-1988			
78.080	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
783341	THRUST REVERSER JACK LOCKING ISOLATION VALVE AE99113G	MOS					11-JAN-1988			
78.090	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0			0 0			
783401	THRUST REVERSER HYDRAULIC CONTROL ACTUATOR 106124-01	MOS					28-NOV-2018			
78.100	12 REF: AMM GENERIC 2	HRS/MSC AFL	O/C				7675 3744			
783411	THRUST REVERSER SYNCHRONIZING BELLCRANK F900HD3200240A5	MOS					09-OCT-1997			
78.110	SN-UNKNOWN REF: AMM GENERIC 2	HRS/MSC AFL	O/C				2185 1589			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783421	THRUST REVERSER LEFT CONTROL DOOR ADJUSTMENT ROD									
78.120	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
783431	THRUST REVERSER RIGHT CONTROL DOOR ADJUSTMENT ROD									
78.120	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
783441	THRUST REVERSER UPPER CATCH UNLOCK JACK									
78.130	106125-01 349 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
783451	THRUST REVERSER LOWER CATCH UNLOCK JACK									
78.130	106125-01 135 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C				28-NOV-2018 7675 3744			
783501	LH THRUST REVERSER DOOR INDICATING MICROSWITCH									
78.150	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
783506	RH THRUST REVERSER DOOR INDICATING MICROSWITCH									
78.150	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			0 0			
783511	THRUST REVERSER SYNCHRONIZING BELLCRANK MICROSWITCH									
78.160	PN SN-UNKNOWN REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			

CHAPTER 79 OIL



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
79-00-00-610-801-01	SERVICING OF THE ENGINE OIL SYSTEM - ENGINE 1 (L4EZ)	MOS						11-JAN-1988		
	REF: AMM 79-00-00-610-801	HRS/MSC	O/C					0		
		AFL						0		
79-00-00-610-801-02	SERVICING OF THE ENGINE OIL SYSTEM - ENGINE 2 (M4EZ)	MOS						11-JAN-1988		
	REF: AMM 79-00-00-610-801	HRS/MSC	O/C					0		
		AFL						0		
79-00-00-610-801-03	SERVICING OF THE ENGINE OIL SYSTEM - ENGINE 3 (R4EZ)	MOS						11-JAN-1988		
	REF: AMM 79-00-00-610-801	HRS/MSC	O/C					0		
		AFL						0		
79-30-01-820-802-01	ADJUSTMENT OF THE ENGINE OIL LEVEL GAUGING SYSTEM	MOS						11-JAN-1988		
	REF: AMM 79-30-01-820-802	HRS/MSC	O/C					0		
		AFL						0		
79-30-17-900-801-04	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 1 OIL PRESSURE/TEMPERATURE INDICATOR (2EM1)	MOS								
79.100	64857-418-1	HRS/MSC	O/C	R:36				30-DEC-2020		
	631	AFL		R:0				7893.8		
	REF: AMM 79-30-17-900-801			R:0				3803		
79-30-17-900-801-05	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 2 OIL PRESSURE/TEMPERATURE INDICATOR (2EM2)	MOS								
79.100	64857-418-1	HRS/MSC	O/C					27-AUG-1992		
	590	AFL						1154		
	REF: AMM 79-30-17-900-801							783		
79-30-17-900-801-06	REMOVAL/INSTALLATION OF ENGINE OIL TEMPERATURE AND PRESSURE INDICATORS - ENGINE 3 OIL PRESSURE/TEMPERATURE INDICATOR (2EM3)	MOS								
79.100	64857-418-1	HRS/MSC	O/C	N:0				11-JAN-1988		
	236	AFL						0		
	REF: AMM 79-30-17-900-801							0		



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
793083	NO. 1 ENGINE LOW OIL PRESSURE SWITCH 8G1126-2	MOS		N:0			30-JUL-2013			
79.075	2222 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0 N:0			7132.2 3577			
793084	NO. 2 ENGINE LOW OIL PRESSURE SWITCH 8G1126-2	MOS					19-SEP-2011			
79.075	2220 REF: AMM GENERIC 2	HRS/MSC AFL	O/C				6734.2 3397			
793085	NO. 3 ENGINE LOW OIL PRESSURE SWITCH 8G1126-1	MOS					13-SEP-2012			
79.075	1239 REF: AMM GENERIC 2	HRS/MSC AFL	O/C				6999.2 3532			
793101	NO. 1 ENGINE OIL PRESSURE TRANSMITTER 64251-417-2	MOS					02-SEP-1998			
79.080	193 REF: AMM GENERIC 2	HRS/MSC AFL	O/C				2580 1723			
793102	NO. 2 ENGINE OIL PRESSURE TRANSMITTER 64251-417-2	MOS					23-JUL-1993			
79.080	183 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:1329 N:921			1370 940			
793103	NO. 3 ENGINE OIL PRESSURE TRANSMITTER 64251-417-2	MOS					28-MAR-2012			
79.080	6900 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:0 N:0 N:0			6954.4 3507			
793119	NO. 1 ENGINE OIL TEMPERATURE PROBE 56B17	MOS					10-FEB-1994			
79.090	93086 REF: AMM GENERIC 2	HRS/MSC AFL	O/C	N:1445 N:993			1495 1038			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
793120	NO. 2 ENGINE OIL TEMPERATURE PROBE 56B17 90887 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1329 N:921			23-JUL-1993 1370 940			
793121	NO. 3 ENGINE OIL TEMPERATURE PROBE 56B17 90062 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1370 N:941			05-NOV-1993 1445 993			
793155	ENGINE OIL LEVEL INDICATOR 267-968-004 061 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
793161	ENGINE OIL LEVEL AMPLIFIER 360-967-004 161 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:0			11-JAN-1988 0 0			
793167	NO. 1 ENGINE OIL LEVEL GAGE 029-907-004 232 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1445 N:993			10-FEB-1994 1495 1038			
793168	NO. 2 ENGINE OIL LEVEL GAGE 029-907-004 183 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1329 N:921			23-JUL-1993 1370 940			
793169	NO. 3 ENGINE OIL LEVEL GAGE 029-907-004 245 REF: AMM GENERIC 2	MOS HRS/MSC AFL	O/C	N:1370 N:941			05-NOV-1993 1445 993			

ENGINE NO. 1 Model : TFE731-5BR-1C Serial # P-97161C Part # 3075330-3



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
790111 (s)	NO. 1 ENGINE - ANALYZE OIL AND FILTER PKG 1	MOS					PKG 27-JUN-2023			
79.010	REF: LMM 72-00-00	HRS/MSC ENC	150	+100			7701.9 3720			
790120	NO. 1 ENGINE - CHANGE OIL	MOS					14-JAN-2016			
79.020	REF: LMM 72-00-00	HRS/MSC ENC	1200	+100			7039 3533	(8239) 8586.3	8339	537.1 (+100)
+ 790130 (s)	NO. 1 ENGINE - INSPECT OIL CHIP DETECTOR PKG 1	MOS					PKG 27-JUN-2023			
79.030	REF: LMM 79-20-03	HRS/MSC ENC	150	+100			7701.9 3720			
792110	NO. 1 ENGINE - OIL PUMP 307949-12	MOS					20-FEB-2017			
79.040	5314 REF: LMM 79-20-03	HRS/MSC ENC	O/C				7134.8 3559			
792120	NO. 1 ENGINE - BY-PASS INDICATOR VALVE 3002780-3	MOS					28-MAR-1987			
79.050	SN-UNKNOWN REF: LMM 79-30-01	HRS/MSC ENC	O/C		N:0 N:0		0 0			
792130	NO. 1 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY 3075323-1	MOS					09-OCT-1997			
79.060	00177 REF: LMM 79-20-02	HRS/MSC ENC	O/C				2083.6 1544			
792140	NO. 1 ENGINE - UPPER OIL COOLER 158600-7	MOS					28-MAR-1987			
79.070	76-8735 REF: LMM 79-20-09	HRS/MSC ENC	O/C		N:0 N:0		0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792150	NO. 1 ENGINE - LOWER LEFT OIL COOLER									
79.080	159900-3 85-6220 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
792160	NO. 1 ENGINE - LOWER RIGHT OIL COOLER									
79.090	159910-3 126-6304 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
792170	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR									
79.100	158610-8 95-6217 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0			28-MAR-1987 0 0			
ENGINE NO. 2 Model : TFE731-5BR-1C Serial # P-97147C Part # 3075330-3										
790111 (s)	NO. 2 ENGINE - ANALYZE OIL AND FILTER						PKG			
79.010	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			27-JUN-2023 7848.8 3735			
790120	NO. 2 ENGINE - CHANGE OIL									
79.020	REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			06-APR-2015 7090.9 3515	(8290.9) 8491.3	8390.9	442.1 (+100)
+ 790130 (s)	NO. 2 ENGINE - INSPECT OIL CHIP DETECTOR						PKG			
79.030	PKG 1 REF: LMM 79-20-03	MOS HRS/MSC ENC	150	+100			27-JUN-2023 7848.8 3735			
792110	NO. 2 ENGINE - OIL PUMP									
79.040	3071949-12 7343C REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			02-FEB-2010 2972			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792120	NO. 2 ENGINE - BY-PASS INDICATOR VALVE									
79.050	3002780-4N 0-09139-210 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:1618 N:1184			02-JAN-1998 2135.3 1546			
792130	NO. 2 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY									
79.060	3075323-3 NSN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			22-JUN-2017 7202 3575			
792140	NO. 2 ENGINE - UPPER OIL COOLER									
79.070	158600-7 56-86821 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
792150	NO. 2 ENGINE - LOWER LEFT OIL COOLER									
79.080	159900-3 106-6444 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
792160	NO. 2 ENGINE - LOWER RIGHT OIL COOLER									
79.090	159910-3 106-6242 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
792170	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR									
79.100	158610-8 65-6058 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0			29-JAN-1987 0 0			
ENGINE NO. 3 Model : TFE731-5BR-1C Serial # P-97149C Part # 3075330-3										
790111 (s)	NO. 3 ENGINE - ANALYZE OIL AND FILTER						PKG			
79.010	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			27-JUN-2023 7677.3 3704			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
790120	NO. 3 ENGINE - CHANGE OIL									
79.020	REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			06-APR-2015 6919.4 3484	(8119.4) 8491.3	8219.4	442.1 (+100)
+ 790130 (s)	NO. 3 ENGINE - INSPECT OIL CHIP DETECTOR									
79.030	PKG 1 REF: LMM 79-20-03	MOS HRS/MSC ENC	150	+100			PKG 27-JUN-2023 7677.3 3704			
792110	NO. 3 ENGINE - OIL PUMP									
79.040	3071949-11 7821 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			
792120	NO. 3 ENGINE - BY-PASS INDICATOR VALVE									
79.050	3002780-4N SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			
792130	NO. 3 ENGINE - PRESSURE BREATHER VALVE ASSEMBLY									
79.060	3071564-8 SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			
792140	NO. 3 ENGINE - UPPER OIL COOLER									
79.070	158600-7 56-8683 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			
792150	NO. 3 ENGINE - LOWER LEFT OIL COOLER									
79.080	159900-3 96-6438 REF: LMM 79-20-09	MOS HRS/MSC ENC	O/C		N:0 N:0		17-FEB-1987 0 0			



Status Report

FALCON 900 S/N 037 (N38TV): 8049.2 HRS, 3853 AFL as of 29-Jun-2023

Owner/Operator: THRESHOLD VENTURES, INC.

Report Date: 18-JUL-2023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792160	NO. 3 ENGINE - LOWER RIGHT OIL COOLER									
	159910-3	MOS						17-FEB-1987		
79.090	106-6243	HRS/MSC	O/C	N:0				0		
	REF: LMM 79-20-09	ENC		N:0				0		
792170	NO. 3 ENGINE - OIL TEMPERATURE REGULATOR									
	158610-8	MOS						17-FEB-1987		
79.100	65-6056	HRS/MSC	O/C	N:0				0		
	REF: LMM 79-20-07	ENC		N:0				0		