

OWNER: GLOBAL JET PARTNERS, LLC
ADDRESS: 5449 ENDEAVOUR COURT
 MOORPARK CA 93021
PHONE: 480-730-6698
FAX:

OPERATOR: GLOBAL JET PARTNERS, LLC
ADDRESS: 5449 ENDEAVOUR COURT
 MOORPARK CA 93021
PHONE: 480-730-6698
FAX:

ANALYST: TIMOTHY MCCANN
EMAIL: TMCCANN@CAMPSYSTEMS.COM

877-411-CAMP (2267) (OFFICE)
 631-588-3200 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 066/N66FJ **MODEL:** FALCON 900EX **MANUFACTURER:** DASSAULT AVIATION S.A.

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 23-MAR-2000	9855:36 A/C HRS	as of 01-JUN-2018	A/C HRS	as of ___/___/___
INSERVICE DATE: 23-AUG-2000	5896 AFL	as of 01-JUN-2018	AFL	as of ___/___/___
	3310:24 APH	as of 01-JUN-2018	APH	as of ___/___/___

APU SERIAL/PART: P370/3800188-2 **MODEL:** GTCP36-150(F) **MANUFACTURER:** HONEYWELL

INSTALLED ON 23-MAR-2000	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	3310:24 APU HRS	as of 01-JUN-2018	APU HRS	as of ___/___/___
0 APUS	0 APUS	as of 04-SEP-2014	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P112311/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 16-APR-2008		LAST ACTUALS		CURRENT ACTUAL	
7104 ENG. HRS	7501 A/C HRS	9484 ENG. HRS	as of 01-JUN-2018	ENG. HRS	as of ___/___/___
4430 ENC		5667 ENC	as of 01-JUN-2018	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P112312/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 16-APR-2008		LAST ACTUALS		CURRENT ACTUAL	
7104 ENG. HRS	7501 A/C HRS	9484 ENG. HRS	as of 01-JUN-2018	ENG. HRS	as of ___/___/___
4430 ENC		5667 ENC	as of 01-JUN-2018	ENC	as of ___/___/___

ENGINE NO. 3 SERIAL/PART: P112313/3060000-4 **MODEL:** TFE731-60-1C **MANUFACTURER:** HONEYWELL

INSTALLED ON 16-APR-2008		LAST ACTUALS		CURRENT ACTUAL	
6693:48 ENG. HRS	7501 A/C HRS	9075:12 ENG. HRS	as of 01-JUN-2018	ENG. HRS	as of ___/___/___
4181 ENC		5417 ENC	as of 01-JUN-2018	ENC	as of ___/___/___

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
+ 05-08-00-200-800-05	12 M/800 FH INSPECTION								
	PKG 5	MOS	12	+1m				01-JUN-2019	M 01-JUL-2019
		HRS/MSC	800	+40				10655:36	M 10695:36
	REF: See Workcard	AFL							
+ 05-08-00-200-800-06	24 M/1600 FH INSPECTION								
	PKG 6	MOS	24	+1m				01-JUN-2020	M 01-JUL-2020
		HRS/MSC	1600	+40				11455:36	M 11495:36
	REF: See Workcard	AFL							
+ 05-08-00-200-800-07	36 M/2400 FH INSPECTION								
	PKG 7	MOS	36	+1m				01-JUN-2021	M 01-JUL-2021
		HRS/MSC	2400	+40				12255:36	M 12295:36
	REF: See Workcard	AFL							
+ 05-08-00-200-800-15	12 M INSPECTION								
	PKG 15	MOS	12	+1m				01-JUN-2019	M 01-JUL-2019
		HRS/MSC							
	REF: See Workcard	AFL							
+ 05-08-00-200-800-16	24 M INSPECTION								
	PKG 16	MOS	24	+1m				01-JUN-2020	M 01-JUL-2020
		HRS/MSC							
	REF: See Workcard	AFL							
+ 05-08-00-200-800-17	36 M INSPECTION								
	PKG 17	MOS	36	+1m				01-JUN-2021	M 01-JUL-2021
		HRS/MSC							
	REF: See Workcard	AFL							
+ 05-08-00-200-800-21	1B INSPECTION								
	PKG 21	MOS					03-JUN-2014		
		HRS/MSC	1600	+40			9560:43	11160:43	11200:43
	REF: See Workcard	AFL					5737		
+ 05-08-00-200-800-22	2B INSPECTION								
	PKG 22	MOS					03-JUN-2014		
		HRS/MSC	3200	+40			9560:43	12760:43	12800:43
	REF: See Workcard	AFL					5737		
+ 05-08-00-200-800-23	3B INSPECTION								
	PKG 23	MOS					03-JUN-2014		
		HRS/MSC	4800	+40			9560:43	14360:43	14400:43
	REF: See Workcard	AFL					5737		
+ 05-08-00-200-800-31	1C INSPECTION								
	PKG 31	MOS	72	+2m			01-JUN-2018	01-JUN-2024	01-AUG-2024
		HRS/MSC					9855:36		
	REF: See Workcard	AFL	3750				5896	9646	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-08-00-200-800-32	2C INSPECTION PKG 32	MOS HRS/MSC AFL	144 +2m 7500	-119 -3374		28-SEP-2012 9012:54 5520	01-JUN-2024 9646	01-AUG-2024
+ 05-08-00-200-800-33	3C INSPECTION PKG 33	MOS HRS/MSC AFL	216 +2m 11250			01-JUN-2018 9855:36 5896	01-JUN-2036 17146	01-AUG-2036
ENGINE NO. 1 Model : TFE731-20/-40/-50/-60 Serial # P112311 Part # 3060000-4								
+ 057110	NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC ENC	150 +100			26-OCT-2017 9478:31 5665	(9628:31) 10000:07	9728:31
+ 057120	NO. 1 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	600 +50			26-OCT-2017 9478:31 5665	(10078:31) 10450:07	10128:31
057125	NO. 1 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3	MOS HRS/MSC ENC	800 +50			26-OCT-2017 9478:31 5665	(10278:31) 10650:07	10328:31
+ 057130	NO. 1 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200 +100			26-OCT-2017 9478:31 5665	(10678:31) 11050:07	10778:31
057135	NO. 1 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600 +50			26-OCT-2017 9478:31 5665	(11078:31) 11450:07	11128:31
ENGINE NO. 2 Model : TFE731-20/-40/-50/-60 Serial # P112312 Part # 3060000-4								
+ 057110	NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC ENC	150 +100			27-OCT-2017 9478:31 5665	(9628:31) 10000:07	9728:31
+ 057120	NO. 2 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	600 +50			27-OCT-2017 9478:31 5665	(10078:31) 10450:07	10128:31
057125	NO. 2 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3	MOS HRS/MSC ENC	800 +50			27-OCT-2017 9478:31 5665	(10278:31) 10650:07	10328:31

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 057130	NO. 2 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200	+100			27-OCT-2017 9478:31 5665	(10678:31) 11050:07	10778:31
	REF: GENERIC NO REF								
057135	NO. 2 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600	+50			27-OCT-2017 9478:31 5665	(11078:31) 11450:07	11128:31
	REF: GENERIC NO REF								
ENGINE NO. 3 Model : TFE731-20/-40/-50/-60 Serial # P112313 Part # 3060000-4									
+ 057110	NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION PKG 1	MOS HRS/MSC ENC	150	+100			08-SEP-2016 9067:27 5414	(9217:27) 9997:51	9317:27
	REF: GENERIC NO REF								
+ 057120	NO. 3 ENGINE - 500 TO 650 HOUR INSPECTION PKG 2	MOS HRS/MSC ENC	600	+50			08-SEP-2016 9067:27 5414	(9667:27) 10447:51	9717:27
	REF: GENERIC NO REF								
057125	NO. 3 ENGINE - 500 TO 850 HOUR INSPECTION PKG 3	MOS HRS/MSC ENC	800	+50			05-DEC-2016 9067:27 5414	(9867:27) 10647:51	9917:27
	REF: GENERIC NO REF								
+ 057130	NO. 3 ENGINE - 1000 TO 1300 HOUR INSPECTION PKG 4	MOS HRS/MSC ENC	1200	+100			08-SEP-2016 9067:27 5414	(10267:27) 11047:51	10367:27
	REF: GENERIC NO REF								
057135	NO. 3 ENGINE - 1500 TO 1650 HOUR INSPECTION PKG 5	MOS HRS/MSC ENC	1600	+50			24-SEP-2012 8206:51 5049	(9806:51) 10587:15	9856:51
	REF: GENERIC NO REF								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00 INFORMATION									
6893-170901	REVIEW MAINTENANCE PLANNING DOCUMENT CHAPTER 5 REVISION 7 DATED SEPTEMBER 2017								
REQUIREMENT CHANGE FORMS	REF:	MOS					(EBT)		
		HRS/MSC -							
		AFL							
6893-170901A	REVIEW FALCON 900EX MAINTENANCE MANUAL CHAPTER 5-40 REVISION 15 - SEPTEMBER 2017								
REQUIREMENT CHANGE FORMS	REF:	MOS					(EBT)		
		HRS/MSC -							
		AFL							
6893-180322	REVIEW DOCUMENT DISCREPANCIES DD 1-307191003 AND 1-303915014								
REQUIREMENT CHANGE FORMS	REF: MPD 6893	MOS					(EBT)		
		HRS/MSC -							
		AFL							
6893-180406	REVIEW FALCON 900EX MPD DOCUMENT DISCREPANCY 1-311875774 CHANGES								
REQUIREMENT CHANGE FORMS	REF: RCF 6893	MOS					(EBT)		
		HRS/MSC -							
		AFL							
APU Model : GTCP36-150(F) Serial # P370 Part # 3800188-2									
A009-170607	APU - REVIEW GTCP36-150(F) MM REV 7								
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS					(EBT)		
		HRS/MSC -							
		APUS							
A009-171115	APU - REVIEW GTCP-150(F) EMM TR 49-42								
REQUIREMENT CHANGE FORMS	REF: RCF A009	MOS					(EBT)		
		HRS/MSC -							
		APUS							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

A009-180112	APU - REVIEW HONEYWELL GTCP 36-150(F) APU-49 SIL REV 10						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	MOS HRS/MSC - APUS							

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4

E004-180118	NO. 1 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM REV 13						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4

E004-180118	NO. 2 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM REV 13						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4

E004-180118	NO. 3 ENGINE - REVIEW TFE731-20/-40/-50/-60 LMM REV 13						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E004	MOS HRS/MSC - ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-50-00-100-801-01	CLEANING AFTER ELECTROLYTE SPILLAGE						23-MAR-2000		
05.030	REF: See Workcard	MOS HRS/MSC A/R AFL APH					0 0 0		

05-50-00-200-801-01	CHECK AFTER A TOWING INCIDENT						23-MAR-2000		
05.040	REF: See Workcard	MOS HRS/MSC A/R AFL APH					0 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-802-01	CHECK AFTER HAILSTORM								
05.050	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-200-803-01	CHECK AFTER A LIGHTNING STRIKE								
05.060	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-200-804-01	CHECK AFTER A REJECTED TAKE-OFF OR EMERGENCY BRAKING								
05.070	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-200-805-01	CHECK AFTER FLYING UNDER EXCESSIVE LOAD FACTOR OR THROUGH EXCESSIVE TURBULENCE								
05.080	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-200-806-01	CHECK AFTER AIRCRAFT TILTING BACKWARD DURING MAINTENANCE OR POWER BACK OPERATIONS								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-809-01	INSPECTION AFTER SLAT EXTENSION IN OVERSPEED CONDITION								
05.090	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-200-810-01	INSPECTION AFTER FLAP EXTENSION IN OVERSPEED CONDITION								
05.100	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-200-812-01	INSPECTION AFTER LANDING GEAR EXTENSION IN OVERSPEED CONDITION								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
05-50-00-200-813-01	CHECK AFTER WHEEL IMPACT WITH AN OBSTACLE AT TAKE OFF OR LANDING								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-801-01	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTIONS AND ANTI-CORROSION TREATMENTS AT SHORT TIME INTERVALS								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-801-02	PERFORM SPECIFIC MAINTENANCE FOR A/C OPERATING IN CORROSIVE AMBIENT CONDITIONS - INSPECTIONS AND ANTI-CORROSION TREATMENTS AT MEDIUM TIME INTERVALS								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
05-50-00-620-803-01	SPECIFIC MAINTENANCE FOR AIRCRAFT OPERATING IN COLD WEATHER								
05.110	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-620-804-01	PROCEDURE FOR AIRCRAFT PROLONGED OPERATION AT LOW TEMPERATURES								
05.120	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-801-01	CHECK AND DECONTAMINATION OF THE AIR CONDITIONING SYSTEM AFTER POLLUTION								
05.130	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-803-01	CHECK AFTEER FIRE EXTINGUISHER PERCUSSION								
05.140	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-806-01	CHECK AFTER LANDING ON A TAR-MACADAM RUNWAY IN VERY HOT WEATHER								
05.150	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-807-01	CHECK AFTER LANDING ON DRY OR DIRT RUNWAY								
05.160	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-808-01	CHECK AFTER HARD / OVERWEIGHT LANDING								
05.170	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-700-810-01	CHECK AFTER A FLIGHT THROUGH SAND	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-700-818-01	CHECK AFTER AN ELECTRICAL FIRE	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-00-700-822-01	CHECK AFTER A FLIGHT THROUGH VOLCANIC ASHES	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-730-801-01	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - FILTER CLOGGING	MOS					23-MAR-2000		
05.180	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-730-801-02	CHECK AFTER AN INCIDENT ON THE HYDRAULIC SYSTEM - PUMP FAILURE	MOS					23-MAR-2000		
05.190	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
05-50-00-730-802-01	CHECK OF THE BRAKING SYSTEM AT ACCELERATION / STOP AFTER TROUBLESHOOTING	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-00-860-801-01	CHECK AND PREPARATION FOR FLIGHT WITH ONE ENGINE INOPERATIVE	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
+ 05-50-00-910-801-01 (s)	PERFORM AIRCRAFT CHECK FLIGHT						PKG		
05.020	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
+ 05-60-00-200-801-01	PERFORM BASIC INSPECTION								
05.010		DAYS		+1m				01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		
+ 05-60-00-200-801-03	PERFORM BASIC INSPECTION - SERVICING OPERATIONS								
05.010		DAYS		+1m				01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		
CHAPTER 08 LEVELING AND WEIGHING									
+ 08-10-00-910-801-01	WEIGHING THE AIRCRAFT								
	REF: AMM 08-10-00-910-801	MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
		AFL					0		
+ 080A01	CHECK AIRCRAFT WEIGHT & BALANCE								
	REF:	MOS					30-MAY-2014		
		HRS/MSC	O/C				9560:43		
		AFL					5737		
CHAPTER 09 TOWING AND TAXING									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
09-10-00-910-810-01	DEBLOGGING THE AIRCRAFT								
09.010	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
CHAPTER 10									
PARKING, MOORING, STORE AND RET TO SERV									
10-10-00-200-801-01	CHECK AFTER PARKING OF THE AIRCRAFT IN HIGH WIND CONDITIONS								
10.010	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
10-10-00-550-801-01	STORAGE OF AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS								
20.010	REF: See Workcard	MOS					21-DEC-2009		
		HRS/MSC	O/C				8322:55		
		AFL					5246		
10-10-00-550-801-02	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWO MONTHS TO 12 MONTHS								
20.010	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-03	STORAGE OF THE AIRCRAFT FOR A MAXIMUM DURATION OF TWELVE MONTHS TO EIGHTEEN MONTHS								
	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
		AFL					0		
10-10-00-550-801-04	PERFORM PERIODIC CHECKS EVERY MONTH DURING THE STORAGE PERIOD								
20.010	REF: See Workcard	MOS					20-JAN-2010		
		HRS/MSC	O/C				8322:55		
		AFL					5246		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
10-10-00-550-801-05	PERFORM PERIODIC CHECKS EVERY TWO MONTHS DURING THE STORAGE PERIOD								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				21-DEC-2009		
10-10-00-550-801-06	PERFORM PERIODIC CHECKS EVERY SIX MONTHS DURING THE STORAGE PERIOD								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				21-DEC-2009		
10-10-00-550-801-07	REMOVAL OF AIRCRAFT FROM STORAGE AFTER TWO MONTHS								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				02-FEB-2010 8322:55 5246		
10-10-00-550-801-08	REMOVAL OF THE AIRCRAFT FROM STORAGE AFTER MORE THAN TWO MONTHS								
20.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
10-10-00-550-801-09	PERFORM PRE-STORAGE OF THE AIRCRAFT FOR A MAXIMUM PERIOD OF 8 WEEKS								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
10-20-00-910-802-01	MOORING THE AIRCRAFT IN CASE OF SNOWFALL								
10.010	REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		

CHAPTER 11 PLACARDS AND MARKINGS

11-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE INTERNAL AND EXTERNAL MARKINGS AND PLACARDS						PKG		
	PKG 31	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
	REF: See Workcard			3750					

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
20-20-00-900-801-01	REMOVAL / INSTALLATION OF THE ELECTRICAL BONDING BRAIDS								
		MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
	REF: AMM 20-20-00-900-801	AFL					0		
20-30-00-330-801-01	TEMPORARY REPAIR AFTER MINOR DAMAGE TO A COMPOSITE MATERIAL COMPONENT								
20.030		MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
		APH					0		
20-31-00-140-801-01	RINSING THE AIRCRAFT EXTERIOR								
20.030		MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
		APH					0		
20-31-00-910-801-01	ACCOMPLISH GROUND DE-ICING AND PREVENTIVE ANTI-ICING PROCEDURE								
20.040		MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
		APH					0		
20-33-00-300-804-01	REPAIR TEMPORARILY OF A HYDRAULIC OR WATER PIPE USING RYNGLOK FITTINGS								
		MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
		APH					0		
20-41-00-910-801-01	TIGHTENING TORQUES FOR SINGLE FLARE COUPLINGS								
		MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
	REF: AMM 20-41-00-910-801	AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-60-00-370-813-01	ACCOMPLISH PAINT REMOVAL ON COMPOSITE HORIZONTAL STABILIZER								
20.050	REF: See Workcard	MOS					23-MAR-2000		
		HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
20-60-00-370-816-03	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG LEG (L2GF)								
	D22801400-6	MOS					23-MAR-2000		
	B66	HRS/MSC	O/C				0		
	REF: AMM 20-60-00-370-816	AFL					0		
20-60-00-370-816-04	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG LEG (R2GF)								
	D22802400-6	MOS					23-MAR-2000		
	B66	HRS/MSC	O/C				0		
	REF: AMM 20-60-00-370-816	AFL					0		
20-60-00-370-816-05	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - LH MLG SHOCK ABSORBER (L2GF5)								
	D22805400-3	MOS					23-MAR-2000		
	B66	HRS/MSC	O/C				0		
	REF: AMM 20-60-00-370-816	AFL					0		
20-60-00-370-816-06	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - RH MLG SHOCK ABSORBER (R2GF5)								
	D22806400-3	MOS					23-MAR-2000		
	B66	HRS/MSC	O/C				0		
	REF: AMM 20-60-00-370-816	AFL					0		
20-60-00-370-816-09	RESTORATION OF THE PAINT SCHEME OF THE LANDING GEARS - NLG LEG (3GF)								
	D22811400-5-13	MOS					23-MAR-2000		
	B69	HRS/MSC	O/C				0		
	REF: AMM 20-60-00-370-816	AFL					0		
20-90-00-200-801-01	INSPECTION / CHECK OF ELECTRICAL AND ELECTRONIC SYSTEMS								
		MOS					23-MAR-2000		
		HRS/MSC	O/C				0		
	REF: AMM 20-90-00-200-801	AFL					0		

CHAPTER 21 AIR CONDITIONING

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-01-350-801-01	RESTORATION LEFT AIR FLOW LIMITER (OVERHAUL)								
21.040	2742A020100 00548 REF: See Workcard	MOS HRS/MSC AFL	4800	+3%			25-JUN-2012 9012:32 5520	13812:32	13956:32
21-20-01-350-801-02	RESTORATION RIGHT AIR FLOW LIMITER (OVERHAUL)								
21.040	2742A020100 037 REF: See Workcard	MOS HRS/MSC AFL	4800	+3%			25-JUN-2012 9012:32 5520	13812:32	13956:32
21-20-01-900-801-01	LEFT AIR FLOW LIMITER								
21.040	2742A020100 00548 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:7 TSO:0 TSO:0		25-JUN-2012 9012:32 5520		
21-20-01-900-801-02	RIGHT AIR FLOW LIMITER								
21.040	2742A020100 037 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:11 TSO:0 TSO:0		25-JUN-2012 9012:32 5520		
+ 21-28-00-710-801-01 (s)	OPERATIONAL TEST OF THE EFIS VENTILATION SYSTEM								
21.010	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
21-30-00-790-801-01	GROUND LEAK CHECK OF THE CABIN SEALING								
	REF: See Workcard	MOS HRS/MSC AFL	A/R				23-MAR-2000 0 0		
+ 21-30-00-790-802-01 (s)	IN-FLIGHT CHECK OF CABIN SEALING								
21.160	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-30-01-900-801-01	CABIN AUTOMATIC PRESSURIZATION CONTROLLER								
21.290	22250J032100 00354 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-JUL-2013 9343:24 5658		
+ 21-30-09-720-801-01	FUNCTIONAL TEST TRIPLE INDICATOR OF THE ALTITUDE ALERT OF THE								
21.260	3311AJ67 266 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			28-APR-2015 9760:57 5832	13760:57	13880:57
+ 21-31-00-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM PNEUMATIC ACTUATOR								
21.220	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 21-31-00-720-801-02 (s)	FUNCTIONAL TEST OF THE NOSE CONE PRESSURIZATION SYSTEM PRESSURE RELIEF VALVE								
21.220	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 21-31-01-720-801-01 (s)	FUNCTIONAL TEST OF THE NOSE CONE OVERHEAT INDICATING SYSTEM								
21.020	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
21-31-09-350-801-01	RESTORATION NOSE CONE FAN (REPLACEMENT OF BEARINGS)								
21.050	AE1103A01 L166202152 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-NOV-2016 9847:51 5893		
21-31-09-900-801-01	NOSE CONE FAN								
21.050	AE1103A01 L166202152 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:12 TSN:0 TSN:0		11-NOV-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-33-900-801-01	NOSE CONE BUTTERFLY VALVE PROXIMITY SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
+ 21-32-00-710-801-01 (s)	OPERATIONAL TEST OF THE CABIN PRESSURIZATION SYSTEM PKG 21 21.170 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 21-32-00-710-802-01 (s)	OPERATIONAL TEST OF THE PRESSURIZATION SYSTEM EMERGENCY SUPPLY PKG 21 21.180 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 21-32-00-790-801-01 (s)	LEAK CHECK AROUND THE LEFT STATIC PRESSURE PROBE PKG 16 21.520 RVSM REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
21-32-00-790-801-02 (s)	LEAK CHECK AROUND THE RIGHT STATIC PRESSURE PROBE PKG 16 21.520 RVSM REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
21-32-00-790-801-03 (s)	LEAK CHECK AROUND THE LEFT STAND-BY STATIC PRESSURE PROBE PKG 16 RVSM REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 11-SEP-2014 9628:50 5770		
21-32-00-790-801-04 (s)	LEAK CHECK AROUND THE RIGHT STAND-BY STATIC PRESSURE PROBE PKG 16 RVSM REF: See Workcard	MOS HRS/MSC AFL	24				PKG 11-SEP-2014 9628:50 5770		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-200-801-01	CLEANING MAIN ELECTRO-PNEUMATIC REGULATION VALVE SEAT 2097N030700 00208 REF: See Workcard	MOS HRS/MSC AFL	1640	+3%			23-MAY-2011 8715:32	10238:36	10287:48
21.230					-116:56				
21-32-06-200-801-02	CLEANING EMERGENCY PNEUMATIC REGULATION VALVE SEAT 2099P030700 01135 REF: See Workcard	MOS HRS/MSC AFL	1640	+3%			23-MAY-2011 8715:32	10238:36	10287:48
21.240					-116:56				
+ 21-32-06-200-801-03	CHECK MAIN ELECTRO-PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS 2097N030700 00208 REF: See Workcard	MOS HRS/MSC AFL	1630				23-MAY-2011 8715:32	10228:36	
21.230					-116:56				
+ 21-32-06-200-801-03A	CHECK MAIN ELECTRO-PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS (MANDATORY REF. 5-40-20) 2097N030700 00208 REF: See Workcard	MOS HRS/MSC AFL	1630				23-MAY-2011 8715:32	10345:32	
21.230									
MANDATORY 5-40									
+ 21-32-06-200-801-04	CHECK EMERGENCY PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS 2099P030700 01135 REF: See Workcard	MOS HRS/MSC AFL	1630				23-MAY-2011 8715:32	10228:36	
21.240					-116:56				
+ 21-32-06-200-801-04A	CHECK EMERGENCY PNEUMATIC REGULATION VALVE OVERPRESSURE TIGHTNESS (MANDATORY REF. 5-40-20) 2099P030700 01135 REF: See Workcard	MOS HRS/MSC AFL	1630				23-MAY-2011 8715:32	10345:32	
21.240									
MANDATORY 5-40									
21-32-06-200-801-05	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES REF: See Workcard	MOS HRS/MSC AFL	7500				27-AUG-2010 8508:33 5310	16008:33	
21.530									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-32-06-200-801-05A	CHECK OF OVERPRESSURE RELIEF VALVE VACUUM SUPPLY LINES (MANDATORY REF. 5-40-20)	MOS					27-AUG-2010		
21.530		HRS/MSC	7500				8508		16008
MANDATORY 5-40	REF: See Workcard	AFL					5310		
+ 21-32-06-720-801-01	FUNCTIONAL TEST MAIN ELECTRO-PNEUMATIC REGULATION VALVE	MOS					14-APR-2006		
21.230	2097N030700	HRS/MSC	4840	+3%			5778:48		10618:48
	00208	AFL					3578		10764
	REF: See Workcard								
+ 21-32-06-720-801-01A	FUNCTIONAL TEST MAIN ELECTRO-PNEUMATIC REGULATION VALVE (MANDATORY REF. 5-40-20)	MOS					14-APR-2006		
21.230	2097N030700	HRS/MSC	14300				5778:48		20078:48
MANDATORY 5-40	REF: See Workcard	AFL					3578		
+ 21-32-06-720-801-02	FUNCTIONAL TEST EMERGENCY PNEUMATIC REGULATION VALVE	MOS					14-APR-2006		
21.240	2099P030700	HRS/MSC	4840	+3%			5778:48		10618:48
	01135	AFL					3578		10764
	REF: See Workcard								
+ 21-32-06-720-801-02A	FUNCTIONAL TEST EMERGENCY PNEUMATIC REGULATION VALVE (MANDATORY REF. 5-40-20)	MOS					14-APR-2006		
21.240	2099P030700	HRS/MSC	14300				5778:48		20078:48
MANDATORY 5-40	REF: See Workcard	AFL					3578		
21-32-06-900-801-01	MAIN ELECTRO-PNEUMATIC REGULATION VALVE	MOS					23-MAY-2011		
21.230	2097N030700	HRS/MSC	O/C		TSR:61		8715:32		
	00208	AFL			TSN:8715:32				
	REF: See Workcard				TSR:2936:44				
21-32-06-900-802-01	EMERGENCY PNEUMATIC REGULATION VALVE	MOS					23-MAY-2011		
21.240	2099P030700	HRS/MSC	O/C		TSR:61		8715:32		
	01135	AFL			TSN:8700:32				
	REF: See Workcard				TSR:2936:44				

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-17-200-801-01 (s)	INSPECTION OF THE LH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
21.190	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
21-32-17-200-801-02 (s)	INSPECTION OF THE RH BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE						PKG		
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 21-32-17-720-801-01 (s)	FUNCTIONAL TEST OF THE LH BAGGAGE COMPARTMENT PRESSURE-RELIEF VALVE						PKG		
21.200	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
21-32-17-720-801-02 (s)	FUNCTIONAL TEST OF THE RH BAGGAGE COMPARTMENT PRESSURE-RELIEF VALVE						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 21-32-33-710-801-01 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE						PKG		
21.030	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
+ 21-32-37-200-801-01 (s)	INSPECTION OF THE NEGATIVE PRESSURE RELIEF VALVES IN BAGGAGE COMPARTMENT						PKG		
21.210	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 21-32-37-720-801-01	FUNCTIONAL TEST LH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 01271 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			23-APR-2015 9760:57 5832	13760:57	13880:57

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-32-37-720-801-02	FUNCTIONAL TEST RH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 304 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			23-APR-2015 9760:57 5832	13760:57	13880:57
+ 21-32-41-200-801-01 (s)	INSPECTION OF THE NICOTINE CABIN AIR FILTER CARTRIDGE								
21.250	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
+ 21-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WATER REINJECTION SYSTEM								
21.400	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
21-52-05-350-801-01	RESTORATION TURBOCOOLER (OVERHAUL)								
21.350 OVERHAUL	3269B0202 331 REF: See Workcard	MOS HRS/MSC AFL	3000	+3%			31-AUG-2016 9847:51 5893	12847:51	12937:51
21-52-05-610-801-01	TOP UP TURBOCOOLER OIL								
21.350	3269B0202 331 REF:	MOS HRS/MSC AFL	O/C				31-AUG-2016 9847:51 5893		
21-52-05-610-801-02 (s)	DRAINING AND REFILLING OF THE TURBOCOOLER OIL								
21.350	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 01-JUN-2018 9855:36 5896		
+ 21-52-05-700-801-01	TURBOCOOLER OIL LEVEL CHECK - TURBOCOOLER (504HN)								
	REF: See Workcard	MOS HRS/MSC AFL	200				(EBT) 10055:36		
	NEW REQUIREMENT ADDED ON 11-OCT-2017. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-05-900-801-01	TURBOCOOLER								
21.350	3269B0202 331 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			31-AUG-2016 9847:51 5893		
+ 21-52-09-210-802-01	GENERAL VISUAL INSPECTION OF THE ECU HEAT EXCHANGER GRID								
21.360	REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
21-52-18-100-801-01	CLEANING OF THE HP WATER SEPARATOR FILTER								
21.370	REF: See Workcard	MOS HRS/MSC AFL	24 1200	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2020 11055:36	01-JUL-2020 11095:36
+ 21-52-19-200-801-01	INSPECTION/CHECK OF THE LP WATER SEPARATOR COMPONENTS								
21.380	REF: See Workcard	MOS HRS/MSC AFL	6	+5d			01-JUN-2018 9855:36 5896	01-DEC-2018	06-DEC-2018
21-52-21-350-801-01	RESTORATION TURBO FAN (OVERHAUL)								
21.410 OVERHAUL	TVT107-28H4 64 REF: See Workcard	MOS HRS/MSC AFL	3000	+3%			18-APR-2006 5778:48 3578	6578	6668
21-52-21-900-801-01	TURBO FAN								
21.410	TVT107-28H4 64 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			18-APR-2006 5778:48 3578		
21-52-33-900-801-01	TURBINE ANTI-ICING VALVE								
21.390	784-723-2 390 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-71-01-350-801-01	RESTORATION LEFT OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)								
36.010	D20425-1 0140 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
+ 21-71-01-350-801-02	RESTORATION RIGHT OZONE CONVERTER (FUNCTIONAL TEST AND CLEANING)								
36.010	D20425-1 0258 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
21-90-01-900-801-01	AFT AVIONICS RACK COOLING VALVE								
	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C		TSN:0 TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0 0		
212801	COCKPIT CONDITIONING ELECTRIC VALVE								
21.060	BYLB51003 751 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
212806	CABIN CONDITIONING ELECTRIC VALVE								
21.060	BYLB51003 797 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
212811	BAGGAGE COMPARTMENT SUPPLY ELECTRIC VALVE								
21.070	B97-26-551 20335 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSR:0 TSN:3087 TSR:0 TSR:0		16-SEP-2003 3300:12 2048		
212816	BAGGAGE COMPARTMENT ISOLATION ELECTRIC VALVE								
21.030	3188-000 292 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212821	AERATOR CHECK VALVE CYLB50712	MOS					23-MAR-2000		
21.080	418 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212826	CREW COLD AIR CHECK VALVE CYLB51162-1	MOS					23-MAR-2000		
21.090	520 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212831	PASSENGER COLD AIR CHECK VALVE PN	MOS							
21.540	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C						
212836	CREW AIR CONDITIONING CHECK VALVE CYLB51111	MOS					23-MAR-2000		
21.110	510 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212841	PASSENGERS AIR CONDITIONING CHECK VALVE CYLB51111	MOS					23-MAR-2000		
21.110	529 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212846	AERATOR PRESSURE REGULATING VALVE 3313-100	MOS					23-MAR-2000		
21.120	230 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
212851	NOSE CONE PNEUMATIC ACTUATOR 7021-200	MOS					15-JAN-2014		
21.130	285 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:6 TSN:11083 TSR:0 TSR:0			9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212856	NOSE CONE OVERPRESSURE VALVE								
21.140	6025-300 405 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-FEB-2004 3767:18 2344		
212861	NOSE CONE THERMOSTAT								
21.150	784-756-1 539 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
212A31	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE								
	CYLB51162-1 535 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
213801	CROSS-FEED VALVE								
21.280	VC1005-1 250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
213811	EMERGENCY PRESSURIZATION CONTROLLER								
21.300	911A0401 319 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-AUG-2009 8246 5216		
213816	LH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 01271 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:122 TSR:6 TSN:3986 TSR:0 TSR:0			23-APR-2015 9760:57 5832		
213821	RH BAGGAGE COMPARTMENT NEGATIVE PRESSURE RELIEF VALVE								
21.270	2827A01 304 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:10613			23-APR-2015 9760:57 5832		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213826	NO. 1 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE 985C63-21	MOS					23-MAR-2000		
21.310	548 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213831	NO. 2 BAGGAGE COMPARTMENT PRESSURE RELIEF VALVE 985C63-21	MOS					23-MAR-2000		
21.310	535 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213836	NO. 1 HP/LP TURBINE BRAKE CHECK VALVE AR88-02-00-03	MOS					23-MAR-2000		
21.320	1213 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213841	NO. 2 HP/LP TURBINE BRAKE CHECK VALVE AR88-02-00-03	MOS					23-MAR-2000		
21.320	1216 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213846	NO. 1 ENGINE PRESSURE SUPPLY CHECK VALVE AR88-02-00-03	MOS					23-MAR-2000		
21.330	1210 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213851	NO. 2 ENGINE PRESSURE SUPPLY CHECK VALVE AR88-02-00-03	MOS					23-MAR-2000		
21.330	1211 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
213856	APU SUPPLY PRESSURE CHECK VALVE AR88-02-00-03	MOS					23-MAR-2000		
21.330	1212 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213861	TRIPLE INDICATOR 3311AJ67 266 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:232 TSR:2 TSO:38 TSR:0 TSR:0			28-APR-2015 9760:57 5832		
213866	PRESSURIZATION JET PUMP FGFB722602A2 265 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
215801	PRIMARY HEAT EXCHANGER 11-831149-1 76 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			11-FEB-2012 8911:19 5476		
215811	HP WATER SEPARATOR 8903D04 00288 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
215816	LP WATER SEPARATOR B31WA3023 00690 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
215821	TURBINE ANTI-ICING TUBING SENSOR 784-646 456 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
215831	TURBINE ANTI-ICING AMPLIFIER 784-688-1 404 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215836	BLOWER BY-PASS ELECTRIC VALVE BYLB51035-1	MOS					23-MAR-2000		
21.450	476 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
215841	ECU OVERHEATING SENSOR RP482-01	MOS		TSN:0			16-DEC-2011		
21.460	DAAA02800 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			5461		
215A01	COALESCAR,WATER TRAP LP B31WA3010-053	MOS		TSR:1			15-AUG-2017		
	1082 REF:	HRS/MSC AFL	O/C	TSR:0 TSR:0					
216801	COCKPIT THERMOSTAT 150T346	MOS					23-MAR-2000		
21.470	953 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216806	CABIN THERMOSTAT 150T346	MOS					23-MAR-2000		
21.470	976 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216811	CABIN TEMPERATURE REGULATION DUAL ELECTRIC VALVE BYLB51226-002	MOS					23-MAR-2000		
21.480	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216816	COCKPIT TEMPERATURE REGULATION DUAL ELECTRIC VALVE BYLB51034-003	MOS					15-JAN-2001		
21.480	190 REF: GENERIC NO REF	HRS/MSC AFL	O/C				406 266		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216821	COCKPIT DUCT TEMPERATURE SENSOR AYLF50425	MOS					23-MAR-2000		
21.490	1898 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216826	CABIN DUCT TEMPERATURE SENSOR AYLF50425	MOS					23-MAR-2000		
21.490	1926 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
216831	COCKPIT THERMO RESISTOR HYLZ50514-042	MOS					04-DEC-2009		
21.500	2110 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:12 TSN:0 TSN:0			8316:45 5245		
216836	CABIN THERMO RESISTOR HYLZ50514-041	MOS					18-JAN-2005		
21.500	1601J REF: GENERIC NO REF	HRS/MSC AFL	O/C				4750:42 2962		
216841	CONDITIONING PANEL 5897-655-80-13	MOS					12-DEC-2014		
21.510	604 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:0 TSN:6613 TSR:0 TSR:0			9708:47 5806		

CHAPTER 22 AUTO FLIGHT

+ 22-10-00-710-801-01 (s)	OPERATIONAL TEST OF THE AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS)						PKG		
22.010	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 22-10-05-710-801-01 (s)	OPERATIONAL TEST OF THE AILERON AUTOPILOT SERVO MOTOR						PKG		
22.020	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			28-SEP-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-10-05-710-801-02 (s)	OPERATIONAL TEST OF THE ELEVATOR AUTOPILOT SERVO MOTOR						PKG		
22.030	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			28-SEP-2012 9012:54 5520		
22-10-05-900-801-01	AILERON AUTOPILOT SERVO MOTOR								
22.020	4006719-942 99011753 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:8 TSR:0 TSR:0		20-MAY-2010 8412:34 5274		
22-10-05-900-801-02	ELEVATOR AUTOPILOT SERVO MOTOR								
22.030	4006719-942 99072656 REF: See Workcard	MOS HRS/MSC AFL	O/C				12-MAY-2005 4984:06 3090		
+ 22-10-07-700-801-01 (s)	CHECK OF THE AILERON AUTOPILOT SERVO MOTOR CABLES AND PULLEY						PKG		
22.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 22-10-07-700-801-02 (s)	CHECK OF THE ELEVATOR AUTOPILOT SERVO MOTOR CABLES AND PULLEY						PKG		
22.030	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 22-15-00-720-801-01 (s)	FUNCTIONAL TEST OF MACH TRIM						PKG		
22.090	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
22-30-05-900-801-01	NO. 1 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	7009025-903 99101244 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-30-05-900-801-02	NO. 2 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	7009025-903 90101243 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
22-30-05-900-801-03	NO. 3 ENGINE AUTOTHROTTLE SERVO MOTOR								
22.070	7009025-903 99091238 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
221801	AUTOPILOT CONTROL UNIT								
22.060	7011702-933 00051032 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:2 TSR:0 TSR:0			04-APR-2013 9269:30 5625		
221806	YAW DAMPER ACTUATOR								
22.040	7002800-901 11471 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			20-APR-2006 5778:48 3578		
221811	AILERON SERVO MOTOR CAPSTAN								
22.050	4005842 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
221816	ELEVATOR SERVO MOTOR CAPSTAN								
22.050	4005842 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

CHAPTER 23 COMMUNICATIONS

+ 23-00-00-710-801-01	OPERATIONAL TEST OF RADIO-COMMUNICATION AND RADIONAVIGATION SYSTEMS								
23.010	REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 23-60-00-760-801-01 (s)	VISUAL INSPECTION AND ELECTRICAL BONDING CHECK OF THE STATIC DISCHARGERS						PKG		
23.130	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
231801	HF (LEADING EDGE) ANTENNA								
23.020	1200008-003 480 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231806	NO. 1 HF TRANSCEIVER								
23.030	822-0102-001 790 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231811	NO. 2 HF TRANSCEIVER								
23.030	822-0102-001 794 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231816	NO. 1 AMPLIFIER COUPLER								
23.040	622-8114-002 2900 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231821	NO. 2 AMPLIFIER COUPLER								
23.040	622-8114-002 2757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231826	NO. 1 HF CONTROL UNIT								
23.050	064-1016-03 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231831	NO. 2 HF CONTROL UNIT 064-1016-03 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231836	NO. 1 HF BRIDGING AMPLIFIER 071-0019-00 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231841	NO. 2 HF BRIDGING AMPLIFIER 071-0019-00 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231846	HF DUAL CAPACITOR 071-1270-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231851	NO. 1 VHF ANTENNA ANV142SZ 5408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:8			18-AUG-2000 23 8		
231856	NO. 2 VHF ANTENNA S65-8280-10 310-23107 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JUL-2012 9012:54 5520		
231859	NO. 3 VHF ANTENNA S65-8280-10 310-23709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231861	NO. 1 VHF TRANSCEIVER								
23.090	822-1115-001 2952 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			13-AUG-2015 9779:37 5841		
231866	NO. 2 VHF TRANSCEIVER								
23.090	822-1115-001 D32R REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			03-OCT-2013 9431:48 5694		
231869	NO. 3 VHF TRANSCEIVER								
23.090	622-7293-001 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231871	NO. 1 VHF CONTROL UNIT								
23.100	822-0730-334 1568 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:4984:06 TSN:3090			12-MAY-2005 4984:06 3090		
231876	NO. 2 VHF CONTROL UNIT								
23.100	822-0730-334 1BX5 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:4984:06 TSN:3090			12-MAY-2005 4984:06 3090		
231879	NO. 3 VHF CONTROL UNIT								
23.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
231A01	FLITEFONE TRANSCEIVER								
	724855-802 MSA5291 REF:	MOS HRS/MSC AFL	O/C				15-JUL-2016 9814:30 5883		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231A02	FLITEFONE ANTENNA DMN129-18-1 3499 REF:	MOS HRS/MSC AFL	O/C	TSN:27 TSN:0 TSN:0			24-OCT-2016 9847:51 5893		
231A04	CALL FLITEFONE ALERTER 725256-801 MSL3083 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A05	FLITEFONE DUPLEXER 620317-2 00601 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A08	FLITEFONE COCKPIT CONTROL 725729-815WH MX43002 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A09	FLITEFONE CABN #1 CONTROL 725729-815WH MX42845 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A10	FLITEFONE CABN #2 CONTROL 725729-815WH MX42796 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A11	FLITEFONE CABN #3 CONTROL 725729-815WH MX43915 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231A12	FLITEFONE CABN #4 CONTROL 725729-815WH MX46645 REF:	MOS HRS/MSC AFL	O/C				20-SEP-2012 9012:54 5520		
231A17	DIST BUS CBN #1 REPEATER 724864-801 MSK5106 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A18	DIST BUS CBN #2 REPEATER 724868-802 MST6982 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A19	DIST BUS CBN #3 REPEATER 902205-803 MSR4770 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A20	DIST BUS CBN #4 REPEATER 902205-803 MSR4761 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A21	DIST BUS CBN #5 REPEATER 902205-803 MSR4683 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
231A22	DIST BUS CBN #6 REPEATER 902205-803 MSR4764 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231A31	COMM UNIT,SATELLITE 3433-105-100A00 3433-105-1000277 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-SEP-2012 9012:54 5520		
231A35	SATCOM DATA UNIT 3433-500-010C02 343-500-010125 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			10-APR-2007 6653:12 4106		
231A46	AMP LN SATCOM #1 DIPLEXER 3433-300-010A02 126 REF:	MOS HRS/MSC AFL	O/C				21-SEP-2001 1126		
231A61	FAX MACHINE F0-375 87118771 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
232801	SELCAL RECEIVER 1200008-003 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
233806	PILOT AUDIO CONTROL 990-3333-142 9904165 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
233811	COPILOT AUDIO CONTROL 990-3333-142 12100065534 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-APR-2013 9281:02 5629		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233A06	PA AMPLIFIER 990-4132-001 00050004692 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
233A07	PA NO.2 AMPLIFIER 990-4132-001 00050004693 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
233A15	VIDEO CABIN FWD MONITOR 990-1810-004 00050004732 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSN:8223 TSR:0 TSR:0			04-AUG-2009 8246 5216		
233A45	SATELLITE TV ANTENNA F50B319B4 BZ11 REF:	MOS HRS/MSC AFL	O/C	TSN:8			18-AUG-2000 23 8		
237A05	CABIN DISPLAY INTERFACE 920050 1505 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-JUN-2006 5918:48 3650		
237A06	DISPLAY CABIN CONTROL 922000-2 1146 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

CHAPTER 24 ELECTRICAL POWER

24-00-00-910-801-01	ELECTRICAL SYSTEM MAINTENANCE AND SAFETY PRECAUTIONS	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
	REF: AMM 24-00-00-910-801								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-20-05-710-801-01	OPERATIONAL TEST OF THE GROUND FAULT INTERRUPTER (GFI)	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC N/A					0		
		AFL					0		
		APH					0		
+ 24-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE VOLTAGE MONITORING CIRCUITS						PKG		
	PKG 21	MOS					03-JUN-2014		
24.030	REF: See Workcard	HRS/MSC 1600		+40			9560:43		
		AFL					5737		
+ 24-30-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 ENGINE VOLTAGE MONITORING CIRCUITS						PKG		
	PKG 21	MOS					03-JUN-2014		
24.180	REF: See Workcard	HRS/MSC 1600		+3%			9560:43		
		AFL					5737		
+ 24-30-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE VOLTAGE MONITORING CIRCUITS						PKG		
	PKG 21	MOS					03-JUN-2014		
24.250	REF: See Workcard	HRS/MSC 1600		+3%			9560:43		
		AFL					5737		
+ 24-30-00-710-801-04 (s)	OPERATIONAL TEST OF THE APU VOLTAGE MONITORING CIRCUITS						PKG		
	PKG 21	MOS					03-JUN-2014		
24.030	REF: See Workcard	HRS/MSC 1600		+3%			9560:43		
		AFL					5737		
+ 24-30-00-710-802-01 (s)	OPERATIONAL TEST OF THE APU SHUTDOWN SAFETIES WITH " MASTER" APU CONTROL						PKG		
	PKG 21	MOS					03-JUN-2014		
24.090	REF: See Workcard	HRS/MSC 1600		+40			9560:43		
		AFL					5737		
24-30-08-700-801-01S	CAPACITY TEST EMERGENCY POWER SUPPLY BATTERY								
	PN	MOS					23-MAR-2000		
	NOT INSTALLED	HRS/MSC N/A					0		
	REF: GENERIC CMM	AFL					0		
		APH					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-08-710-801-01S	OPERATIONAL TEST EMERGENCY POWER SUPPLY PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC N/A AFL APH					23-MAR-2000 0 0 0		
24-30-08-900-801-01	EMERGENCY POWER SUPPLY PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC O/C AFL APH		TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
24-31-13-350-801-01	RESTORATION ENGINE NO.1 STARTER/GENERATOR (OVERHAUL) 8060-160 426 REF: See Workcard	MOS HRS/MSC 1240 AFL	+3%				23-JUL-2013 9343:24 5658	10583:24	10620:36
24-31-13-350-801-02	RESTORATION ENGINE NO.2 STARTER/GENERATOR (OVERHAUL) 8060-160 1394 REF: See Workcard	MOS HRS/MSC 1240 AFL	+3%				03-APR-2013 9269:30 5625	10509:30	10546:42
24-31-13-350-801-03	RESTORATION ENGINE NO.3 STARTER/GENERATOR (OVERHAUL) 8060-160 1833 REF: See Workcard	MOS HRS/MSC 1240 AFL	+3%				03-APR-2013 9269:30 5625	10509:30	10546:42
24-31-13-350-801-04	RESTORATION APU STARTER/GENERATOR (OVERHAUL) 8060-160 1908 REF: See Workcard	MOS HRS/MSC AFL APH 1240	+3%				14-NOV-2016 3303:24	4543:24	4580:36
24-31-13-900-802-01	NO. 1 STARTER/GENERATOR 8060-160 426 REF: See Workcard	MOS HRS/MSC O/C AFL					02-FEB-2017 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-13-900-802-02	NO. 2 STARTER/GENERATOR								
24.050	8060-160 1394 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSN:1142 TSO:0 TSO:0			03-APR-2013 9269:30 5625		
24-31-13-900-802-03	NO. 3 STARTER/GENERATOR								
24.040	8060-160 1833 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSN:1049 TSO:0 TSO:0			03-APR-2013 9269:30 5625		
24-31-13-900-802-04	APU STARTER/GENERATOR								
24.060	8060-160 1908 REF: See Workcard	MOS HRS/MSC AFL APH	O/C 0	TSN:202 TSO:2 TSO:0			14-NOV-2016		
+ 24-31-17-220-803-01	CHECK NO. 1 STARTER/GENERATOR BRUSHES								
24.040	8060-160 426 REF: See Workcard	MOS HRS/MSC AFL	150	+3%			02-FEB-2017 9847:51 5893	9997:51	10002:21
+ 24-31-17-220-803-02	CHECK NO. 2 STARTER/GENERATOR BRUSHES								
24.050	8060-160 1394 REF: See Workcard	MOS HRS/MSC AFL	600	+30			29-APR-2016 9805:22 5878	10405:22	10435:22
+ 24-31-17-220-803-03	CHECK NO. 3 STARTER/GENERATOR BRUSHES								
24.040	8060-160 1833 REF: See Workcard	MOS HRS/MSC AFL	600	+30			29-APR-2016 9805:22 5878	10405:22	10435:22
24-31-17-960-801-01	REPLACEMENT ENGINE NO.1 STARTER/GENERATOR BRUSHES (P/N 8060-150 & 8060-160 ONLY)								
24.040	8060-160 426 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-JUL-2013 9343:24 5658		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-17-960-801-02	REPLACEMENT ENGINE NO.2 STARTER/GENERATOR BRUSHES (P/N 8060-150 & 8060-160 ONLY)								
24.050	8060-160 1394 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-APR-2013 9269:30 5625		
24-31-17-960-801-03	REPLACEMENT ENGINE NO.3 STARTER/GENERATOR BRUSHES (P/N 8060-150 & 8060-160 ONLY)								
24.040	8060-160 1833 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-APR-2013 9269:30 5625		
24-31-17-960-801-04	REPLACEMENT APU STARTER/GENERATOR BRUSHES (P/N 8060-150 & 8060-160 ONLY)								
24.060	8060-160 1908 REF: See Workcard	MOS HRS/MSC AFL APH	O/C 0				14-NOV-2016		
24-32-01-350-801-01	RESTORATION NO. 1 MAIN BATTERY (OVERHAUL) (NICKEL-CADMIUM BATTERY ONLY)								
24.070 OVERHAUL	4076-10 N03004 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			14-AUG-2017	14-AUG-2018	14-SEP-2018
24-32-01-350-801-02	RESTORATION NO. 2 MAIN BATTERY (OVERHAUL) (NICKEL-CADMIUM BATTERY ONLY)								
24.080 OVERHAUL	4076-10 N03003 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			14-AUG-2017	14-AUG-2018	14-SEP-2018
24-32-01-700-801-01	REGULAR CHECK NO. 1 MAIN BATTERY (NICKEL-CADMIUM BATTERY ONLY)								
24.070	4076-10 N03004 REF: See Workcard	MOS HRS/MSC AFL	6 250	+18d +25			01-JUN-2018 9855:36 5896	01-DEC-2018 10105:36	19-DEC-2018 10130:36
24-32-01-700-801-02	REGULAR CHECK NO. 2 MAIN BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.080	4076-10 N03003 REF: See Workcard	MOS HRS/MSC AFL	6 250	+18d +25			01-JUN-2018 9855:36 5896	01-DEC-2018 10105:36	19-DEC-2018 10130:36

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-32-01-700-802-01	REGULAR CHECK NO. 1 MAIN BATTERY (LEAD / ACID BATTERY ONLY)								
24.070	4076-10 N03004 REF: See Workcard	MOS HRS/MSC AFL	N/A						
+ 24-32-01-700-802-02	REGULAR CHECK NO. 2 MAIN BATTERY (LEAD / ACID BATTERY ONLY)								
24.080	4076-10 N03003 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-01-900-801-01	NO. 1 MAIN BATTERY								
24.070	4076-10 N03004 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			01-JUN-2018 9855:36 5896		
24-32-01-900-801-02	NO. 2 MAIN BATTERY								
24.080	4076-10 N03003 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:10 TSO:5:29 TSO:2			01-JUN-2018 9855:36 5896		
24-32-01-960-801-01	DISCARD NO. 1 MAIN BATTERY (LEAD / ACID BATTERY ONLY)								
24.070	4076-10 N03004 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-01-960-801-02	DISCARD NO. 2 MAIN BATTERY (LEAD / ACID BATTERY ONLY)								
24.080	4076-10 N03003 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-09-610-801-01	SERVICE STAND-BY HORIZON BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.210	100-0540-04 1019142 REF:	MOS HRS/MSC AFL	N/A				02-DEC-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-610-801-02	SERVICE NO. 1 IRS (IRS 1) STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.220	100-0540-02 1051 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-09-610-801-03	SERVICE NO. 2 IRS (IRS 2) STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.220	100-0540-02 1464 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-09-610-801-04	SERVICE ENGINE INSTRUMENT DISPLAY (EID) STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.240	100-0540-03 1380 REF:	MOS HRS/MSC AFL	N/A						
24-32-09-610-801-05	SERVICE NO. 3 IRS (IRS 3) STAND-BY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
24.230	100-0540-02 1159 REF: See Workcard	MOS HRS/MSC AFL	N/A						
24-32-09-610-801-06	SERVICE AUXILIARY BATTERY (SAFT NICKEL-CADMIUM BATTERY ONLY)								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				23-AUG-2000 0 0		
24-32-09-710-802-01	OPERATIONAL TEST STAND-BY HORIZON BATTERY (SECURAPLANE XL245 TYPE BATTERY)								
24.210	100-0540-04 1019142 REF:	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019
24-32-09-710-802-02	OPERATIONAL TEST NO. 1 IRS (IRS 1) STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY)								
24.220	100-0540-02 1051 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-710-802-03 24.220	OPERATIONAL TEST NO. 2 IRS (IRS 2) STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY) 100-0540-02 1464 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019
24-32-09-710-802-04 24.240	OPERATIONAL TEST ENGINE INSTRUMENT DISPLAY (EID) STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY) 100-0540-03 1380 REF:	MOS HRS/MSC AFL	12	+3%			08-AUG-2017 9850:07 5894	08-AUG-2018	19-AUG-2018
24-32-09-710-802-05 24.230	OPERATIONAL TEST NO. 3 IRS (IRS 3) STAND-BY BATTERY (SECURAPLANE XL245 TYPE BATTERY) 100-0540-02 1159 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019
24-32-09-710-802-06	OPERATIONAL TEST AUXILIARY BATTERY (SECURAPLANE XL245 TYPE BATTERY) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				23-AUG-2000 0 0		
24-32-09-900-801-01 24.210	STAND-BY HORIZON BATTERY 100-0540-04 1019142 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:21 TSR:7:45 TSR:3		01-JUN-2018 9855:36 5896		
24-32-09-900-801-02 24.220	NO. 1 IRS (IRS 1) STAND-BY BATTERY 100-0540-02 1051 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:2 TSR:0 TSR:0		21-APR-2015 9760:57 5832		
24-32-09-900-801-03 24.220	NO. 2 IRS (IRS 2) STAND-BY BATTERY 100-0540-02 1464 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:39 TSR:94:39 TSR:64		01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-900-801-04 24.240	ENGINE INSTRUMENT DISPLAY (EID) STAND-BY BATTERY 100-0540-03 1380 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:12 TSN:9850:07 TSN:5894			08-AUG-2017 9850:07 5894		
24-32-09-900-801-05 24.230	NO. 3 IRS (IRS 3) STAND-BY BATTERY 100-0540-02 1159 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:39 TSR:94:39 TSR:64			01-JUN-2018 9855:36 5896		
24-32-09-900-801-06 24.210	AUXILIARY BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
24-32-09-960-802-01 24.210 LIFE LIMIT	DISCARD STAND-BY HORIZON BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY) 100-0540-04 1019142 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				02-DEC-2016 9847:51 5893	02-DEC-2020	
24-32-09-960-802-02 24.220 LIFE LIMIT	DISCARD NO. 1 IRS (IRS 1) STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY) 100-0540-02 1051 REF: See Workcard	MOS HRS/MSC AFL	48				27-FEB-2015	27-FEB-2019	
24-32-09-960-802-03 24.220 LIFE LIMIT	DISCARD NO. 2 IRS (IRS 2) STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY) 100-0540-02 1464 REF: See Workcard	MOS HRS/MSC AFL	48				09-MAR-2015	09-MAR-2019	
24-32-09-960-802-04 24.240 LIFE LIMIT	DISCARD ENGINE INSTRUMENT DISPLAY (EID) STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY) 100-0540-03 1380 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				22-AUG-2016	22-AUG-2020	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-32-09-960-802-05	DISCARD NO. 3 IRS (IRS 3) STAND-BY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY)								
24.230	100-0540-02	MOS	48				06-MAR-2015	06-MAR-2019	
LIFE LIMIT	1159	HRS/MSC							
	REF: See Workcard	AFL							
24-32-09-960-802-06	DISCARD AUXILIARY BATTERY PACK (SECURAPLANE XL245 TYPE BATTERY)								
	PN	MOS					23-AUG-2000		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
24-33-05-220-803-01	CHECK APU STARTER/GENERATOR BRUSHES								
24.060	8060-160	MOS					14-NOV-2016		
	1908	HRS/MSC							
	REF: See Workcard	AFL							
		APH	600	+30			3303:24	3903:24	3933:24
+ 24-40-00-720-801-01 (s)	FUNCTIONAL TEST OF THE GROUND POWER RECEPTACLE OVERVOLTAGE PROTECTION PCB								
24.170	PKG 21	MOS					03-JUN-2014		
	REF: See Workcard	HRS/MSC	1600	+40			9560:43		
		AFL					5737		
+ 24-41-00-720-801-01	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - GENERAL TEST OF THE FUNCTION								
24.190		MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
24-41-00-720-801-02	FUNCTIONAL TEST OF BATTERY CHARGING BY GPU - TEST OF THE SAFETY DEVICES								
24.190		MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
		APH					0		
24-61-01-900-801-01	MAIN ELECTRICAL BOX								
24.010	430GC02V01	MOS					23-MAR-2000		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-63-13-710-801-01 (s)	OPERATIONAL TEST OF THE DOME LIGHT CONTROL PCB (CRASH CONDITION)						PKG		
24.200	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
24-90-01-900-801-01	GROUND FAULT (GFI) INTERRUPTER								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C			TSN:0 TSN:0 TSN:0 TSN:0	23-MAR-2000 0 0 0		
240A25	LEFT MASTER AVIONICS SWITCH								
	319VL21AAAAPY00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	23-SEP-2008 7867:48 4944		
240A26	RIGHT MASTER AVIONICS SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	23-MAR-2000 0 0		
240A27	MASTER AVIONICS(MINI LOAD) SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	23-MAR-2000 0 0		
243801	NO. 1 GENERATOR CONTROL								
24.100	D22-600 1279 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	09-AUG-2007 6917:42 4277		
243802	NO. 2 GENERATOR CONTROL								
24.100	D22-600 1622 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0	23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243803	NO. 3 GENERATOR CONTROL								
24.100	D22-600 1707 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-JUL-2002 2015:24 1261		
243804	APU GENERATOR CONTROL								
24.110	D22-600 1624 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243806	BATTERY BLOWER								
24.120	VA0906XXA 11214 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243811	UPPER ELECTRICAL PANEL								
24.130	132TS09Y02 215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243816	LEFT DC VOLTMETER								
24.140	2396-118-1 2245 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243821	RIGHT DC VOLTMETER								
24.140	2396-118-1 2241 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243826	LEFT DC AMMETER								
24.150	2396-323-0 1569 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243831	RIGHT DC AMMETER								
24.150	2396-323-0 1568 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243836	BATTERY TEMPERATURE DUAL INDICATOR								
24.160	206-0002-202S 310 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
243A18	(C18) PCB								
	805GC01Y04 656 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JAN-2005 4750:42 2962		
243A81	COMMUNICATIONS STANDBY BATTERY								
	100-0540-02 2045 REF:	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			12-AUG-2015 9779:37 5841		
243A82	SERVICE COMMUNICATIONS STANDBY BATTERY (SAFT BATTERY ONLY)								
	100-0540-02 2045 REF:	MOS HRS/MSC AFL	N/A						
+ 243A85	FUNCTIONAL TEST COMMUNICATIONS STANDBY BATTERY (SECURAPLANE BATTERY ONLY)								
	100-0540-02 2045 REF:	MOS HRS/MSC AFL	12				01-JUN-2018 9855:36 5896	01-JUN-2019	
243A86	REPLACE COMMUNICATIONS STANDBY BATTERY --								
	100-0540-02 2045 REF:	MOS HRS/MSC AFL	48				06-JUL-2015	06-JUL-2019	
LIFE LIMIT									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
244801	GROUND POWER RECEPTACLE								
24.170	C0BAQXH0004 18183 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-00-05-200-801-01 (s)	INSPECTION OF THE CREW AND PASSENGER SEAT HARNESSES AND SAFETY BELTS						PKG		
25.010	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 25-00-09-200-801-01	CHECK OF THE CLOSING AND SEALING OF TRASH CANS								
25.090	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
25-11-01-900-801-01	PILOT SEAT								
25.030	132-051-101 262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
25-11-01-900-801-02	COPILOT SEAT								
25.030	132-050-101 261 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
25-11-13-640-801-01 (s)	GREASING OF THE PILOT SEAT ACTUATOR ROD END-FITTING						PKG		
25.020	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
25-11-13-640-801-02 (s)	GREASING OF THE COPILOT SEAT ACTUATOR ROD END-FITTING						PKG		
25.020	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-19-960-801-01 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - LH PILOT SEAT PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
25-11-19-960-801-02 (s)	REPLACEMENT OF THE PILOT SEAT LOCKING PIN SPRINGS - RH PILOT SEAT PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
+ 25-11-25-200-801-01 (s)	INSPECTION OF THE PILOT SEAT ROLLER PINS PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
25.185	REF: See Workcard	HRS/MSC AFL	3750						
+ 25-11-25-200-801-02 (s)	INSPECTION OF THE COPILOT SEAT ROLLER PINS PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
25.185	REF: See Workcard	HRS/MSC AFL	3750						
25-12-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THIRD CREW MEMBER SEAT - THIRD CREW MEMBER SEAT (M1001MP) PKG 5	MOS	12	+1m			PKG 01-JUN-2018 9855:36 5896		
	REF: SMM 25-90-01	HRS/MSC AFL	800	+40					
25-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - PASSENGER DOOR ASSIST HANDLE PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
25-20-00-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE ASSIST HANDLES - AFT LAVATORY ASSIST HANDLE PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: AMM 25-20-00-210-801	HRS/MSC AFL	3750						

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20-00-220-801-04	INSPECTION / TEST OF THE WASTE CONTAINERS - INSPECTION / TEST OF WASTE CONTAINERS	MOS					01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	1000	+40			9855:36 5896	10855:36	10895:36
25-20-00-220-802-01 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF DOORS, DRAWERS AND THEIR RESPECTIVE LATCHING MECHANISMS	MOS					01-JUN-2018		
	PKG 31	HRS/MSC AFL	72	+2m			9855:36 5896		
	REF: See Workcard		3750						
25-20-00-220-802-02 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - INSPECTION OF THE POP OUT WORK SURFACE	MOS					01-JUN-2018		
	PKG 31	HRS/MSC AFL	72	+2m			9855:36 5896		
	REF: See Workcard		3750						
25-20-00-220-802-05 (s)	INSPECTION / TEST OF THE INTERIOR COMPLETION ELEMENTS - OPERATIONAL TEST OF TAMBOUR DOOR POWER CUT OFF FUNCTION	MOS					01-JUN-2018		
	PKG 31	HRS/MSC AFL	72	+2m			9855:36 5896		
	REF: See Workcard		3750						
25-21-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE SINGLE AND DOUBLE SEATS	MOS					01-JUN-2018		
	PKG 7	HRS/MSC AFL	36	+1m			9855:36 5896		
	REF: SMM 25-90-03		2400	+40					
25-21-00-220-801-02 (s)	DETAILED INSPECTION OF THE PASSENGER SEATS AND DIVAN - DETAILED INSPECTION OF THE DIVAN	MOS					01-JUN-2018		
	PKG 7	HRS/MSC AFL	36	+1m			9855:36 5896		
	REF: SMM 25-90-05		2400	+40					

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-22-01-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE CONSOLE TABLES - CONSOLE TABLES IN LOCATIONS OTHER THAN EMERGENCY EXIT PKG 31 REF: SMM 25-90-27	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
25-22-05-220-802-01 (s)	DETAILED INSPECTION OF THE DINING TABLE PKG 31 REF: SMM 25-90-29	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
25-30-16-900-801-01	COFFEE MAKER PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C		TSN:0 TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0 0		
25-30-33-900-801-01	CONVECTION OVEN 500-0590-01 98-10-24488 REF: GENERIC CMM	MOS HRS/MSC AFL	O/C		TSR:2 TSR:0 TSR:0		09-JAN-2013 9160:32 5590		
25-33-09-210-801-01	INSPECTION OF THE COFFEE MAKER/ESPRESSO MACHINE REF: GENERIC CMM	MOS HRS/MSC AFL	A/R				23-MAR-2000 0 0		
25-33-17-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE MICROWAVE OVEN PKG 7 REF: See Workcard	MOS HRS/MSC AFL	36 2400	+1m +40			PKG 01-JUN-2018 9855:36 5896		
25-33-50-900-801-01	PILOT FLASHLIGHT PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C		TSN:219 TSO:0 TSO:0 TSN:5896 TSO:0		01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-33-50-900-801-02	COPILOT FLASHLIGHT PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	TSN:219 TSO:0 TSO:0 TSN:5896 TSO:0			01-JUN-2018 9855:36 5896		
+ 25-60-00-200-801-02 (s)	INSPECTION OF THE SAFETY EQUIPMENT - SAFETY EQUIPMENT PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
25-60-00-200-801-03 (s)	INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT PKG 16 REF:	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
25-60-01-900-801-01	NO. 1 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
25-60-01-900-801-02	NO. 2 EMERGENCY VISION ASSURANCE SYSTEM (EVAS) UNIT PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
25-61-00-200-881-01	INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207) MANDATORY REF: GENERIC NO REF	MOS HRS/MSC AFL	12				01-JUN-2018 9855:36 5896	01-JUN-2019	
+ 25-61-00-710-801-01	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT UNIT CONTROLS REF:	MOS HRS/MSC AFL	O/C				08-JAN-2017 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-00-710-801-02 (s)	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - CHECK OF ELT COCKPIT CONTROLS PKG 17 REF:	MOS HRS/MSC AFL	36	+1m			PKG 01-JUN-2018 9855:36 5896		
25-61-00-710-801-03	OPERATIONAL TEST OF THE EMERGENCY LOCATOR SYSTEM - SELF-TEST OF ELT REF:	MOS HRS/MSC AFL	6	+5d			01-JUN-2018 9855:36 5896	01-DEC-2018	06-DEC-2018
25-61-01-710-801-01	OPERATIONAL TEST EMERGENCY LOCATOR (ELT) TRANSMITTER G-SWITCH ELT90A2560102001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60	+3%				? ?	
25-61-01-900-802-01 25.070	EMERGENCY LOCATOR (ELT) TRANSMITTER ELT90A2560102001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
25-61-13-960-801-01 25.070 LIFE LIMIT	DISCARD EMERGENCY LOCATOR (ELT) TRANSMITTER BATTERY PACK ELT90A2560102001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	DUE				01-JUN-2018 9855:36 5896	01-APR-2021 M	
25-61-21-900-801-01 25.080	EMERGENCY LOCATOR TRANSMITTER ANTENNA 62080 171 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:8			18-AUG-2000 23 8		
25-62-00-900-801-01 25.175	COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON ELP-362D 59767 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:26 TSN:287:08 TSN:156			16-AUG-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-00-900-801-02	DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
25.180	DK120 SD49407 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-AUG-2016 9847:51 5893		
+ 25-62-01-720-801-01	FUNCTIONAL CHECK COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON								
25.175	ELP-362D 59767 REF: See Workcard	MOS HRS/MSC AFL	25	+3%			16-AUG-2016 9847:51 5893	16-SEP-2018	08-OCT-2018
+ 25-62-01-720-801-02	FUNCTIONAL CHECK DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON								
25.180	DK120 SD49407 REF: See Workcard	MOS HRS/MSC AFL	25	+3%			17-AUG-2016 9847:51 5893	17-SEP-2018	09-OCT-2018
25-62-05-960-801-01	DISCARD COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR BEACON BATTERY								
25.175 LIFE LIMIT	ELP-362D 59767 REF: See Workcard	MOS HRS/MSC AFL	DUE				02-JUN-2014 9560:43 5737	01-NOV-2020 M	
25-62-05-960-801-02	DISCARD DIGITAL FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY								
25.180 LIFE LIMIT	DK120 SD49407 REF: See Workcard	MOS HRS/MSC AFL	DUE				17-AUG-2016 9847:51 5893	30-NOV-2020 M	
+ 25-64-13-200-801-01	INSPECTION NO. 1 LIFE RAFT								
	1015FAUL-290-1-102 10UL-00188 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			26-AUG-2016 9847:51 5893	26-AUG-2019	28-SEP-2019
+ 25-64-13-200-801-02	INSPECTION NO. 2 LIFE RAFT								
	1015FAUL-290-1-102 10UL-00189 REF: AMM 25-64-13-200-801	MOS HRS/MSC AFL	36	+3%			26-AUG-2016 9847:51 5893	26-AUG-2019	28-SEP-2019

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-13-350-801-01	OVERHAUL NO. 1 LIFE RAFT 1015FAUL-290-1-102 10UL-00188 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	36				26-AUG-2016 9847:51 5893	26-AUG-2019	
25.160									
25-64-13-350-801-02	OVERHAUL NO. 2 LIFE RAFT 1015FAUL-290-1-102 10UL-00189 REF: AMM 25-64-13-350-801	MOS HRS/MSC AFL	36	+3%			26-AUG-2016 9847:51 5893	26-AUG-2019	28-SEP-2019
25.160									
OVERHAUL									
25-64-13-900-801-01	NO. 1 LIFE RAFT 1015FAUL-290-1-102 10UL-00188 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	26-AUG-2016 9847:51 5893		
25.160									
25-64-13-900-801-02	NO. 2 LIFE RAFT 1015FAUL-290-1-102 10UL-00189 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSO:0 TSO:0 TSO:0	26-AUG-2016 9847:51 5893		
25.160									
25-64-13-900-801-03	NO. 3 LIFE RAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0	23-MAR-2000 0 0		
25.165									
25-64-13-900-801-04	NO. 4 LIFE RAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSN:0	23-MAR-2000 0 0		
25.165									
25-64-17-200-802-01	INSPECTION PILOT LIFE VEST P01074-101C 170117000010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-JUN-2017		
25.100									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-802-02	INSPECTION COPILOT LIFE VEST								
25.100	63600-505 L1080507 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015 9760:30 5832		
25-64-17-200-802-03	INSPECTION THIRD CREW MEMBER LIFE VEST								
25.105	63600-505 L1080508 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015 9760:57 5832		
25-64-17-200-803-01	INSPECTION NO. 1 PASSENGER LIFE VEST								
25.110	63600-105 L1030223 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015		
25-64-17-200-803-02	INSPECTION NO. 2 PASSENGER LIFE VEST								
25.110	63600-105 L1030221 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25-64-17-200-803-03	INSPECTION NO. 3 PASSENGER LIFE VEST								
25.115	63600-105 L1030228 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25-64-17-200-803-04	INSPECTION NO. 4 PASSENGER LIFE VEST								
25.115	63600-105 L1030225 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25-64-17-200-803-05	INSPECTION NO. 5 PASSENGER LIFE VEST								
25.120	63600-105 L1030215 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-06	INSPECTION NO. 6 PASSENGER LIFE VEST 63600-105 L1030224 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25.120									
25-64-17-200-803-07	INSPECTION NO. 7 PASSENGER LIFE VEST 63600-105 L1030222 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25.125									
25-64-17-200-803-08	INSPECTION NO. 8 PASSENGER LIFE VEST 63600-105 L103020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25.125									
25-64-17-200-803-09	INSPECTION NO. 9 PASSENGER LIFE VEST 63600-105 L1030226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25.130									
25-64-17-200-803-10	INSPECTION NO. 10 PASSENGER LIFE VEST 63600-105 L1030225 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015		
25.130									
25-64-17-200-803-11	INSPECTION NO. 11 PASSENGER LIFE VEST 63600-105 L1030214 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-MAR-2018		
25.135									
25-64-17-200-803-12	INSPECTION NO. 12 PASSENGER LIFE VEST 63600-105 L1030220 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2015		
25.135									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-200-803-13	INSPECTION NO. 13 PASSENGER LIFE VEST								
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-14	INSPECTION NO. 14 PASSENGER LIFE VEST								
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-15	INSPECTION NO. 15 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-16	INSPECTION NO. 16 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-17	INSPECTION NO. 17 PASSENGER LIFE VEST								
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-18	INSPECTION NO. 18 PASSENGER LIFE VEST								
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-200-803-19	INSPECTION NO. 19 PASSENGER LIFE VEST								
25.155	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-802-01	RESTORATION PILOT LIFE VEST (OVERHAUL OR DISCARD) P01074-101C 170117000010 REF: See Workcard	MOS HRS/MSC AFL	120	+3%			21-JUN-2017 9849:54 5894	21-JUN-2027	09-OCT-2027
25.100 OVERHAUL									
25-64-17-350-802-02	RESTORATION COPILOT LIFE VEST (OVERHAUL OR DISCARD) 63600-505 L1080507 REF: See Workcard	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	13-AUG-2018	M 01-DEC-2018
25.100 OVERHAUL									
25-64-17-350-802-03	RESTORATION THIRD CREW MEMBER LIFE VEST (OVERHAUL OR DISCARD) 63600-505 L1080508 REF: See Workcard	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	13-AUG-2018	M 01-DEC-2018
25.105 OVERHAUL									
25-64-17-350-803-01	RESTORATION NO. 1 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L1030223 REF:	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	13-AUG-2018	M 01-DEC-2018
25.110 OVERHAUL									
25-64-17-350-803-02	RESTORATION NO. 2 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L1030221 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25.110 OVERHAUL									
25-64-17-350-803-03	RESTORATION NO. 3 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L1030228 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25.115 OVERHAUL									
25-64-17-350-803-04	RESTORATION NO. 4 PASSENGER LIFE VEST (OVERHAUL OR DISCARD) 63600-105 L1030225 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25.115 OVERHAUL									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-05	RESTORATION NO. 5 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.120 OVERHAUL	63600-105 L1030215 REF:	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	13-AUG-2018 M	01-DEC-2018
25-64-17-350-803-06	RESTORATION NO. 6 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.120 OVERHAUL	63600-105 L1030224 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25-64-17-350-803-07	RESTORATION NO. 7 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.125 OVERHAUL	63600-105 L1030222 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25-64-17-350-803-08	RESTORATION NO. 8 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.125 OVERHAUL	63600-105 L103020 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25-64-17-350-803-09	RESTORATION NO. 9 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.130 OVERHAUL	63600-105 L1030226 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028
25-64-17-350-803-10	RESTORATION NO. 10 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.130 OVERHAUL	63600-105 L1030225 REF:	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	13-AUG-2018 M	01-DEC-2018
25-64-17-350-803-11	RESTORATION NO. 11 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.135 OVERHAUL	63600-105 L1030214 REF:	MOS HRS/MSC AFL	120	+3%			01-JUN-2018 9855:36 5896	01-JUN-2028	19-SEP-2028

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-12	RESTORATION NO. 12 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.135 OVERHAUL	63600-105 L1030220 REF:	MOS HRS/MSC AFL	120	+3%			16-FEB-2010 8327:15 5249	16-FEB-2020	03-JUN-2020
25-64-17-350-803-13	RESTORATION NO. 13 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.140	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-803-14	RESTORATION NO. 14 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.140	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-803-15	RESTORATION NO. 15 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.145	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-803-16	RESTORATION NO. 16 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.145	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-803-17	RESTORATION NO. 17 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.150	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-803-18	RESTORATION NO. 18 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.150	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-350-803-19	RESTORATION NO. 19 PASSENGER LIFE VEST (OVERHAUL OR DISCARD)								
25.155	PN NOT INSTALLED REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
25-64-17-350-804-01S	RESTORATION NO. 1 INFANT LIFE VEST								
	PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
25-64-17-900-802-01	PILOT LIFE VEST								
25.100	P01074-101C 170117000010 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			21-JUN-2017 9849:54 5894		
25-64-17-900-802-02	COPILOT LIFE VEST								
25.100	63600-505 L1080507 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:62 TSN:1433:15 TSN:583			20-APR-2015 9760:30 5832		
25-64-17-900-802-03	THIRD CREW MEMBER LIFE VEST								
25.105	63600-505 L1080508 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2010 8327:15 5249		
25-64-17-900-803-01	NO. 1 PASSENGER LIFE VEST								
25.110	63600-105 L1030223 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2010 8327:15 5249		
25-64-17-900-803-02	NO. 2 PASSENGER LIFE VEST								
25.110	63600-105 L1030221 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-03	NO. 3 PASSENGER LIFE VEST 63600-105 L1030228 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-04	NO. 4 PASSENGER LIFE VEST 63600-105 L1030225 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-05	NO. 5 PASSENGER LIFE VEST 63600-105 L1030215 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2010 8327:15 5249		
25-64-17-900-803-06	NO. 6 PASSENGER LIFE VEST 63600-105 L1030224 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-07	NO. 7 PASSENGER LIFE VEST 63600-105 L1030222 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-08	NO. 8 PASSENGER LIFE VEST 63600-105 L103020 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-09	NO. 9 PASSENGER LIFE VEST 63600-105 L1030226 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-10	NO. 10 PASSENGER LIFE VEST								
25.130	63600-105 L1030225 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2010 8327:15 5249		
25-64-17-900-803-11	NO. 11 PASSENGER LIFE VEST								
25.135	63600-105 L1030214 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-JUN-2018 9855:36 5896		
25-64-17-900-803-12	NO. 12 PASSENGER LIFE VEST								
25.135	63600-105 L1030220 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-FEB-2010 8327:15 5249		
25-64-17-900-803-13	NO. 13 PASSENGER LIFE VEST								
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-803-14	NO. 14 PASSENGER LIFE VEST								
25.140	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-803-15	NO. 15 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-803-16	NO. 16 PASSENGER LIFE VEST								
25.145	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-64-17-900-803-17	NO. 17 PASSENGER LIFE VEST								
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-803-18	NO. 18 PASSENGER LIFE VEST								
25.150	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-803-19	NO. 19 PASSENGER LIFE VEST								
25.155	PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
25-64-17-900-804-01	NO. 1 INFANT LIFE VEST								
	PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
25-90-01-900-801-03	THIRD CREW MEMBER SEAT								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
25-90-18-900-801-01	ESPRESSO MAKER								
	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-90-19-900-801-01	MICROWAVE OVEN PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
25-90-45-350-801-01S	RESTORATION PILOT FLASHLIGHT BATTERIES (MAGLITE ONLY) PN SN-UNKNOWN REF: SMM 25-90-45	MOS HRS/MSC AFL	N/A						
25-90-45-350-801-02S	RESTORATION COPILOT FLASHLIGHT BATTERIES (MAGLITE ONLY) PN SN-UNKNOWN REF: SMM 25-90-45	MOS HRS/MSC AFL	N/A						
+ 25-90-53-220-801-01S	DETAILED INSPECTION OF THE PILOT FLASHLIGHT (AIR LITE ONLY) REF: SMM 25-90-53	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
+ 25-90-53-220-801-02S	DETAILED INSPECTION OF THE COPILOT FLASHLIGHT (AIR LITE ONLY) REF: SMM 25-90-53	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
251811 25.020	PILOT SEAT ACTUATOR 8260 788 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
251816 25.020	COPILOT SEAT ACTUATOR 8260 908 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251821	PILOT SEAT BELT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
251826	COPILOT SEAT BELT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
251831	PILOT SEAT HARNESS								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
251836	COPILOT SEAT HARNESS								
25.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
256A01	REPLACE NO. 1 LIFE RAFT ELT BATTERY								
SCRAP	1015FAUL-290-1-102 10UL-00188 REF:	MOS HRS/MSC AFL	DUE				26-AUG-2016 9847:51 5893	30-NOV-2019 M	
256A02	REPLACE NO. 2 LIFE RAFT ELT BATTERY								
SCRAP	1015FAUL-290-1-102 10UL-00189 REF:	MOS HRS/MSC AFL	DUE				26-AUG-2016 9847:51 5893	30-NOV-2019 M	
256A54	FIRST AID KIT								
	AFAK 1.0 012314008 REF:	MOS HRS/MSC AFL	O/C				20-JUN-2017 9849:54 5894		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256A56	INSPECT FIRST AID KIT AFAK 1.0 012314008 REF:	MOS HRS/MSC AFL	12				20-JUN-2017 9849:54 5894	30-JUN-2018 M	
33-50-05-350-801-01	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019
OVERHAUL									
33-50-05-350-801-02	RESTORATION OF THE DME EF-2C RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12	+3%			01-JUN-2018 9855:36 5896	01-JUN-2019	11-JUN-2019
OVERHAUL									
33-50-05-350-802-01	RESTORATION OF THE MAGLITE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A						
33-50-05-350-802-02	RESTORATION OF THE MAGLITE RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A						
33-50-05-350-803-01	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
33-50-05-350-803-02	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT) PN SN-UNKNOWN REF: AMM 33-50-05-350-803	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-05-960-801-01	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - LH FLASHLIGHT BATTERY (9610ME) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
33-50-05-960-801-02	DISCARD OF THE RECHARGEABLE FLASHLIGHT BATTERY - RH FLASHLIGHT BATTERY (9620ME) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
CHAPTER 26 FIRE PROTECTION									
+ 26-10-00-720-801-01	FUNCTIONAL TEST NO. 1 ENGINE FIRE DETECTOR 36017090040013 103719 REF: See Workcard	MOS HRS/MSC AFL	7500/E/C	+3%			07-NOV-2017 9850:07 5894	17350:07	17575:07
+ 26-10-00-720-801-02	FUNCTIONAL TEST NO. 2 ENGINE FIRE DETECTOR 360113190040017 221719 REF: See Workcard	MOS HRS/MSC AFL	7500/E/C	+3%			07-NOV-2017 9850:07 5894	17350:07	17575:07
+ 26-10-00-720-801-03	FUNCTIONAL TEST NO. 3 ENGINE FIRE DETECTOR 36017090040013 103720 REF: See Workcard	MOS HRS/MSC AFL	7500/E/C	+3%			16-APR-2008 7501 4649	15001	15226
+ 26-10-00-720-801-04	FUNCTIONAL TEST APU FIRE DETECTOR 36018190040009 92621 REF: See Workcard	MOS HRS/MSC AFL APH	E/C	5000	+3%		26-JAN-2012 8911:19 5476 2460:06	7460:06	7610:06
26-10-00-720-801-05	FUNCTIONAL TEST REAR COMPARTMENT FIRE DETECTOR FAL1786076 NOT INST. REF: See Workcard	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-10-00-720-802-01 (s)	FUNCTIONAL TEST OF THE LEFT MAIN LANDING GEAR PIN POINT FIRE DETECTOR						PKG		
26.050	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 26-10-00-720-802-02 (s)	FUNCTIONAL TEST OF THE RIGHT MAIN LANDING GEAR PIN POINT FIRE DETECTOR						PKG		
26.050	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 26-10-00-720-802-03 (s)	FUNCTIONAL TEST OF THE NO. 1 REAR (MECHANIC'S SERVICING) COMPARTMENT PIN POINT FIRE DETECTOR						PKG		
26.090	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 26-10-00-720-802-04 (s)	FUNCTIONAL TEST OF THE NO. 2 REAR (MECHANIC'S SERVICING) COMPARTMENT PIN POINT FIRE DETECTOR						PKG		
26.090	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
26-10-13-900-801-01	NO. 1 REAR (MECHANIC'S SERVICING) COMPARTMENT PIN POINT FIRE DETECTOR								
26.090	B200 711 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
26-10-13-900-801-02	NO. 2 REAR (MECHANIC'S SERVICING) COMPARTMENT PIN POINT FIRE DETECTOR								
26.090	B200 710 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
26-10-17-900-801-01	LEFT MAIN LANDING GEAR PIN POINT FIRE DETECTOR								
26.050	B160 141 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-SEP-2000 108 83		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-10-17-900-801-02	RIGHT MAIN LANDING GEAR PIN POINT FIRE DETECTOR								
26.050	B160 4789 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
26-10-19-900-801-01	NO. 1 ENGINE FIRE DETECTOR								
26.010	36017090040013 103719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2008 7501 4649		
26-10-19-900-801-02	NO. 2 ENGINE FIRE DETECTOR								
26.020	360113190040017 221719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
26-10-19-900-801-03	NO. 3 ENGINE FIRE DETECTOR								
26.010	36017090040013 103720 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2008 7501 4649		
26-10-19-900-801-04	APU FIRE DETECTOR								
26.030	36018190040009 92621 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
26-20-00-760-801-01	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (R5WB), (R6WB), (8WB) AND (22WB)								
26.240	REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JAN-2012 8911:19 5476		
26-20-00-760-801-02	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (R3WB) AND (R4WB)								
26.240	REF: See Workcard	MOS HRS/MSC AFL	O/C				12-SEP-2011 8792:13		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-00-760-801-03	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (L5WB) AND (L6WB)	MOS					13-SEP-2011		
26.240	REF: See Workcard	HRS/MSC AFL	O/C				8792:22		
26-20-00-760-801-04	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (L3WB) AND (L4WB)	MOS					13-SEP-2011		
26.240	REF: See Workcard	HRS/MSC AFL	O/C				8792:22		
26-20-00-760-801-05	INSULATION TEST OF EXTINGUISHER PERCUSSION CIRCUITS OF PERCUSSION CARTRIDGES (9WB)	MOS					13-SEP-2011		
26.240	REF: See Workcard	HRS/MSC AFL	O/C				8792:22		
+ 26-20-01-760-801-01 (s)	CHECK OF THE CORRECT OPERATION OF NO.1 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "1") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-02 (s)	CHECK OF THE CORRECT OPERATION OF NO.1 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "2") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-03 (s)	CHECK OF THE CORRECT OPERATION OF NO.2 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "1") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-01-760-801-04 (s)	CHECK OF THE CORRECT OPERATION OF NO.2 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "2") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-05 (s)	CHECK OF THE CORRECT OPERATION OF NO.3 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "1") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-06 (s)	CHECK OF THE CORRECT OPERATION OF NO.3 ENGINE FIRE EXTINGUISHER "DISCH" (POSITION "2") CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-07 (s)	CHECK OF THE CORRECT OPERATION OF "FIRE APU" FIRE EXTINGUISHER CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-08 (s)	CHECK OF THE CORRECT OPERATION OF "FIRE BAG COMP" FIRE EXTINGUISHER CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 26-20-01-760-801-09 (s)	CHECK OF THE CORRECT OPERATION OF "FIRE REAR COMP" FIRE EXTINGUISHER CONTROL SWITCH						PKG		
26.100	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-220-801-01	WEIGHT CHECK 504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER								
26.110	861630 54752 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
+ 26-20-09-220-801-02	WEIGHT CHECK 505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.120	861630 56866 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
+ 26-20-09-220-801-03	WEIGHT CHECK 506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER								
26.130	861630 22635 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
+ 26-20-09-220-801-04	WEIGHT CHECK 508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.140	861630 55877 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
+ 26-20-09-220-801-05	WEIGHT CHECK 507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER								
26.150	861630 57255 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
+ 26-20-09-220-801-06	WEIGHT CHECK 503WB MECHANIC'S SERVICING COMPARTMENT (MSC) FIRE EXTINGUISHER								
26.160	863470-01 UE002828 REF: See Workcard	MOS HRS/MSC AFL	18	+3%			01-JUN-2018	01-DEC-2019	17-DEC-2019
+ 26-20-09-350-801-01	RESTORATION 504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.110 MANDATORY	861630 54752 REF: See Workcard	MOS HRS/MSC AFL	60				21-JUN-2017	21-JUN-2022	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-09-350-801-02	RESTORATION 505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.120	861630	MOS	60				21-JUN-2017	21-JUN-2022	
MANDATORY	56866 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-03	RESTORATION 506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.130	861630	MOS	60				21-JUN-2017	21-JUN-2022	
MANDATORY	22635 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-04	RESTORATION 508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.140	861630	MOS	60				21-JUN-2017	21-JUN-2022	
MANDATORY	55877 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-05	RESTORATION 507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.150	861630	MOS	60				21-JUN-2017	21-JUN-2022	
MANDATORY	57255 REF: See Workcard	HRS/MSC AFL							
+ 26-20-09-350-801-06	RESTORATION 503WB MECHANIC'S SERVICING COMPARTMENT (MSC) FIRE EXTINGUISHER (HYDROSTATIC TEST AND PRESSURE GAGE CALIBRATION)								
26.160	863470-01	MOS	120				01-OCT-2014	01-OCT-2024	
MANDATORY	UE002828 REF: See Workcard	HRS/MSC AFL							
26-20-09-900-801-01	504WB APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER								
26.110	861630	MOS		TSO:0			21-JUN-2017		
	54752	HRS/MSC	O/C	TSO:0			9849:54		
	REF: See Workcard	AFL		TSO:0			5894		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-09-900-801-02	505WB ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.120	861630 56866 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JUN-2017 9849:54 5894		
26-20-09-900-801-03	506WB ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER								
26.130	861630 22635 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JUN-2017 9849:54 5894		
26-20-09-900-801-04	508WB ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER								
26.140	861630 55877 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JUN-2017 9849:54 5894		
26-20-09-900-801-05	507WB ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER								
26.150	861630 57255 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JUN-2017 9849:54 5894		
26-20-09-900-801-06	503WB MECHANIC'S SERVICING COMPARTMENT (MSC) FIRE EXTINGUISHER								
26.160	863470-01 UE002828 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:18 TSN:125:32 TSN:76			24-AUG-2016 9847:51 5893		
+ 26-20-11-700-801-01 (s)	CHECKING APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
+ 26-20-11-700-801-02 (s)	CHECKING ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-11-700-801-03 (s)	CHECKING ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 26-20-11-700-801-04 (s)	CHECKING ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 26-20-11-700-801-05 (s)	CHECKING ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHING LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 26-20-11-700-801-06 (s)	CHECKING MSC EXTINGUISHER LINES FOR CLOGGING						PKG		
26.230	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
26-20-12-900-801-01	NO. 1 ENGINE EXTINGUISHER SHUTTLE VALVE								
26.200	861585 3695 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		10-DEC-2004 4655:24 2891		
26-20-12-900-801-02	NO. 3 ENGINE EXTINGUISHER SHUTTLE VALVE								
26.200	861585 5893 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		14-JUL-2012 9012:54 5520		
26-20-12-900-801-03	NO. 2 ENGINE EXTINGUISHER LEFT SHUTTLE VALVE								
26.210	861585 4558 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		TSN:0 TSN:0 TSN:0		10-DEC-2004 4655:24 2891		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-12-900-801-04	NO. 2 ENGINE EXTINGUISHER RIGHT SHUTTLE VALVE								
26.210	861585 3693 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			10-DEC-2004 4655:24 2891		
26-20-12-960-801-01	DISCARD NO. 1 ENGINE EXTINGUISHER SHUTTLE VALVE								
26.250 REPLACE	861585 3695 REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
26-20-12-960-801-02	DISCARD NO. 3 ENGINE EXTINGUISHER SHUTTLE VALVE								
26.250 REPLACE	861585 5893 REF: See Workcard	MOS HRS/MSC AFL	A/R				14-JUL-2012 9012:54 5520		
26-20-12-960-801-03	DISCARD NO. 2 ENGINE EXTINGUISHER LEFT SHUTTLE VALVE								
26.250 REPLACE	861585 4558 REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
26-20-12-960-801-04	DISCARD NO. 2 ENGINE EXTINGUISHER RIGHT SHUTTLE VALVE								
26.250 REPLACE	861585 3693 REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
26-20-13-900-802-01	ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE								
26.260	862710-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:9 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-02	ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE								
26.260	862710-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			14-JUL-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-802-03	ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE								
26.260	862700-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:10 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-04	ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE								
26.260	862700-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:10 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-05	ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE								
26.260	862710-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:9 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-06	ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE								
26.260	862710-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:9 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-07	ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE								
26.260	862710-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:7 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-802-08	ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE								
26.260	862700-00 N/A REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:7 TSN:0 TSN:0			29-APR-2016 9805:22 5878		
26-20-13-900-803-01	APU PERCUSSION RED (22WB) CARTRIDGE								
26.270	862710-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:7 TSN:0 TSN:0			03-JAN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-900-803-02	BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE								
26.270	862700-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:6 TSN:0 TSN:0			06-FEB-2017 9847:51 5893		
26-20-13-900-803-03	MSC PERCUSSION CARTRIDGE								
26.270	862700-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:5 TSN:0 TSN:0			23-FEB-2015 9722:19 5817		
26-20-13-960-801-01	DISCARD ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE (SERVICE LIFE)								
26.120 SCRAP	862710-00 N/A REF:	MOS HRS/MSC AFL	120				29-APR-2016	29-APR-2026	
26-20-13-960-801-01M	DISCARD ENGINE 1 FIRST-SHOOT PERCUSSION GREEN (L3WB) CARTRIDGE (LIFE LIMIT)								
26.120 LIFE LIMIT	862710-00 N/A REF:	MOS HRS/MSC AFL	144				07-JUL-2015	07-JUL-2027	
26-20-13-960-801-02	DISCARD ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE (SERVICE LIFE)								
26.140 SCRAP	862710-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				14-JUL-2012	14-JUL-2022	
26-20-13-960-801-02M	DISCARD ENGINE 3 FIRST-SHOOT PERCUSSION GREEN (R3WB) CARTRIDGE (LIFE LIMIT)								
26.140 LIFE LIMIT	862710-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				01-NOV-2011	01-NOV-2023	
26-20-13-960-801-03	DISCARD ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE (SERVICE LIFE)								
26.120 SCRAP	862700-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				29-APR-2016	29-APR-2026	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-03M 26.120 LIFE LIMIT	DISCARD ENGINE 2 SECOND-SHOOT LH PERCUSSION RED (L4WB) CARTRIDGE (LIFE LIMIT) 862700-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				30-JUN-2015	30-JUN-2027	
26-20-13-960-801-04 26.140 SCRAP	DISCARD ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE (SERVICE LIFE) 862700-00 N/A REF:	MOS HRS/MSC AFL	120				29-APR-2016	29-APR-2026	
26-20-13-960-801-04M 26.140 LIFE LIMIT	DISCARD ENGINE 2 SECOND-SHOOT RH PERCUSSION RED (R4WB) CARTRIDGE (LIFE LIMIT) 862700-00 N/A REF:	MOS HRS/MSC AFL	144				30-JUN-2015	30-JUN-2027	
26-20-13-960-801-05 26.130 SCRAP	DISCARD ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE (SERVICE LIFE) 862710-00 N/A REF:	MOS HRS/MSC AFL	120				29-APR-2016	29-APR-2026	
26-20-13-960-801-05M 26.130 LIFE LIMIT	DISCARD ENGINE 1 SECOND-SHOOT PERCUSSION GREEN (L5WB) CARTRIDGE (LIFE LIMIT) 862710-00 N/A REF:	MOS HRS/MSC AFL	144				07-JUL-2015	07-JUL-2027	
26-20-13-960-801-06 26.150 SCRAP	DISCARD ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE (SERVICE LIFE) 862710-00 N/A REF:	MOS HRS/MSC AFL	120				29-APR-2016	29-APR-2026	
26-20-13-960-801-06M 26.150 LIFE LIMIT	DISCARD ENGINE 3 SECOND-SHOOT PERCUSSION GREEN (R5WB) CARTRIDGE (LIFE LIMIT) 862710-00 N/A REF:	MOS HRS/MSC AFL	144				07-JUL-2015	07-JUL-2027	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-07	DISCARD ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE (SERVICE LIFE)								
26.130	862710-00	MOS	120				29-APR-2016	29-APR-2026	
SCRAP	N/A	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-07M	DISCARD ENGINE 2 FIRST-SHOOT LH PERCUSSION RED (L6WB) CARTRIDGE (LIFE LIMIT)								
26.130	862710-00	MOS	144				09-SEP-2015	09-SEP-2027	
LIFE LIMIT	N/A	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-08	DISCARD ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE (SERVICE LIFE)								
26.150	862700-00	MOS	120				29-APR-2016	29-APR-2026	
SCRAP	N/A	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-08M	DISCARD ENGINE 2 FIRST-SHOOT RH PERCUSSION RED (R6WB) CARTRIDGE (LIFE LIMIT)								
26.150	862700-00	MOS	144				09-SEP-2015	09-SEP-2027	
LIFE LIMIT	N/A	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-09	DISCARD APU PERCUSSION RED (22WB) CARTRIDGE (SERVICE LIFE)								
26.110	862710-00	MOS	120				03-JAN-2014	03-JAN-2024	
SCRAP	SN-UNKNOWN	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-09M	DISCARD APU PERCUSSION RED (22WB) CARTRIDGE (LIFE LIMIT)								
26.110	862710-00	MOS	144				01-JUN-2013	01-JUN-2025	
LIFE LIMIT	SN-UNKNOWN	HRS/MSC							
	REF:	AFL							
26-20-13-960-801-10	DISCARD BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (SERVICE LIFE)								
26.110	862700-00	MOS	120				06-FEB-2017	06-FEB-2027	
SCRAP	SN-UNKNOWN	HRS/MSC							
	REF:	AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-13-960-801-10M	DISCARD BAGGAGE COMPARTMENT PERCUSSION CARTRIDGE (LIFE LIMIT)								
26.110	862700-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				24-AUG-2016	24-AUG-2028	
LIFE LIMIT									
26-20-13-960-801-11	DISCARD MSC PERCUSSION CARTRIDGE (SERVICE LIFE)								
26.160	862700-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120				23-FEB-2015	23-FEB-2025	
SCRAP									
26-20-13-960-801-11M	DISCARD MSC PERCUSSION CARTRIDGE (LIFE LIMIT)								
26.160	862700-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	144				01-AUG-2014	01-AUG-2026	
LIFE LIMIT									
+ 26-20-15-720-801-01	WEIGHING COCKPIT PORTABLE EXTINGUISHER								
26.190	898052 B71138928 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			24-OCT-2017	24-OCT-2019	15-NOV-2019
+ 26-20-15-720-801-02	WEIGHING FORWARD CABIN PORTABLE EXTINGUISHER								
26.170	898052 B71138929 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			24-OCT-2017	24-OCT-2019	15-NOV-2019
+ 26-20-15-720-801-03	WEIGHING REAR CABIN PORTABLE EXTINGUISHER								
26.180	898052 B71138930 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			24-OCT-2017	24-OCT-2019	15-NOV-2019
+ 26-20-15-790-801-01	HYDROSTATIC TEST COCKPIT PORTABLE EXTINGUISHER								
26.190	898052 B71138928 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			01-JAN-2016	01-JAN-2028	10-MAY-2028

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-20-15-790-801-02	HYDROSTATIC TEST FORWARD CABIN PORTABLE EXTINGUISHER								
26.170	898052 B71138929 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			01-JAN-2016	01-JAN-2028	10-MAY-2028
+ 26-20-15-790-801-03	HYDROSTATIC TEST REAR CABIN PORTABLE EXTINGUISHER								
26.180	898052 B71138930 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			01-JAN-2016	01-JAN-2028	10-MAY-2028
26-20-15-900-801-01	COCKPIT PORTABLE EXTINGUISHER								
26.190	898052 B71138928 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		29-APR-2016 9805:22 5878		
26-20-15-900-801-02	FORWARD CABIN PORTABLE EXTINGUISHER								
26.170	898052 B71138929 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		29-APR-2016 9805:22 5878		
26-20-15-900-801-03	REAR CABIN PORTABLE EXTINGUISHER								
26.180	898052 B71138930 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		29-APR-2016 9805:22 5878		
26-20-15-900-801-04	BAGGAGE COMPARTMENT PORTABLE FIRE EXTINGUISHER								
	PN NOT INSTALLED REF:	MOS HRS/MSC AFL APH	O/C		TSN:0 TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0 0		
26-20-19-720-801-01	WEIGHING DISPOSABLE FIRE EXTINGUISHER								
	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-39-790-801-01S	HYDROSTATIC TEST PORTABLE (9LB) FIRE EXTINGUISHER PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
26-21-39-900-801-01	PORTABLE (9LB) FIRE EXTINGUISHER PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
26-90-01-900-801-01	DISPOSABLE FIRE EXTINGUISHER PN NOT INSTALLED REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
261005 26.220	REAR COMPARTMENT FIRE DETECTOR FAL1786076 NOT INST. REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
261021 26.040	BAGGAGE COMPARTMENT SMOKE DETECTOR FR2220 FW654 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:15 TSR:0 TSR:0			01-AUG-2013 9343:24 5658		
261816 26.060	NO.1 AND NO.3 ENGINE FIRE MONITOR BOX 6342-01 868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
261821 26.070	NO.2 AND APU ENGINE FIRE MONITOR BOX 6342-01 871 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261826	EXTINGUISHING FIRE PANEL								
26.080	121TS09Y2 105 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			06-DEC-2002 2463:06 1531		
CHAPTER 27 FLIGHT CONTROLS									
+ 27-00-00-220-801-01A	VISUAL INSPECTION OF FLIGHT CONTROL HYDRAULIC COMPONENTS (MANDATORY REF 5-40-20)								
27.025 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	4000				12-NOV-2008 7993:06 5030	11993:06	
27-00-00-640-801-01 (s)	PRESSURE GREASING OF LEFT AILERON SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 14-JUL-2012 9012:54 5520		
+ 27-00-00-640-801-02 (s)	PRESSURE GREASING OF RIGHT AILERON SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 14-JUL-2012 9012:54 5520		
27-00-00-640-801-03 (s)	PRESSURE GREASING RUDDER SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 15-JUL-2012 9012:54 5520		
27-00-00-640-801-04 (s)	PRESSURE GREASING ELEVATOR SERVO-ACTUATOR BEARINGS								
27.030	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 15-JUL-2012 9012:54 5520		
27-00-00-640-802-01 (s)	PRESSURE GREASING/LUBRICATION PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN PRESSURIZED AREA								
27.035	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 25-SEP-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-640-802-02 (s)	PRESSURE GREASING/LUBRICATION OF FLIGHT CONTROL BEARINGS AND HINGE PINS IN NON PRESSURIZED AREA						PKG		
27.035	PKG 32	MOS	144	+2m			25-SEP-2012		
	REF: See Workcard	HRS/MSC AFL	7500				9012:54 5520		
+ 27-00-00-640-805-01 (s)	REMOVAL/INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - ROLL PRESSURE SEALED BOX						PKG		
27.050	PKG 32	MOS	144	+2m			25-JUL-2012		
	REF: See Workcard	HRS/MSC AFL	7500				9012:54 5520		
+ 27-00-00-640-805-02 (s)	REMOVAL/INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - YAW PRESSURE SEALED BOX						PKG		
27.050	PKG 32	MOS	144	+2m			25-JUL-2012		
	REF: See Workcard	HRS/MSC AFL	7500				9012:54 5520		
+ 27-00-00-640-805-03 (s)	REMOVAL/INSTALLATION OF THE FLIGHT CONTROL SEALED BOXES FOR VISUAL INSPECTION AND GREASING OF BEARINGS - PITCH PRESSURE SEALED BOX						PKG		
27.050	PKG 32	MOS	144	+2m			25-JUL-2012		
	REF: See Workcard	HRS/MSC AFL	7500				9012:54 5520		
+ 27-00-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO.1 SYSTEM FLIGHT CONTROLS						PKG		
27.010	PKG 21	MOS	1600	+40			06-FEB-2017		
	REF: See Workcard	HRS/MSC AFL					9847:51 5893		
+ 27-00-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO.2 SYSTEM FLIGHT CONTROLS						PKG		
27.010	PKG 21	MOS	1600	+40			06-FEB-2017		
	REF: See Workcard	HRS/MSC AFL					9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-710-802-01 (s)	OPERATIONAL TEST OF AILERON TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
+ 27-00-00-710-802-02 (s)	OPERATIONAL TEST OF EMERGENCY AILERON TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
+ 27-00-00-710-802-03 (s)	OPERATIONAL TEST OF RUDDER TRIM SYSTEM						PKG		
27.015	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
+ 27-00-00-720-804-01 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU						PKG		
27.045	PKG 32	MOS	144	+2m			02-JUL-2012		
	REF:	HRS/MSC					9012:54		
		AFL	7500				5520		
+ 27-00-00-720-804-01A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF LH ROLL AAFU (MANDATORY REF. 5-40-20)								
27.045		MOS					02-JUL-2012		
CMR	REF:	HRS/MSC	10000				9012:54		19012:54
		AFL					5520		
27-00-00-720-804-02 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF LH ROLL AAFU						PKG		
	PKG 32	MOS	144				02-JUL-2012		
	REF:	HRS/MSC					9012:54		
		AFL	7500				5520		
27-00-00-720-804-02A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF LH ROLL AAFU (MANDATORY REF. 5-40-20)								
		MOS					02-JUL-2012		
CMR	REF:	HRS/MSC	10000				9012:54		19012:54
		AFL					5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-804-03 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU PKG 32	MOS	144				PKG 02-JUL-2012 9012:54 5520		
	REF:	AFL	7500						
27-00-00-720-804-03A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF RH ROLL AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012 9012:54 5520		19012:54
CMR	REF:	HRS/MSC AFL	10000						
27-00-00-720-804-04 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF RH ROLL AAFU PKG 32	MOS	144				PKG 02-JUL-2012 9012:54 5520		
	REF:	AFL	7500						
27-00-00-720-804-04A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF RH ROLL AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012 9012:54 5520		19012:54
CMR	REF:	HRS/MSC AFL	10000						
+ 27-00-00-720-804-05 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF YAW AAFU PKG 32	MOS	144	+2m			PKG 02-JUL-2012 9012:54 5520		
27.045	REF:	AFL	7500						
+ 27-00-00-720-804-05A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF YAW AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012 9012:54 5520		19012:54
27.045	REF:	HRS/MSC AFL	10000						
CMR									
27-00-00-720-804-06 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF YAW AAFU PKG 32	MOS	144				PKG 02-JUL-2012 9012:54 5520		
	REF:	AFL	7500						

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-720-804-06A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF YAW AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012		
CMR	REF:	HRS/MSC AFL	10000				9012:54 5520	19012:54	
+ 27-00-00-720-804-07 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF PITCH AAFU	MOS	144	+2m			PKG		
27.045	PKG 32	HRS/MSC AFL	7500				02-JUL-2012 9012:54 5520		
CMR	REF:								
+ 27-00-00-720-804-07A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - INSPECTION OF PITCH AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012		
27.045		HRS/MSC AFL	10000				9012:54 5520	19012:54	
CMR	REF:								
27-00-00-720-804-08 (s)	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF PITCH AAFU	MOS	144				PKG		
	PKG 32	HRS/MSC AFL	7500				02-JUL-2012 9012:54 5520		
CMR	REF:								
27-00-00-720-804-08A	CHECK OF THE AUXILIARY AFU NON-DISCONNECTION - FUNCTIONAL TEST OF PITCH AAFU (MANDATORY REF. 5-40-20)	MOS					02-JUL-2012		
CMR	REF:	HRS/MSC AFL	10000				9012:54 5520	19012:54	
+ 27-00-00-790-804-01 (s)	CHECK OF THE INTERNAL LEAKS OF LEFT AILERON SERVO-ACTUATORS	MOS	72	+2m			PKG		
27.040	PKG 31	HRS/MSC AFL	3750				01-JUN-2018 9855:36 5896		
CMR	REF: See Workcard								
+ 27-00-00-790-804-02 (s)	CHECK OF THE INTERNAL LEAKS OF RIGHT AILERON SERVO-ACTUATORS	MOS	72	+2m			PKG		
27.040	PKG 31	HRS/MSC AFL	3750				01-JUN-2018 9855:36 5896		
CMR	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-00-00-790-804-03 (s)	CHECK OF THE INTERNAL LEAKS OF RUDDER SERVO-ACTUATORS						PKG		
27.040	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
+ 27-00-00-790-804-04 (s)	CHECK OF THE INTERNAL LEAKS OF ELEVATOR SERVO-ACTUATORS						PKG		
27.040	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
27-12-01-900-801-01	LEFT AILERON SERVO ACTUATOR								
27.145	103117-05 1533 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:4 TSR:0 TSR:0		14-AUG-2012 9012:54 5520		
27-12-01-900-801-02	RIGHT AILERON SERVO ACTUATOR								
27.145	103117-06 1225 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
27-13-01-640-805-01 (s)	LUBRICATION OF THE ROLL PRESSURE-SEALED-BOX BELLCRANK OUTSIDE PRESSURIZED AREA						PKG		
27.320	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
27-13-01-640-806-01 (s)	LUBRICATION OF THE ROLL CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
27-13-01-640-807-01 (s)	GREASING OF THE ROLL CONTROL BALL BUSHINGS IN PRESSURIZED AREA						PKG		
27.100	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-13-01-640-808-01 (s)	GREASING OF THE ROLL CONTROL BALL BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.095	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
27-13-03-960-801-01 (s)	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - LH FR15 ROLL BELLCRANK (L930CC) BALL BEARINGS						PKG		
27.565	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
27-13-03-960-801-02 (s)	REPLACEMENT OF THE FR15 ROLL BELLCRANK BALL BEARINGS - RH FR15 ROLL BELLCRANK (R930CC) BALL BEARINGS						PKG		
27.565	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 27-14-01-350-801-01	RESTORATION AILERON TRIM ACTUATOR (FUNCTIONAL TEST)								
27.125	021057-37 8844 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			29-JUL-2012 9012:54 5520	29-JUL-2024	08-DEC-2024
27-14-01-900-801-01	AILERON TRIM ACTUATOR								
27.125	021057-37 8844 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSO:0 TSN:9012:32 TSO:0 TSO:0		29-JUL-2012 9012:54 5520		
+ 27-14-03-350-801-01	RESTORATION ROLL (AILERON) EMERGENCY TRIM ACTUATOR (FUNCTIONAL TEST)								
27.130	021127-01 680 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			27-JUL-2012 9012:54 5520	27-JUL-2024	06-DEC-2024
27-14-03-900-801-01	ROLL (AILERON) EMERGENCY TRIM ACTUATOR								
27.130	021127-01 680 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:9012:54		27-JUL-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-14-05-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAY BOX						PKG		
27.110	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			27-JUL-2012 9012:54 5520		
+ 27-14-05-720-801-01A	FUNCTIONAL TEST OF THE ROLL TRIM CONTROL SAFETY RELAY BOX (MANDATORY REF 5-40-20)								
27.110 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				27-JUL-2012 9012:54 5520	29012:54	
27-15-01-640-801-01 (s)	PRESSURE GREASE OF THE ROLL ARTHUR VARIABLE BELLCRANK BEARINGS						PKG		
27.105	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			28-SEP-2012 9012:54 5520		
+ 27-15-01-720-801-01 (s)	FUNCTIONAL TEST OF THE ROLL ARTHUR VARIABLE BELLCRANK						PKG		
27.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
27-15-01-900-801-01	ROLL (AILERON) ARTHUR VARIABLE BELLCRANK								
27.150	8421-5 314 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
27-15-03-960-801-01	REPLACEMENT OF THE SEALS ON THE SWIVEL COUPLING OF THE ROLL ARTHUR VARIABLE BELLCRANK								
	REF: AMM 27-15-03-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
+ 27-15-05-350-801-01	RESTORATION AILERON ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)								
27.135	105124 365 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			30-JUL-2012 9012:54 5520	30-JUL-2024	09-DEC-2024

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-15-05-900-801-01	AILERON ARTIFICIAL FEEL UNIT								
27.135	105124 365 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:32 TSR:0			30-JUL-2012 9012:54 5520		
27-15-07-640-801-01 (s)	PRESSURE GREASING OF THE LEFT ROLL AUXILIARY AFU BEARING						PKG		
27.115	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			28-SEP-2012 9012:54 5520		
+ 27-15-07-640-801-02 (s)	PRESSURE GREASING OF THE RIGHT ROLL AUXILIARY AFU BEARING						PKG		
27.115	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			28-SEP-2012 9012:54 5520		
+ 27-22-01-350-801-01	RESTORATION RUDDER SERVO ACTUATOR (FUNCTIONAL TEST)								
27.190	103103-18 1054 REF: See Workcard	MOS HRS/MSC AFL	4000				15-APR-2008 7501 4649	11501	
+ 27-22-01-350-801-01A	RESTORATION RUDDER SERVO ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40)								
27.190 MANDATORY 5-40	103103-18 1054 REF: See Workcard	MOS HRS/MSC AFL	4000				15-APR-2008 7501 4649	11501	
27-22-01-900-801-01	RUDDER SERVO ACTUATOR								
27.190	103103-18 1054 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-APR-2008 7501 4649		
27-23-01-640-806-01 (s)	LUBRICATION OF THE YAW CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.160	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-23-01-640-807-01 (s)	GREASING/LUBRICATION OF THE YAW CONTROL BALL BUSHINGS IN PRESSURIZED AREA						PKG		
27.165	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
27-23-01-640-808-01 (s)	GREASING OF THE YAW CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.160	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 27-24-01-350-801-01	RESTORATION YAW (RUDDER) TRIM ACTUATOR (FUNCTIONAL TEST)								
27.185	021057-36 9462 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			21-APR-2016	21-APR-2028	30-AUG-2028
27-24-01-900-801-01	YAW (RUDDER) TRIM ACTUATOR								
27.185	021057-36 9462 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSO:0 TSR:0 TSO:0 TSR:0 TSO:0 TSR:0	08-JAN-2017 9847:51 5893		
27-24-01-900-801-02	YAW (RUDDER) ARTIFICIAL FEEL UNIT								
27.175	105125 376 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSR:0 TSN:9012:54 TSR:0 TSR:0	03-AUG-2012 9012:54 5520		
+ 27-24-05-720-802-01 (s)	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS						PKG		
27.170	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			27-JUL-2012 9012:54 5520		
+ 27-24-05-720-802-01A	FUNCTIONAL TEST OF THE YAW TRIM CONTROL SAFETY RELAYS (MANDATORY REF 5-40-20)								
27.170 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	20000				27-JUL-2012 9012:54 5520	29012:54	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-25-05-350-801-01	RESTORATION YAW (RUDDER) ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)								
27.175	105125 376 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			03-AUG-2012 9012:54 5520	03-AUG-2024	12-DEC-2024
+ 27-25-07-350-801-01	RESTORATION RUDDER AUXILIARY ARTIFICIAL FEEL UNIT (FUNCTIONAL TEST / SERVICING)								
27.175	105070-04 1198 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			27-JUL-2012 9012:54 5520	27-JUL-2024	06-DEC-2024
27-25-07-900-801-01	RUDDER AUXILIARY ARTIFICIAL FEEL UNIT								
27.175	105070-04 1198 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:9012:54		27-JUL-2012 9012:54 5520		
27-31-01-640-801-01 (s)	GREASING OF THE PILOT CONTROL COLUMN (AND WHEEL)								
27.345	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 27-JUL-2012 9012:54 5520		
27-31-01-640-801-02 (s)	GREASING OF THE COPILOT CONTROL COLUMN (AND WHEEL)								
27.345	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 27-JUL-2012 9012:54 5520		
27-31-01-900-801-01	PILOT CONTROL COLUMN								
27.345	FGFB215001D1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
27-31-01-900-801-02	COPILOT CONTROL COLUMN								
27.345	FGFB215001D1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-32-01-350-801-01	RESTORATION ELEVATOR SERVO ACTUATOR (FUNCTIONAL TEST)								
27.235	103129 336 REF: See Workcard	MOS HRS/MSC AFL	10000	+3%	TSI:0		12-DEC-2014 9708:47 5806	16096:47	16396:47
+ 27-32-01-350-801-01A	RESTORATION ELEVATOR SERVO ACTUATOR (FUNCTIONAL TEST) (MANDATORY REF 5-40-20)								
27.235 MANDATORY 5-40	103129 336 REF: See Workcard	MOS HRS/MSC AFL	14000		TSI:0		12-DEC-2014 9708:47 5806	20096:47	
27-32-01-900-801-01	ELEVATOR SERVO ACTUATOR								
27.235	103129 336 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSN:3612 TSR:0 TSN:1674 TSR:0		12-DEC-2014 9708:47 5806		
27-33-01-640-806-01 (s)	LUBRICATION OF THE PITCH CONTROL LINKAGE HINGE PINS OUTSIDE PRESSURIZED AREA						PKG		
27.205	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
27-33-01-640-807-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS IN PRESSURIZED AREA						PKG		
27.195	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
27-33-01-640-808-01 (s)	GREASING OF THE PITCH CONTROL LINKAGE BALL-BUSHINGS OUTSIDE PRESSURIZED AREA						PKG		
27.200	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 27-35-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PITCH ARTHUR CONTROL SYSTEM						PKG		
27.225	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-01-640-801-01 (s)	PRESSURE GREASE OF THE PITCH (ELEVATOR) ARTHUR VARIABLE BELLCRANK BEARINGS						PKG		
27.215	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			09-APR-2013 9269:30 5625		
27-35-01-900-801-01	PITCH (ELEVATOR) ARTHUR VARIABLE BELLCRANK								
27.215	106126-01 118 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-APR-2013 9269:30 5625		
27-35-03-900-801-01	PITCH (ELEVATOR) ARTHUR VARIABLE BELLCRANK SWIVEL COUPLING SEALS								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-35-03-960-801-01	REPLACE PITCH (ELEVATOR) ARTHUR VARIABLE BELLCRANK SWIVEL COUPLING SEALS								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
+ 27-35-05-350-801-01	RESTORATION PITCH (ELEVATOR) ARTIFICIAL FEEL UNIT (FUNCTIONAL/TEST / SERVICING)								
27.230	105122-02 374 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			18-JUL-2012 9012:54 5520	18-JUL-2024	27-NOV-2024
27-35-07-350-801-01	RESTORATION PITCH (ELEVATOR) AUXILIARY ARTIFICIAL FEEL UNIT (DISCARD OF BUSHINGS 1050450002)								
27.240	105045-13 4314 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-35-07-350-801-01A	RESTORATION PITCH (ELEVATOR) AUXILIARY ARTIFICIAL FEEL UNIT (DISCARD OF BUSHINGS 1050450002)(MANDATORY REF 5-40)								
27.240 MANDATORY 5-40	105045-13 4314 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-07-640-801-01 (s)	PRESSURE GREASING OF THE PITCH AUXILIARY AFU BEARINGS						PKG		
27.220	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			20-JUL-2012 9012:54 5520		
27-35-07-900-801-01	PITCH (ELEVATOR) AUXILIARY ARTIFICIAL FEEL UNIT								
27.240	105045-13 4314 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 27-40-00-720-801-01 (s)	FUNCTIONAL TEST OF HORIZONTAL STABILIZER CONTROL AND INDICATING SYSTEM						PKG		
27.275	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 27-40-01-210-802-01 (s)	VISUAL CHECK HORIZONTAL STABILIZER ELECTRIC ACTUATOR						PKG		
27.285	021121-12 PKG 31 702 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+3% +3%			09-AUG-2012 9012:54 5520		
27-40-01-350-801-01 (s)	RESTORATION HORIZONTAL STABILIZER ELECTRIC ACTUATOR (FULL DISASSEMBLY, INSPECTION/CHECK AND NDT)						PKG		
27.285	021121-12 PKG 32 702 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+3% +3%			09-AUG-2012 9012:54 5520		
27-40-01-640-802-01 (s)	GREASING HORIZONTAL STABILIZER ACTUATOR HINGES AND JACK SCREW						PKG		
27.260	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896		
27-40-01-900-801-01	HORIZONTAL STABILIZER ELECTRIC ACTUATOR								
27.285	021121-12 702 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:9012:54			09-AUG-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-03-100-801-01	CHECK/CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER NORMAL ACTUATOR MOTOR								
27.290	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-40-03-100-801-02	CHECK/CLEANING OF THE ELECTROMAGNETIC BRAKE OF THE HORIZONTAL STABILIZER EMERGENCY ACTUATOR MOTOR								
27.290	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-40-05-900-801-01	HORIZONTAL STABILIZER POSITION REPEATER BOX								
27.300	016095-01 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 27-40-15-710-801-01 (s)	OPERATIONAL TEST OF THE HS EMERGENCY TRIM CONTROL RELAY								
27.295	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			PKG 24-SEP-2012 9012:54 5520		
+ 27-40-15-710-801-01A	OPERATIONAL TEST OF RELAY IN THE HS EMERGENCY TRIM CONTROL RELAY (MANDATORY REF 5-40-20)								
27.295 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	16000				24-SEP-2012 9012:54 5520	25012:54	
+ 27-40-17-720-801-01 (s)	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX								
27.280	PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4800	+40			PKG 03-JUN-2014 9560:43 5737		
+ 27-40-17-720-801-01A	FUNCTIONAL TEST OF THE HORIZONTAL STABILIZER RELAY BOX (MANDATORY REF 5-40-20)								
27.280 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	5000				03-JUN-2014 9560:43 5737	14560:43	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-00-640-801-01 (s)	GREASING/LUBRICATION OF FLAP MECHANISMS						PKG		
27.570	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
27-50-00-710-801-01	OPERATIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				03-JUN-2014 9560:43 5737		
+ 27-50-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FLAP CONTROL AND INDICATING SYSTEM						PKG		
27.335	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 27-50-00-720-802-01	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM								
27.330	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
+ 27-50-00-720-802-01A	FUNCTIONAL TEST OF THE FLAP ASYMMETRY DETECTION SYSTEM (MANDATORY 5-40)								
27.330 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	450				01-JUN-2018 9855:36 5896	10305:36	
+ 27-50-00-720-803-01 (s)	CHECK OF THE GEAR BACKLASH OF FLAP LINKAGE						PKG		
27.560	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
27-52-01-900-801-01	FLAP POWER DRIVE UNIT								
27.375	5-4440-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-52-13-200-801-01 (s)	CHECK/GREASING OF FLAP CONTROL ROD SPLINES - LH WING						PKG		
27.350	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
27-52-13-200-801-02 (s)	CHECK/GREASING OF FLAP CONTROL ROD SPLINES - RH WING						PKG		
	PKG 31	MOS	72				01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		
27-53-01-220-801-01	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH OUTBOARD FLAP SCREW JACK (L502CG)								
27.575		MOS	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		
27-53-01-220-801-02	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)								
27.575		MOS	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		
27-53-01-220-801-03	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - LH INBOARD FLAP CENTER SCREW JACK (L500CG)								
27.575		MOS	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		
27-53-01-220-801-04	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP CENTER SCREW JACK (R500CG)								
27.575		MOS	12	+1m			01-JUN-2018	01-JUN-2019	01-JUL-2019
	REF: See Workcard	HRS/MSC	400	+40			9855:36	10255:36	10295:36
		AFL					5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-220-801-05	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)								
27.575	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-220-801-06	CLEANING / CHECK OF THE FLAP SCREW JACK ACTUATING SCREW - RH OUTBOARD FLAP SCREW JACK (R502CG)								
27.575	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-350-801-01	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
27.360 OVERHAUL	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL		4500			14-FEB-2008 7330:24 4558	9058	
27-53-01-350-801-01A	RESTORATION LH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
MANDATORY 5-40	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL		4500			14-FEB-2008 7330:24 4558	9058	
27-53-01-350-801-02	RESTORATION LH INBOARD FLAP EXTERNAL SCREW JACK (OVERHAUL)								
27.365 OVERHAUL	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL		3500			26-AUG-2010 8508 5310	8810	
27-53-01-350-801-02A	RESTORATION LH INBOARD FLAP EXTERNAL SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL		3500			26-AUG-2010 8508 5310	8810	
27-53-01-350-801-03	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
27.370 OVERHAUL	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL		3500			14-JAN-2009 8092:48 5100	8600	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-801-03A	RESTORATION LH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					14-JAN-2009		
	305	HRS/MSC					8092:48		
MANDATORY 5-40	REF: See Workcard	AFL	3500				5100		8600
27-53-01-350-801-04	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL)								
	5318-3	MOS					03-FEB-2012		
27.371	840	HRS/MSC					8911:19		
OVERHAUL	REF: See Workcard	AFL	3500				5476		8976
27-53-01-350-801-04A	RESTORATION RH INBOARD FLAP CENTER SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					03-FEB-2012		
	840	HRS/MSC					8911:19		
MANDATORY 5-40	REF: See Workcard	AFL	3500				5476		8976
27-53-01-350-801-05	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL)								
	5318-3	MOS					26-AUG-2010		
27.366	1337	HRS/MSC					8508		
OVERHAUL	REF: See Workcard	AFL	3500				5310		8810
27-53-01-350-801-05A	RESTORATION RH INBOARD FLAP LATERAL SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	5318-3	MOS					26-AUG-2010		
	1337	HRS/MSC					8508		
MANDATORY 5-40	REF: See Workcard	AFL	3500				5310		8810
27-53-01-350-801-06	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL)								
	2-5319-3	MOS					14-FEB-2008		
27.361	165	HRS/MSC					7330:24		
OVERHAUL	REF: See Workcard	AFL	4500				4558		9058
27-53-01-350-801-06A	RESTORATION RH OUTBOARD FLAP SCREW JACK (OVERHAUL) (MANDATORY REF 5-40)								
	2-5319-3	MOS					14-FEB-2008		
	165	HRS/MSC					7330:24		
MANDATORY 5-40	REF: See Workcard	AFL	4500				4558		9058

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-802-01	UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY)								
27.360	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-01A	UPGRADE LH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-02	UPGRADE LH INBOARD FLAP EXTERNAL SCREW JACK (AVIAC ONLY)								
27.365	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-02A	UPGRADE LH INBOARD FLAP EXTERNAL SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-03	UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY)								
27.370	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-03A	UPGRADE LH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-350-802-04	UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY)								
27.371	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	N/A						
27-53-01-350-802-04A	UPGRADE RH INBOARD FLAP CENTER SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	N/A						
27-53-01-350-802-05	UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY)								
27.366	5318-3 1337 REF: See Workcard	MOS HRS/MSC AFL	N/A						
27-53-01-350-802-05A	UPGRADE RH INBOARD FLAP LATERAL SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 1337 REF: See Workcard	MOS HRS/MSC AFL	N/A						
27-53-01-350-802-06	UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY)								
27.361	2-5319-3 165 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-350-802-06A	UPGRADE RH OUTBOARD FLAP SCREW JACK (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	2-5319-3 165 REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
27-53-01-640-802-01	GREASING OF FLAP SCREW JACKS - LH OUTBOARD FLAP SCREW JACK (L502CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-640-802-02	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP LATERAL SCREW JACK (L501CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-640-802-03	GREASING OF FLAP SCREW JACKS - LH INBOARD FLAP CENTER SCREW JACK (L500CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-640-802-04	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP CENTER SCREW JACK (R500CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-640-802-05	GREASING OF FLAP SCREW JACKS - RH INBOARD FLAP LATERAL SCREW JACK (R501CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-640-802-06	GREASING OF FLAP SCREW JACKS - RH OUTBOARD FLAP SCREW JACK (R502CG)								
27.585	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
27-53-01-720-803-01	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
27.360	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL	3000				14-FEB-2008 7330:24 4558	7558	
27-53-01-720-803-01A	CHECK LH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)(MANDATORY REF 5-40)								
MANDATORY 5-40	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL	3000				14-FEB-2008 7330:24 4558	7558	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-720-803-02	CHECK LH INBOARD FLAP EXTERNAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
27.365	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL	450				29-APR-2016 9805:22 5878	10255:22	
27-53-01-720-803-02A	CHECK LH INBOARD FLAP EXTERNAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL	450				29-APR-2016 9805:22 5878	10255:22	
27-53-01-720-803-03	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
27.370	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL	450				29-APR-2016 9805:22 5878	10255:22	
27-53-01-720-803-03A	CHECK LH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL	450				29-APR-2016 9805:22 5878	10255:22	
27-53-01-720-803-04	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
27.371	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	450				01-FEB-2017 9847:51 5893	10297:51	
27-53-01-720-803-04A	CHECK RH INBOARD FLAP CENTER SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)								
MANDATORY 5-40	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	450				01-FEB-2017 9847:51 5893	10297:51	
27-53-01-720-803-05	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
27.366	5318-3 1337 REF: See Workcard	MOS HRS/MSC AFL	450				29-APR-2016 9805:22 5878	10255:22	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-720-803-05A	CHECK RH INBOARD FLAP LATERAL SCREW JACK SCREW/NUT PLAY (AVIAC ONLY) (MANDATORY REF 5-40)								
	5318-3	MOS					29-APR-2016		
	1337	HRS/MSC	450				9805:22		10255:22
MANDATORY 5-40	REF: See Workcard	AFL					5878		
27-53-01-720-803-06	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)								
	2-5319-3	MOS					14-FEB-2008		
27.361	165	HRS/MSC					7330:24		
	REF: See Workcard	AFL	3000				4558		7558
27-53-01-720-803-06A	CHECK RH OUTBOARD FLAP SCREW JACK SCREW/NUT PLAY (AVIAC ONLY)(MANDATORY REF 5-40)								
	2-5319-3	MOS					14-FEB-2008		
	165	HRS/MSC					7330:24		
MANDATORY 5-40	REF: See Workcard	AFL	3000				4558		7558
+ 27-53-01-720-804-01	CHECK OF THE LEFT OUTBOARD FLAP ACTUATOR SCREW/NUT PLAY (DED ONLY)								
		MOS							
27.340		HRS/MSC	N/A						
	REF: See Workcard	AFL							
+ 27-53-01-720-804-02	CHECK OF THE LEFT INBOARD FLAP EXTERNAL ACTUATOR SCREW/NUT PLAY (DED ONLY)								
		MOS							
27.340		HRS/MSC	N/A						
	REF: See Workcard	AFL							
+ 27-53-01-720-804-03	CHECK OF THE LEFT INBOARD FLAP INTERNAL ACTUATOR SCREW/NUT PLAY (DED ONLY)								
		MOS							
27.340		HRS/MSC	N/A						
	REF: See Workcard	AFL							
+ 27-53-01-720-804-04	CHECK OF THE RIGHT INBOARD FLAP INTERNAL ACTUATOR SCREW/NUT PLAY (DED ONLY)								
		MOS							
27.340		HRS/MSC	N/A						
	REF: See Workcard	AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-53-01-720-804-05	CHECK OF THE RIGHT INBOARD FLAP EXTERNAL ACTUATOR SCREW/NUT PLAY (DED ONLY)								
27.340	REF: See Workcard	MOS HRS/MSC AFL	N/A						
+ 27-53-01-720-804-06	CHECK OF THE RIGHT OUTBOARD FLAP ACTUATOR SCREW/NUT PLAY (DED ONLY)								
27.340	REF: See Workcard	MOS HRS/MSC AFL	N/A						
27-53-01-900-803-01	LH OUTBOARD FLAP SCREW JACK								
27.360	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-FEB-2008 7330:24 4558		
27-53-01-900-803-02	LH INBOARD FLAP EXTERNAL SCREW JACK								
27.365	5318-3 565 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-AUG-2010 8508 5310		
27-53-01-900-803-03	LH INBOARD FLAP CENTER SCREW JACK								
27.370	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:37 TSR:0 TSN:5029 TSR:0 TSN:2516 TSR:0			14-JAN-2009 8092:48 5100		
27-53-01-900-803-04	RH INBOARD FLAP CENTER SCREW JACK								
27.371	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:26 TSO:649:24 TSO:261			13-JAN-2014 9560:43 5737		
27-53-01-900-803-05	RH INBOARD FLAP LATERAL SCREW JACK								
27.366	5318-3 1337 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-AUG-2010 8508 5310		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01-900-803-06	RH OUTBOARD FLAP SCREW JACK								
27.361	2-5319-3 165 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			14-FEB-2008 7330:24 4558		
27-53-01-960-801-01	DISCARD LH OUTBOARD FLAP SCREW JACK								
27.360	1-5319-3 756 REF: See Workcard	MOS HRS/MSC AFL	16000				14-FEB-2008 7330:24 4558	20558	
LIFE LIMIT									
27-53-01-960-801-02	DISCARD LH INBOARD FLAP EXTERNAL SCREW JACK								
27.365	5318-3 565 REF:	MOS HRS/MSC AFL	15000				26-AUG-2010 8508 5310	20310	
LIFE LIMIT									
27-53-01-960-801-03	DISCARD LH INBOARD FLAP CENTER SCREW JACK								
27.370	5318-3 305 REF: See Workcard	MOS HRS/MSC AFL	15000	TSI:37 TSI:0 TSI:0			14-JAN-2009 8092:48 5100	20100	
LIFE LIMIT									
27-53-01-960-801-04	DISCARD RH INBOARD FLAP CENTER SCREW JACK								
27.371	5318-3 840 REF: See Workcard	MOS HRS/MSC AFL	15000				03-FEB-2012 8911:19 5476	20476	
LIFE LIMIT									
27-53-01-960-801-05	DISCARD RH INBOARD FLAP LATERAL SCREW JACK								
27.366	5318-3 1337 REF: See Workcard	MOS HRS/MSC AFL	15000				26-AUG-2010 8508 5310	20310	
LIFE LIMIT									
27-53-01-960-801-06	DISCARD RH OUTBOARD FLAP SCREW JACK								
27.361	2-5319-3 165 REF: See Workcard	MOS HRS/MSC AFL	16000				14-FEB-2008 7330:24 4558	20558	
LIFE LIMIT									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-60-00-710-803-01 (s)	OPERATIONAL TEST OF THE AIRBRAKES IN NORMAL MODE AND AUTOMATIC RETRACTION MODES						PKG		
27.410	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 27-61-01-720-801-01 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD AIRBRAKE POSITION MICROSWITCH						PKG		
27.405	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-61-01-720-801-02 (s)	FUNCTIONAL TEST OF THE LH CENTER AIRBRAKE POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-61-01-720-801-03 (s)	FUNCTIONAL TEST OF THE LH INBOARD AIRBRAKE POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-61-01-720-801-04 (s)	FUNCTIONAL TEST OF THE RH INBOARD AIRBRAKE POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-61-01-720-801-05 (s)	FUNCTIONAL TEST OF THE RH CENTER AIRBRAKE POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-61-01-720-801-06 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD AIRBRAKE POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-01-900-801-01	LH OUTBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-900-801-02	LH CENTER AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-900-801-03	LH INBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-900-801-04	RH INBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-900-801-05	RH CENTER AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-900-801-06	RH OUTBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
27-61-01-960-801-01	REPLACE LH OUTBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-61-01-960-801-02	REPLACE LH CENTER AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-61-01-960-801-03	REPLACE LH INBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-61-01-960-801-04	REPLACE RH INBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-61-01-960-801-05	REPLACE RH CENTER AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-61-01-960-801-06	REPLACE RH OUTBOARD AIRBRAKE POSITION MICROSWITCH PN SN-UNKNOWN REF: AMM 27-61-01-960-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
27-62-01-900-801-01	LEFT OUTBOARD AIRBRAKE ACTUATOR 106091-07 5117 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-62-01-900-801-02	LEFT MIDDLE AIRBRAKE ACTUATOR 106091-08 5019 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-62-01-900-801-03	LEFT INBOARD AIRBRAKE ACTUATOR 106091-09 5000 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-62-01-900-801-04	RIGHT INBOARD AIRBRAKE ACTUATOR 106091-09 5034 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-62-01-900-801-05	RIGHT MIDDLE AIRBRAKE ACTUATOR 106091-08 5020 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-62-01-900-801-06	RIGHT OUTBOARD AIRBRAKE ACTUATOR 106091-07 5118 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 27-80-00-710-804-02	OPERATIONAL TEST OF THE SLATS IN NORMAL AND EMERGENCY MODES - EMERGENCY MODE REF: AMM 27-80-00-710-804	MOS HRS/MSC AFL	10000				23-AUG-2000 0 0	10000	
+ 27-80-00-710-806-01 (s)	FUNCTIONAL TEST OF THE GROUND / FLIGHT RELAYS AND ANGLE-OF- ATTACK SENSOR CONTACTS PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
27-80-00-710-807-01	OPERATIONAL TEST OF SLAT EXTENSION THROUGH LH SOLENOID (S1) - OUTBOARD SLAT MANIFOLD REF: See Workcard	MOS HRS/MSC AFL	1000	+40			01-JUN-2018 9855:36 5896	10855:36	10895:36

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-01	LEFT INBOARD SLAT ACTUATOR 106132-05 2329 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-80-05-900-801-02	RIGHT INBOARD SLAT ACTUATOR 106132-05 2330 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-80-05-900-801-03	LEFT OUTBOARD SLAT INBOARD ACTUATOR 106132-06 3030 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:5847 TSR:0 TSN:3774 TSR:0			05-DEC-2016 9847:51 5893		
27-80-05-900-801-04	RIGHT OUTBOARD SLAT INBOARD ACTUATOR 106132-06 2127 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-80-05-900-801-05	LEFT OUTBOARD SLAT EMERGENCY ACTUATOR 106132-07 2140 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-80-05-900-801-06	RIGHT OUTBOARD SLAT EMERGENCY ACTUATOR 106132-07 2141 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
27-80-05-900-801-07	LEFT OUTBOARD SLAT OUTBOARD ACTUATOR 106132-08 2257 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-05-900-801-08	RIGHT OUTBOARD SLAT OUTBOARD ACTUATOR								
27.525	106132-08 2258 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 27-80-17-720-802-01 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT EXTENDED MICROSWITCH						PKG		
27.470	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 27-80-17-720-802-02 (s)	FUNCTIONAL TEST OF THE LH INBOARD SLAT RETRACTED MICROSWITCH						PKG		
27.470	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-80-17-720-802-03 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT RETRACTED POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
27-80-17-720-802-04 (s)	FUNCTIONAL TEST OF THE LH OUTBOARD SLAT EXTENDED POSITION MICROSWITCH						PKG		
	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 27-80-17-720-802-05 (s)	FUNCTIONAL TEST OF THE RH INBOARD SLAT EXTENDED MICROSWITCH						PKG		
27.475	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		
+ 27-80-17-720-802-06 (s)	FUNCTIONAL TEST OF RH INBOARD SLAT RETRACTED MICROSWITCH						PKG		
27.475	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-80-17-720-802-07 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD SLAT RETRACTED POSITION MICROSWITCH PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
27-80-17-720-802-08 (s)	FUNCTIONAL TEST OF THE RH OUTBOARD SLAT EXTENDED POSITION MICROSWITCH PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
+ 27-80-17-720-802-09 (s) 27.480	FUNCTIONAL TEST OF THE FLAP POSITION MICROSWITCH PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
27-80-23-720-801-01 27.495	FUNCTIONAL TEST INBOARD SLAT VALVE BOX 108117-06 516 REF: See Workcard	MOS HRS/MSC AFL	144	+3%			27-JUL-2012 9012:54 5520	27-JUL-2024	06-DEC-2024
270801 27.060	TRIM/AIRBRAKE CONTROL 013015-18 1630 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	30-NOV-2007 7190:18 4460		
270806 27.065	TRIPLE TRIM INDICATOR 4863-557-80-13 147 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			TSR:0 TSR:0 TSR:0	04-AUG-2009 8246 5216		
270816 27.075	SLATS/FLAPS CONTROL 7061-1 142 REF: AMM 27-51-01-900-801	MOS HRS/MSC AFL	O/C			TSR:15 TSN:7278 TSR:0 TSN:4888 TSR:0	29-APR-2016 9805:22 5878		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270821	PILOT RUDDER BAR PEDAL FE213-002 FR122 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
270826	COPILOT RUDDER BAR PEDAL FE213-003 FR240 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
270831	PILOT PEDALS ADJUSTMENT ROD BOX 4505-1 894 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
270836	COPILOT PEDALS ADJUSTMENT ROD BOX 4505-1 895 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
270841	PILOT COLUMN WHEEL VLP202 304 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
270842	COPILOT COLUMN WHEEL VLC202 304 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
271191	LEFT AILERON AUXILIARY ARTIFICIAL FEEL UNIT 105045-12 4472 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271192	RIGHT AILERON AUXILIARY ARTIFICIAL FEEL UNIT								
27.140	105045-12 4473 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
273806	PITCH (ELEVATOR) ARTIFICIAL FEEL UNIT								
27.230	105122-02 374 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			25-JUL-2012 9012:54 5520		
273821	Q-UNIT ELEVATOR SERVO VALVE								
27.245	108019-13 1949 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
273826	ELEVATOR Q-UNIT BOX								
27.250	062198-01 80 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
274801	HORIZONTAL STABILIZER POSITION TRANSMITTER								
27.310	016095-02 238 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
275801	FLAP MOTOR-GEAR ASSEMBLY								
27.380	4440-5 330 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
275836	LEFT DOUBLE ANGLE GEARBOX								
27.385	1-5593 298 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275841	RIGHT DOUBLE ANGLE GEARBOX								
27.385	2-5593 296 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
275846	LEFT INTERMEDIATE TRANSFER FLAP GEARBOX								
27.390	5592 459 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
275851	RIGHT INTERMEDIATE TRANSFER FLAP GEARBOX								
27.390	5592 460 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
275856	LEFT FLAP POSITION TRANSMITTER								
27.395	1-4414-2 771 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:2			08-APR-2013 9269:30 5625		
275861	RIGHT FLAP POSITION TRANSMITTER								
27.395	2-4414-2 623 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
276801	INBOARD/OUTBOARD AIRBRAKE SELECTOR VALVE								
27.430	65670-1 2730AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
276806	MIDDLE AIRBRAKE SELECTOR VALVE								
27.430	65670-1 2745AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276811	AIRBRAKE HOLD VALVE D25AB1703	MOS					29-DEC-2000		
27.435	101 REF: GENERIC NO REF	HRS/MSC AFL	O/C				384 253		
276816	AIRBRAKE ACCUMULATOR PRESSURE GAUGE 18040100	MOS					23-MAR-2000		
27.440	20900B REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276821	LEFT OUTBOARD AIRBRAKE RESTRICTOR C24370-202	MOS					23-MAR-2000		
27.445	H1407 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276826	RIGHT OUTBOARD AIRBRAKE RESTRICTOR C24370-202	MOS					23-MAR-2000		
27.445	H1408 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276831	LEFT INBOARD AIRBRAKE RESTRICTOR C24370-302	MOS					23-MAR-2000		
27.450	H1819 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276836	RIGHT INBOARD AIRBRAKE RESTRICTOR C24370-302	MOS					23-MAR-2000		
27.450	H1780 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
276841	LEFT MIDDLE AIRBRAKE RESTRICTOR C24370-402	MOS					23-MAR-2000		
27.455	H1334 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276846	RIGHT MIDDLE AIRBRAKE RESTRICTOR C24370-402	MOS					23-MAR-2000		
27.455	H1346 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278061	OUTBOARD SLAT MANIFOLD 108143-01	MOS		TSR:1			03-AUG-2012		
27.490	202 REF: See Workcard	HRS/MSC AFL	O/C	TSN:9012:54 TSR:0			9012:54 5520		
278811	INBOARD SLAT VALVE BOX 108117-06	MOS		TSR:0			03-AUG-2012		
27.495	516 REF: See Workcard	HRS/MSC AFL	O/C	TSN:9012:54 TSR:0			9012:54 5520		
278816	OUTBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR 65670-1	MOS					23-MAR-2000		
27.510	2747AB REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278821	INBOARD SLAT STANDBY ELECTRIC DISTRIBUTOR 65670-1	MOS					23-MAR-2000		
27.515	2718AB REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278866	LEFT ACTUATOR STANDBY RESTRICTOR VALVE FCFA1875150D	MOS					23-MAR-2000		
27.540	MA623 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278871	RIGHT ACTUATOR STANDBY RESTRICTOR VALVE FCRA1875150D	MOS					23-MAR-2000		
27.540	MA620 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278876	OUTBOARD SLAT RESTRICTOR CHECK VALVE C24815000	MOS					23-MAR-2000		
27.545	593 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278881	LEFT INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR C24346-102	MOS					23-MAR-2000		
27.550	H0322 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278886	RIGHT INBOARD SLAT ACTUATOR EXTENSION RESTRICTOR C24346-102	MOS					23-MAR-2000		
27.550	H0323 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278891	LEFT OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE C24370-102	MOS					23-MAR-2000		
27.555	H2117 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
278896	RIGHT OUTBOARD SLAT ACTUATOR EXTENSION RESTRICTOR VALVE C24370-102	MOS					23-MAR-2000		
27.555	H2121 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
57-41-13-640-801-01 (s)	GREASING/LUBRICATION OF THE SLAT MECHANISMS PKG 16	MOS	24	+1m			PKG 01-JUN-2018		
27.460	REF: See Workcard	HRS/MSC AFL					9855:36 5896		
CHAPTER 28	FUEL								
28-00-00-280-801-01 (s)	PERFORM FUEL CONTAMINATION DETECTION TEST PKG 15	MOS	12	+1m			PKG 01-JUN-2018		
28.010	REF: See Workcard	HRS/MSC AFL					9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-910-804-01	MEASURES TO BE TAKEN AFTER MAINTENANCE OPERATIONS IN THE FUEL TANKS								
28.500	REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
+ 28-10-00-280-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE FUEL TANK FLAPPER VALVES								
28.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
28-21-01-900-801-01	NO. 1 ENGINE LOW PRESSURE PUMP								
28.320	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-21-01-900-801-02	NO. 2 ENGINE LOW PRESSURE (NORMAL) PUMP								
28.330	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-21-01-900-801-03	NO. 2 ENGINE LOW PRESSURE (STAND-BY) PUMP								
28.330	P99C31-604 522 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-OCT-2013 9431:48 5694		
28-21-01-900-801-04	NO. 3 ENGINE LOW PRESSURE PUMP								
28.320	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-21-05-900-801-01	BP1 MANIFOLD								
28.340	L88A31-662-1 21158 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9855:36 TSR:0			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-05-900-801-02	BP2 MANIFOLD L88A31-663 20314 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9855:36 TSR:0			01-JUN-2018 9855:36 5896		
28-21-05-900-801-03	BP3 MANIFOLD L88A31-664-1 21160 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9855:36 TSR:0			01-JUN-2018 9855:36 5896		
+ 28-21-13-710-801-01 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
+ 28-21-13-710-801-01A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 1 MANIFOLD ENGINE SOV (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	11600				01-JUN-2018 9855:36 5896	21455:36	
+ 28-21-13-710-801-02 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
+ 28-21-13-710-801-02A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 2 MANIFOLD ENGINE SOV (MANDATORY 5-40) REF: See Workcard	MOS HRS/MSC AFL	11600				01-JUN-2018 9855:36 5896	21455:36	
+ 28-21-13-710-801-03 (s)	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-21-13-710-801-03A	OPERATIONAL TEST OF THE FUEL SHUT-OFF VALVES - BP 3 MANIFOLD ENGINE SOV (MANDATORY 5-40)	MOS					01-JUN-2018		
76.150		HRS/MSC	11600				9855:36		21455:36
MANDATORY 5-40	REF: See Workcard	AFL					5896		
+ 28-21-13-790-801-01	LEAK TEST OF THE NO. 1 ENGINE FUEL SHUTOFF VALVE	MOS					07-NOV-2017		
76.130		HRS/MSC	E/C				9850:07		
	REF: See Workcard	AFL					5894		
+ 28-21-13-790-801-02	LEAK TEST OF THE NO. 2 ENGINE FUEL SHUTOFF VALVE	MOS					07-NOV-2017		
76.140		HRS/MSC	E/C				9850:07		
	REF: See Workcard	AFL					5894		
+ 28-21-13-790-801-03	LEAK TEST OF THE NO. 3 ENGINE FUEL SHUTOFF VALVE	MOS					16-APR-2008		
76.150		HRS/MSC	E/C				7501		
	REF: See Workcard	AFL					4649		
+ 28-21-14-720-801-01	FUNCTIONAL TEST BP1 MANIFOLD THERMAL EXPANSION SYSTEMS	MOS					01-JUN-2018		
28.340	L88A31-662-1	HRS/MSC	10000	+3%			9855:36		19855:36
	21158	AFL					5896		20155:36
	REF: See Workcard								
+ 28-21-14-720-801-02	FUNCTIONAL TEST BP2 MANIFOLD THERMAL EXPANSION SYSTEMS	MOS					01-JUN-2018		
28.340	L88A31-663	HRS/MSC	10000	+3%			9855:36		19855:36
	20314	AFL					5896		20155:36
	REF: See Workcard								
+ 28-21-14-720-801-03	FUNCTIONAL TEST BP3 MANIFOLD THERMAL EXPANSION SYSTEMS	MOS					01-JUN-2018		
28.340	L88A31-664-1	HRS/MSC	10000	+3%			9855:36		19855:36
	21160	AFL					5896		20155:36
	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-17-790-801-01	SEALING TEST OF THE APU FUEL SHUT-OFF VALVE								
28.510	REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
+ 28-21-25-710-801-01 (s)	OPERATIONAL TEST OF THE CROSSFEED UNITS						PKG		
28.315	PKG 7 REF: See Workcard	MOS HRS/MSC AFL	36 2400	+1m +40			01-JUN-2018 9855:36 5896		
28-21-25-900-801-01	NO. 1 ENGINE BOOSTER CROSSFEED UNIT								
28.160	L88A31-665-2 21287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-21-25-900-801-02	NO. 3 ENGINE BOOSTER CROSSFEED UNIT								
28.160	L88A31-666-2 21275 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-21-27-900-801-01	LP 3-1 BOOSTER CROSSFEED VALVE								
28.480	D97C00-218 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
28-21-27-900-801-02	LP 1-3 BOOSTER CROSSFEED VALVE								
28.485	D97C00-219 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
+ 28-21-29-100-801-01 (s)	CLEANING OF THE LH CROSSFEED UNIT FILTER								
28.310	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	25	+50			01-JUN-2018 9855:36 5896	9880:36 M 9930:36	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-21-29-100-801-02 (s)	CLEANING OF THE RH CROSSFEED UNIT FILTER PKG 5 REF: See Workcard	MOS HRS/MSC AFL	25	+50			01-JUN-2018 9855:36 5896	9880:36 M 9930:36	
+ 28-21-29-100-801-03 (s)	CLEANING OF THE BOOSTER PUMP 2 UNIT FILTER PKG 5 REF: See Workcard	MOS HRS/MSC AFL	25	+50			01-JUN-2018 9855:36 5896	9880:36 M 9930:36	
28-22-00-710-802-01 (s) 28.345	OPERATIONAL TEST OF THE MANUAL "REAR XFR" SYSTEM PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
28-30-00-680-802-01	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE LH TANK GROUP REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
28-30-00-680-802-02	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE RH TANK GROUP REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
28-30-00-680-802-03	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - DRAINING OF THE CENTER TANK GROUP REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
28-30-00-680-802-04	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - FUEL SAMPLING REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-30-00-680-802-06	DRAINING OF THE FUEL TANKS / FUEL SAMPLING - LEAK CHECK OF THE DRY BAY	MOS	2	+5d			01-JUN-2018 9855:36 5896	01-AUG-2018	06-AUG-2018
	REF: See Workcard	HRS/MSC AFL							
28-30-00-680-803-01	DRAINING OF THE GRAVITY DEFUELING LINE	MOS	2	+5d			01-JUN-2018 9855:36 5896	01-AUG-2018	06-AUG-2018
28.490	REF: See Workcard	HRS/MSC AFL							
28-30-00-680-804-01	DRAINING WATER FROM THE FUEL TANKS	MOS	2	+5d			01-JUN-2018 9855:36 5896	01-AUG-2018	06-AUG-2018
	REF: See Workcard	HRS/MSC AFL							
28-30-11-960-802-01	DISCARD OF THE FUEL DRAIN CAPS	MOS					23-MAR-2000 0 0		
	REF: AMM 28-30-11-960-802	HRS/MSC AFL	O/C						
+ 28-41-00-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL QUANTITY INDICATING SYSTEM						PKG 03-JUN-2014 9560:43 5737		
28.420	PKG 22	MOS	3200	+40					
	REF: See Workcard	HRS/MSC AFL							
28-41-05-900-801-01	LH WING CENTER TANK GAUGE (L6EJ)						06-AUG-2012 9012:54 5520		
28.390	766-189-4	MOS				TSR:0			
	705	HRS/MSC	O/C			TSN:9012:54			
	REF: AMM 28-41-05-900-801	AFL				TSR:0			
28-41-05-900-801-02	RH WING CENTER TANK GAUGE (R6EJ)						06-AUG-2012 9012:54 5520		
28.390	766-189-4	MOS				TSR:0			
	715	HRS/MSC	O/C			TSN:9012:54			
	REF: AMM 28-41-05-900-801	AFL				TSR:0			

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05-900-801-03	LH FEEDER TANK GAUGE (L7EJ)								
28.385	766190-2 672 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-04	CENTER FEEDER TANK GAUGE (25EJ)								
28.385	764129 175 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-05	RH FEEDER TANK GAUGE (R7EJ)								
28.385	766-190-2 687 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-06	FRONT TANK REAR GAUGE (23EJ)								
28.380	764008-2 183 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-07	FRONT TANK FRONT GAUGE (24EJ)								
28.380	764009-3 172 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0 TSR:0			03-AUG-2012 9012:54 5520		
28-41-05-900-801-08	REAR TANK GAUGE (26EJ)								
28.395	764128 173 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-09	LH FRONT TANK GAUGE (L9EJ)								
28.410	764023 182 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-05-900-801-10	RH FRONT TANK GAUGE (R9EJ)								
28.410	764024 172 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			06-AUG-2012 9012:54 5520		
28-41-05-900-801-11	MSC TANK GAUGE (29EJ)								
28.170	L85-25-002 20134 REF: AMM 28-41-05-900-801	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28-41-09-900-801-01	LEFT WING INBOARD FUEL TANK GAUGE								
28.365	764-652 203 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			06-AUG-2012 9012:54 5520		
28-41-09-900-801-02	RIGHT WING INBOARD FUEL TANK GAUGE								
28.365	764-652 205 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			06-AUG-2012 9012:54 5520		
28-41-09-900-801-03	LEFT WING CENTER FUEL TANK GAUGE								
28.370	792-367-2 1337 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			06-AUG-2012 9012:54 5520		
28-41-09-900-801-04	RIGHT WING CENTER FUEL TANK GAUGE								
28.370	792-367-2 1336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			03-AUG-2012 9012:54 5520		
28-41-09-900-801-05	LEFT WING OUTBOARD FUEL TANK GAUGE								
28.375	792-368-2 1369 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			03-AUG-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-09-900-801-06	RIGHT WING OUTBOARD FUEL TANK GAUGE								
28.375	792-368-2 1313 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			03-AUG-2012 9012:54 5520		
+ 28-43-01-720-801-01 (s)	FUNCTIONAL TEST OF THE FUEL TEMPERATURE SENSOR								
28.470	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
28-70-01-780-801-01 (s)	CHECK FOR CORRECT CALIBRATION OF THE PRESSURE GAUGE								
28.215	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
28-70-05-900-801-01	PRESSURE REDUCING VALVE								
28.270	B14DE2080 792 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-OCT-2007 7098:36 4403		
28-70-09-350-801-01	RESTORATION LEFT PRESSURIZATION VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)								
28.220	B04BA1006 3854 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
28-70-09-350-801-02	RESTORATION RIGHT PRESSURIZATION VALVE BOX (FILTER CLEANING AND CALIBRATION CHECK)								
28.220	B04BA1006 3520 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
28-70-09-900-801-01	LEFT PRESSURIZATION VALVE BOX								
28.220	B04BA1006 3854 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-09-900-801-02	RIGHT PRESSURIZATION VALVE BOX								
28.220	B04BA1006 3520 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2018 9855:36 5896		
28-70-13-350-801-01	RESTORATION LH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST)								
	B06GA1052 4552 REF: See Workcard	MOS HRS/MSC AFL	O/C				(EBT)		
28-70-13-350-801-02	RESTORATION RH WING TANK NEGATIVE PRESSURE RELIEF VALVE (AIR FLOW AND PRESSURE DROP TEST / LEAK TEST)								
	B06GA1052 4403 REF: See Workcard	MOS HRS/MSC AFL	O/C				(EBT)		
+ 28-70-13-720-802-01	FUNCTIONAL TEST LH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1052 4552 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			9012:32	14012:32	14162:32
+ 28-70-13-720-802-02	FUNCTIONAL TEST RH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1052 4403 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			9012:32	14012:32	14162:32
28-70-13-900-801-01	LH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1052 4552 REF: See Workcard	MOS HRS/MSC AFL	O/C				26-JUL-2012 9012:54 5520		
28-70-13-900-801-02	RH WING TANK NEGATIVE PRESSURE RELIEF VALVE								
28.210	B06GA1052 4403 REF: See Workcard	MOS HRS/MSC AFL	O/C				26-JUL-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-70-17-130-801-01 (s)	CLEANING OF NO. 1 ENGINE FUEL TANK PRESSURIZATION AIR FILTER						PKG		
28.200	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 28-70-17-130-801-02 (s)	CLEANING OF NO. 2 ENGINE FUEL TANK PRESSURIZATION AIR FILTER						PKG		
28.200	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
281801	PRESSURIZATION PRESSURE FUEL GAUGE								
28.025	MPMC50701-01 447 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281803	FRONT TANK FRONT DRAIN								
28.030	142D12-11 2178 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281806	LEFT WING INBOARD TANK DRAIN								
28.040	142D12-11 F55643 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-AUG-2012 9012:54 5520		
281808	RIGHT WING INBOARD TANK DRAIN								
28.040	142D12-11 2159 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281811	FRONT TANK REAR DRAIN								
28.045	142G12-32 J46680 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:12 TSN:0 TSN:0			21-OCT-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281813	LEFT FRONT TANK DRAIN								
28.050	142G12-32 F55699 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-AUG-2012 9012:54 5520		
281816	RIGHT FRONT TANK DRAIN								
28.050	142G12-32 3737 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281818	RIGHT CENTERWING TANK DRAIN								
28.055	142G12-32 3729 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281821	REAR TANK DRAIN								
28.060	142G12-32 F55707 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				01-AUG-2012 9012:54 5520		
281823	TANK COMPARTMENT SERVICING DRAIN								
28.065	142G12-32 3517 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281826	NO. 1 ENGINE FEEDER TANK DRAIN								
28.070	142G12-32 J40115 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:16 TSN:0 TSN:0			15-OCT-2016 9847:51 5893		
281828	NO. 2 ENGINE FEEDER TANK DRAIN								
28.070	142G12-32 J40117 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:16 TSN:0 TSN:0			15-OCT-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281831	NO. 3 ENGINE FEEDER TANK DRAIN 142G12-32	MOS					23-MAR-2000		
28.070	4133 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281833	NO. 3 ENGINE REAR FEEDER TANK DRAIN 142G12-32	MOS					23-MAR-2000		
28.075	4156 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281836	REFUELING PRESSURE CONNECTOR K97-63-206	MOS					23-MAR-2000		
28.080	20622 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281838	LEFT TANK FUELING ELECTRIC VALVE L94Z31-201	MOS					23-MAR-2000		
28.085	22050 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281841	RIGHT TANK FUELING ELECTRIC VALVE L94Z31-201	MOS					23-MAR-2000		
28.085	22051 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281843	CENTER WING TANK FUELING ELECTRIC VALVE L94Z31-201	MOS					23-MAR-2000		
28.090	22052 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
281846	SERVICE COMPARTMENT TANK FUELING ELECTRIC VALVE L94Z31-201	MOS					23-MAR-2000		
28.095	22049 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281848	LEFT WING TANKS NON-RETURN VALVE L96Z31-201 22456 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281851	RIGHT WING TANKS NON-RETURN VALVE L96Z31-201 22464 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281853	CENTER WING TANKS NON-RETURN VALVE L96Z31-201 22465 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281856	NO. 2 ENGINE FEEDER TANK NON-RETURN VALVE L85D38-001 20265 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281858	LOW LEVEL DETECTION BOX 722-087-2 903 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281861	1000 LBS LEVEL DETECTION BOX 722-087-2 829 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281863	LOW LEVEL THERMISTOR RELAY BOX 772-087-2 0793 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-AUG-2009 8246 5216		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281866	PRESSURE FUELING PANEL								
28.130	19-55-31 176 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281868	REFUELING MANIFOLD								
28.135	K99-31-008 20256 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281871	LEFT WING TANK VENT VALVE								
28.140	B97F38-653 20450 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-APR-2003 2911:24 1803		
281873	RIGHT WING TANK VENT VALVE								
28.140	B97F38-653 20187 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-JAN-2004 3723:54 2308		
281876	TANK CENTRAL VENT VALVE								
28.140	B97E38-652 20029 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:26			18-AUG-2000 23 8		
281878	WING TANK CROSSFEED VALVE								
28.145	L87B63-653 20415 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
281881	TANK TRANSFER ELECTRIC VALVE								
28.150	B97E25-601 20035 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281883	TANK TRANSFER MANUAL VALVE								
28.150	B97E25-601 20049 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:27			18-AUG-2000 23 8		
281891	SERVICING COMPARTMENT FEEDER TANK NON-RETURN VALVE								
28.165	L85-25-001 20063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
282811	NO. 1 ENGINE PUMP BOOSTER								
28.250	P99C31-604 A31278 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			07-AUG-2012 9012:54 5520		
282812	NO. 2 ENGINE PUMP (NORMAL) BOOSTER								
28.260	P99C31-604 1524 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			02-AUG-2012 9012:54 5520		
282813	NO. 3 ENGINE PUMP BOOSTER								
28.250	226-650-51 1347 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSN:9012:54 TSR:0			07-AUG-2012 9012:54 5520		
282814	NO. 2 ENGINE PUMP (STAND-BY) BOOSTER								
28.260	226-650-51 1365 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-AUG-2012 9012:54 5520		
282816	NO. 2 ENGINE UNIT PUMP								
28.265	L88A31-206-1 21155 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282826	NO. 1 ENGINE NON-RETURN VALVE L96Z19-003	MOS					23-MAR-2000		
28.280	22349 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282831	NO. 2 ENGINE NON-RETURN VALVE L96Z19-003	MOS					23-MAR-2000		
28.285	22368 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282846	NO. 1 ENGINE PRESSURIZATION AIR FILTER 018500AA000NF0A	MOS					23-MAR-2000		
28.300	665090003 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282851	NO. 2 ENGINE PRESSURIZATION AIR FILTER 018500AA000NF0A	MOS					23-MAR-2000		
28.300	565090012 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
282866	FUELING SELECTOR SWITCH 798562	MOS					23-MAR-2000		
28.305	181 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
284801	NO. 1 ENGINE LOW PRESSURE PRESSURE SWITCH 8G1256-1	MOS		TSN:23			02-SEP-2010		
28.360	3973 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			8508:33 5310		
284802	NO. 2 ENGINE LOW PRESSURE PRESSURE SWITCH 8G1256-1	MOS		TSN:23			02-SEP-2010		
28.360	3974 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			8508:33 5310		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284803	NO. 3 ENGINE LOW PRESSURE PRESSURE SWITCH								
28.360	8G1256-1 2446 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
284876	LEFT FUEL GAUGE AMPLIFIER								
28.400	736-327-50 1128 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
284881	RIGHT FUEL GAUGE AMPLIFIER								
28.400	736-327-50 1129 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
284888	FUEL CENTRAL GAUGE COMPUTER								
28.405	736913-4 0192 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:25			18-AUG-2000 23 8		
28501A	LEFT WING INBOARD QUANTITY GAUGE								
28.425	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501B	RIGHT WING INBOARD QUANTITY GAUGE								
28.425	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501C	LEFT WING MIDDLE QUANTITY GAUGE								
28.430	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28501D	RIGHT WING MIDDLE QUANTITY GAUGE								
28.430	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501E	LEFT WING OUTBOARD QUANTITY GAUGE								
28.435	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501F	RIGHT WING OUTBOARD QUANTITY GAUGE								
28.435	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501G	LEFT WING CENTER SECTION QUANTITY GAUGE								
28.440	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501H	RIGHT WING CENTER SECTION QUANTITY GAUGE								
28.440	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501I	NO. 1 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501J	NO. 2 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28501K	NO. 3 ENGINE FEEDER TANK QUANTITY GAUGE								
28.445	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501L	LEFT TANK FRONT QUANTITY GAUGE								
28.450	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501M	RIGHT TANK FRONT QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501N	FRONT TANK REAR QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501P	FRONT TANK FRONT QUANTITY GAUGE								
28.455	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501Q	REAR TANK QUANTITY GAUGE								
28.460	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
28501R	SERVICING COMPARTMENT TANK QUANTITY GAUGE								
28.465	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

CHAPTER 29 HYDRAULIC POWER

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-10-00-720-801-01 (s)	FUNCTIONAL TEST NO.1 OF THE NO. 1 MAIN HYDRAULIC SYSTEM						PKG		
29.020	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 29-10-00-720-801-02 (s)	FUNCTIONAL TEST NO.2 OF THE NO. 2 MAIN HYDRAULIC SYSTEM						PKG		
29.020	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
29-11-01-350-801-01	RESTORATION NO. 1 HYDRAULIC PUMP (OVERHAUL)								
29.030	4204501	MOS					23-MAY-2011		
OVERHAUL	BD56	HRS/MSC	3240	+3%			8715:32	11955:32	12052:44
	REF: See Workcard	AFL							
29-11-01-350-801-02	RESTORATION NO. 2 HYDRAULIC PUMP (OVERHAUL)								
29.030	4204501	MOS					23-MAY-2011		
OVERHAUL	AE953	HRS/MSC	3240	+3%			8715:32	11955:32	12052:44
	REF: See Workcard	AFL							
29-11-01-350-801-03	RESTORATION NO. 3 HYDRAULIC PUMP (OVERHAUL)								
29.030	4204501	MOS					23-MAY-2011		
OVERHAUL	FM87	HRS/MSC	3240	+3%			8715:32	11955:32	12052:44
	REF: See Workcard	AFL							
29-11-01-900-801-01	NO. 1 HYDRAULIC PUMP								
29.030	4204501	MOS					23-MAY-2011		
	BD56	HRS/MSC	O/C				8715:32		
	REF: See Workcard	AFL							
				TSO:0					
				TSO:0					
				TSO:0					
29-11-01-900-801-02	NO. 2 HYDRAULIC PUMP								
29.030	4204501	MOS					23-MAY-2011		
	AE953	HRS/MSC	O/C				8715:32		
	REF: See Workcard	AFL							
				TSO:0					
				TSO:0					
				TSO:0					

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-01-900-801-03	NO. 3 HYDRAULIC PUMP 4204501 FM87 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-MAY-2011 8715:32		
29-11-25-900-801-01	NO. 1 SYSTEM STAND-BY PUMP PRESSURE SWITCH 15H0090PH 0123 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-MAR-2007 6593:48 4071		
29-11-25-900-801-02	NO. 2 SYSTEM STAND-BY PUMP PRESSURE SWITCH 15H0090PH 0963 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:40 TSN:0 TSN:0			13-NOV-2013 9448:25 5701		
29-11-25-900-801-03	NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 1820 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 8246 5216		
29-11-25-900-801-04	NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 4040 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			13-NOV-2013 9448:25 5701		
29-11-25-900-801-05	NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 1303 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-MAR-2007 6593:48 4071		
29-11-25-960-801-01	DISCARD NO. 1 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 1820 REF: See Workcard	MOS HRS/MSC AFL	O/C				04-AUG-2009 8246 5216		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-25-960-801-02	DISCARD NO. 2 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 4040 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-NOV-2013 9448:25 5701		
29-11-25-960-801-03	DISCARD NO. 3 HYDRAULIC PUMP PRESSURE SWITCH 15H0088PH 1303 REF: See Workcard	MOS HRS/MSC AFL	O/C				14-MAR-2007 6593:48 4071		
29-13-09-960-801-01 (s)	REPLACEMENT OF THE STANDBY PUMP FILTER PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29-13-09-960-801-02 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 1 RETURN FILTER PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29-13-09-960-801-03 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 2 RETURN FILTER PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29-13-09-960-801-04 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 3 RETURN FILTER PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29-13-09-960-801-05 (s)	REPLACEMENT OF THE SYSTEM 1 GENERAL RETURN FILTER PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-13-09-960-801-06 (s)	REPLACEMENT OF THE SYSTEM 2 GENERAL RETURN FILTER PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
29-13-09-960-801-07 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 1 DELIVERY FILTER PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
29-13-09-960-801-08 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 2 DELIVERY FILTER PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
29-13-09-960-801-09 (s)	REPLACEMENT OF THE HYDRAULIC PUMP 3 DELIVERY FILTER PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
29-14-01-680-801-01 (s)	DRAINING OF THE NO. 1 SYSTEM HYDRAULIC RESERVOIR PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29.040	REF: See Workcard	HRS/MSC AFL	3750						
29-14-01-680-801-02 (s)	DRAINING OF THE NO. 2 SYSTEM HYDRAULIC RESERVOIR PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
29.040	REF: See Workcard	HRS/MSC AFL	3750						
29-14-01-900-801-01	NO. 1 SYSTEM HYDRAULIC RESERVOIR 029029-08	MOS					23-MAR-2000		
29.050	549	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-14-01-900-801-02	NO. 2 SYSTEM HYDRAULIC RESERVOIR 029029-07	MOS					23-MAR-2000		
29.050	552 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
29-14-11-900-801-01	NO. 1 SYSTEM HYDRAULIC ACCUMULATOR 60967-1	MOS					23-MAR-2000		
29.070	EFS451 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
29-14-11-900-801-02	NO. 2 SYSTEM HYDRAULIC ACCUMULATOR 47723-1000VA	MOS					04-AUG-2009		
29.070	403 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			8246 5216		
29-20-01-900-801-01	STAND-BY ELECTRIC PUMP 1291	MOS					12-MAY-2005		
29.120	411 REF: See Workcard	HRS/MSC AFL	O/C	TSO:0 TSO:0			4984:06 3090		
+ 29-20-03-220-801-01	CHECK STAND-BY ELECTRIC PUMP MOTOR BRUSHES 1291	MOS					01-JUN-2018		
29.120	411 REF: See Workcard	HRS/MSC AFL	5000	+3%			9855:36 5896	14855:36	15005:36
+ 29-20-03-720-801-01	FUNCTIONAL TEST STAND-BY ELECTRIC PUMP MOTOR 1291	MOS					01-JUN-2018		
29.120	411 REF: See Workcard	HRS/MSC AFL	5000	+3%			9855:36 5896	14855:36	15005:36
29-20-05-900-801-01	ELECTRIC PUMP STAND-BY SELECTOR VALVE B94A13-205	MOS					23-MAR-2000		
29.140	20586 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-20-07-960-801-01	DISCARD NO. 1 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 0123 REF: See Workcard	MOS HRS/MSC AFL	O/C				14-MAR-2007 6593:48 4071		
29-20-07-960-801-02	DISCARD NO. 2 SYSTEM STAND-BY PUMP PRESSURE SWITCH								
29.150	15H0090PH 0963 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-NOV-2013 9448:25 5701		
291811	NO. 1 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR								
29.060	034001 556 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
291816	NO. 2 SYSTEM HYDRAULIC RESERVOIR DE-AERATOR								
29.060	034001 557 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
291831	NO. 1 SYSTEM PRESSURE HOLDING VALVE ACCUMULATOR GAUGE								
29.080	18040100 3397 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
291836	NO. 1 SYSTEM PRESSURE ACCUMULATOR GAUGE								
29.090	18040100 4674 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
291841	NO. 2 SYSTEM PRESSURE ACCUMULATOR GAUGE								
29.090	18040100 4682 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291846	NO. 1 SYSTEM HYDRAULIC MANIFOLD AEB937-81	MOS					23-MAR-2000		
29.100	121 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291851	NO. 2 SYSTEM HYDRAULIC MANIFOLD AEB938-81	MOS					23-MAR-2000		
29.100	181 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
291856	NO. 1 SYSTEM PRESSURE HOLDING VALVE 70073	MOS					17-AUG-2001		
29.110	12 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			1026 663		
291861	NO. 2 SYSTEM PRESSURE HOLDING VALVE 70073	MOS					23-MAR-2000		
29.110	399 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
293801	NO. 1 SYSTEM PRESSURE TRANSMITTER 8107-132-00-10	MOS					23-MAR-2000		
29.160	681 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
293806	NO. 2 SYSTEM PRESSURE TRANSMITTER 8107-132-00-10	MOS					23-MAR-2000		
29.160	682 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
293811	NO. 1 SYSTEM QUANTITY-PRESSURE INDICATOR 5502-380-80-10	MOS					18-AUG-2000		
29.170	808 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:34			23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293816	NO. 2 SYSTEM QUANTITY-PRESSURE INDICATOR								
29.170	5502-380-80-10 867 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
30-00-00-960-801-01 (s)	REPLACE OF THE ANTI-ICING SYSTEM WIGGINS COUPLING SEALS						PKG		
30.220	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			28-SEP-2012 9012:54 5520		
30-11-00-720-801-01	FUNCTIONAL TEST LEFT HAND INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-600 334 REF: See Workcard	MOS HRS/MSC AFL	1240	+3%			14-JAN-2014 9560:43 5737	10800:43 6737	10837:55 6767
30-11-00-720-801-02	FUNCTIONAL TEST RIGHT HAND INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-700 351 REF: See Workcard	MOS HRS/MSC AFL	1240	+3%			14-JAN-2014 9560:43 5737	10800:43 6737	10837:55 6767
30-11-00-720-801-03	FUNCTIONAL TEST LEFT HAND OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-600 316 REF: See Workcard	MOS HRS/MSC AFL	1240	+3%			14-JAN-2014 9560:43 5737	10800:43 6737	10837:55 6767
30-11-00-720-801-04	FUNCTIONAL TEST RIGHT HAND OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-700 637R REF: See Workcard	MOS HRS/MSC AFL	1240	+3%			14-JAN-2014 9560:43 5737	10800:43 6737	10837:55 6767
30-11-00-900-801-01	LEFT HAND INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-600 334 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-SEP-2007 6997:36 4328		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-11-00-900-801-02	RIGHT HAND INBOARD SLAT TELESCOPIC DUCT								
30.010	5036-700 351 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-SEP-2007 6997:36 4328		
30-11-00-900-801-03	LEFT HAND OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-600 316 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-SEP-2007 6997:36 4328		
30-11-00-900-801-04	RIGHT HAND OUTBOARD SLAT TELESCOPIC DUCT								
30.020	5035-700 637R REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-SEP-2007 6997:36 4328		
+ 30-11-17-200-803-01 (s)	INSPECTION OF THE WING ANTI-ICING SYSTEM GENERAL CONNECTOR COUPLINGS								
30.210	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m 3750			PKG 01-JUN-2018 9855:36 5896		
+ 30-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 ENGINE AIR INTAKE ANTI-ICING SYSTEM								
30.090	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 30-20-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO.2 ENGINE AIR INTAKE ANTI-ICING SYSTEM								
30.090	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 30-20-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 ENGINE AIR INTAKE ANTI-ICING SYTEM								
30.090	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20-01-700-801-01	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 1 AIR INTAKE ANTI-ICING VALVE (L3HA)								
30.100	6911C020200 101 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
+ 30-20-01-700-801-02	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 2 AIR INTAKE ANTI-ICING VALVE (M3HA)								
30.100	6911C020200 00586 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			12-MAY-2014 9560:43 5737	14560:43	14710:43
+ 30-20-01-700-801-03	FUNCTIONAL / LEAKAGE TEST OF THE ENGINE AIR INTAKE ANTI-ICING VALVES - ENGINE 3 AIR INTAKE ANTI-ICING VALVE (R3HA)								
30.100	6911C020200 183 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			01-JUN-2018 9855:36 5896	14855:36	15005:36
+ 30-30-00-710-801-01 (s)	OPERATIONAL TEST OF THE AIR DATA PROBE ANTI-ICING SYSTEM								
30.150	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 30-41-00-710-801-01 (s)	OPERATIONAL TEST OF THE WINDSHIELD DE-ICING SYSTEM								
30.160	PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4800	+40			PKG 03-JUN-2014 9560:43 5737		
30-43-05-900-801-01	PILOT WINDSHIELD WIPER MOTOR								
30.170	4267568 26079 REF: See Workcard	MOS HRS/MSC AFL	O/C				02-OCT-2012 9013:18 5521		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-43-05-900-801-02	COPILOT WINDSHIELD WIPER MOTOR								
30.170	4267575 25965 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			20-SEP-2012 9012:54 5520		
+ 30-43-09-220-801-01	CHECK PILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.170	4267568 26079 REF: See Workcard	MOS HRS/MSC AFL	15000	+3%			02-OCT-2012 9013:18 5521	24013:18	24463:18
+ 30-43-09-220-801-02	CHECK COPILOT WINDSHIELD WIPER MOTOR BRUSHES								
30.170	4267575 25965 REF: See Workcard	MOS HRS/MSC AFL	15000	+3%			20-SEP-2012 9012:54 5520	24012:54	24462:54
30-90-00-710-801-01 (s)	OPERATIONAL TEST OF THE BRAKE HEATING SYSTEM								
30.030	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
301801	WING ANTI-ICING VALVE								
30.040	BYLB52642 123 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
301806	LEFT WING ANTI-ICING PRESSURE SWITCH								
30.050	8G1199-4 1599 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
301811	RIGHT WING ANTI-ICING PRESSURE SWITCH								
30.050	8G1199-4 1600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301816	COCKPIT TEMPERATURE CONDITONING PROBE								
30.060	RP161-00 1362 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
301821	S-DUCT ANTI-ICING TEMPERATURE PROBE								
30.070	RP161-00 1315 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
301826	WING ANTI-ICING TEMPERATURE PROBE								
30.080	RP161-00 3376 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-MAR-2008 7439 4612		
302031	NO. 1 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 101 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSO:4871:30 TSO:2806			01-JUN-2018 9855:36 5896		
302032	NO. 2 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 00586 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:1 TSN:3710 TSR:0 TSR:0			12-MAY-2014 9560:43 5737		
302033	NO. 3 ENGINE AIR INTAKE ANTI-ICING PRESSURE REGULATING VALVE								
30.100	6911C020200 183 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-JUN-2018 9855:36 5896		
302801	ENGINE S-DUCT ANTI-ICING VALVE								
30.110	BYLBS2643 24 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				30-JAN-2004 3723:54 2308		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302806	NO. 1 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-4 1940 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
302811	NO. 2 ENGINE DUCT ANTI-ICING PRESSURE SWITCH 8G1199-4 1968 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
302816	NO. 2 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-5 0006 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
302821	NO. 3 ENGINE INTAKE LOW PRESSURE ANTI-ICING PRESSURE SWITCH 8G1199-5 0007 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
302826	NO. 1 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-5 206 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
302831	NO. 2 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-5 534 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-DEC-2003 3577:54 2205		
302836	NO. 3 ENGINE INTAKE HIGH PRESSURE ANTI-ICING PRESSURE SWITCH 8G1340-5 209 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304801	PILOT WINDSHIELD TEMPERATURE REGULATOR AV30559060030-1 606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
304806	COPILOT WINDSHIELD TEMPERATURE REGULATOR AV30559060030-1 608 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
304811	LEFT SIDE WINDOW TEMPERATURE REGULATOR AV30564060030 596 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
304816	REAR WINDOW TEMPERATURE REGULATOR AV30564060030 600 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
309A01	ANTI-ICE BRAKE L VALVE B97-26-555 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			09-FEB-2001 454 290		
309A02	ANTI-ICE BRAKE R VALVE B97-26-555 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			09-FEB-2001 454 290		

CHAPTER 31 INDICATING/RECORDING SYSTEMS

31-21-05-900-801-01	PILOT CLOCK 811BFTR24HR 34068 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:9847:51			16-AUG-2016 9847:51 5893		
---------------------	--	-----------------------	-----	-------------	--	--	--------------------------------	--	--

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-21-05-900-801-02	COPILOT CLOCK								
31.020	811BFTR24HR 32923 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:9847:51			18-AUG-2016 9847:51 5893		
31-21-05-960-801-01	REPLACEMENT PILOT CLOCK BATTERY								
31.020 LIFE LIMIT	811BFTR24HR 34068 REF: See Workcard	MOS HRS/MSC AFL	25				16-AUG-2016 9847:51 5893	16-SEP-2018	
31-21-05-960-801-02	REPLACEMENT COPILOT CLOCK BATTERY								
31.020 LIFE LIMIT	811BFTR24HR 32923 REF: See Workcard	MOS HRS/MSC AFL	25				18-AUG-2016 9847:51 5893	18-SEP-2018	
+ 31-31-00-710-802-01 (s)	OPERATIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER								
31.120	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			PKG 01-JUN-2018 9855:36 5896		
31-31-00-720-802-01	FUNCTIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER 57-PARAMETER								
31.120	REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
31-31-00-720-803-01	FUNCTIONAL TEST OF THE DIGITAL FLIGHT DATA RECORDER 32-PARAMETER								
31.120	REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
31-31-00-970-801-01	DOWNLOAD OF THE DIGITAL FLIGHT DATA RECORDER								
31.120	REF: See Workcard	MOS HRS/MSC AFL	A/R				23-AUG-2000		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-31-09-710-801-01	OPERATIONAL TEST COCKPIT VOICE RECORDER ACCELERATION CONTACT								
31.090	400-10B 6230 REF: See Workcard	MOS HRS/MSC AFL	240	+3%			09-MAR-2010 8327:25 5249	09-MAR-2030	15-OCT-2030
+ 31-31-09-710-801-02	OPERATIONAL TEST DIGITAL FLIGHT DATA RECORDER ACCELERATION CONTACT								
31.090	400-10B 6251 REF: See Workcard	MOS HRS/MSC AFL	240	+3%			09-MAR-2010 8327:15 5249	09-MAR-2030	15-OCT-2030
31-31-09-900-801-01	COCKPIT VOICE RECORDER ACCELERATION CONTACT								
31.090	400-10B 6230 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-MAR-2010 8327:25 5249		
31-31-09-900-801-02	DIGITAL FLIGHT DATA RECORDER ACCELERATION CONTACT								
31.090	400-10B 6251 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-MAR-2010 8327:15 5249		
31-31-31-900-801-01	DIGITAL FLIGHT DATA RECORDER								
31.120	980-4700-025 4557 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
31-31-37-900-801-01	YAW CONTROL POSITION POTENTIOMETER								
	PN SN-UNKNOWN REF: AMM 31-31-37-900-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
31-31-37-900-801-02	ROLL CONTROL POSITION POTENTIOMETER								
	PN SN-UNKNOWN REF: AMM 31-31-37-900-801	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-37-900-801-03	PITCH CONTROL POSITION POTENTIOMETER PN SN-UNKNOWN REF: AMM 31-31-37-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
+ 31-31-50-710-801-01 (s)	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER PKG 17 31.080 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			PKG 01-JUN-2018 9855:36 5896		
31-31-50-970-801-01	DOWNLOAD OF THE COCKPIT VOICE RECORDER (CVR) REF: See Workcard	MOS HRS/MSC AFL	A/R				23-MAR-2000 0 0		
31-31-51-900-801-01	COCKPIT VOICE RECORDER 980-6020-011 2802 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
31-32-00-970-801-01	DOWNLOAD QUICK ACCESS (QAR) RECORDER PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
31-32-01-900-801-01	QUICK ACCESS (QAR) RECORDER PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
31-32-05-960-801-01	REPLACEMENT QUICK ACCESS (QAR) RECORDER BATTERY PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-52-00-710-801-01 (s)	OPERATIONAL TEST OF THE WARNING PANEL EMERGENCY POWER SUPPLY						PKG		
31.010	PKG 7 REF: See Workcard	MOS HRS/MSC AFL	36 2400	+1m +40			01-JUN-2018 9855:36 5896		
+ 31-54-00-720-801-01	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: ALARM TEST						01-JUN-2018		
31.030	REF: See Workcard	MOS HRS/MSC AFL	600	+40			9855:36 5896	10455:36	10495:36
+ 31-54-00-720-802-01 (s)	FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES: LOGIC TEST						PKG		
31.030	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 31-55-00-720-801-01 (s)	FUNCTIONAL TEST OF THE LANDING SAFETIES						PKG		
31.040	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
+ 31-60-00-710-801-01 (s)	OPERATIONAL TEST OF THE ENGINE INSTRUMENT ELECTRONIC DISPLAY						PKG		
31.050	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			13-AUG-2015 9779:37 5841		
31-60-51-900-802-01	ENGINE INSTRUMENT ELECTRONIC DISPLAY								
31.050	7014300-901 01038847 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-AUG-2015 9779:37 5841		
310811	LANDING GEAR CONFIGURATION PANEL								
27.070	205TS04Y02 868 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:28			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
315801	WARNING AUDIO UNIT 244ZS01Y1	MOS					23-MAR-2000		
31.060	287 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
315806	WARNING PANEL 110TS09Y2AB	MOS					18-AUG-2000		
31.070	172 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:23			23 8		
315A03	BEZEL EID CONTROL 7014332-831	MOS					23-MAR-2000		
	99052809 REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
316A01	CVR MICROPHONE 980-6113-001	MOS					23-MAR-2000		
	1110 REF:	HRS/MSC AFL	O/C	TSN:0			0 0		

CHAPTER 32 LANDING GEAR

+ 32-00-00-700-801-01	CHECK OF THE NOSE LANDING GEAR LEG UPLOCK								
32.170	REF: See Workcard	MOS HRS/MSC AFL	O/C				21-APR-2015 9760:57 5832		
+ 32-00-00-700-801-02	CHECK OF THE LEFT MAIN LANDING GEAR LEG UPLOCK								
32.190	REF: See Workcard	MOS HRS/MSC AFL	18	+1m			08-FEB-2018 9855:36 5896	08-AUG-2019	08-SEP-2019
+ 32-00-00-700-801-03	CHECK OF THE RIGHT MAIN LANDING GEAR LEG UPLOCK								
32.190	REF: See Workcard	MOS HRS/MSC AFL	18	+1m			08-FEB-2018 9855:36 5896	08-AUG-2019	08-SEP-2019

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-640-801-01	LUBRICATION OF THE LH MAIN LANDING GEARS (MLG) AND MLG DOORS								
32.010	REF: See Workcard	MOS HRS/MSC AFL	8 400	+1m			01-JUN-2018 9855:36 5896	01-FEB-2019 6296	01-MAR-2019
+ 32-10-00-640-801-02	LUBRICATION OF THE RH MAIN LANDING GEARS (MLG) AND MLG DOORS								
32.010	REF: See Workcard	MOS HRS/MSC AFL	8 400	+1m			01-JUN-2018 9855:36 5896	01-FEB-2019 6296	01-MAR-2019
+ 32-11-00-220-801-01	DETAILED INSPECTION LEFT MAIN LANDING GEAR LEG								
32.020	D22801400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	72	+8m			01-JUN-2018 9855:36 5896	01-JUN-2024	01-FEB-2025
+ 32-11-00-220-801-02	DETAILED INSPECTION RIGHT MAIN LANDING GEAR LEG								
32.030	D22802400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	72	+8m			01-JUN-2018 9855:36 5896	01-JUN-2024	01-FEB-2025
32-11-00-350-801-01	RESTORATION LEFT MAIN LANDING GEAR LEG (OVERHAUL)								
32.040 OVERHAUL	D22801400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	144 6000	+3%			13-SEP-2012 9012:54 5520	13-SEP-2024 11520	22-JAN-2025
32-11-00-350-801-02	RESTORATION RIGHT MAIN LANDING GEAR LEG (OVERHAUL)								
32.040 OVERHAUL	D22802400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	144 6000	+3%			13-SEP-2012 9012:54 5520	13-SEP-2024 11520	22-JAN-2025
32-11-00-900-801-01	LEFT MAIN LANDING GEAR LEG								
32.020	D22801400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	H/T				TSO:69 TSN:9855:36 TSO:842:42 5896	01-JUN-2018 9855:36 5896	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-900-801-02	RIGHT MAIN LANDING GEAR LEG								
32.030	D22802400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:0 TSN:9012:54 TSO:0 TSN:5520 TSO:0			13-SEP-2012 9012:54 5520		
32-11-00-960-801-01	REPLACEMENT LEFT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.020 LIFE LIMIT	D22801400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			13-SEP-2012 9012:54 5520	20000	
32-11-00-960-801-01A	REPLACEMENT LEFT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22801400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			13-SEP-2012 9012:54 5520	20000	
32-11-00-960-801-02	REPLACEMENT RIGHT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.030 LIFE LIMIT	D22802400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			13-SEP-2012 9012:54 5520	20000	
32-11-00-960-801-02A	REPLACEMENT RIGHT MAIN LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22802400-6 B66 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			13-SEP-2012 9012:54 5520	20000	
32-11-05-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE LEFT MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
32.055	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
32-11-05-780-801-02 (s)	CHECK OF THE CHARGING PRESSURE OF THE RIGHT MAIN LANDING GEAR (MLG) SHOCK ABSORBER								
32.055	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-05-900-801-01	LEFT MAIN LANDING GEAR SHOCK ABSORBER D22805400-3 B66 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSN:9012:54 TSO:0 TSN:5520 TSO:0			13-SEP-2012 9012:54 5520		
32-11-05-900-801-02	RIGHT MAIN LANDING GEAR SHOCK ABSORBER D22806400-3 B66 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSN:9012:54 TSO:0 TSN:5520 TSO:0			13-SEP-2012 9012:54 5520		
32-11-21-900-801-01	LEFT MAIN LANDING GEAR STRUT D22791400-1 B113 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSN:9012:54 TSO:0 TSN:5520 TSO:0			13-SEP-2012 9012:54 5520		
32-11-21-900-801-02	RIGHT MAIN LANDING GEAR STRUT D22792400-1 B111 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSN:9012:54 TSO:0 TSO:0			13-SEP-2012 9012:54 5520		
+ 32-11-25-220-801-01 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA) PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			23-MAR-2000 0 0		
+ 32-11-25-220-801-02 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA) PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-25-220-801-03 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)						PKG		
	PKG 31	MOS	72	+2m			23-MAR-2000		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
+ 32-11-25-220-801-04 (s)	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)						PKG		
	PKG 31	MOS	72	+2m			23-MAR-2000		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
32-12-25-900-801-01	LEFT MAIN LANDING GEAR DOORS ACTUATOR CYLINDER								
	VN1031-2	MOS					23-MAR-2000		
32.060	759	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL					0		
32-12-25-900-801-02	RIGHT MAIN LANDING GEAR DOORS ACTUATOR CYLINDER								
	VN1031-2	MOS					23-MAR-2000		
32.060	760	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL					0		
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS								
		MOS	8	+5d			01-JUN-2018	01-FEB-2019	06-FEB-2019
32.070		HRS/MSC					9855:36		
	REF: See Workcard	AFL	400				5896	6296	
+ 32-21-00-220-801-01	DETAILED INSPECTION NOSE LANDING GEAR LEG								
	D22811400-5-13	MOS	72	+8m			01-JUN-2018	01-JUN-2024	01-FEB-2025
32.080	B69	HRS/MSC					9855:36		
	REF: See Workcard	AFL					5896		
32-21-00-350-801-01	RESTORATION NOSE LANDING GEAR LEG (OVERHAUL)								
	D22811400-5-13	MOS	144	+3%			12-NOV-2012	12-NOV-2024	21-MAR-2025
32.090	B69	HRS/MSC					9013:18		
OVERHAUL	REF: See Workcard	AFL	6000				5521	11521	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-900-801-01	NOSE LANDING GEAR LEG								
32.080	D22811400-5-13 B69 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:70 TSN:9855:12 TSO:842:18 TSN:5895 TSO:375			01-JUN-2018 9855:36 5896		
32-21-00-960-801-01	REPLACEMENT NOSE LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS)								
32.080 LIFE LIMIT	D22811400-5-13 B69 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			12-NOV-2012 9013:18 5521	20001	
32-21-00-960-801-01A	REPLACEMENT NOSE LANDING GEAR LEG (DISCARD OF LIFE LIMITED PARTS) (MANDATORY REF 5-40)								
MANDATORY 5-40	D22811400-5-13 B69 REF: See Workcard	MOS HRS/MSC AFL	20000	TSI:9012:54 TSI:0			12-NOV-2012 9013:18 5521	20001	
+ 32-21-01-780-801-01 (s)	CHECK OF THE CHARGING PRESSURE OF THE NOSE LANDING GEAR (NLG) SHOCK ABSORBER						PKG		
32.095	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
32-21-01-780-802-01	CHECK OF THE CHARGING PRESSURE OF THE NOSE LANDING GEAR (NLG) SHOCK ABSORBER BY APPLYING A ROTATIONAL TORQUE								
32.095	REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
32-21-01-900-801-01	NOSE LANDING GEAR SHOCK ABSORBER								
32.090	D22813400-2-1-4 B71 REF: See Workcard	MOS HRS/MSC AFL	H/T	TSO:3 TSO:0 TSO:0			12-NOV-2012 9013:18 5521		
+ 32-21-09-220-801-01 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH						PKG		
	NLG DRAG BRACE BALL-JOINT BEARING								
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-09-220-801-02 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING						PKG		
	PKG 31	MOS	72	+2m			23-MAR-2000		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
+ 32-21-09-220-801-03 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING						PKG		
	PKG 31	MOS	72	+2m			23-MAR-2000		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
+ 32-21-09-220-801-04 (s)	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING						PKG		
	PKG 31	MOS	72	+2m			23-MAR-2000		
		HRS/MSC					0		
	REF: See Workcard	AFL	3750				0		
32-21-09-900-801-01	NOSE LANDING GEAR DRAG BRACE YOKE ASSEMBLY								
	GA62269	MOS					06-AUG-2012		
32.105	SN-UNKNOWN	HRS/MSC	O/C				9012:54		
	REF: See Workcard	AFL					5520		
32-22-01-350-801-01	RESTORATION NOSE LANDING GEAR DRAG BRACE YOKE ASSEMBLY (OVERHAUL)								
	GA62269	MOS	144	+3%			06-AUG-2012	06-AUG-2024	15-DEC-2024
32.105	SN-UNKNOWN	HRS/MSC					9012:54		
OVERHAUL	REF: See Workcard	AFL	6000				5520	11520	
32-22-01-900-801-01	NOSE LANDING GEAR TELESCOPIC TUBE								
	D23334000-1	MOS					23-MAR-2000		
32.100	B194	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-22-13-900-801-01	NOSE LANDING GEAR ACTUATOR D22795001	MOS					23-MAR-2000		
32.110	B280 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
+ 32-30-00-720-801-01 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS NORMAL OPERATION PKG 21	MOS					PKG 03-JUN-2014		
32.120	REF: See Workcard	HRS/MSC AFL	1600	+40			9560:43 5737		
+ 32-30-00-720-801-02 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS HYDRAULIC EMERGENCY OPERATION PKG 21	MOS					PKG 03-JUN-2014		
32.120	REF: See Workcard	HRS/MSC AFL	1600	+40			9560:43 5737		
+ 32-30-00-720-801-03 (s)	FUNCTIONAL OF EXTENSION/RETRACTION TEST OF LANDING GEARS AND DOORS MECHANICAL EMERGENCY OPERATION PKG 21	MOS					PKG 03-JUN-2014		
32.120	REF: See Workcard	HRS/MSC AFL	1600	+40			9560:43 5737		
32-30-13-900-801-01	NORMAL/EMERGENCY SELECTOR VALVE B94B09-202-1	MOS					23-MAR-2000		
32.200	20446 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
+ 32-31-00-700-801-01 (s)	CHECK OF THE LANDING GEARS RETRACTION INHIBITION ON THE GROUND PKG 21	MOS					PKG 03-JUN-2014		
32.150	REF: See Workcard	HRS/MSC AFL	1600	+40			9560:43 5737		
32-32-00-640-801-01 (s)	LUBRICATION OF THE NOSE LANDING GEAR (NLG) MECHANICAL EMERGENCY RELEASE CONTROL PKG 16	MOS	24	+1m			PKG 08-FEB-2018		
32.140	REF: See Workcard	HRS/MSC AFL					9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-00-640-801-02 (s)	CHECK OF THE NOSE LANDING GEAR (NLG) MECHANICAL EMERGENCY RELEASE CONTROL ACTUATION FORCE PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 08-FEB-2018 9855:36 5896		
32-32-00-640-801-03 (s)	LUBRICATION OF THE MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY RELEASE CONTROLS PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 08-FEB-2018 9855:36 5896		
32-32-00-640-801-04 (s)	CHECK OF THE MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY RELEASE CONTROL ACTUATION FORCE PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 08-FEB-2018 9855:36 5896		
32-32-00-700-801-01	CHECK AFTER LANDING GEAR EMERGENCY EXTENSION 32.710 REF: See Workcard	MOS HRS/MSC AFL APH	A/R				23-MAR-2000 0 0 0		
32-32-05-900-801-01	LH MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY EXTENSION CONTROL CABLE 32.750 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0		
32-32-05-900-801-02	RH MAIN LANDING GEAR (MLG) MECHANICAL EMERGENCY EXTENSION CONTROL CABLE 32.750 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0		
32-32-17-640-801-01 (s)	LUBRICATION OF THE LANDING GEAR (L/G) HYDRAULIC EMERGENCY EXTENSION CONTROL 32.130 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 08-FEB-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-32-17-640-801-02 (s)	CHECK OF LANDING GEAR HYDRAULIC EMERGENCY EXTENSION CONTROL ACTUATION LOADS PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard								
32-32-17-900-801-01	LANDING GEAR EXTENSION FLEXIBLE EMERGENCY CONTROL PN	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32.160	SN-UNKNOWN REF: See Workcard								
+ 32-40-00-780-801-01 (s)	CHECK OF NO.1 SYSTEM BRAKING PRESSURE PKG 22	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
32.290	REF: See Workcard								
+ 32-40-00-780-801-02 (s)	CHECK OF NO.2 SYSTEM BRAKING PRESSURE PKG 22	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
32.290	REF: See Workcard								
+ 32-40-00-780-801-03 (s)	CHECK PARKING BRAKE SYSTEM BRAKING PRESSURES PKG 22	MOS HRS/MSC AFL	3200	+40			PKG 03-JUN-2014 9560:43 5737		
32.290	REF: See Workcard								
32-40-00-780-801-04	CHECK BRAKING PRESSURES AT FULL POWER	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
	REF: See Workcard								
+ 32-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE BRAKE LINKAGE CONTROL PKG 16	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
32.340	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-00-710-802-01 (s)	OPERATIONAL TEST OF THE LEFT MAIN LANDING GEAR (MLG) OUTBOARD WHEEL BLOCKED WHEEL DETECTION PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
	REF: See Workcard								
+ 32-41-00-710-802-02 (s)	OPERATIONAL TEST OF THE LEFT MAIN LANDING GEAR (MLG) INBOARD WHEEL BLOCKED WHEEL DETECTION PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
32.550	REF: See Workcard								
32-41-00-710-802-03 (s)	OPERATIONAL TEST OF THE RIGHT MAIN LANDING GEAR (MLG) OUTBOARD WHEEL BLOCKED WHEEL DETECTION PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
	REF: See Workcard								
+ 32-41-00-710-802-04 (s)	OPERATIONAL TEST OF THE RIGHT MAIN LANDING GEAR (MLG) INBOARD WHEEL BLOCKED WHEEL DETECTION PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
32.720	REF: See Workcard								
32-41-07-610-801-01 (s)	SERVICING OF THE PEDAL INTERCONNECTION FLEXIBLE CONTROLS PKG 31	MOS HRS/MSC AFL	72	+2m			PKG 01-JUN-2018 9855:36 5896		
32.350	REF: See Workcard		3750						
32-41-37-960-801-01 (s)	REPLACEMENT OF THE LEFT MAIN LANDING GEAR (MLG) BRAKING SYSTEM FILTER ELEMENT PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
32.300	REF: See Workcard								
32-41-37-960-801-02 (s)	REPLACEMENT OF THE RIGHT MAIN LANDING GEAR (MLG) BRAKING SYSTEM FILTER ELEMENT PKG 21	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
32.300	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-37-960-801-03	REPLACEMENT OF THE PARKING BRAKE SYSTEM FILTER OF THE PARK BRAKE SELECTOR VALVE UPSTREAM FILTER ELEMENT								
32.305	REF: See Workcard	DAYS HRS/MSC AFL	N/A				0 0		
32-41-37-960-801-04	REPLACEMENT OF THE DOWNSTREAM FILTER OF PARK BRAKE SELECTOR VALVE								
32.730	REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
32-41-49-900-801-01	LEFT INBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.310	C20260000-1 760 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			18-JAN-2005 4750:42 2962		
32-41-49-900-801-02	RIGHT INBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.320	C20260000 197 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-JAN-2008 7268:54 4522		
32-41-49-900-801-03	LEFT OUTBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.310	C20260000 1455 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2007 6526:30 4032		
32-41-49-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR TACHOMETER- GENERATOR								
32.320	C20260000-1 3472 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			09-APR-2013 9269:30 5625		
32-41-49-900-801-05	LEFT NOSE LANDING GEAR TACHOMETER- GENERATOR								
32.330	C20260000-1 1745 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2009 8294:25 5239		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-49-900-801-06	RIGHT NOSE LANDING GEAR TACHOMETER- GENERATOR								
32.330	C20260000-1 1476 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2007 6526:30 4032		
32-42-00-610-801-01	SERVICING OF THE PARK BRAKE CONTROL CABLE								
32.370	REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
+ 32-42-05-720-801-01 (s)	FUNCTIONAL TEST OF THE PARK BRAKE ACCUMULATOR CAPACITY								
32.280	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			PKG 01-JUN-2018 9855:36 5896		
32-42-05-780-801-01	CHECK OF THE PARK BRAKE SYSTEM ACCUMULATOR PRESSURE - PARK BRAKE ACCUMULATOR								
	REF: See Workcard	MOS HRS/MSC AFL	600	+40			01-JUN-2018 9855:36 5896	10455:36	10495:36
32-42-13-900-801-01	PARK BRAKE FLEXIBLE CONTROL								
32.360	4807971 15011 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-44-00-220-801-01	DETAILED INSPECTION OF THE MLG AND NLG WHEEL TIRES								
	REF: See Workcard	MOS HRS/MSC AFL	2	+5d			01-JUN-2018 9855:36 5896	01-AUG-2018	06-AUG-2018
32-44-00-250-801-01	SPECIAL DETAILED INSPECTION LEFT OUTBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLIES								
32.260	C20180400 01946 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			24-APR-2015 9760:57 5832	6232	6244

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-00-250-801-02	SPECIAL DETAILED INSPECTION LEFT INBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLIES								
32.250	C20180400 1948 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			03-OCT-2016 9847:51 5893	6293	6305
32-44-00-250-801-03	SPECIAL DETAILED INSPECTION RIGHT INBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLIES								
32.255	C20180400 1943 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			03-OCT-2016 9847:51 5893	6293	6305
32-44-00-250-801-04	SPECIAL DETAILED INSPECTION RIGHT OUTBOARD MAIN LANDING GEAR WHEEL SUBASSEMBLIES								
32.265	C20180400 02141 REF: See Workcard	MOS HRS/MSC AFL	400	+3%			24-APR-2015 9760:57 5832	6232	6244
32-44-00-250-801-05	SPECIAL DETAILED INSPECTION LEFT NOSE LANDING GEAR WHEEL SUBASSEMBLIES								
32.270	C20182100 983 REF: See Workcard	MOS HRS/MSC AFL	500	+3%			19-SEP-2016 9847:51 5893	6393	6408
32-44-00-250-801-06	SPECIAL DETAILED INSPECTION RIGHT NOSE LANDING GEAR WHEEL SUBASSEMBLIES								
32.275	C20182100 956 REF: See Workcard	MOS HRS/MSC AFL	500	+3%			19-SEP-2016 9847:51 5893	6393	6408
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES								
	REF: See Workcard	MOS HRS/MSC AFL	2	+5d			01-JUN-2018 9855:36 5896	01-AUG-2018	06-AUG-2018
32-44-01-900-801-01	LEFT NOSE LANDING GEAR WHEEL								
32.270	C20182100 983 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSO:90 TSO:1645:58 TSO:714 19-SEP-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-01-900-801-02	RIGHT NOSE LANDING GEAR WHEEL C20182100 956 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:17 TSO:306:40 TSO:131			31-AUG-2010 8508:33 5310		
32-44-05-900-801-01	LEFT NOSE LANDING GEAR TIRE M13301IND02 3074S146 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:32 TSN:287:08 TSN:156			19-SEP-2016 9847:51 5893		
32-44-05-900-801-02	RIGHT NOSE LANDING GEAR TIRE M13301IND02 3073S152 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JAN-2014 9560:43 5737		
32-44-09-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR WHEEL C20180400 01946 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2015 9760:57 5832		
32-44-09-900-801-02	LEFT INBOARD MAIN LANDING GEAR WHEEL C20180400 1948 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-OCT-2016 9847:51 5893		
32-44-09-900-801-03	RIGHT INBOARD MAIN LANDING GEAR WHEEL C20180400 1943 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-OCT-2016 9847:51 5893		
32-44-09-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR WHEEL C20180400 02141 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2015 9760:57 5832		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-13-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR TIRE M06201IND04 4216S098 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-APR-2015 9760:57 5832		
32-44-13-900-801-02	LEFT INBOARD MAIN LANDING GEAR TIRE M06201IND04 5235S112 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:13 TSN:0 TSN:0			03-OCT-2016 9847:51 5893		
32-44-13-900-801-03	RIGHT INBOARD MAIN LANDING GEAR TIRE M06201IND04 5237S131 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:13 TSN:0 TSN:0			03-OCT-2016 9847:51 5893		
32-44-13-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR TIRE M06201IND04 4220S106 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-APR-2015 9760:57 5832		
32-44-17-350-801-01	RESTORATION LEFT OUTBOARD MAIN LANDING GEAR BRAKE (OVERHAUL) C20181100-8 F884 REF: See Workcard	MOS HRS/MSC AFL	A/R				18-JUN-2008 7649:36 4769		
32-44-17-350-801-02	RESTORATION LEFT INBOARD MAIN LANDING GEAR BRAKE (OVERHAUL) C20181100-8 1262 REF: See Workcard	MOS HRS/MSC AFL	A/R				18-JUN-2008 7649:36 4769		
32-44-17-350-801-03	RESTORATION RIGHT INBOARD MAIN LANDING GEAR BRAKE (OVERHAUL) C20181100-8 F852 REF: See Workcard	MOS HRS/MSC AFL	A/R				18-JUN-2008 7649:36 4769		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-17-350-801-04	RESTORATION RIGHT OUTBOARD MAIN LANDING GEAR BRAKE (OVERHAUL)								
32.390	C20181100-8 F894 REF: See Workcard	MOS HRS/MSC AFL	A/R				29-AUG-2008 7831:42 4913		
32-44-17-900-801-01	LEFT OUTBOARD MAIN LANDING GEAR BRAKE								
32.380	C20181100-8 F884 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-JUN-2008 7649:36 4769		
32-44-17-900-801-02	LEFT INBOARD MAIN LANDING GEAR BRAKE								
32.380	C20181100-8 1262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JUN-2008 7649:36 4769		
32-44-17-900-801-03	RIGHT INBOARD MAIN LANDING GEAR BRAKE								
32.390	C20181100-8 F852 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-JUN-2008 7649:36 4769		
32-44-17-900-801-04	RIGHT OUTBOARD MAIN LANDING GEAR BRAKE								
32.390	C20181100-8 F894 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			03-SEP-2008 7835:54 4917		
32-44-18-960-801-01	REPLACEMENT LEFT OUTBOARD MAIN LANDING GEAR BRAKE SEALS								
32.400	C20181100-8 F884 REF: See Workcard	MOS HRS/MSC AFL	C/C				18-JUN-2008 7649:36 4769		
32-44-18-960-801-02	REPLACEMENT LEFT INBOARD MAIN LANDING GEAR BRAKE SEALS								
32.400	C20181100-8 1262 REF: See Workcard	MOS HRS/MSC AFL	C/C				18-JUN-2008 7649:36 4769		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-18-960-801-03	REPLACEMENT RIGHT INBOARD MAIN LANDING GEAR BRAKE SEALS C20181100-8 F852 REF: See Workcard	MOS HRS/MSC AFL	C/C				18-JUN-2008 7649:36 4769		
32-44-18-960-801-04	REPLACEMENT RIGHT OUTBOARD MAIN LANDING GEAR BRAKE SEALS C20181100-8 F894 REF: See Workcard	MOS HRS/MSC AFL	C/C				03-SEP-2008 7835:54 4917		
32-50-01-900-801-01	NOSE WHEEL STEERING REPEATER BOX PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-50-05-900-801-01	STEERING HYDRAULIC UNIT C24248003-1 U428 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			15-SEP-2016 9847:51 5893		
32-50-13-900-801-01	STEERING SERVOVALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-01	LH MLG BRACE ACTUATOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-02	LH MLG BRACE ACTUATOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-03	RH MLG BRACE ACTUATOR PROXIMITY SENSOR								
32.630	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-04	RH MLG BRACE ACTUATOR PROXIMITY SWITCH								
32.630	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-05	LH MLG UPLOCK BOX PROXIMITY SWITCH								
32.640	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-06	RH MLG UPLOCK BOX PROXIMITY SWITCH								
32.640	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-07	NLG UPLOCK BOX PROXIMITY SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-08	NLG UPLOCK BOX PROXIMITY SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-09	LH UPLOCK BOX PROXIMITY SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-10	LH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-11	RH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-12	RH UPLOCK BOX PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-13	LH MLG LEG OUTBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-14	LH MLG LEG INBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-15	RH MLG LEG OUTBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-16	RH MLG LEG INBOARD PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-49-900-801-17	NLG DRAG BRACE LH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-18	NLG DRAG BRACE RH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-19	NLG LEG LH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-20	NLG LEG RH PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-21	NLG LH DOOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
32-61-49-900-801-22	NLG RH DOOR PROXIMITY SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
322801 32.115	NOSE LANDING GEAR STRUT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSO:3 TSO:0 TSO:0			12-NOV-2012 9013:18 5521		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323801	NOSE LANDING GEAR LEG UPLOCK								
32.170	C24245006-3 U260 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-AUG-2009 8246 5216		
323811	NOSE LANDING GEAR TELESCOPIC STRUT UNLOCKING RESTRICTOR VALVE								
32.180	A24508-5180 H2315 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
323816	NOSE LANDING GEAR UNLOCKING GEAR RESTRICTOR VALVE								
32.180	A24508-5090 H2460 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
323821	LEFT MAIN LANDING GEAR LEG UPLOCK								
32.190	C24244007-2 H0682 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
323826	RIGHT MAIN LANDING GEAR LEG UPLOCK								
32.190	C24245007-2 H1348 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
323836	GEAR/DOOR CONTROL UNIT								
32.210	BHC1031-2 386 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
323841	LEFT MAIN LANDING GEAR DOOR MAIN UPLOCK								
32.220	C24257002-1 H1604 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:8			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323846	RIGHT MAIN LANDING GEAR DOOR MAIN UPLOCK C24257002-1	MOS					18-AUG-2000		
32.220	H1605 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:8			23 8		
323851	LEFT MAIN GEAR EXTENSION ACTUATOR GEAR RESTRICTOR VALVE A24508-5220	MOS					23-MAR-2000		
32.230	H2527 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323856	RIGHT MAIN GEAR EXTENSION ACTUATOR GEAR RESTRICTOR VALVE A24508-5220	MOS					23-MAR-2000		
32.230	H2526 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323861	NORMAL/EMERGENCY SELECTOR VALVE CHECK VALVE C24816000	MOS					23-MAR-2000		
32.240	609 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
323A03	SWIVEL UPLOCK NLG FITTING C24266	MOS					23-MAR-2000		
	H0929 REF:	HRS/MSC AFL	O/C	TSN:0			0 0		
324801	NORMAL/EMERGENCY BRAKE DISTRIBUTOR 57530-25	MOS		TSO:8			01-SEP-2010		
32.420	0027 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSO:0			8508:33 5310		
324803	BRAKE PARKING DISTRIBUTOR 70012-1	MOS					23-MAR-2000		
32.430	409 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324811	NORMAL BRAKE ELECTRIC DISTRIBUTOR								
32.440	65660-1 457A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324813	EMERGENCY BRAKE ELECTRIC DISTRIBUTOR								
32.440	65670-1 2719AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324816	PARKING BRAKE ACCUMULATOR OVERPRESSURE VALVE								
32.450	D25AB1310 286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324826	PARKING BRAKE ACCUMULATOR CHECK VALVE								
32.460	A24515 FM02691 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324831	PARKING BRAKE ACCUMULATOR								
32.470	60967-1 EFS0254 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324836	LEFT BRAKE NORMAL SYSTEM PRESSURE SWITCH								
32.480	7G1090 289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324841	RIGHT BRAKE NORMAL SYSTEM PRESSURE SWITCH								
32.480	7G1090 271 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324843	LEFT BRAKE EMERGENCY SYSTEM PRESSURE SWITCH 7G1108	MOS					23-MAR-2000		
32.490	368 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324846	RIGHT BRAKE EMERGENCY SYSTEM PRESSURE SWITCH 7G1108	MOS					23-MAR-2000		
32.490	262 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324851	PARKING BRAKE PRESSURE SWITCH 95G51	MOS					01-JUL-2015		
32.500	560 REF: See Workcard	HRS/MSC AFL	O/C	TSN:28 TSN:0 TSN:0					
324856	ANTI-SKID REGULATION UNIT C20188102-1	MOS					30-SEP-2009		
32.510	H0272 REF: GENERIC NO REF	HRS/MSC AFL	O/C				8273:54 5233		
324861	LEFT NORMAL BRAKING SERVOVALVE C20103300	MOS					23-MAR-2000		
32.520	565 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324863	RIGHT NORMAL BRAKING SERVOVALVE C20103300	MOS					23-MAR-2000		
32.520	566 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
324866	LEFT BRAKING SYSTEM FILTER ADB295-4	MOS					23-MAR-2000		
32.530	0921 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324871	RIGHT BRAKING SYSTEM FILTER								
32.530	ADB295-4 0912 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324876	PARKING BRAKE SYSTEM FILTER								
32.305	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
324881	LEFT BRAKE NORMAL RESTRICTOR VALVE								
32.540	C24758140 H0665 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324886	RIGHT BRAKE NORMAL RESTRICTOR VALVE								
32.540	C24758140 H0664 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324A01	SHUTL BRK EMR/PRK L VALVE								
	CN100 853 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
324A02	SHUTL BRK EMR/PRK R VALVE								
	CN100 854 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
325801	STEERING SLIDING DISTRIBUTOR VALVE								
32.590	C24166-1 H0620 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325806	STEERING CONTROL BOX								
32.600	287837-1 H1121 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
325811	STEERING AMPLIFIER								
32.610	C24242010 H0582 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:9012:54			11-SEP-2012 9012:54 5520		
325816	STEERING SOLENOID SELECTOR VALVE								
32.700	65670-1 4625AB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-SEP-2016 9847:51 5893		
CHAPTER 33 LIGHTS									
33-20-00-200-801-01	INSPECTION "ALC" LIGHTING TUBES								
33.200	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
33-40-37-900-801-01	LEFT LANDING LIGHT								
33.100	4240531 74779 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
33-40-37-900-801-02	RIGHT LANDING LIGHT								
33.100	4240531 76080 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-SEP-2012 9012:54 5520		
33-40-41-900-801-01	TAXI LIGHT								
33.110	01-0790589-00 00212 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			17-APR-2013 9281:02 5629		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-40-41-960-801-01	REPLACEMENT TAXI LIGHT BULB 01-0790589-00 00212 REF:	MOS HRS/MSC AFL	O/C				17-APR-2013 9281:02 5629		
+ 33-50-00-710-804-01 (s)	OPERATIONAL TEST OF THE EMERGENCY LIGHTING SYSTEM - EMERGENCY LIGHTING SYSTEM PKG 23 REF: See Workcard	MOS HRS/MSC AFL	4800	+40			PKG 23-MAR-2000 0 0		
+ 33-50-00-720-801-01	FUNCTIONAL TEST NO. 1 EMERGENCY LIGHTING (EPS1) POWER SUPPLY SYSTEM D734-02-001 2793/07-2006 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
+ 33-50-00-720-801-02	FUNCTIONAL TEST NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY SYSTEM D734-02-001 2993/04-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
+ 33-50-00-720-801-03	FUNCTIONAL TEST NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY SYSTEM D734-02-001 3150/11-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-FEB-2017 9847:51 5893		
33-50-33-610-801-01	SERVICING NO. 1 EMERGENCY LIGHTING (EPS1) POWER SUPPLY D734-02-001 2793/07-2006 REF: See Workcard	MOS HRS/MSC AFL	O/C						
33-50-33-610-801-02	SERVICING NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY D734-02-001 2993/04-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-33-610-801-03	SERVICING NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
33.190	D734-02-001 3150/11-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C						
33-50-33-900-801-01	NO. 1 EMERGENCY LIGHTING (EPS1) POWER SUPPLY								
33.180	D734-02-001 2793/07-2006 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-OCT-2017 9850:07 5894		
33-50-33-900-801-02	NO. 2 EMERGENCY LIGHTING (EPS 2) POWER SUPPLY								
33.180	D734-02-001 2993/04-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-OCT-2017 9850:07 5894		
33-50-33-900-801-03	NO. 3 EMERGENCY LIGHTING (EPS 3) POWER SUPPLY								
33.190	D734-02-001 3150/11-2007 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-AUG-2016 9847:51 5893		
33-50-37-900-801-01	NO. 1 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	C734-01-030 CF26443/21/16 REF:	MOS HRS/MSC AFL	O/C	TSN:11 TSN:0 TSN:0			24-OCT-2017 9850:07 5894		
33-50-37-900-801-02	NO. 2 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	C734-01-030 CF26678/25/16 REF:	MOS HRS/MSC AFL	O/C	TSN:6 TSN:0 TSN:0			24-OCT-2017 9850:07 5894		
33-50-37-900-801-03	NO. 3 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE)								
	D734-02-001 3819145 REF:	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-50-37-900-801-04	NO. 4 EMERGENCY POWER SUPPLY (EPS) BATTERY PACK (PAGE) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
33-50-37-960-802-01	DISCARD PACK BATTERY PACK C734-01-030 CF26443/21/16 REF: See Workcard	MOS HRS/MSC AFL	25				24-OCT-2017 9850:07 5894	24-NOV-2019	
33-50-37-960-802-02	DISCARD PACK BATTERY PACK C734-01-030 CF26678/25/16 REF: See Workcard	MOS HRS/MSC AFL	25				24-OCT-2017 9850:07 5894	24-NOV-2019	
33-50-37-960-802-03	DISCARD PACK BATTERY PACK D734-02-001 3819145 REF: See Workcard	MOS HRS/MSC AFL	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
331801	PILOT DIMMER BOX 24-01 18013 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
331806	COPILOT DIMMER BOX 24-01 18011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
331811	PILOT FLUORESCENT GLARESHIELD TUBE 997EL01Y00 236 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:13 TSN:0 TSN:0			05-APR-2013 9269:30 5625		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331816	COPILOT FLUORESCENT GLARESHIELD TUBE								
33.020	992EL01Y00 223 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:13 TSN:0 TSN:0			05-APR-2013 9269:30 5625		
331821	LEFT FLUORESCENT STRIP TUBE								
33.030	982EL01Y00 251 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:18 TSN:0 TSN:0			05-APR-2013 9269:30 5625		
331826	CENTER FLUORESCENT STRIP TUBE								
33.030	972EL01Y00 316 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:18 TSN:0 TSN:0			05-APR-2013 9269:30 5625		
331831	RIGHT FLUORESCENT STRIP TUBE								
33.030	987EL01Y00 240 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:5 TSN:0 TSN:0			05-APR-2013 9269:30 5625		
331836	GLARESHIELD/STRIP POWER SUPPLY								
33.040	480ZT01Y01 311 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
331841	PILOT LIGHTING INSTRUMENT TRANSFORMER								
33.050	96PS002 495 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
331846	COPILOT LIGHTING INSTRUMENT TRANSFORMER								
33.050	96PS002 497 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334801	VERTICAL STABILIZER ANTI-COLLISION LIGHT 01-0790044-09	MOS					23-MAR-2000		
33.060	1983 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
334803	REAR STROBE/NAVIGATION LIGHT 6480651	MOS		TSN:0			28-MAY-2014		
33.070	150 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			9560:43 5737		
334806	VERTICAL STABILIZER ANTI-COLLISION POWER SUPPLY 39-42-4	MOS		TSN:0			04-JUN-2008		
33.080	2070 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			7619:54 4745		
334811	FUSELAGE ANTI-COLLISION POWER SUPPLY 39-42-2-3	MOS					23-MAR-2000		
33.090	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
334823	LEFT WING STROBE LIGHT 39-28-21	MOS					23-MAR-2000		
33.120	1427 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
334826	RIGHT WING STROBE LIGHT 39-28-21	MOS					23-MAR-2000		
33.120	1428 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
334828	LEFT WING STROBE POWER SUPPLY 39-42-1	MOS		TSR:0			15-OCT-2004		
33.130	372 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSR:0 TSR:0			4493:30 2784		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334831	RIGHT WING STROBE POWER SUPPLY								
33.130	39-42-3 2069 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-JUN-2008 7616:54 4745		
334833	FUSELAGE LOW POWER SUPPLY								
33.140	39-44-31 731 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				04-AUG-2009 8246 5216		
334836	FUSELAGE ANTI-COLLISION LIGHT								
33.150	39-59-2 636 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-JUL-2003 3099:06 1918		
334841	LEFT WING ICE DETECTION LIGHT								
33.160	4371567 46 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
334842	RIGHT WING ICE DETECTION LIGHT								
33.160	4371574 46 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

CHAPTER 34	NAVIGATION								
+ 34-01-00-720-801-01 (s)	FUNCTIONAL TEST OF THE EFIS SYSTEM						PKG		
34.010	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	24 1600	+1m +40			01-JUN-2018 9855:36 5896		
+ 34-01-00-720-801-01A	FUNCTIONAL TEST OF THE EFIS SYSTEM (MANDATORY REF. 5-40-20)								
34.010 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	2000				01-JUN-2018 9855:36 5896	11855:36	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-01-13-900-801-01	PILOT PFD DISPLAY SCREEN 7014300-901 00036440 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-OCT-2012 9013:18 5521		
34-01-13-900-801-02	PILOT MFD DISPLAY SCREEN 7014300-901 97031995 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:3 TSR:0 TSR:0		22-OCT-2015 9780:43 5843		
34-01-13-900-801-03	COPILOT MFD DISPLAY SCREEN 7014300-901 99064922 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
34-01-13-900-801-04	COPILOT PFD DISPLAY SCREEN 7014300-901 99095430 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:4 TSR:0 TSR:0		22-OCT-2015 9780:43 5843		
+ 34-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE AIR DATA SYSTEM PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
34-10-01-900-801-01	REMOVAL / INSTALLATION OF THE OUTSIDE AIR TEMPERATURE PROBE - OUTSIDE AIR TEMPERATURE PROBE (52FL) 102AU1CK A63797 REF: AMM 34-10-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		19-APR-2006 5778:48 3578		
+ 34-10-11-720-801-01 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF LEFT ANGLE-OF-ATTACK SENSOR PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-10-11-720-801-02 (s)	CHECK OF THE ELECTRICAL ZERO SETTING OF RIGHT ANGLE-OF-ATTACK SENSOR						PKG		
27.485	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			01-JUN-2018 9855:36 5896		
34-10-11-900-801-01	LEFT ANGLE-OF-ATTACK SENSOR								
27.500	861CAU2 0439A REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUL-2012 9012:54 5520		
34-10-11-900-801-02	RIGHT ANGLE-OF-ATTACK SENSOR								
27.500	861CAU2 0513A REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		17-JUL-2007 6869:06 4241		
34-11-00-680-801-01 (s)	DRAINING OF THE TOTAL / STATIC PRESSURE SYSTEM - AIR DATA SYSTEM						PKG		
	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
34-11-00-790-801-01	LEAK TEST STATIC PRESSURE SYSTEM								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2017 9849:54 5894		
34-11-00-790-801-02	LEAK TEST TOTAL PRESSURE SYSTEM								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2017 9849:54 5894		
34-11-00-790-801-03	LEAK TEST STATIC PRESSURE SYSTEM								
	REF: See Workcard	MOS HRS/MSC AFL	O/C				20-JUN-2017 9849:54 5894		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-790-801-04	LEAK TEST TOTAL PRESSURE SYSTEM	MOS					20-JUN-2017		
	REF: See Workcard	HRS/MSC	O/C				9849:54		
		AFL					5894		
34-11-00-790-801-05	LEAK TEST STATIC PRESSURE SYSTEM	MOS					20-JUN-2017		
	REF:	HRS/MSC	O/C				9849:54		
		AFL					5894		
34-11-00-790-801-06	LEAK TEST TOTAL PRESSURE SYTEM	MOS					20-JUN-2017		
	REF:	HRS/MSC	O/C				9849:54		
		AFL					5894		
+ 34-11-01-200-801-01	CHECK OF THE LEFT TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					01-JUN-2018		
34.090	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
+ 34-11-01-200-801-02	CHECK OF THE RIGHT TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					01-JUN-2018		
34.550	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
+ 34-11-01-200-801-03	CHECK OF STAND-BY TOTAL PRESSURE PROBE DRAIN HOLES FOR CLOGGING	MOS					01-JUN-2018		
34.090	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
34-11-05-900-801-01	LEFT STATIC PRESSURE PROBE	MOS					10-NOV-2016		
34.120	C16757AA	HRS/MSC	O/C	TSN:4			9847:51		
	765	AFL		TSN:0			5893		
	REF: See Workcard			TSN:0					

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-05-900-801-02	RIGHT STATIC PRESSURE PROBE								
34.120	C16757AA 755 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			10-NOV-2016 9847:51 5893		
+ 34-14-01-700-881-01	TEST PILOT DIGITAL AIR DATA COMPUTER (FAR 91.411)								
34.050 MANDATORY	7014700-629 97101481 REF: FAR 91.411	MOS HRS/MSC AFL	24				20-JUN-2017	20-JUN-2019	
+ 34-14-01-700-881-02	TEST COPILOT DIGITAL AIR DATA COMPUTER (FAR 91.411)								
34.060 MANDATORY	7014700-629 96070899 REF: FAR 91.411	MOS HRS/MSC AFL	24				20-JUN-2017	20-JUN-2019	
34-14-01-900-801-01	PILOT DIGITAL AIR DATA COMPUTER								
34.050	7014700-629 97101481 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:20 TSR:993:09 TSR:708			23-SEP-2009 8257:15 5224		
34-14-01-900-801-02	COPILOT DIGITAL AIR DATA COMPUTER								
34.060	7014700-629 96070899 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-SEP-2009 8257:15 5224		
+ 34-16-00-720-801-01	FUNCTIONAL TEST PILOT DIGITAL AIR DATA COMPUTER								
34.050	7014700-629 97101481 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019
+ 34-16-00-720-801-02	FUNCTIONAL TEST COPILOT DIGITAL AIR DATA COMPUTER								
34.060	7014700-629 96070899 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-16-00-720-801-03	FUNCTIONAL TEST PILOT STAND-BY ALTIMETER								
34.070	64141-530-1 01 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019
+ 34-16-00-720-801-04	FUNCTIONAL TEST STAND-BY MACH-AIRSPEED INDICATOR								
34.080	64032-229-1 1708 REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019
+ 34-18-01-700-881-01	TEST STATIC PRESSURE SYSTEM (FAR 91.411)								
34.100 MANDATORY	REF: FAR 91.411	MOS HRS/MSC AFL	24				20-JUN-2017 9849:54 5894	20-JUN-2019	
+ 34-18-41-700-881-01	TEST PILOT STAND-BY ALTIMETER (FAR 91.411)								
34.070 MANDATORY	64141-530-1 01 REF: FAR 91.411	MOS HRS/MSC AFL	24				20-JUN-2017	20-JUN-2019	
+ 34-21-00-710-801-01 (s)	OPERATIONAL TEST OF THE NO. 1 INERTIAL REFERENCE UNIT								
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG		
+ 34-21-00-710-801-02 (s)	OPERATIONAL TEST OF THE NO. 2 INERTIAL REFERENCE UNIT								
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			26-JUN-2012 9012:54 5520		
+ 34-21-00-710-801-03 (s)	OPERATIONAL TEST OF THE NO. 3 INERTIAL REFERENCE UNIT								
	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			26-JUN-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-21-13-100-801-01 (s)	CLEANING/REPLACEMENT OF THE NO.1 INERTIAL REFERENCE UNIT (IRU1) FAN FILTER						PKG		
34.140	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200				01-JUN-2018 9855:36 5896		
34-21-13-100-801-02 (s)	CLEANING/REPLACEMENT OF THE NO.2 INERTIAL REFERENCE UNIT (IRU2) FAN FILTER						PKG		
34.140	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			01-JUN-2018 9855:36 5896		
34-21-13-100-801-03 (s)	CLEANING/REPLACEMENT OF THE NO.3 INERTIAL REFERENCE UNIT (IRU3) FAN FILTER						PKG		
34.140	PKG 22 REF: See Workcard	MOS HRS/MSC AFL	3200	+40			01-JUN-2018 9855:36 5896		
34-25-00-820-801-01	COMPENSATION STAND-BY COMPASS								
	WL1001KCA1 AL388 REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
34-31-00-710-801-01	OPERATIONAL TEST OF THE HEAD-UP GUIDANCE SYSTEM (HGS)								
34.540	REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
34-31-01-900-801-01	HEAD-UP GUIDANCE SUSTEM (HGS) OVERHEAD UNIT								
	PN SN-UNKNOWN REF: AMM 34-31-01-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0		
34-31-05-900-801-01	HEAD-UP GUIDANCE (HGS) COMBINER								
	PN SN-UNKNOWN REF: AMM 34-31-05-900-801	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-31-09-900-801-01	HEAD-UP GUIDANCE SYSTEM (HGS) COMPUTER PN SN-UNKNOWN REF: AMM 34-31-09-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
34-31-17-900-801-01	HGS CONTROL PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
34-41-01-900-801-01 34.270	WEATHER RADAR 7021450-801 07057493 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:3 TSR:0 TSR:0			02-MAR-2010		
+ 34-42-01-820-801-01 34.280	CALIBRATION NO. 1 RADIO-ALTIMETER RECEIVER / TRANSMITTER WITH CABLE 7001840-932 91104676 REF: See Workcard	MOS HRS/MSC AFL	O/C				17-DEC-2010		
+ 34-42-01-820-801-02 34.280	CALIBRATION NO. 2 RADIO-ALTIMETER RECEIVER / TRANSMITTER WITH CABLE 7001840-932 0304A793 REF: See Workcard	MOS HRS/MSC AFL	O/C				17-DEC-2010		
34-42-01-820-801-03	CALIBRATION NO. 1 RADIO-ALTIMETER RECEIVER / TRANSMITTER WITHOUT CABLE 7001840-932 91104676 REF: See Workcard	MOS HRS/MSC AFL	O/C						
34-42-01-820-801-04	CALIBRATION NO. 2 RADIO-ALTIMETER RECEIVER / TRANSMITTER WITHOUT CABLE 7001840-932 0304A793 REF: See Workcard	MOS HRS/MSC AFL	O/C						

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-42-01-900-801-01	NO. 1 RADIO-ALTIMETER RECEIVER / TRANSMITTER 7001840-932 91104676 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-SEP-2014 9628:50 5770		
34-42-01-900-801-02	NO. 2 RADIO-ALTIMETER RECEIVER / TRANSMITTER 7001840-932 0304A793 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-SEP-2014 9628:50 5770		
34-44-01-900-801-01	TCAS TRANSCEIVER 622-8971-122 7972 REF: See Workcard	DAYS HRS/MSC AFL	O/C	TSN:431:54 TSN:282			09-FEB-2001 454:54 290		
+ 34-51-01-820-801-01	CALIBRATION NO. 1 VOR/ILS/MARKER RECEIVER 622-7194-201 1FNA REF: See Workcard	MOS HRS/MSC AFL	O/C						
+ 34-51-01-820-801-02	CALIBRATION NO. 2 VOR/ILS/MARKER RECEIVER 622-7194-201 1ATC REF: See Workcard	MOS HRS/MSC AFL	O/C						
34-51-05-900-801-01	NO. 1 VOR/LOC ANTENNA DMN4-45-3 12524 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-2012 8911:19 5476		
34-51-05-900-801-02	NO. 2 VOR/LOC ANTENNA DMN4-45-3 7440 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-51-60-200-881-01 (s)	INSPECT GLSSU WIRING (ADS-B OUT) PKG 21,31 REF:	MOS HRS/MSC AFL	72 1600 3750				PKG 23-MAR-2000 0 0		
+ 34-51-60-200-881-02 (s)	INSPECT GLSSU EQUIPMENT (ADS-B OUT) PKG 21,31 REF:	MOS HRS/MSC AFL	72 1600 3750				PKG 23-MAR-2000 0 0		
+ 34-51-60-200-881-03 (s)	INSPECT GLSSU ANTENNAS (ADS-B OUT) PKG 21,31 REF:	MOS HRS/MSC AFL	72 1600 3750				PKG 23-MAR-2000 0 0		
+ 34-54-00-700-881-01 34.300 MANDATORY	TEST NO. 1 ATC TRANSPONDER (FAR 91.413) 622-9210-008 2LBXV REF: FAR 91.413	MOS HRS/MSC AFL	24				20-JUN-2017	20-JUN-2019	
+ 34-54-00-700-881-02 34.300 MANDATORY	TEST NO. 2 ATC TRANSPONDER (FAR 91.413) 622-9210-008 30NIN REF: FAR 91.413	MOS HRS/MSC AFL	24				20-JUN-2017	20-JUN-2019	
+ 34-54-00-720-802-01 34.300 RVSM	FUNCTIONAL TEST NO. 1 ATC TRANSPONDER 622-9210-008 2LBXV REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019
+ 34-54-00-720-802-02 34.300 RVSM	FUNCTIONAL TEST NO. 2 ATC TRANSPONDER 622-9210-008 30NIN REF: See Workcard	MOS HRS/MSC AFL	24	+3%			20-JUN-2017 9849:54 5894	20-JUN-2019	11-JUL-2019

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-58-01-710-881-01	CHECK VOR EQUIPMENT FOR IFR OPERATIONS (FAR 91.171)								
34.390		DAYS	30				01-JUN-2018	01-JUL-2018	
MANDATORY	REF: FAR 91.171	HRS/MSC					9855:36		
		AFL					5896		
+ 34-61-00-200-881-01 (s)	INSPECT FMS WIRING (ADS-B OUT)						PKG		
	PKG 21,31	MOS	72				23-MAR-2000		
	REF:	HRS/MSC	1600				0		
		AFL	3750				0		
+ 34-61-00-200-881-02 (s)	INSPECT FMS EQUIPMENT (ADS-B OUT)						PKG		
	PKG 21,31	MOS	72				23-MAR-2000		
	REF:	HRS/MSC	1600				0		
		AFL	3750				0		
+ 34-61-00-710-801-01	OPERATIONAL TEST OF NO.1 FLIGHT MANAGEMENT SYSTEMS (FMS1)								
34.530		MOS					01-JUN-2018		
	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
+ 34-61-00-710-801-02	OPERATIONAL TEST OF NO.2 FLIGHT MANAGEMENT SYSTEMS (FMS2)								
34.530		MOS					01-JUN-2018		
	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
+ 34-61-00-710-801-03	OPERATIONAL TEST OF NO.3 FLIGHT MANAGEMENT SYSTEMS (FMS3)								
34.530		MOS					01-JUN-2018		
	REF: See Workcard	HRS/MSC	O/C				9855:36		
		AFL					5896		
34-90-10-900-801-01	CONTROL DISPLAY UNIT (CDU) (GNS-XLS BATTERY ONLY) BATTERY								
	PN	MOS		TSN:0			23-MAR-2000		
	NOT INSTALLED	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC CMM	AFL		TSN:0			0		
		APH		TSN:0			0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-90-10-960-801-01S	REPLACEMENT CONTROL DISPLAY UNIT (CDU) (GNS-XLS BATTERY ONLY) BATTERY PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
340A10	BEZEL PFD PILOT CONTROL 7014332-831 99052810 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
340A11	BEZEL MFD PILOT CONTROL 7014332-961 99052793 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
340A12	BEZEL PFD COPILOT CONTROL 7014332-831 99062834 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
340A13	BEZEL MFD COPILOT CONTROL 7014332-961 99052795 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
341801	LEFT PITOT PRESSURE TOTAL PROBE 50520 4277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JAN-2012 8911:19 5476		
341806	RIGHT PITOT PRESSURE TOTAL PROBE 50520 4251 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JAN-2012 8911:19 5476		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341811	STAND-BY PITOT PRESSURE TOTAL PROBE								
34.110	50520 4250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JAN-2012 8911:19 5476		
341831	PILOT STAND-BY ALTIMETER								
34.070	64141-530-1 01 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0			24-JUL-2015 9765:57 5832		
341836	STAND-BY MACH-AIRSPEED INDICATOR								
34.080	64032-229-1 1708 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:8242:15			21-SEP-2009 8257:15 5224		
342801	STAND-BY COMPASS								
34.180	WL1001KCA1 AL388 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
342811	LEFT DATA ACQUISITION UNIT								
34.190	7013348-926 01114812 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-DEC-2014 9708:47 5806		
342812	RIGHT DATA ACQUISITION UNIT								
34.190	7013348-926 01013999 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				14-JUN-2001 828 526		
342821	NO. 1 AVIONIC INTEGRATED COMPUTER								
34.200	7017300-41124 96070671 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-SEP-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342822	NO. 2 AVIONIC INTEGRATED COMPUTER								
34.200	7017300-41124 01102718 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-NOV-2013 9448:25 5701		
342823	NO. 3 AVIONIC INTEGRATED COMPUTER								
34.200	7017300-45124 98061112 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-APR-2016 9805:22 5878		
342831	PILOT CONTROL DISPLAY UNIT								
34.210	7007549-905 94021512 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-DEC-2004 4681:30 2908		
342832	COPILOT CONTROL DISPLAY UNIT								
34.210	7007549-905 96092166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-JUL-2016 9814:30 5883		
342836	STAND-BY HORIZON								
34.220	501-1197-25 5561 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:2 TSO:0 TSO:0			24-MAY-2010 8412:34 5274		
342851	PILOT CONTROL DISPLAY PANEL								
34.230	7016683-931 99070685 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
342852	COPILOT CONTROL DISPLAY PANEL								
34.230	7016683-931 99080689 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342861	PILOT REVERSIONARY CONTROL								
34.240	7007280-903 99060649 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
342862	COPILOT REVERSIONARY CONTROL								
34.240	7007280-903 99060650 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
342A11	CONTROL #3 DISPLAY UNIT								
	7007549-905 95091843 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-SEP-2012 9012:54 5520		
343801	NO. 1 RADIO-ALTIMETER TRANSMITTER ANTENNA								
34.250	S67-2002-13 545-5697 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-SEP-2014 9628:50 5770		
343806	NO. 1 RADIO-ALTIMETER RECEPTION ANTENNA								
34.250	S67-2002-13 1218 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
343811	NO. 2 RADIO-ALTIMETER TRANSMITTER ANTENNA								
34.260	S67-2002-13 545-5698 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-SEP-2014 9628:50 5770		
343816	NO. 2 RADIO-ALTIMETER RECEPTION ANTENNA								
34.260	S67-2002-13 1551 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344801	NO. 1 INERTIAL REFERENCE UNIT HG2001GD03 56013914 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-OCT-2013 9431:48 5694		
344802	NO. 2 INERTIAL REFERENCE UNIT HG2001GD03 99061817 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344803	NO. 3 INERTIAL REFERENCE UNIT HG2001GD03 00033164 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
344806	NO. 1 IRS MODE SELECTOR UNIT CG1042AB03 01073440 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-AUG-2009 8246 5216		
344807	NO. 2 IRS MODE SELECTOR UNIT CG1042AB03 00043009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-AUG-2009 8246 5216		
344808	NO. 3 IRS MODE SELECTOR UNIT CG1042AB03 00043009 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
344816	NO. 1 ATC TRANSPONDER 622-9210-008 2LBXV REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-SEP-2011 8792:22		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344817	NO. 2 ATC TRANSPONDER 622-9210-008 30NIN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-JUN-2017 9849:54 5894		
344821	TCAS LOWER ANTENNA 622-8973-001 43YMJ REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-FEB-2012 8911:19 5476		
344822	TCAS UPPER ANTENNA 622-8973-001 27504 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344823	NO. 1 TCAS CONTROL BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344824	PILOT TCAS VSI PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344825	COPILOT TCAS VSI PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344826	NO. 1 ATC LOWER ANTENNA DMNI50-2-2 71863 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344827	NO. 1 ATC UPPER ANTENNA DMNI50-2-2 71876 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344828	NO. 2 ATC LOWER ANTENNA DMNI50-2-2 69286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344829	NO. 2 ATC UPPER ANTENNA DMNI50-2-2 71831 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344830	NO. 2 TCAS CONTROL BOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344831	NO. 1 WEATHER RADAR CONTROL 7008471-417 99054012 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
344832	NO. 2 WEATHER RADAR CONTROL 7008471-417 00044715 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
345801	NO. 1 ADF RECEIVER 622-7382-101 6101 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345802	NO. 2 ADF RECEIVER								
34.410	622-7382-101 6065 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345806	NO. 1 ADF LOOP ANTENNA								
34.420	622-7383-001 44PPLD REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-SEP-2016 9847:51 5893		
345807	NO. 2 ADF LOOP ANTENNA								
34.420	622-7383-001 44PV72 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-SEP-2016 9847:51 5893		
345811	NO. 1 VOR/ILS/MARKER RECEIVER								
34.400	622-7194-201 1FNA REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345812	NO. 2 VOR/ILS/MARKER RECEIVER								
34.400	622-7194-201 1ATC REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345816	MARKER ANTENNA								
34.430	S35-1000-1 4388 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345818	GLIDE SLOPE ANTENNA								
34.430	DMN25-2 4585 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345821	NO. 1 DME TRANSCEIVER 622-7309-101 5221 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345822	NO. 2 DME TRANSCEIVER 622-7309-101 128N REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345826	NO. 1 DME ANTENNA DMNI50-2-2 137788 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:16 TSN:0 TSN:0			07-NOV-2016 9847:51 5893		
345827	NO. 2 DME ANTENNA DMNI50-2-2 137236 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-DEC-2016 9847:51 5893		
345831	AFIS DATA MANAGEMENT UNIT 400-045500-0005 1606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-2002 1614:12 991		
345836	AFIS CONFIGURATION MODULE 31990-1 9660 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
345838	AFIS ANTENNA S65-8280-10 6393 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345841	EGPWS COMPUTER								
34.490	965-0976-040-212-212 7580 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:1551:30 TSN:959			15-FEB-2002 1574:30 967		
345846	GPWS INVERTER								
34.500	1A50-1B1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345851	NO. 1 GPS SENSOR								
34.510	HG2021GD02 000555153 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
345852	NO. 2 GPS SENSOR								
34.510	HG2021GD02 00055097 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
345853	NO. 3 GPS SENSOR								
34.510	HG2021GD02 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345855	NO. 1 GPS ANTENNA								
34.520	S67-1575-20 5850 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
345856	NO. 2 GPS ANTENNA								
34.520	S67-1575-20 5846 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345857	NO. 3 GPS ANTENNA								
34.520	121-017686-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
345A09	AFIS PRINTER								
	1815 401010209007 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			20-MAR-2009 8217:06 5192		
346A10	DATA FMS LOADER								
	G7226-01 1995 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-MAY-2010 8412:34 5274		
CHAPTER 35 OXYGEN									
35-10-05-350-801-01	RESTORATION PILOT OXYGEN MASK (OVERHAUL)								
35.040	MC10-12-151 75085 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			01-OCT-2012 9012:54 5520	01-OCT-2018	05-DEC-2018
OVERHAUL									
35-10-05-350-801-02	RESTORATION COPILOT OXYGEN MASK (OVERHAUL)								
35.050	MC10-12-151 17707 REF: See Workcard	MOS HRS/MSC AFL	72	+3%			09-JUL-2013	09-JUL-2019	13-SEP-2019
OVERHAUL									
35-10-05-350-801-03	RESTORATION THIRD CREW MEMBER OXYGEN MASK (OVERHAUL)								
35.060	289-601-228 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				01-JUN-2018 9855:36 5896		
+ 35-10-05-710-801-01	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - LH PILOT OXYGEN MASK (L502WH)								
35.040		MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896	01-JUN-2019	01-JUL-2019
REF: See Workcard									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10-05-710-801-02	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - RH PILOT OXYGEN MASK (R502WH)								
35.050	REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896	01-JUN-2019	01-JUL-2019
35-10-05-710-801-03	OPERATIONAL TEST OF THE CREW OXYGEN MASKS - THIRD CREW MEMBER OXYGEN MASK (524WH)								
35.060	REF: See Workcard	MOS HRS/MSC AFL	O/C				10-APR-2007 6653:12 4106		
35-10-05-900-801-01	PILOT OXYGEN MASK								
35.040	MC10-12-151 75085 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:48 TSO:834:57 TSO:373			24-AUG-2016 9847:51 5893		
35-10-05-900-801-02	COPILOT OXYGEN MASK								
35.050	MC10-12-151 17707 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:106 TSO:37 TSN:1726:03 TSO:416:03 TSN:712 TSO:199			21-AUG-2016 9847:51 5893		
35-10-05-900-801-03	THIRD CREW MEMBER OXYGEN MASK								
35.060	289-601-228 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-JUN-2018 9855:36 5896		
35-20-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER OXYGEN MASKS AND PORTABLE OXYGEN MASKS								
35.230	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
+ 35-20-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM								
35.080	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-20-00-720-801-01A	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM (MANDATORY REF 5-40-20)								
35.080		MOS					03-JUN-2014		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	O/C				9560:43 5737		
35-20-01-350-801-01	RESTORATION PASSENGER OXYGEN CONTROLLER (OVERHAUL)								
35.090	RCA74-07	MOS	72	+3%			29-APR-2016	29-APR-2022	03-JUL-2022
OVERHAUL	1186 REF: See Workcard	HRS/MSC AFL					9805:22 5878		
35-20-01-900-801-01	PASSENGER OXYGEN CONTROLLER								
35.090	RCA74-07	MOS				TSO:0	29-APR-2016		
	1186 REF: See Workcard	HRS/MSC AFL	O/C			TSO:0 TSO:0	9805:22 5878		
35-20-09-900-801-01	NO. 1 PASSENGER OXYGEN MASK								
35.100	289-601-228	MOS				TSN:0	24-APR-2015		
	SN-UNKNOWN REF:	HRS/MSC AFL	O/C			TSN:0 TSN:0	9760:57 5832		
35-20-09-900-801-02	NO. 2 PASSENGER OXYGEN MASK								
35.100	289-601-228	MOS				TSN:0	24-APR-2015		
	SN-UNKNOWN REF:	HRS/MSC AFL	O/C			TSN:0 TSN:0	9760:57 5832		
35-20-09-900-801-03	NO. 3 PASSENGER OXYGEN MASK								
35.110	289-601-228	MOS				TSN:0	24-APR-2015		
	SN-UNKNOWN REF:	HRS/MSC AFL	O/C			TSN:0 TSN:0	9760:57 5832		
35-20-09-900-801-04	NO. 4 PASSENGER OXYGEN MASK								
35.110	289-601-228	MOS				TSN:0	24-APR-2015		
	SN-UNKNOWN REF:	HRS/MSC AFL	O/C			TSN:0 TSN:0	9760:57 5832		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-05	NO. 5 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-06	NO. 6 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-JAN-2014 9560:43 5737		
35-20-09-900-801-07	NO. 7 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-08	NO. 8 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		
35-20-09-900-801-09	NO. 9 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-10	NO. 10 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-11	NO. 11 PASSENGER OXYGEN MASK 289-601-228-7 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				31-AUG-2016 9847:51 5893		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-12	NO. 12 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-JAN-2014 9560:43 5737		
35-20-09-900-801-13	NO. 13 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-14	NO. 14 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-APR-2015 9760:57 5832		
35-20-09-900-801-15	NO. 15 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		
35-20-09-900-801-16	NO. 16 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		
35-20-09-900-801-17	NO. 17 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		
35-20-09-900-801-18	NO. 18 PASSENGER OXYGEN MASK 289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-20-09-900-801-19	NO. 19 PASSENGER OXYGEN MASK								
35.190	289-601-228 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-APR-2006 5778:48 3578		
35-21-05-210-801-01	INSPECTION OF THE RILSAN OXYGEN TUBE								
	REF: See Workcard	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
35-21-20-350-801-01S	OVERHAUL FIRST AID OXYGEN CYLINDER								
	PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
35-21-20-900-801-01	FIRST AID OXYGEN CYLINDER								
	PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
35-30-01-960-801-01	DISCARD PILOT PROTECTIVE BREATHING EQUIPMENT HOOD								
35.210	802300-14 E08050670 REF: See Workcard	MOS HRS/MSC AFL	120				16-JUL-2009 8246 5216	16-JUL-2019	
LIFE LIMIT									
35-30-01-960-801-02	DISCARD COPILOT PROTECTIVE BREATHING EQUIPMENT HOOD								
35.210	802300-14 E08050673 REF: See Workcard	MOS HRS/MSC AFL	120				16-JUL-2009 8246 5216	16-JUL-2019	
LIFE LIMIT									
+ 35-30-05-210-801-01	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)								
35.220	894-20330 ST1944 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			16-AUG-2017 9850:07 5894	16-AUG-2018	27-AUG-2018

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-30-05-350-801-01	RESTORATION OF THE PORTABLE OXYGEN BOTTLE (OVERHAUL) - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)								
35.220	894-20330 ST1944 REF: See Workcard	MOS HRS/MSC AFL	60	+3%			09-SEP-2014	09-SEP-2019	02-NOV-2019
OVERHAUL									
35-30-05-900-801-01	PORTABLE OXYGEN CYLINDER								
35.220	894-20330 ST1944 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				11-SEP-2014 9628:50 5770		
35-30-09-100-801-01	CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)								
35.220	894-20330 ST1944 REF: See Workcard	MOS HRS/MSC AFL	12	+3%			21-AUG-2017 9850:07 5894	21-AUG-2018	01-SEP-2018
35-32-18-350-804-01S	RESTORATION MASK (OVERHAUL) (SCOTT 5600-9-PIA-YOEN ONLY)								
	REF: GENERIC CMM	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
+ 35-40-01-790-801-01	HYDROSTATIC TEST OXYGEN CYLINDER								
35.010	176219-115 1807-18513 REF: See Workcard	MOS HRS/MSC AFL	60				02-MAY-2014	02-MAY-2019	
MANDATORY									
35-40-01-900-801-01	OXYGEN CYLINDER								
35.010	176219-115 1807-18513 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-MAY-2014 9560:43 5737		
35-40-01-960-801-01	DISCARD OXYGEN CYLINDER								
35.010	176219-115 1807-18513 REF: See Workcard	MOS HRS/MSC AFL	180				01-AUG-2007	01-AUG-2022	
LIFE LIMIT									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-40-05-720-801-01	FUNCTIONAL TEST OXYGEN CYLINDER	PRESSURE REDUCE VALVE							
35.010	176219-115 1807-18513 REF: See Workcard	MOS HRS/MSC AFL	60				02-MAY-2014	02-MAY-2019	
350801	HP PRESSURE CYLINDER GAUGE								
35.020	LM40AMD SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
351801	PILOT OXYGEN MASK HOSE								
35.070	DTF44A260 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
351806	COPILOT OXYGEN MASK HOSE								
35.070	DTF5AA180-25 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
351811	PILOT OXYGEN COUPLING								
35.030	DBP179 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
351812	COPILOT OXYGEN COUPLING								
35.030	DBP179 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
352831	NO. 1 THERAPEUTIC MASK								
35.200	289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-APR-2006 5783:30 3581		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352832	NO. 2 THERAPEUTIC MASK								
35.200	289-601-228 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-APR-2006 5783:30 3581		
353801	PILOT PROTECTIVE BREATHING EQUIPMENT HOOD								
35.210	802300-14 E08050670 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-JUL-2009 8246 5216		
353802	COPILOT PROTECTIVE BREATHING EQUIPMENT HOOD								
35.210	802300-14 E08050673 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-JUL-2009 8246 5216		
CHAPTER 36 PNEUMATIC									
36-00-05-900-801-01	AUTOMATIC BLEED OVERRIDE (ABOC) CONTROLLER								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
36-10-02-900-801-01	NO. 1 ENGINE HP BLEED AIR ELECTRIC VALVE								
36.020	6038A030002 1098 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-JUN-2006 5898:24 3635		
36-10-02-900-801-02	NO. 2 ENGINE HP BLEED AIR ELECTRIC VALVE								
36.020	6038A03000 587 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-DEC-2003 3610:06 2227		
36-10-02-900-801-03	NO. 3 ENGINE HP BLEED AIR ELECTRIC VALVE								
36.020	6038A030002 455 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-APR-2004 3927:06 2449		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-10-29-280-801-01	SPECIAL DETAILED INSPECTION OF THE ENGINE 2 HP BLEED AIR PIPE								
36.080	REF: See Workcard	MOS HRS/MSC AFL	O/C				14-OCT-2003 3409:36 2113		
36-10-33-350-801-01	RESTORATION NO. 1 ENGINE BLEED AIR ARTICULATED PIPE (OVERHAUL)								
36.030 OVERHAUL	B45CB1120 01637 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			07-NOV-2017 9850:07 5894	14850:07	15000:07
36-10-33-350-801-02	RESTORATION NO. 3 ENGINE BLEED AIR ARTICULATED PIPE (OVERHAUL)								
36.030 OVERHAUL	B45CB1120 249 REF: See Workcard	MOS HRS/MSC AFL	5000	+3%			12-MAY-2005 4984:06 3090	9984:06	10134:06
361801	LEFT OZONE CONVERTER								
36.010	D20425-1 0140 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		01-JUN-2018 9855:36 5896		
361802	RIGHT OZONE CONVERTER								
36.010	D20425-1 0258 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		01-JUN-2018 9855:36 5896		
361806	BLEED AIR SYSTEM COMPUTER								
36.070	92138C020500 307 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		07-AUG-2005 5245:06 3250		
361811	NO. 1 ENGINE BLEED AIR ARTICULATED PIPE								
36.030	B45CB1120 01637 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:117 TSO:0 TSN:3040 TSO:0 TSO:0		07-NOV-2017 9850:07 5894		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361812	NO. 3 ENGINE BLEED AIR ARTICULATED PIPE B45CB1120	MOS					12-MAY-2005		
36.030	249 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSO:0 TSO:0			4984:06 3090		
362801	NO. 1 ENGINE TEMPERATURE PROBE RP129-02	MOS		TSN:0			14-AUG-2001		
36.040	4012 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			1023 661		
362802	NO. 2 ENGINE TEMPERATURE PROBE RP129-02	MOS		TSN:0			16-DEC-2003		
36.040	3967 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			3622:24 2239		
362803	NO. 3 ENGINE TEMPERATURE PROBE RP129-02	MOS					17-APR-2001		
36.040	3548 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			424		
362806	WING HIGH/LOW PRESSURE TRANSMITTER ZRA233-00	MOS					23-MAR-2000		
36.050	377 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
362811	S-DUCT HIGH/LOW PRESSURE TRANSMITTER ZRA233-00	MOS					23-MAR-2000		
36.060	380 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
CHAPTER 38	WATER/WASTE								
38-00-00-610-801-01 (s)	SERVICING OF THE WATER SYSTEM						PKG		
38.070	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-10-00-210-801-01 (s)	DETAILED INSPECTION OF WATER SYSTEM COMPONENTS PKG 31	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL							
38-10-00-670-801-01	STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION	MOS	6	+5d			01-JUN-2018 9855:36 5896	01-DEC-2018	06-DEC-2018
38.020	REF: See Workcard	HRS/MSC AFL							
38-13-01-960-801-01	REPLACEMENT OF THE MAIN FILTER CARTRIDGE	MOS					23-MAR-2000 0 0		
	REF: See Workcard	HRS/MSC AFL	O/C						
38-13-09-900-801-01	FORWARD WATER HEATER	MOS			TSN:0		23-MAR-2000 0 0 0		
	PN SN-UNKNOWN REF: See Workcard	HRS/MSC AFL APH	O/C		TSN:0 TSN:0 TSN:0				
38-15-01-710-801-01	OPERATIONAL TEST OF THE UV WATER PURIFIER	MOS					23-MAR-2000 0 0 0		
	REF: See Workcard	HRS/MSC AFL APH	N/A						
38-15-09-960-801-01	REPLACEMENT OF THE UV LAMP	MOS					23-MAR-2000 0 0 0		
	REF: See Workcard	HRS/MSC AFL APH	N/A						
+ 38-30-00-710-801-01	OPERATIONAL TEST OF THE DRAIN MAST ANTI-ICING SYSTEMS	MOS					05-JUN-2009 8246 5216		
30.200	REF: See Workcard	HRS/MSC AFL	O/C						

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-31-01-900-801-01	FRONT DRAIN MAST PN SN-UNKNOWN REF: AMM 38-31-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0		
38-31-13-960-801-01	REPLACEMENT OF THE GALLEY WATER FILTER REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
38-31-17-200-801-01 38.080	INSPECTION OF THE DRAIN TANK BOX REF: See Workcard	MOS HRS/MSC AFL APH	O/C				23-MAR-2000 0 0 0		
38-34-21-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE AFT TOILET DRAIN CONTROL PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			PKG 01-JUN-2018 9855:36 5896		
38-90-13-100-801-01S	CLEANING OF THE MINI-DEMAND DRAIN TANK REF: SMM 38-90-13	MOS HRS/MSC AFL APH	N/A				23-MAR-2000 0 0 0		
381801 38.030	POTABLE WATER TWO WAYS VALVE 879B14-13 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
381A11	WATER LAV HEATER 8921082G6 335 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381A12	DRAIN WATER FWD MAST MAT-302706-A 043 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 8246 5216		
381A13	DRAIN WATER AFT MAST 200438 P4WS/01 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
CHAPTER 46 INFORMATION SYSTEMS									
46-20-02-720-801-01	FUNCTIONAL TEST OF THE EDU BATTERIES - LH EDU (L7101NS) PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A						
46-20-02-720-801-02	FUNCTIONAL TEST OF THE EDU BATTERIES - RH EDU (R7101NS) PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A						
46-90-03-900-801-01	LH ELECTRONIC FLIGHT BAG (EFB) DISPLAY UNIT PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
46-90-03-900-801-02	RH ELECTRONIC FLIGHT BAG (EFB) DISPLAY UNIT PN NOT INSTALLED REF: GENERIC CMM	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
CHAPTER 49 AIRBORNE AUXILIARY POWER									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496301	APU T5 INDICATOR 2396-507-00-10 635 REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C 0	TSN:0 TSN:0			23-MAR-2000 0		
496401	APU N1 TACHOMETER 2396-506-00-10 624 REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C 0	TSN:0 TSN:0			23-MAR-2000 0		
497A01	FAULT APU PANEL F90-11173-501 00-003 REF:	MOS HRS/MSC AFL	O/C	TSN:0			18-AUG-2000 23 8		
49APU1	APU 3800188-2 P370 REF: See Workcard	MOS HRS/MSC AFL	E/C						
APU Model : GTCP36-150(F) Serial # P370 Part # 3800188-2									
+ 491010	APU - TURBINE ROTOR 3615880-1 990134502336 REF: GENERIC NO REF	MOS HRS/MSC APUS	10000	TSN:0 TSN:0			23-MAR-2000 0 0		10000
491020	APU - COMPRESSOR ROTOR 3822101-1 070350106080 REF: GENERIC NO REF	MOS HRS/MSC APUS	100000	TSN:0 TSN:0			02-JAN-2008 1846:54		101846:54

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 491025	APU - VISUAL CHECK COMPRESSOR ROTOR 3822101-1 070350106080 REF: MM 49-20-00	MOS HRS/MSC APUS	4500				02-JAN-2008 1846:54		4500 M
+ 491030	APU - HOT SECTION INSPECTION REF: MM 49-20-00	MOS HRS/MSC APUS	4500	TSI:0			23-MAR-2000 0 0		4500
493010 49.030	APU - FUEL CONTROL 3882730-9 21748 REF:	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
493020	APU - REMOVE AND REPLACE FUEL CONTROL FUEL FILTER ELEMENT 3882730-9 21748 REF: MM 49-30-52	MOS HRS/MSC APUS	1000				29-MAY-2014 2878:03		3878:03
493030	APU - ORIFICE FITTING 3606721-1 SN-UNKNOWN REF: MM 49-30-56	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
493040	APU - FUEL SHUTOFF VALVE 692545-17 2416 REF: MM 49-30-54	MOS HRS/MSC APUS	O/C	TSO:0			20-AUG-2001 320:30		
+ 493050	APU - CHECK FUEL NOZZLE FLOW RATE REF: MM 49-20-00	MOS HRS/MSC APUS	4500	TSI:0			23-MAR-2000 0 0		4500

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493060	APU - CONTROLLER 2118306-3 108-383 REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
493070	APU - LOAD CONTROL VALVE 109812-10 2261 REF: MM 49-50-33	MOS HRS/MSC APUS	O/C	TSO:0 TSO:0			24-JUL-2006 1536:30		
494010	APU - IGNITION UNIT 3888000-2 990218000905 REF: MM 49-40-32	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
494020	APU - IGNITOR PLUG 3888002-2 SN-UNKNOWN REF: MM 49-40-33	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			09-APR-2013 2659:48 0		
+ 494030	APU - INSPECT/CLEAN IGNITOR PLUG 3888002-2 SN-UNKNOWN REF: MM 49-40-33	MOS HRS/MSC APUS	750				01-JUN-2018 3310:24	4060:24	
496401	APU - N1 APU TACHOMETER 2396-506-00-10 624 REF:	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
497010	APU - MOTION PICK UP TRANSDUCER 3876104-1 SN-UNKNOWN REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
497020	APU - IMMERSION THERMOCOUPLE 3876003-3 SN-UNKNOWN REF: MM 49-60-45	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
497030	APU - HOURMETER 3888126-1 SN-UNKNOWN REF: MM 49-70-41	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
499010	APU - ROTARY OIL PUMP 3880225-2 SN-UNKNOWN REF: MM 49-90-51	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
+ 499020	APU - REMOVE AND INSPECT REF: MM 49-90-46	MAGNETIC DRAIN PLUG MOS HRS/MSC APUS	17 750				01-JUN-2018 3310:24	01-NOV-2019 4060:24	
499030	APU - DRAIN AND REFILL OIL REF: MM 49-20-00	MOS HRS/MSC APUS	17 750				01-JUN-2018 3310:24	01-NOV-2019 4060:24	
499040	APU - REMOVE AND REPLACE REF: MM 49-90-47	OIL FILTER ELEMENT MOS HRS/MSC APUS	17 750				01-JUN-2018 3310:24	01-NOV-2019 4060:24	
499050	APU - PRESSURE REGULATING VALVE 3880021-13 SN-UNKNOWN REF: MM 49-90-52	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499060	APU - HIGH OIL TEMPERATURE SWITCH 3888030-1 SN-UNKNOWN REF: MM 49-60-46	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
499070	APU - LOW OIL PRESSURE SWITCH 3876001-6 SN-UNKNOWN REF: MM 49-60-43	MOS HRS/MSC APUS	O/C	TSN:0			23-MAR-2000 0 0		
499110	APU - SOAP CHECK OIL REF: SIL SIL APU-49	MOS HRS/MSC APUS	O/C				04-AUG-2009 2109		
CHAPTER 52 DOORS									
+ 52-00-00-200-801-01 (s)	INSPECTION/CHECK OF THE PASSENGER DOORS SEALS						PKG		
53.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 52-00-00-200-801-02 (s)	INSPECTION/CHECK OF THE BAGGAGE COMPARTMENT DOORS SEALS						PKG		
53.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 52-00-00-200-801-03 (s)	INSPECTION/CHECK OF THE SERVICING COMPARTMENT DOORS SEALS						PKG		
53.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
52-00-00-640-801-01 (s)	LUBRICATION OF SERVICE DOORS						PKG		
52.010	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR COUNTERBALANCING SYSTEM						PKG		
52.030	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
52-10-00-610-801-01 (s)	SERVICING OF THE PASSENGER DOOR						PKG		
52.020	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			01-JUN-2018 9855:36 5896		
52-10-00-610-802-01 (s)	SERVICING OF THE PASSENGER DOOR SAFETY CATCH						PKG		
	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			01-JUN-2018 9855:36 5896		
52-10-00-640-801-01	LUBRICATION OF THE PASSENGER DOOR LOWER MECHANISM ROLLERS						PKG		
52.020	REF: See Workcard	MOS HRS/MSC AFL	N/A				23-MAR-2000 0 0		
+ 52-10-00-720-801-01 (s)	FUNCTIONAL TEST OF THE PASSENGER DOOR						PKG		
52.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
52-10-01-900-801-01	PASSENGER DOOR						PKG		
52.020	FGFB295D4 167HP358 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
52-10-03-900-801-01	PASSENGER DOOR PNEUMATIC ACTUATOR						PKG		
52.150	222900M02 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-03-960-801-01	DISCARD PASSENGER DOOR PNEUMATIC ACTUATOR 222900M02	MOS					23-MAR-2000		
52.140	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	N/A				0 0		
52-10-11-900-801-01	PASSENGER DOOR COMPENSATION ACTUATOR AE40122007	MOS		TSN:0			09-AUG-2012		
52.030	2319365 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			9012:54 5520		
52-20-00-610-801-01 (s)	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN						PKG		
52.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24				01-JUN-2018 9855:36 5896		
52-20-00-610-801-01A	SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40)						01-JUN-2018	01-JUN-2020	
52.040 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	24				9855:36 5896		
+ 52-20-00-610-801-02 (s)	SERVICING OF THE EMERGENCY EXIT DOOR						PKG		
	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24				01-JUN-2018 9855:36 5896		
+ 52-20-00-710-801-01 (s)	OPERATIONAL TEST OF THE EMERGENCY EXIT DOOR FROM OUTSIDE						PKG		
52.040	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
52-20-01-900-801-01	EMERGENCY EXIT DOOR F2MA296001A1	MOS					23-MAR-2000		
52.040	BZ232 REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-30-00-610-801-01 (s)	SERVICING OF THE BAGGAGE COMPARTMENT DOOR						PKG		
52.050	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			01-JUN-2018 9855:36 5896		
+ 52-30-00-710-801-01 (s)	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM						PKG		
52.060	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 52-30-00-710-801-01A	CHECK OF BAGGAGE COMPARTMENT DOOR MECHANISM (MANDATORY REF. 5-40-20)								
52.060 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	8000				01-JUN-2018 9855:36 5896	17855:36	
52-30-01-900-801-01	BAGGAGE COMPARTMENT DOOR								
52.050	FGFB299B5 HAI001 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
52-40-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE SERVICE DOORS						PKG		
52.090	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
52-41-07-610-801-01 (s)	SERVICING OF NOSE LANDING GEAR (NLG) WELL CEILING DOOR						PKG		
52.100	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
52-50-00-710-801-01 (s)	INSPECTION/TEST OF THE BLOWOUT DOORS/PANELS						PKG		
52.160	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-53-00-610-801-01 (s)	SERVICING OF THE CABIN / BAGGAGE COMPARTMENT DOOR						PKG		
52.110	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			01-JUN-2018 9855:36 5896		
52-54-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF CABIN DOORS, DIVIDERS AND BULKHEADS						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
52-54-05-210-801-02 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR - INSPECTION OF MOUNTING LOCATIONS, LAMINATE AND MECHANISM						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 52-54-05-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER - INSPECTION OF THE GALLEY POCKET SLIDING DOOR CABLES AND CABLE SILENCER						PKG		
	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			23-MAR-2000 0 0		
52-54-09-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE MID-CABIN SLIDING DOOR MECHANISM						PKG		
	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
52-55-00-610-801-01 (s)	SERVICING OF THE S-DUCT DOOR						PKG		
52.120	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
52-60-09-610-801-01 (s)	SERVICING OF THE MECHANIC'S SERVICING COMPARTMENT (MSD) DOOR						PKG		
52.080	PKG 17 REF: See Workcard	MOS HRS/MSC AFL	36	+1m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-70-00-710-802-01 (s)	OPERATIONAL TEST OF THE PASSENGER DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
+ 52-70-00-710-802-02 (s)	OPERATIONAL TEST OF THE ENGINE S-DUCT INSPECTION DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
+ 52-70-00-710-802-03 (s)	OPERATIONAL TEST OF THE BAGGAGE COMPARTMENT DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
+ 52-70-00-710-802-04 (s)	OPERATIONAL TEST OF THE MECHANIC'S SERVICING COMPARTMENT DOOR INDICATION SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
+ 52-70-00-710-802-05 (s)	OPERATIONAL TEST OF THE FORWARD TOILET SERVICING DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
+ 52-70-00-710-802-06 (s)	OPERATIONAL TEST OF THE CABIN/ BAGGAGE COMPARTMENT COMMUNICATION DOOR INDICATING SYSTEM						PKG		
52.130	PKG 6	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC	1600	+40			9855:36		
		AFL					5896		
52-90-01-200-801-01S (s)	INSPECTION OF THE MID-CABIN DIVIDER/DOOR/BULKHEAD, ALL MOUNTING LOCATIONS FOR CORROSION, CRACKS, OR DAMAGE						PKG		
	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: SMM 52-90-01	HRS/MSC					9855:36		
		AFL	3750				5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
523801	BAGGAGE COMPARTMENT DOOR REDUCER MOTOR								
52.070	4220-5 670 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-SEP-2014 9628:50 5770		
523A02	BAGGAGE DOOR CABLE								
	4220-250 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			04-DEC-2003 3585:18 2209		
524801	MECHANIC'S SERVICING COMPARTMENT (MSD) DOOR								
52.080	FGFB297A1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
CHAPTER 53 FUSELAGE									
+ 53-00-00-200-803-01	INSPECTION OF THE FUSELAGE SKIN -FRAME 4 TO FRAME 30								
53.150	REF: See Workcard	MOS HRS/MSC AFL	11250				12-APR-2006 5778:48 3578		11250
+ 53-00-00-200-803-01A	INSPECTION OF THE FUSELAGE SKIN -FRAME 4 TO FRAME 30 (MANDATORY REF. 5-40-10)								
53.150 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	11250				12-APR-2006 5778:48 3578		11250
53-00-00-200-803-02	DETAILED INSPECTION IN SPECIFIC AREAS OF FUSELAGE SKIN- FROM FRAME 4 TO FRAME 30								
	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0		11250

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-00-200-803-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF FUSELAGE SKIN- FROM FRAME 4 TO FRAME 30 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 53-00-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR						PKG		
53.010	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
53-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
53-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR						PKG		
	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
53-00-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE EXTERIOR (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
+ 53-10-00-200-808-01 (s)	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY						PKG		
53.110	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
53-10-00-200-808-01C	INSPECTION OF THE NOSE LANDING GEAR (NLG) BAY (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	13				01-JUN-2018 9855:36 5896	01-JUL-2019	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-00-200-810-01	GENERAL VISUAL INSPECTION F THE FUSELAGE SKIN -FRAME 0 TO FRAME 4								
53.140	REF: See Workcard	MOS HRS/MSC AFL	7500				24-MAR-2006 5778:48 3578	7500	
+ 53-10-00-200-810-01A	GENERAL VISUAL INSPECTION F THE FUSELAGE SKIN -FRAME 0 TO FRAME 4 (MANDATORY REF. 5-40-10)								
53.140 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	7500				24-MAR-2006 5778:48 3578	7500	
53-10-00-200-810-02	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4								
	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
53-10-00-200-810-02A	DETAILED INSPECTION IN SPECIFIC AREAS OF THE FUSELAGE SKIN -FRAME 0 TO FRAME 4 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 53-10-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT								
53.0301	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24 4000	+1m			01-JUN-2018 9855:36 5896	01-JUN-2020 13855:36	01-JUL-2020
+ 53-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE STATIC PRESSURE PROBES AND OF THE FUSELAGE SKIN IN THE PROBE AREAS								
53.250 RVSM	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 53-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT								
53.0302	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-220-802-01C	DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-10-01-250-801-01 (s)	EDDY CURRENT INSPECTION OF THE FRAME 0 STIFFENER TIP	MOS	144	+2m			PKG 27-JUL-2012 9012:54 5520		
53.190	PKG 32	HRS/MSC AFL	7500						
	REF: See Workcard								
+ 53-10-03-220-801-03 (s)	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS	MOS	144	+2m			PKG 01-JUN-2018 9855:36 5896		
	PKG 32	HRS/MSC AFL	7500						
	REF: See Workcard								
+ 53-10-03-220-801-03C	DETAILED INSPECTION OF THE PASSENGER DOOR FRAME UNDER THE UPPER AND LOWER EDGING STRIPS (CPCP)	MOS	148				01-JUN-2018 9855:36 5896	01-OCT-2030	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-10-03-250-801-01 (s)	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
53.180	PKG 31	HRS/MSC AFL	3750						
	REF: See Workcard								
+ 53-10-03-250-801-01A	SPECIAL DETAILED INSPECTION OF THE UPPER PASSENGER DOOR FRAME EDGING (MANDATORY REF. 5-40-10)	MOS					01-JUN-2018 9855:36 5896	9646	
53.180		HRS/MSC AFL	3750						
MANDATORY 5-40	REF: See Workcard								
+ 53-10-39-220-801-01 (s)	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
53.220	PKG 31	HRS/MSC AFL	3750						
	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-39-220-801-01C	DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-10-39-220-802-01 (s)	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES	MOS	144	+2m			PKG 01-JUN-2018 9855:36 5896		
53.260	PKG 32	HRS/MSC AFL	7500						
	REF: See Workcard								
53-10-39-220-802-01C	DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)	MOS	148				01-JUN-2018 9855:36 5896	01-OCT-2030	
CPCP	REF: See Workcard	HRS/MSC AFL							
53-10-41-220-801-01	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NOSE LANDING GEAR (NLG) ACTUATOR	MOS					23-MAR-2000 0 0		
53.230		HRS/MSC AFL	O/C						
	REF: See Workcard								
53-10-41-220-801-01A	DETAILED INSPECTION OF THE ATTACHMENT FITTING OF THE NOSE LANDING GEAR (NLG) ACTUATOR (MANDATORY REF. 5-40-10)	MOS					23-MAR-2000 0 0		
53.230		HRS/MSC AFL	O/C						
MANDATORY 5-40	REF: See Workcard								
+ 53-10-43-220-801-01 (s)	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LEFT WALL	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
53.240	PKG 31	HRS/MSC AFL	3750						
	REF: See Workcard								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-43-220-801-01A	DETAILED INSPECTION OF THE STIFFENERS AT THE BOTTOM OF THE NOSE LANDING GEAR (NLG) WELL LEFT WALL (MANDATORY REF. 5-40-10)								
53.240		MOS					01-JUN-2018		
MANDATORY 5-40	REF: See Workcard	HRS/MSC					9855:36		
		AFL	3750				5896		9646
<hr/>									
+ 53-11-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA						PKG		
53.0201	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
<hr/>									
53-11-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)								
		MOS	25				01-JUN-2018		01-JUL-2020
CPCP	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
<hr/>									
+ 53-11-00-760-801-01 (s)	CHECK OF THE NOSE CONE ELECTRICAL BONDING						PKG		
53.270	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
<hr/>									
53-11-01-900-801-01	NOSE CONE								
53.210	FGFB208D1	MOS					23-MAR-2000		
	BZ63	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL					0		
<hr/>									
53-11-21-960-801-01	REPLACEMENT OF THE NOSE CONE SEAL								
53.290	PKG 31	MOS					01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL	7500				5896		13396
<hr/>									
+ 53-30-00-210-802-01 (s)	GENERAL VISUAL INSPECTION OF THE PASSENGER CABIN						PKG		
53.0401	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-00-220-801-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR						PKG		
53.0402	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
53-30-00-220-801-01C	DETAILED INSPECTION OF THE PASSENGER CABIN UNDER THE FLOOR (CPCP)						01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	MOS HRS/MSC AFL	74						
+ 53-30-00-220-807-01 (s)	DETAILED INSPECTION OF THE PASSENGER CABIN ABOVE THE FLOOR						PKG		
53.0402	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			25-JUL-2012 9012:54 5520		
+ 53-30-00-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES						PKG		
53.170	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 53-30-00-250-801-01A	EDDY-CURRENT INSPECTION OF THE EMERGENCY EXIT DOOR FRAME ROUNDED ANGLES (MANDATORY 5-40)						01-JUN-2018 9855:36 5896	9646	
53.170	REF: See Workcard	MOS HRS/MSC AFL	3750						
MANDATORY 5-40									
+ 53-30-00-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS						PKG		
53.160	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 53-30-00-250-802-01A	EDDY CURRENT INSPECTION OF THE SKIN PANELS AROUND CABIN WINDOW CUT-OUTS (MANDATORY REF. 5-40-10)						01-JUN-2018 9855:36 5896	9646	
53.160	REF: See Workcard	MOS HRS/MSC AFL	3750						
MANDATORY 5-40									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-03-960-801-01	REPLACEMENT OF THE ALUMINUM LIGHTNING DIVERTER STRIPS ON REAR TANK	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
		APH					0		
+ 53-40-00-200-804-01 (s)	INSPECTION OF THE LEFT MAIN LANDING GEAR (MLG) BAYS						PKG		
53.100	PKG 15	MOS	12	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
53-40-00-200-804-01C	INSPECTION OF THE LEFT MAIN LANDING GEAR (MLG) BAYS (CPCP)								
		MOS	13				01-JUN-2018	01-JUL-2019	
CPCP	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
+ 53-40-00-200-804-02 (s)	INSPECTION OF THE RIGHT MAIN LANDING GEAR (MLG) BAYS						PKG		
53.100	PKG 15	MOS	12	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
53-40-00-200-804-02C	INSPECTION OF THE RIGHT MAIN LANDING GEAR (MLG) BAYS (CPCP)								
		MOS	13				01-JUN-2018	01-JUL-2019	
CPCP	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		
+ 53-40-00-210-802-01	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS								
53.0601	PKG 16	MOS	24	+1m			01-JUN-2018	01-JUN-2020	01-JUL-2020
	REF: See Workcard	HRS/MSC	4000				9855:36	13855:36	
		AFL					5896		
53-40-00-210-802-01C	GENERAL VISUAL INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)								
		MOS	25				01-JUN-2018	01-JUL-2020	
CPCP	REF: See Workcard	HRS/MSC					9855:36		
		AFL					5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-00-220-801-01 (s)	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS						PKG		
53.0602	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
53-40-00-220-801-01C	DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)						01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	MOS HRS/MSC AFL	74						
+ 53-40-00-220-802-01 (s)	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS						PKG		
53.050	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)						01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	MOS HRS/MSC AFL	74						
+ 53-41-00-220-801-01 (s)	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES						PKG		
57.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
53-41-00-220-801-01C	DETAILED INSPECTION OF THE LH UPPER WING ROOT BOLT RECESSES (CPCP)						01-JUN-2018 9855:36 5896	01-JUL-2020	
CPCP	REF: See Workcard	MOS HRS/MSC AFL	25						
+ 53-41-00-220-801-02 (s)	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES						PKG		
57.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-220-801-02C	DETAILED INSPECTION OF THE RH UPPER WING ROOT BOLT RECESSES (CPCP)	MOS	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-41-00-220-802-01 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING	MOS	72	+2m			01-JUN-2018 9855:36 5896		
53.130	PKG 31 REF: See Workcard	HRS/MSC AFL	3750						
+ 53-41-00-220-802-01A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - LH WING (MANDATORY 5-40)	MOS					01-JUN-2018 9855:36 5896	13396	
53.130 MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	7500						
+ 53-41-00-220-802-02 (s)	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING	MOS	72				01-JUN-2018 9855:36 5896		
	PKG 31 REF: See Workcard	HRS/MSC AFL	3750						
+ 53-41-00-220-802-02A	DETAILED INSPECTION OF THE LOWER WING ROOT BOLT RECESSES - RH WING (MANDATORY 5-40)	MOS					01-JUN-2018 9855:36 5896	13396	
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	7500						
53-41-00-620-802-01 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - UPPER LEFT WING ROOT BOLT RECESSES	MOS	72	+2m			01-JUN-2018 9855:36 5896		
57.050	PKG 31 REF: See Workcard	HRS/MSC AFL	3750						
53-41-00-620-802-01C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES - UPPER LEFT WING ROOT BOLT RECESSES (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-620-802-02 (s)	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES						PKG		
57.050	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
53-41-00-620-802-02C	RENEWAL OF THE TEMPORARY PROTECTION OF THE WING ROOT BOLT RECESSES (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
53-41-01-640-801-01 (s)	LUBRICATION OF THE LEFT WING TO FUSELAGE CONNECTING ROD						PKG		
57.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
53-41-01-640-801-02 (s)	LUBRICATION OF THE RIGHT WING TO FUSELAGE CONNECTING ROD						PKG		
57.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896		
+ 53-50-00-210-804-02 (s)	GENERAL VISUAL INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT						PKG		
53.0801	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
53-50-00-210-804-02C	GENERAL VISUAL INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	13				01-JUN-2018 9855:36 5896	01-JUL-2019	
+ 53-50-00-210-806-01 (s)	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT						PKG		
53.0701	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-50-00-210-807-01 (s)	GENERAL VISUAL INSPECTION OF THE APU AREA	MOS	12	+1m			PKG 01-JUN-2018 9855:36 5896		
53.090	PKG 15	HRS/MSC AFL							
	REF: See Workcard								
+ 53-50-00-220-803-01 (s)	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
53.0702	PKG 31	HRS/MSC AFL							
	REF: See Workcard								
53-50-00-220-803-01A	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (MADATORY 5-40)	MOS					01-JUN-2018 9855:36 5896		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	3750					9646	
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 53-50-00-220-805-01 (s)	DETAILED INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT	MOS	72	+2m			PKG 01-JUN-2018 9855:36 5896		
53.0802	PKG 31	HRS/MSC AFL							
	REF: See Workcard								
53-50-00-220-805-01C	DETAILED INSPECTION OF THE MECHANIC'S SERVICING COMPARTMENT (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-220-807-01	DETAILED INSPECTION OF THE FRAME 30 UPPER PART	MOS HRS/MSC AFL					01-JUN-2018 9855:36 5896		9646
	REF: See Workcard		3750						
53-50-00-220-807-01A	DETAILED INSPECTION OF THE FRAME 30 UPPER PART (MANDATORY 5-40)	MOS HRS/MSC AFL					01-JUN-2018 9855:36 5896		9646
	MANDATORY 5-40		3750						
+ 53-50-30-250-802-01 (s)	EDDY CURRENT INSPECTION OF THE REAR EDGE OF BEAMS AT FRAME 30						PKG		
	PKG 31	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
53.200	REF: See Workcard		3750						
+ 53-60-00-760-801-01 (s)	CHECK OF THE FUSELAGE VENTRAL FAIRING ELECTRICAL BONDING						PKG		
	PKG 17	MOS HRS/MSC AFL	36	+1m			01-JUN-2018 9855:36 5896		
53.280	REF: See Workcard								
+ 53-80-00-200-801-01 (s)	CHECK OF THE FUSELAGE CONDENSATION AND STREAM WATER DRAINS						PKG		
	PKG 16	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
51.010	REF: See Workcard								
53-80-01-710-801-02 (s)	OPERATIONAL TEST OF THE WATER DETECTION SYSTEM - "AFT WATER LEAK" SENSOR (55MD)						PKG		
	PKG 31	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
	REF: See Workcard		3750						
+ 53-80-09-710-801-01 (s)	OPERATIONAL TEST OF THE "CIRCLE SEAL" AUTOMATIC DRAINS						PKG		
	PKG 31	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
51.020	REF: See Workcard		3750						

CHAPTER 54 NACELLES/PYLONS

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-00-00-210-810-01 (s)	GENERAL VISUAL INSPECTION OF THE NO.1 ENGINE NACELLE AND PYLON						PKG		
54.0102	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896		
+ 54-00-00-210-810-02 (s)	GENERAL VISUAL INSPECTION OF THE NO.3 ENGINE NACELLE AND PYLON						PKG		
54.0201	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896		
+ 54-00-00-210-811-01 (s)	GENERAL VISUAL INSPECTION OF THE NO.2 ENGINE NACELLE						PKG		
54.0301	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896		
+ 54-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE NO.1 ENGINE NACELLE AND PYLON						PKG		
54.0105	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			16-APR-2008 7501 4649		
54-00-00-220-801-01C	DETAILED INSPECTION OF THE NO. 1 ENGINE NACELLE AND PYLON (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	148				16-APR-2008 7501 4649	28-SEP-2024 M	13020 M
+ 54-00-00-220-801-02 (s)	DETAILED INSPECTION OF THE NO.3 ENGINE NACELLE AND PYLON						PKG		
54.0202	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			16-APR-2008 7501 4649		
54-00-00-220-801-02C	DETAILED INSPECTION OF THE NO. 3 ENGINE NACELLE AND PYLON (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	148				16-APR-2008 7501 4649	28-SEP-2024 M	13020 M

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-11-00-610-801-01 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 1 COWLINGS						PKG		
54.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
54-11-00-610-801-02 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 2 COWLINGS						PKG		
54.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
54-11-00-610-801-03 (s)	SERVICING OF THE ENGINE COWLINGS - ENGINE 3 COWLINGS						PKG		
54.040	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 54-11-00-760-801-01 (s)	CHECK OF THE ENGINE COWLING ELECTRICAL BONDING						PKG		
54.080	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 54-42-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE NO. 2 ENGINE S-DUCT						PKG		
54.050	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
543A01	NO.1 ENGINE AFTERBODY COWLING								
	FGFB581800D2 GA025LN026 REF:	MOS HRS/MSC AFL	O/C		TSR:3 TSR:0 TSR:0		28-MAY-2014 9560:43 5737		
543A02	NO.3 ENGINE AFTERBODY COWLING								
	FGFB582800D1 GA15LN16 REF:	MOS HRS/MSC AFL	O/C		TSR:5 TSR:0 TSR:0		09-MAY-2014 9560:43 5737		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
544A01	AIR ENGINE #1 INTAKE FGFB581100D3 FA145LN153 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
544A02	AIR ENGINE #2 INTAKE FGFB258701D1 BZ256 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
544A03	ENG #2 LEFT COWLING FGFB583200A5 LE258 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
544A04	ENG #2 RIGHT COWLING FGFB583201A3 LE258 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
544A05	AIR ENGINE #3 INTAKE FGFB581100D3 FA262LN277 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			22-MAR-2010		

CHAPTER 55		STABILIZERS							
+ 55-00-00-210-801-01		GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT							
55.0101	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24 4000	+1m			01-JUN-2018 9855:36 5896	01-JUN-2020 13855:36	01-JUL-2020

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S- DUCT (CPCP)	MOS	25				01-JUN-2018	01-JUL-2020	
CPCP	REF: See Workcard	HRS/MSC AFL					9855:36 5896		
+ 55-00-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF NO. 2 ENGINE AIR INTAKE AND S-DUCT						PKG		
55.0102	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)	MOS	74				01-JUN-2018	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL					9855:36 5896		
+ 55-00-00-760-801-01 (s)	CHECK OF THE RUDDER STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.120	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL					9855:36 5896		
+ 55-00-00-760-801-02 (s)	CHECK OF THE LEFT ELEVATOR STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.130	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL					9855:36 5896		
+ 55-00-00-760-801-03 (s)	CHECK OF THE RIGHT ELEVATOR STABILIZER MOVABLE SURFACE ELECTRICAL BONDING						PKG		
55.130	PKG 16	MOS	24	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL					9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-220-801-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE PKG 32	MOS	144	+2m			PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	AFL	7500						
55-10-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE (CPCP)	MOS	148				01-JUN-2018 9855:36 5896	01-OCT-2030	
CPCP	REF: See Workcard	AFL							
55-10-00-220-802-01 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS PKG 32	MOS	144				PKG 01-JUN-2018 9855:36 5896		
	REF: See Workcard	AFL	7500						
55-10-00-220-802-01C	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER FRONT AND REAR SPARS (CPCP)	MOS	148				01-JUN-2018 9855:36 5896	01-OCT-2030	
CPCP	REF: See Workcard	AFL							
+ 55-10-00-270-801-01	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS	MOS	288	+2m			23-MAR-2000 0	23-MAR-2024	23-MAY-2024
55.020	REF: See Workcard	AFL	11250				0	11250	
+ 55-10-00-270-801-01A	ULTRASONIC INSPECTION OF THE HORIZONTAL STABILIZER HINGE FITTINGS (MANDATORY REF. 5-40-10)	MOS					23-MAR-2000 0		
55.020	REF: See Workcard	AFL	11250				0	11250	
MANDATORY 5-40									
55-10-00-640-802-01 (s)	GREASING OF THE HORIZONTAL STABILIZER ELECTRICAL ACTUATOR FRONT TORQUE LINK AND ACTUATOR UPPER HINGE PKG 16	MOS	24	+1m			PKG 01-JUN-2018 9855:36 5896		
27.270	REF: See Workcard	AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-03-640-801-01 (s)	LUBRICATION OF THE SPRING-LOADED FAIRING MECHANISM						PKG		
55.060	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
55-10-03-900-801-01	LEFT SPRING LOADED FAIRING								
55.070	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
55-10-03-900-801-02	RIGHT SPRING LOADED FAIRING								
55.070	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 55-10-31-220-801-01 (s)	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS						PKG		
55.030	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 55-10-31-220-801-01A	DIMENSIONAL CHECK OF HORIZONTAL STABILIZER REAR HINGE BUSHINGS (MANDATORY REF. 5-40-10)								
55.030 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	3750				01-JUN-2018 9855:36 5896	9646	
55-10-33-640-801-01	LUBRICATION OF THE HORIZONTAL STABILIZER REAR HINGE PINS								
27.255	REF: See Workcard	MOS HRS/MSC AFL	36 600	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2021 10455:36	01-JUL-2021 10495:36
+ 55-10-39-220-801-01	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE								
55.040	REF: See Workcard	MOS HRS/MSC AFL	11250				23-MAR-2000 0 0	11250	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-39-220-801-01A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - LOWER FIN SIDE (MANDATORY REF. 5-40-10)								
55.040		MOS					23-MAR-2000		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	11250				0 0		11250
+ 55-10-39-220-801-02	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE								
55.040		MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC AFL	11250				0 0		11250
+ 55-10-39-220-801-02A	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTINGS AND PINS - HORIZONTAL STABILIZER SIDE (MANDATORY REF. 5-40-10)								
55.040		MOS					23-MAR-2000		
MANDATORY 5-40	REF: See Workcard	HRS/MSC AFL	11250				0 0		11250
55-20-01-900-801-01	LEFT ELEVATOR								
55.090	FGFB341D3 BZ231	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
55-20-01-900-801-02	RIGHT ELEVATOR								
55.090	FGFB342D3 PT064	MOS					23-MAR-2000		
	REF: See Workcard	HRS/MSC AFL	O/C	TSN:0			0 0		
+ 55-20-03-640-801-01 (s)	LUBRICATION OF THE ELEVATOR BEARINGS						PKG		
55.080	PKG 32	MOS	144	+2m			28-SEP-2012		
	REF: See Workcard	HRS/MSC AFL	7500				9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-03-640-802-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL SURFACE HINGES						PKG		
27.180	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		
55-20-05-640-801-01 (s)	LUBRICATION OF THE ELEVATOR CONTROL BEARINGS AND UJOINTS						PKG		
27.265	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896		
+ 55-30-00-270-801-01	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS								
55.050	REF: See Workcard	MOS HRS/MSC AFL	288 11250	+2m			23-MAR-2000 0 0	23-MAR-2024 11250	23-MAY-2024
+ 55-30-00-270-801-01A	ULTRASONIC INSPECTION OF THE VERTICAL STABILIZER / STUB ATTACHMENTS (MANDATORY REF. 5-40-10)								
55.050 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	11250				23-MAR-2000 0 0	11250	
55-40-01-900-801-01	RUDDER								
55.110	FGFB321B1 TW098 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
+ 55-40-05-640-801-01 (s)	LUBRICATION OF THE RUDDER BEARINGS						PKG		
55.100	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			25-JUL-2012 9012:54 5520		
55-40-05-640-802-01 (s)	LUBRICATION OF THE RUDDER CONTROL SURFACE HINGES						PKG		
27.155	PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			01-JUN-2018 9855:36 5896		

CHAPTER 56 WINDOWS

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-01-900-801-01	PILOT WINDSHIELD								
56.020	SPSF900-2-8-3 2749 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 8246 5216		
56-10-01-900-801-02	COPILOT WINDSHIELD								
56.020	SPSF900-3-8-3 2056 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
56-10-01-900-801-03	FRONT WINDSHIELD								
56.020	SPSF2M1-3-2 894 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-SEP-2014 9628:50 5770		
56-10-07-900-801-01	RIGHT LATERAL WINDOW								
56.030	SPSF900-5-8-2 1920 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 8246 5216		
56-10-09-640-801-01 (s)	LUBRICATION OPENING WINDOW MECHANISM								
56.010	SPSF900-4-6-1 PKG 16 1960 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
56-10-09-900-801-01	OPENING WINDOW								
56.010	SPSF900-4-6-1 1960 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 8246 5216		
56-10-11-900-801-01	LEFT REAR WINDOW								
56.040	SPSF900-6-8-2 2197 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-11-900-801-02	RIGHT REAR WINDOW SPSF900-7-8-2 2202 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
56-20-05-900-801-01	NO. 1 LEFT PASSENGER CABIN WINDOW SPSF2000-8-1-0 4737 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
56-20-05-900-801-02	NO. 2 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 19770 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-03	NO. 3 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 11785 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			12-MAY-2005 4984:06 3090		
56-20-05-900-801-04	NO. 4 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22164 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-05	NO. 5 LEFT PASSENGER CABIN WINDOW SPSF900-8-7-0 5035 REF:	MOS HRS/MSC AFL	O/C				14-JUN-2001 828 526		
56-20-05-900-801-06	NO. 6 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22165 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-07	NO. 7 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22166 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-08	NO. 8 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 19671 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-09	NO. 9 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22162 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-10	NO. 10 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22161 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-11	NO. 11 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22163 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-12	NO. 12 LEFT PASSENGER CABIN WINDOW SPSF2M8-3-0 22510 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-2012 9012:54 5520		
56-20-05-900-801-13	NO. 1 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 19670 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-14	NO. 2 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 19666 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		
56-20-05-900-801-15	NO. 3 RIGHT PASSENGER CABIN WINDOW FGFB201400100A5 001542605-003 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			19-MAY-2014 9560:43 5737		
56-20-05-900-801-16	NO. 4 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 19767 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		
56-20-05-900-801-17	NO. 5 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 19665 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		
56-20-05-900-801-18	NO. 6 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 22571 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		
56-20-05-900-801-19	NO. 7 RIGHT PASSENGER CABIN WINDOW SPSF2M8-3-0 21530 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-FEB-2012 8911:19 5476		
56-20-05-900-801-20	NO. 8 RIGHT PASSENGER CABIN WINDOW SPSF2000-8-1-0 4729 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-05-900-801-21	NO. 9 RIGHT PASSENGER CABIN WINDOW								
56.150	SPSF2M8-3-0 19772 REF:	MOS HRS/MSC AFL	O/C				21-JUN-2012 9012:32 5520		
56-20-05-900-801-22	NO. 10 RIGHT PASSENGER CABIN WINDOW								
56.150	SPSF2M8-3-0 22512 REF:	MOS HRS/MSC AFL	O/C				21-JUL-2012 9012:54 5520		
56-20-05-900-801-23	NO. 11 RIGHT PASSENGER CABIN WINDOW								
56.160	SPSF2M8-3-0 19769 REF:	MOS HRS/MSC AFL	O/C				21-JUL-2012 9012:54 5520		
56-20-05-900-801-24	NO. 12 RIGHT PASSENGER CABIN WINDOW								
56.160	SPSF2M8-3-0 19667 REF:	MOS HRS/MSC AFL	O/C				21-JUL-2012 9012:54 5520		

CHAPTER 57 WINGS

+ 57-00-00-210-801-01	GENERAL VISUAL INSPECTION OF THE LEFT WING								
57.0101	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24 4000	+1m			01-JUN-2018 9855:36 5896	01-JUN-2020 13855:36	01-JUL-2020
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE LEFT WING (CPCP)								
CPCP	REF: See Workcard	MOS HRS/MSC AFL	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
+ 57-00-00-210-801-02	GENERAL VISUAL INSPECTION OF THE RIGHT WING								
57.0101	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24 4000	+1m			01-JUN-2018 9855:36 5896	01-JUN-2020 13855:36	01-JUL-2020

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE RIGHT WING (CPCP)	MOS	25				01-JUN-2018 9855:36 5896	01-JUL-2020	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 57-00-00-220-802-01 (s)	DETAILED INSPECTION OF THE LEFT WING						PKG		
57.0102	PKG 31	MOS	72	+2m			01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
57-00-00-220-802-01C	DETAILED INSPECTION OF THE LEFT WING (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 57-00-00-220-802-02 (s)	DETAILED INSPECTION OF THE RIGHT WING						PKG		
57.0102	PKG 31	MOS	72	+2m			01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL	3750						
57-00-00-220-802-02C	DETAILED INSPECTION OF THE RIGHT WING (CPCP)	MOS	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
CPCP	REF: See Workcard	HRS/MSC AFL							
+ 57-00-00-760-801-01 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LHAILERON						PKG		
57.245	PKG 16	MOS	24	+1m			01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL							
+ 57-00-00-760-801-02 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RHAILERON						PKG		
57.245	PKG 16	MOS	24	+1m			01-JUN-2018 9855:36 5896		
	REF: See Workcard	HRS/MSC AFL							

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00-00-760-801-03 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH FLAPS						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 57-00-00-760-801-04 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH FLAPS						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 57-00-00-760-801-05 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH SLATS						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 57-00-00-760-801-06 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH SLATS						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 57-00-00-760-801-07 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - LH AIRBRAKES						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
+ 57-00-00-760-801-08 (s)	ELECTRICAL BONDING CHECK OF THE WING MOVABLE SURFACES - RH AIRBRAKES						PKG		
57.245	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			01-JUN-2018 9855:36 5896		
57-00-01-900-801-01	LEFT WING								
57.220	FGFB101 365MA066 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-01-900-801-02	RIGHT WING FGFB102 364MA066 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57-10-00-290-801-01 (s)	BORESCOPE INSPECTION WING TANKS PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP) CPCP REF: See Workcard	MOS HRS/MSC AFL	74				01-JUN-2018 9855:36 5896	01-AUG-2024	
57-10-01-210-801-01	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-01-210-801-01A	GENERAL VISUAL INSPECTION OF THE WING LOWER PANELS (MANDATORY REF. 5-40-10) MANDATORY 5-40 REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-14-220-801-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-14-220-801-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM ROOT TO RIB 17 EXCEPT RIB 6 TO RIB 9 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-14-220-802-01	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9								
	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-14-220-802-01A	DETAILED INSPECTION OF THE WING FRONT SPAR FROM RIB 6 TO RIB 9 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-15-220-801-01	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3								
	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-15-220-801-01A	DETAILED INSPECTION OF THE WING REAR SPAR 1 FROM ROOT TO RIB 3 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
57-10-15-220-802-01	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17								
	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-15-220-802-01A	DETAILED INSPECTION OF THE WING REAR SPAR 2 FROM RIB 3 TO RIB 17 (MANDATORY REF. 5-40-10)								
MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 57-10-15-250-801-01	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE								
57.130	REF: See Workcard	MOS HRS/MSC AFL	11250				23-MAR-2000 0 0	11250	
+ 57-10-15-250-801-01A	EDDY-CURRENT INSPECTION OF THE RIB 8 REAR WING SPAR SPLICE PLATE (MANDATORY REF. 5-40-10)								
57.130	REF: See Workcard	MOS HRS/MSC AFL	11250				23-MAR-2000 0 0	11250	
57-45-01-900-801-01	LEFT INBOARD SLAT								
57.140	FGFB133A9 ARG51/574 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57-45-01-900-801-02	RIGHT INBOARD SLAT								
57.140	FGFB143A9 ARG50/574 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57-45-13-900-801-01	LEFT OUTBOARD SLAT								
57.150	FGFB134A3 ARG81/699 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57-45-13-900-801-02	RIGHT OUTBOARD SLAT								
57.150	FGFB144A1 ARG70/673 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-45-25-250-801-01 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 5 AND 10						PKG		
57.255	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			01-JUN-2018 9855:36 5896		
57-45-25-250-801-02 (s)	EDDY CURRENT INSPECTION OF SLAT TRACKS - INSPECTION OF SLAT TRACKS 1 AND 4						PKG		
	PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144	+2m			01-JUN-2018 9855:36 5896		
+ 57-55-00-700-801-01 (s)	CHECK OF THE FLAP LATERAL CLEARANCE						PKG		
57.250	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
57-55-01-900-801-01	LEFT INBOARD FLAP ASSEMBLY								
57.180	FGFB161A3 LE249 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
57-55-01-900-801-02	RIGHT INBOARD FLAP ASSEMBLY								
57.180	FGFB162A3 LE249 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
57-55-05-900-801-01	LEFT OUTBOARD FLAP ASSEMBLY								
57.190	FGFB163A1 LE402 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
57-55-05-900-801-02	RIGHT OUTBOARD FLAP ASSEMBLY								
57.190	FGFB164A1 LE402 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-55-07-220-801-01 (s)	DETAILED INSPECTION OF THE PROTECTION ON THE LEFT WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.160	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 57-55-07-220-801-02 (s)	DETAILED INSPECTION OF THE PROTECTION ON THE RIGHT WING INBOARD / OUTBOARD FLAP JUNCTION FAIRING FRICTION AREAS						PKG		
57.160	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
+ 57-55-11-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE FOREFLAP BRACKETS						PKG		
57.170	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
57-55-13-640-801-01 (s)	GREASING/LUBRICATION OF THE LEFT WING FLAP ROLLERS AND TRACKS						PKG		
	PKG 5	MOS	12	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	800	+40			9855:36 5896		
57-55-13-640-801-02 (s)	GREASING/LUBRICATION OF THE RIGHT WING FLAP ROLLERS AND TRACKS						PKG		
	PKG 5	MOS	12	+1m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	800	+40			9855:36 5896		
+ 57-55-21-250-801-01 (s)	EDDY-CURRENT INSPECTION OF THE FLAP TRACKS 2 AND 5						PKG		
57.200	PKG 31	MOS	72	+2m			01-JUN-2018		
	REF: See Workcard	HRS/MSC AFL	3750				9855:36 5896		
57-60-01-900-801-01	LEFTAILERON								
57.210	F50B151B6	MOS					23-MAR-2000		
	147IA0256	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-01-900-801-02	RIGHT AILERON F50B152B6 144IA0255 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
+ 57-60-05-640-801-01 (s)	PRESSURE LUBRICATION OF THE LEFT AILERON BEARINGS PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
+ 57-60-05-640-801-02 (s)	PRESSURE LUBRICATION OF THE RIGHT AILERON BEARINGS PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		
57-60-05-640-802-01 (s)	LUBRICATION OF THE LEFT AILERON CONTROL SURFACE HINGES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 01-JUN-2018 9855:36 5896		
+ 57-60-05-640-802-02 (s)	LUBRICATION OF THE RIGHT AILERON CONTROL SURFACE HINGES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 01-JUN-2018 9855:36 5896		
57-70-01-900-801-01	LEFT OUTBOARD AIRBRAKE FGFB165A1 654LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57-70-01-900-801-02	LEFT MIDDLE AIRBRAKE FGFB169A1 1295LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-01-900-801-03	LEFT INBOARD AIRBRAKE FGFB167A1 646LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57.230									
57-70-01-900-801-04	RIGHT INBOARD AIRBRAKE FGFB168A1 649LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57.240									
57-70-01-900-801-05	RIGHT MIDDLE AIRBRAKE FGFB166A1 647LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57.240									
57-70-01-900-801-06	RIGHT OUTBOARD AIRBRAKE FGFB169A1 1296LE463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
57.240									
57-70-03-640-801-01 (s)	LUBRICATION OF THE AIRBRAKE HINGES PKG 15 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			PKG 01-JUN-2018 9855:36 5896		
27.400									
572A01	WING TIP LEFT FAIRING FGFB181A5 676HP REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-NOV-2016 9847:51 5893		
572A02	WING TIP RIGHT FAIRING FGFB182A4 475HP REF:	MOS HRS/MSC AFL	O/C				05-DEC-2016 9847:51 5893		

CHAPTER 71 POWER PLANT

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-20-02-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT								
54.060	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-02-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 1 FRONT MOUNT (MANDATORY 5-40)								
54.060 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-02-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT								
54.060	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-02-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 FRONT MOUNTS - ENGINE 3 FRONT MOUNT (MANDATORY 5-40)								
54.060 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-07-250-801-01	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT								
54.070	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-07-250-801-01A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 1 REAR MOUNT (MANDATORY 5-40)								
54.070 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-20-07-250-801-02	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT								
54.070	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
+ 71-20-07-250-801-02A	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE ENGINE 1 AND 3 REAR MOUNTS - ENGINE 3 REAR MOUNT (MANDATORY 5-40)								
54.070 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL APH	11250				23-MAR-2000 0 0 0	11250	
71-20-17-230-801-01	SPECIAL DETAILED INSPECTION NO. 2 ENGINE LEFT HAND FRONT VIBRATION ISOLATOR /REPLACEMENT OF RUBBER CORES								
71.040 LIFE LIMIT	LM833SA13 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	6000	+3%			19-APR-2006 5778:48 3578	11778:48	11958:48
71-20-17-230-801-02	SPECIAL DETAILED INSPECTION NO. 2 ENGINE RIGHT HAND FRONT VIBRATION ISOLATOR /REPLACEMENT OF RUBBER CORES								
71.040 LIFE LIMIT	LM833SA13 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	6000	+3%			19-APR-2006 5778:48 3578	11778:48	11958:48
710801	NO. 2 ENGINE LEFT HAND FRONT VIBRATION ISOLATOR								
71.040	LM833SA13 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
710802	NO. 2 ENGINE RIGHT HAND FRONT VIBRATION ISOLATOR								
71.040	LM833SA13 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712201	NO. 1 ENGINE FORWARD UPPER MOUNT 3071070-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-APR-2008 7501 4649		
712203	NO. 3 ENGINE FORWARD UPPER MOUNT 3071070-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
712204	NO. 1 ENGINE FORWARD LOWER MOUNT 3071070-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
712206	NO. 3 ENGINE FORWARD LOWER MOUNT 3071070-4 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL APH	O/C	TSN:0 TSN:0 TSN:0 TSN:0			23-MAR-2000 0 0 0		
712210	NO. 1 ENGINE AFT MOUNT 3075291-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
712211	NO. 2 ENGINE AFT MOUNT 3075291 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
712212	NO. 3 ENGINE AFT MOUNT 3075291-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE 3060000-4 P112311 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:7104			16-APR-2008 7501 4649		
71EN2	NO. 2 ENGINE 3060000-4 P112312 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:7104			16-APR-2008 7501 4649		
71EN3	NO. 3 ENGINE 3060000-4 P112313 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:6693:48			16-APR-2008 7501 4649		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4									
71-00-00-700-801-01	NO. 1 ENGINE - PERFORM ENGINE STARTING AND SHUTDOWN	MOS HRS/MSC ENC	A/R				13-MAR-2015 9326:59 5596		
+ 710120	NO. 1 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			26-OCT-2017 9478:31 5665	(12478:31) 12850:07	12578:31
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			26-OCT-2017 9478:31 5665		
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			26-OCT-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 714010 (s)	NO. 1 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 26-OCT-2017 9478:31 5665		
+ 715010 (s)	NO. 1 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 26-OCT-2017 9478:31 5665		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4									
71-00-00-700-801-02	NO. 2 ENGINE - PERFORM ENGINE STARTING AND SHUTDOWN REF:	MOS HRS/MSC ENC	A/R				13-MAR-2015 9326:59 5596		
+ 710120	NO. 2 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			27-OCT-2017 9478:31 5665	(12478:31) 12850:07	12578:31
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			PKG 27-OCT-2017 9478:31 5665		
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			PKG 27-OCT-2017 9478:31 5665		
+ 714010 (s)	NO. 2 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 27-OCT-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 715010 (s)	NO. 2 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 27-OCT-2017 9478:31 5665		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4									
71-00-00-700-801-03	NO. 3 ENGINE - PERFORM ENGINE STARTING AND SHUTDOWN REF:	MOS HRS/MSC ENC	A/R				13-MAR-2015 8918:07 5346		
+ 710120	NO. 3 ENGINE - MAJOR PERIODIC INSPECTION (MPI) REF: LMM 72-00-00	MOS HRS/MSC ENC	2500	+100			15-APR-2008 6691:18 4181	(9191:18) 9971:42	9291:18
+ 710130 (s)	NO. 3 ENGINE - INSPECT TAILPIPE/LPT 3 ROTOR ASSEMBLY PKG 3 REF: LMM 72-50-04	MOS HRS/MSC ENC	800	+50			PKG 05-DEC-2016 9067:27 5414		
+ 710140 (s)	NO. 3 ENGINE - INSPECT INLET/FAN AREA PKG 3 REF: LMM 72-00-00	MOS HRS/MSC ENC	800	+50			PKG 05-DEC-2016 9067:27 5414		
+ 714010 (s)	NO. 3 ENGINE - VISUALLY INSPECT ELECTRICAL WIRES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 05-DEC-2016 9067:27 5414		
+ 715010 (s)	NO. 3 ENGINE - VISUALLY INSPECT PLUMBING LINES AND CONNECTIONS PKG 3 REF: LMM 70-00-00	MOS HRS/MSC ENC	800	+50			PKG 05-DEC-2016 9067:27 5414		

CHAPTER 72 ENGINE

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4									
72-00-00-200-006	NO. 1 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-007	NO. 1 ENGINE - ACCIDENT OR INCIDENT							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-008	NO. 1 ENGINE - LIGHTING STRIKE							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-009	NO. 1 ENGINE - OVERTEMPERATURE							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-010	NO. 1 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-011	NO. 1 ENGINE - OVERSPEED							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
72-00-00-200-012	NO. 1 ENGINE - LPC1 BLADE BORESCOPE							24-JUL-1999	
		MOS					0		
	REF: LMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-013	NO. 1 ENGINE - HP IMPELLER BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				24-JUL-1999 0 0		
72-00-00-200-014	NO. 1 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				24-JUL-1999 0 0		
720012	NO. 1 ENGINE - INPUT SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720013	NO. 1 ENGINE - FAN STATOR VANE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720014	NO. 1 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720016	NO. 1 ENGINE - N1 MONOPOLE LEAD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720018	NO. 1 ENGINE - LPT1 SHROUD SEGMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720019	NO. 1 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720110	NO. 1 ENGINE - ACCESSORY GEARBOX 3060827-2 S723 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
720210	NO. 1 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				24-JUL-1999 0 0		
720211	NO. 1 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720212	NO. 1 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720213	NO. 1 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720214	NO. 1 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720215	NO. 1 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720216	NO. 1 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720217	NO. 1 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720218	NO. 1 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
721001	NO. 1 ENGINE - PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				04-JAN-2017		
721002	NO. 1 ENGINE - PERFORM ENGINE PRESERVATION CHECK REF: LMM 72-00-00	DAYS HRS/MSC ENC	O/C				20-JAN-2010 7925:50 5025		
721003	NO. 1 ENGINE - DE-PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				02-FEB-2010 7925:50 5025		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH PKG 5 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50			PKG 26-OCT-2017 9478:31 5665		
725010	NO. 1 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3060625-1 980322904005 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			23-JUL-1999 0 0	(12000) 12229	
725020	NO. 1 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3060611-1 980322901167 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2154:30 TSR:0 TSN:1356 TSR:0			04-NOV-2002 2154:30 1356	(12000) 12229	
725030	NO. 1 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3060671-2 970322903976 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			23-JUL-1999 0 0	(12000) 12229	
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISC 3060841.1 011217200870 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			02-NOV-2002 2134:30 1336	(11336) 11565	
725050	NO. 1 ENGINE - FAN DISC 3060241-1 980322903508 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:4675:30 TSN:2915			20-MAY-2005 4675:30 2915	(20000) 20229	
725060	NO. 1 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 980316005052 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			23-JUL-1999 0 0	(10000) 10229	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 1 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 980316005141	MOS HRS/MSC ENC					23-JUL-1999 0 0		
LIFE LIMIT	REF: GENERIC NO REF		10000	TSN:0 TSN:0				(10000) 10229	
725080	NO. 1 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 980316005074	MOS HRS/MSC ENC					20-MAY-2005 4675:30 2915		
LIFE LIMIT	REF: GENERIC NO REF		20000	TSN:4675:30 TSN:2915				(20000) 20229	
725090	NO. 1 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 990350100354	MOS HRS/MSC ENC					23-JUL-1999 0 0		
LIFE LIMIT	REF: GENERIC NO REF		20000	TSN:0 TSN:0				(20000) 20229	
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 991119500099	MOS HRS/MSC ENC					23-JUL-1999 0 0		
LIFE LIMIT	REF: GENERIC NO REF			TSN:0 TSN:0	O/C			(20000) 20229	
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 1618244923003	MOS HRS/MSC ENC					26-OCT-2017 9478:31 5665		
LIFE LIMIT	REF: GENERIC NO REF		8000	TSN:0 TSN:0				(13665) 13894	
725130	NO. 1 ENGINE - FAN SPINNER 3060242-2 992428000107	MOS HRS/MSC ENC					23-JUL-1999 0 0		
LIFE LIMIT	REF: GENERIC NO REF		20000	TSN:0 TSN:0				(20000) 20229	
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060291-2 980339000050	MOS HRS/MSC ENC					23-JUL-1999 0 0		
LIFE LIMIT	REF: GENERIC NO REF			TSN:0 TSN:0	O/C				

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725150 (s)	NO. 1 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2 REF: LMM 72-70-05	MOS HRS/MSC ENC	600	+50			PKG 26-OCT-2017 9478:31 5665		
725160	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 981903301959 REF: GENERIC NO REF	MOS HRS/MSC ENC	7000	TSN:0 TSN:0			23-JUL-1999 0 0	(7000) 7229	
LIFE LIMIT									
725170	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-1 99P12504 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-JUL-1999 0 0		
725180	NO. 1 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4 05P23450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				26-OCT-2017 9478:31 5665		
725210	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 980322902413 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			23-JUL-1999 0 0	(10000) 10229	
LIFE LIMIT									
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-7 07P11799 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				26-OCT-2017 9478:31 5665		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 98P26450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:19421			15-APR-2008 7104 4430		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-9 13-3300-00088 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C				26-OCT-2017 9478:31 5665		
725250	NO. 1 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 99P12772 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-JUL-1999 0 0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 99P10694 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			23-JUL-1999 0 0		
725270	NO. 1 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 98P18398 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:1942:06			15-APR-2008 7104 4430		
+ 726010	NO. 1 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			26-OCT-2017 9478:31 5665	(15478:31) 15850:07	15678:31
726020	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 26-OCT-2017 9478:31 5665		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-006	NO. 2 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-007	NO. 2 ENGINE - ACCIDENT OR INCIDENT	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-008	NO. 2 ENGINE - LIGHTING STRIKE	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-009	NO. 2 ENGINE - OVERTEMPERATURE	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-010	NO. 2 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-011	NO. 2 ENGINE - OVERSPEED	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-012	NO. 2 ENGINE - LPC1 BLADE BORESCOPE	MOS					24-JUL-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-013	NO. 2 ENGINE - HP IMPELLER BORESCOPE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				24-JUL-1999 0 0		
72-00-00-200-014	NO. 2 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				24-JUL-1999 0 0		
720012	NO. 2 ENGINE - INPUT SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720013	NO. 2 ENGINE - FAN STATOR VANE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720014	NO. 2 ENGINE - OUTER TRANSITION LINER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720016	NO. 2 ENGINE - N1 MONOPOLE LEAD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720018	NO. 2 ENGINE - LPT1 SHROUD SEGMENT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720019	NO. 2 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720110	NO. 2 ENGINE - ACCESSORY GEARBOX 3060827-2 S728 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
720210	NO. 2 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				24-JUL-1999 0 0		
720211	NO. 2 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720212	NO. 2 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720213	NO. 2 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720214	NO. 2 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720215	NO. 2 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720216	NO. 2 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720217	NO. 2 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
720218	NO. 2 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
721001	NO. 2 ENGINE - PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				04-JAN-2017		
721002	NO. 2 ENGINE - PERFORM ENGINE PRESERVATION CHECK REF: LMM 72-00-00	DAYS HRS/MSC ENC	O/C				20-JAN-2010 7925:50 5025		
721003	NO. 2 ENGINE - DE-PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				02-FEB-2010 7925:50 5025		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH PKG 5 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50			PKG 27-OCT-2017 9478:31 5665		
725010	NO. 2 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3060625-1 980322904010 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:4675:30 TSR:0 TSN:2915 TSR:0			07-JUN-2005 4675:30 2915	(12000) 12229	
725020	NO. 2 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3060611-1 980322901163 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			24-JUL-1999 0 0	(12000) 12229	
725030	NO. 2 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3060671-2 980322900812 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:0 TSN:0			24-JUL-1999 0 0	(12000) 12229	
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 041217200697 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			07-JUN-2005 4675:30 2915	(12915) 13144	
725050	NO. 2 ENGINE - FAN DISC 3060241-1 980322903509 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:4675:30 TSR:0 TSN:2915 TSR:0			07-JUN-2005 4675:30 2915	(20000) 20229	
725060	NO. 2 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3060372-1 980316004024 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			24-JUL-1999 0 0	(10000) 10229	

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 2 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 980316005145	MOS HRS/MSC		TSN:0			24-JUL-1999 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	TSN:0			0	(10000) 10229	
725080	NO. 2 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 980316005084	MOS HRS/MSC		TSN:0			24-JUL-1999 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:0			0	(20000) 20229	
725090	NO. 2 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 990350100341	MOS HRS/MSC		TSN:2154:30 TSR:0			08-NOV-2002 2154:30		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:1356 TSR:0			1356	(20000) 20229	
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 991119500105	MOS HRS/MSC	O/C	TSN:0			24-JUL-1999 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 010322908229	MOS HRS/MSC		TSN:0			08-NOV-2002 2154:30		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	TSN:0			1356	(9356) 9585	
725130	NO. 2 ENGINE - FAN SPINNER 3060242-2 992428000046	MOS HRS/MSC		TSN:0			24-JUL-1999 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:0			0	(20000) 20229	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060291-2 980339000255	MOS HRS/MSC	O/C	TSN:0			24-JUL-1999 0		
	REF: GENERIC NO REF	ENC		TSN:0			0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725150 (s)	NO. 2 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2	MOS					PKG		
	REF: LMM 72-70-05	HRS/MSC ENC	600	+50			27-OCT-2017 9478:31 5665		
725160	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1	MOS					24-JUL-1999		
LIFE LIMIT	981903301989 REF: GENERIC NO REF	HRS/MSC ENC	7000	TSN:0			0 0		(7000) 7229
725170	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-1	MOS					24-JUL-1999		
	99P12510 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0			0 0		
725180	NO. 2 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4	MOS					27-OCT-2017		
	06P05410 REF: GENERIC NO REF	HRS/MSC ENC	O/C				9478:31 5665		
725210	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1	MOS					24-JUL-1999		
LIFE LIMIT	980322905707 REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0			0 0		(10000) 10229
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-7	MOS					27-OCT-2017		
	96P07584 REF: GENERIC NO REF	HRS/MSC ENC	O/C				9478:31 5665		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1	MOS					15-APR-2008		
	071756500341 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0			7104 4430		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-9 17-3300-03542 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C				27-OCT-2017 9478:31 5665		
725250	NO. 2 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 99P11278 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 99P10693 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
725270	NO. 2 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 071756500381 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			15-APR-2008 7104 4430		
+ 726010	NO. 2 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			27-OCT-2017 9478:31 5665	(15478:31) 15850:07	15678:31
726020	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 27-OCT-2017 9478:31 5665		

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-006	NO. 3 ENGINE - RENTAL/LOANER ENGINE PRE-REMOVAL SERVICEABILITY AND ENGINE PRESERVATION	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-007	NO. 3 ENGINE - ACCIDENT OR INCIDENT	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-008	NO. 3 ENGINE - LIGHTING STRIKE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-009	NO. 3 ENGINE - OVERTEMPERATURE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-010	NO. 3 ENGINE - SEVERE HAILSTORM, FOD, AND/OR BIRD STRIKE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-011	NO. 3 ENGINE - OVERSPEED	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-012	NO. 3 ENGINE - LPC1 BLADE BORESCOPE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-200-013	NO. 3 ENGINE - HP IMPELLER BORESCOPE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-00-200-014	NO. 3 ENGINE - NO. 4 AND NO.5 BEARING/SEAL RUNNER FAILURE	MOS					10-AUG-1999		
	REF: LMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
720012	NO. 3 ENGINE - INPUT SHAFT	MOS		TSN:0			10-AUG-1999		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								
720013	NO. 3 ENGINE - FAN STATOR VANE	MOS		TSN:0			10-AUG-1999		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								
720014	NO. 3 ENGINE - OUTER TRANSITION LINER	MOS		TSN:0			10-AUG-1999		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								
720016	NO. 3 ENGINE - N1 MONOPOLE LEAD	MOS		TSN:0			10-AUG-1999		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								
720018	NO. 3 ENGINE - LPT1 SHROUD SEGMENT	MOS		TSN:0			10-AUG-1999		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720019	NO. 3 ENGINE - 1ST LPT NOZZLE RETAINING PIN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720110	NO. 3 ENGINE - ACCESSORY GEARBOX 3060827-2 S716 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
720210	NO. 3 ENGINE - CHECK AUTO-IGNITION REF: LMM 72-00-00	DAYS HRS/MSC ENC	N/A				10-AUG-1999 0 0		
720211	NO. 3 ENGINE - LPT2 BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720212	NO. 3 ENGINE - HPT BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720213	NO. 3 ENGINE - FUEL NOZZLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720214	NO. 3 ENGINE - A/G/B BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720215	NO. 3 ENGINE - A/G/B COVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720216	NO. 3 ENGINE - AIR OIL SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720217	NO. 3 ENGINE - ROTOR SEAL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
720218	NO. 3 ENGINE - FUEL PUMP DRIVE GEARSHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
721001	NO. 3 ENGINE - PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				04-JAN-2017		
721002	NO. 3 ENGINE - PERFORM ENGINE PRESERVATION CHECK REF: LMM 72-00-00	DAYS HRS/MSC ENC	O/C				20-JAN-2010 7513:15 4776		
721003	NO. 3 ENGINE - DE-PRESERVATION OF ENGINE REF: LMM 72-00-00	MOS HRS/MSC ENC	O/C				02-FEB-2010 7513:15 4776		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723010 (s)	NO. 3 ENGINE - CHECK CARBON SEAL HEALTH PKG 5 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50			PKG 21-SEP-2012 8206:51 5049		
725010	NO. 3 ENGINE - STAGE 1 LOW PRESSURE TURBINE DISC 3060625-1 980322904003 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:4675:18 TSR:2521 TSN:2915 TSR:1559			01-JUL-2005 4675:30 2915	(12000) 12479	
LIFE LIMIT									
725020	NO. 3 ENGINE - STAGE 2 LOW PRESSURE TURBINE DISC 3060611-1 980322901153 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:4675:30 TSR:2521 TSN:2915 TSR:1559			01-JUL-2005 4675:30 2915	(12000) 12479	
LIFE LIMIT									
725030	NO. 3 ENGINE - STAGE 3 LOW PRESSURE TURBINE DISC 3060671-2 980322903855 REF: GENERIC NO REF	MOS HRS/MSC ENC	12000	TSN:2154:30 TSR:0 TSN:1356 TSR:0			05-NOV-2002 2154:30 1356	(12000) 12479	
LIFE LIMIT									
725040	NO. 3 ENGINE - HIGH PRESSURE TURBINE DISC 3060841-1 041217200727 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			01-JUL-2005 4675:30 2915	(12915) 13394	
LIFE LIMIT									
725050	NO. 3 ENGINE - FAN DISC 3060241-1 980322905803 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:4675:30 TSN:2915			01-JUL-2005 4675:30 2915	(20000) 20479	
LIFE LIMIT									
725060	NO. 3 ENGINE - STAGE 1 LOW PRESSURE COMPRESSOR DISC 3072395-3 980316005046 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			08-AUG-1999 0 0	(10000) 10479	
LIFE LIMIT									

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 3 ENGINE - STAGE 2 LOW PRESSURE COMPRESSOR DISC 3060373-1 990316000910 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0			08-AUG-1999 0 0	(10000) 10479	
725080	NO. 3 ENGINE - STAGE 3 LOW PRESSURE COMPRESSOR DISC 3060374-1 980316005072 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:2154:30 TSR:0 TSN:1356 TSR:0			05-NOV-2002 2154:30 1356	(20000) 20479	
725090	NO. 3 ENGINE - STAGE 4 LOW PRESSURE COMPRESSOR DISC 3075326-5 990350101167 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			08-AUG-1999 0 0	(20000) 20479	
725110	NO. 3 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 991119500093 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-AUG-1999 0 0		
725120	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR IMPELLER 3060371-1 995332200729 REF: GENERIC NO REF	MOS HRS/MSC ENC	8000	TSN:4675:30 TSN:2915			01-JUL-2005 4675:30 2915	(8000) 8479	
725130	NO. 3 ENGINE - FAN SPINNER 3060242-2 992428000057 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	TSN:0 TSN:0			08-AUG-1999 0 0	(20000) 20479	
725140	NO. 3 ENGINE - FAN DRIVE SHAFT 3060291-2 980339000253 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-AUG-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725150 (s)	NO. 3 ENGINE - VISUALLY INSPECT FAN BYPASS DUCT BLEED/SERVICE STRUT BOSS PKG 2	MOS					PKG		
	REF: LMM 72-70-05	HRS/MSC ENC	600	+50			08-SEP-2016 9067:27 5414		
725160	NO. 3 ENGINE - HIGH PRESSURE TURBINE FORWARD ROTATING SEAL 3060698-1 981903301976	MOS					08-AUG-1999 0		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	7000	TSN:0 TSN:0			0	(7000) 7479	
725170	NO. 3 ENGINE - HIGH PRESSURE COMPRESSOR SHOULDERED SHAFT 3060366-1 99P12507	MOS					08-AUG-1999 0		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0		
725180	NO. 3 ENGINE - COMBUSTION CHAMBER PLENUM CASE 3060534-4 99P1135B	MOS					08-AUG-1999 0		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0		
725210	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SEAL PLATE 3060514-1 980322905719	MOS					08-AUG-1999 0		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSN:0 TSN:0			0	(10000) 10479	
725220	NO. 3 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-5 08P02413	MOS					15-APR-2008 6691:18		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			4181		
725230	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE SEAL SUPPORT 3060693-1 98P26456	MOS					15-APR-2008 6691:18		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:4723:03			4181		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725240	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE ASSEMBLY 3060666-7 06P33863 REF: LMM 05-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			15-APR-2008 6691:18 4181		
725250	NO. 3 ENGINE - FORWARD HIGH PRESSURE TURBINE SHAFT COUPLING 3060502-2 99P13972 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-AUG-1999 0 0		
725260	NO. 3 ENGINE - AFT HIGH PRESSURE TURBINE SHAFT COUPLING 3060599-2 99P13924 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			08-AUG-1999 0 0		
725270	NO. 3 ENGINE - LOW PRESSURE TURBINE 1 NOZZLE (A5) SEAL 3073765-12 98P24588 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:4723:03			15-APR-2008 6691:18 4181		
+ 726010	NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI) REF: LMM 72-00-00	MOS HRS/MSC ENC	5000	+200			01-JUL-2005 4675:30 2915	(9675:30) 10455:54	9875:30
726020	NO. 3 ENGINE - TRANSFER GEARBOX ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
727010 (s)	NO. 3 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY PKG 4 REF: See Workcard	MOS HRS/MSC ENC	1200	+100			PKG 08-SEP-2016 9067:27 5414		

CHAPTER 73 ENGINE FUEL AND CONTROL

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-20-01-710-802-01 (s)	OPERATIONAL TEST OF THE ENGINE DIGITAL ELECTRONIC COMPUTER (DEEC) POWER SUPPLY						PKG		
76.160	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737		
733213	NO.1 ENGINE FUEL PRESSURE SWITCH								
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733214	NO.2 ENGINE FUEL PRESSURE SWITCH								
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733215	NO.3 ENGINE FUEL PRESSURE SWITCH								
73.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733225	NO.1 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733226	NO.2 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733227	NO.3 ENGINE FUEL THERMOCOUPLE								
73.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
733801	NO. 1 ENGINE FUEL TEMPERATURE PROBE 56B17 G99226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733802	NO. 2 ENGINE FUEL TEMPERATURE PROBE 56B17 H3101 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733803	NO. 3 ENGINE FUEL TEMPERATURE PROBE 56B17 H04167 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733811	NO.1 ENGINE FUEL FLOW TRANSMITTER 9-231-14 H7181 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733812	NO.2 ENGINE FUEL FLOW TRANSMITTER 9-231-14 H7167 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
733813	NO.3 ENGINE FUEL FLOW TRANSMITTER 9-231-14 H7189 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4

730110	NO. 1 ENGINE - FUEL CONTROL UNIT 3070800-39 17615 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:0			18-APR-2013 8883:49 5408		
--------	--	-----------------------	-----	-------	--	--	--------------------------------	--	--

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730120 (s)	NO. 1 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50			PKG 26-OCT-2017 9478:31 5665		
730130	NO. 1 ENGINE - ENGINE FUEL PUMP 3060760-3 0607 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
731110	NO. 1 ENGINE - PRESSURE LIMITER VALVE 3070685-12 14102 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 745 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
732120	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				24-JUL-1999 0 0		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-39 17028 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:1 TSN:4383:12 TSR:0			27-JAN-2012 8514:01 5254		
730120 (s)	NO. 2 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50			PKG 27-OCT-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730130	NO. 2 ENGINE - ENGINE FUEL PUMP 3060760-3 0609 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
731110	NO. 2 ENGINE - PRESSURE LIMITER VALVE 3070685-12 14136 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 541C REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
732120	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				24-JUL-1999 0 0		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4									
730110	NO. 3 ENGINE - FUEL CONTROL UNIT 3070800-30 13264 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			12-DEC-2014 8902:42 5335		
730120 (s)	NO. 3 ENGINE - REMOVE AND REPLACE FUEL FILTER ELEMENT PKG 2 REF: LMM 73-21-02	MOS HRS/MSC ENC	600	+50			PKG 08-SEP-2016 9067:27 5414		
730130	NO. 3 ENGINE - ENGINE FUEL PUMP 3060760-3 0613 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731110	NO. 3 ENGINE - PRESSURE LIMITER VALVE 3070685-12 14126 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
731120	NO. 3 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 760 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
732120	NO. 3 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE REF: LMM 73-21-04	MOS HRS/MSC ENC	N/A				10-AUG-1999 0 0		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4

740110	NO. 1 ENGINE - IGNITION UNIT 3073914-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 NSN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			26-OCT-2017 9478:31 5665		
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 26-OCT-2017 9478:31 5665		
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 NSN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			26-OCT-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 26-OCT-2017 9478:31 5665		
+ 740210 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITION SYSTEM PKG 2 REF: LMM 74-00-01	MOS HRS/MSC ENC	600	+50			PKG 26-OCT-2017 9478:31 5665		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4									
740110	NO. 2 ENGINE - IGNITION UNIT 3073914-4 SN-UNKNOWN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0		24-JUL-1999 0 0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 NSN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		27-OCT-2017 9478:31 5665		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 27-OCT-2017 9478:31 5665		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 NSN REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		27-OCT-2017 9478:31 5665		
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 5 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50			PKG 27-OCT-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740210 (s)	NO. 2 ENGINE - OPERATIONAL CHECK PKG 2 REF: LMM 74-00-01	IGNITION SYSTEM MOS HRS/MSC ENC	600	+50			PKG 27-OCT-2017 9478:31 5665		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4									
740110	NO. 3 ENGINE - IGNITION UNIT 3061186-1 040218044287 REF: LMM 74-00-01	IGNITION UNIT MOS HRS/MSC ENC	O/C			TSO:0 TSO:0 TSO:0	03-OCT-2013 8625:43 5223		
740130	NO. 3 ENGINE - 5 O'CLOCK IGNITER PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	IGNITER PLUG MOS HRS/MSC ENC	O/C			TSN:0 TSN:0	15-APR-2008 6691:18 4181		
+ 740140 (s)	NO. 3 ENGINE - REMOVE AND INSPECT PKG 5 REF: LMM 74-00-01	5 O'CLOCK IGNITER PLUG AND LEAD MOS HRS/MSC ENC	1600	+50			PKG 20-JUL-2012 8206:51 5049		
740150	NO. 3 ENGINE - 7 O'CLOCK IGNITER PLUG 3074541-4 SN-UNKNOWN REF: LMM 74-00-01	IGNITER PLUG MOS HRS/MSC ENC	O/C			TSN:0	15-APR-2008 6691:18 4181		
+ 740160 (s)	NO. 3 ENGINE - REMOVE AND INSPECT PKG 5 REF: LMM 74-00-01	7 O'CLOCK IGNITER PLUG AND LEAD MOS HRS/MSC ENC	1600	+50			PKG 20-JUL-2012 8206:51 5049		
+ 740210 (s)	NO. 3 ENGINE - OPERATIONAL CHECK PKG 2 REF: LMM 74-00-01	IGNITION SYSTEM MOS HRS/MSC ENC	600	+50			PKG 08-SEP-2016 9067:27 5414		

CHAPTER 75 AIR

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4									
754210	NO. 1 ENGINE - INLET TEMPERATURE SENSOR								
	3070816-14	MOS					24-JUL-1999		
75.010	9918055G8879	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4									
754210	NO. 2 ENGINE - INLET TEMPERATURE SENSOR								
	3070816-14	MOS		TSN:10			21-SEP-2009		
75.010	081789323170	HRS/MSC	O/C	TSN:0			7857:45		
	REF: LMM 75-40-01	ENC		TSN:0			5002		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4									
754210	NO. 3 ENGINE - INLET TEMPERATURE SENSOR								
	3070816-14	MOS					10-AUG-1999		
75.010	9918055G8881	HRS/MSC	O/C	TSN:0			0		
	REF: LMM 75-40-01	ENC		TSN:0			0		
CHAPTER 76 ENGINE CONTROLS									
+ 76-10-00-220-801-01 CHECK OF THE NO. 1 ENGINE THROTTLE LEVERS FOR FRICTION POINTS									
		MOS					01-JUN-2018		
76.010		HRS/MSC	O/C				9855:36		
	REF: See Workcard	AFL					5896		
+ 76-10-00-220-801-02 CHECK OF THE NO. 2 ENGINE THROTTLE LEVERS FOR FRICTION POINTS									
		MOS					01-JUN-2018		
76.010		HRS/MSC	O/C				9855:36		
	REF: See Workcard	AFL					5896		
+ 76-10-00-220-801-03 CHECK OF THE NO. 3 ENGINE THROTTLE LEVERS FOR FRICTION POINTS									
		MOS					01-JUN-2018		
76.010		HRS/MSC	O/C				9855:36		
	REF: See Workcard	AFL					5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10-00-220-802-01	MEASUREMENT OF THE NO. 1 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: See Workcard	MOS HRS/MSC AFL	O/C				16-APR-2008 7501 4649		
76-10-00-220-802-02	MEASUREMENT OF THE NO. 2 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: See Workcard	MOS HRS/MSC AFL	O/C				16-APR-2008 7501 4649		
76-10-00-220-802-03	MEASUREMENT OF THE NO. 3 ENGINE THROTTLE LEVER OPERATING FORCES								
76.110	REF: See Workcard	MOS HRS/MSC AFL	O/C				16-APR-2008 7501 4649		
76-10-01-900-801-01	THROTTLE CONTROL UNIT								
76.090	FGFB771100D8 74 REF:	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
76-10-21-640-802-01 (s)	LUBRICATION OF THE NO. 1 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS								
76.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
76-10-21-640-802-02 (s)	LUBRICATION OF THE NO. 2 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS								
76.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
76-10-21-640-802-03 (s)	LUBRICATION OF THE NO. 3 ENGINE TELEFLEX CONTROL CABLE BALL-JOINTS								
76.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
76-10-21-900-801-01	NO. 1 ENGINE TELEFLEX CONTROL CABLE PN 76.060 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
76-10-21-900-801-02	NO. 3 ENGINE TELEFLEX CONTROL CABLE 4387567 16224 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-JAN-2015 9713:14 5809		
76-10-21-900-802-01	NO. 2 ENGINE TELEFLEX CONTROL CABLE PN 76.070 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
76-10-25-640-801-01 (s)	GREASING OF THE NO. 1 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS PKG 32 76.080 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			PKG 25-JUL-2012 9012:54 5520		
76-10-25-640-801-02 (s)	GREASING OF THE NO. 2 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS PKG 32 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			PKG 26-JUL-2012 9012:54 5520		
76-10-25-640-801-03 (s)	GREASING OF THE NO. 3 ENGINE TORQUE TUBE AND TELEFLEX CABLE END-FITTING BEARINGS PKG 32 76.080 REF: See Workcard	MOS HRS/MSC AFL	144 7500	+2m			PKG 25-JUL-2012 9012:54 5520		
+ 76-10-33-820-801-01 (s)	CHECK NO. 1 ENGINE THROTTLE CABLE TENSION PKG 31 76.120 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			PKG 01-JUN-2018 9855:36 5896		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-10-33-820-801-02 (s)	CHECK NO. 2 ENGINE THROTTLE CABLE TENSION						PKG		
76.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
+ 76-10-33-820-801-03 (s)	CHECK NO. 3 ENGINE THROTTLE CABLE TENSION						PKG		
76.120	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72	+2m			01-JUN-2018 9855:36 5896		
76-10-33-900-801-01	NO. 1 ENGINE THROTTLE CONTROL CABLE								
76.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
76-10-33-900-801-02	NO. 2 ENGINE THROTTLE CONTROL CABLE								
76.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
76-10-33-900-801-03	NO. 3 ENGINE THROTTLE CONTROL CABLE								
76.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
761207	NO. 1 ENGINE POWER LEVER CONTROL								
76.100	4338037 15054 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		
761208	NO. 2 ENGINE POWER LEVER CONTROL								
76.100	4234483 15066 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0		23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761209	NO. 3 ENGINE POWER LEVER CONTROL 4338051	MOS					23-MAR-2000		
76.100	15053 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
762011	NO. 1 ENGINE FUEL SHUTOFF VALVE PN	MOS					23-MAR-2000		
76.130	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
762012	NO. 2 ENGINE FUEL SHUTOFF VALVE PN	MOS					23-MAR-2000		
76.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
762013	NO. 3 ENGINE FUEL SHUTOFF VALVE PN	MOS					23-MAR-2000		
76.150	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0			0 0		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4									
+ 761210	NO. 1 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM 2118882-2009	MOS					20-JUN-2017		
76.010	57-P0012 REF: See Workcard	HRS/MSC ENC	50				9479:31 5665	(9529:31)	9901:07
761310	NO. 1 ENGINE - SURGE BLEED VALVE 978812-7-1	MOS					26-OCT-2017		
76.020	8529 REF: LMM 76-10-01	HRS/MSC ENC	O/C				9478:31 5665		
761320	NO. 1 ENGINE - SOLENOID CONTROL VALVE 109696-6-1	MOS					24-JUL-1999		
76.030	9641 REF: LMM 76-10-01	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761330	NO. 1 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-2009 57-P0012 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			24-AUG-2009 7851:30 4997		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4

+ 761210	NO. 2 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010	2118882-2009 94-AW0038 REF: See Workcard	MOS HRS/MSC ENC	50				20-JUN-2017 9479:31 5665	(9529:31) 9901:07	

761310	NO. 2 ENGINE - SURGE BLEED VALVE								
76.020	978812-6-1 8609 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C				27-OCT-2017 9478:31 5665		

761320	NO. 2 ENGINE - SOLENOID CONTROL VALVE								
76.030	109696-6-1 9628 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		

761330	NO. 2 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL								
76.040	2118882-2009 94-AW0038 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:1 TSR:0 TSR:0			16-NOV-2009 7897:25 5018		

ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4

+ 761210	NO. 3 ENGINE - DOWNLOAD DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL ECTM								
76.010	2118882-2009 59AB0065 REF: See Workcard	MOS HRS/MSC ENC	50				20-JUN-2017 9069:43 5415	(9119:43) 9900:07	

761310	NO. 3 ENGINE - SURGE BLEED VALVE								
76.020	978812-6-1 9953 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
761320	NO. 3 ENGINE - SOLENOID CONTROL VALVE									
76.030	109696-6-1 9629 REF: LMM 76-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0			
761330	NO. 3 ENGINE - DIGITAL ELECTRONIC ENGINE (DEEC) CONTROL									
76.040	2118882-2009 59AB0065 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:4969:06 TSN:3110			19-APR-2006 4969:06 3110			
CHAPTER 77 ENGINE INDICATING										
+ 77-11-00-710-801-01 (s)	OPERATIONAL TEST OF THE " ENG 2 FAIL" WARNING INDICATION						PKG			
77.050	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			03-JUN-2014 9560:43 5737			
+ 77-11-00-710-801-01A	OPERATIONAL TEST OF THE " ENG 2 FAIL" WARNING INDICATION (MANDATORY REF 5-40-00)									
77.050 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	1800				03-JUN-2014 9560:43 5737	11360:43		
77-30-01-900-801-01	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 1 (L2EZ)									
77.080	C12438AB01 550 REF: AMM 77-30-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0			
77-30-01-900-801-02	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 2 (M2EZ)									
77.080	C12438AB01 554 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0			
77-30-01-900-801-03	REMOVAL / INSTALLATION OF THE ENGINE VIBRATION MONITORING COMPUTER (EVMC) - EVMC 3 (R2EZ)									
77.080	C12438AB01 555 REF: AMM 77-30-01-900-801	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0			

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770237	NO. 1 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
770238	NO. 2 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
770239	NO. 3 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4

771210	NO. 1 ENGINE - N1 COMPENSATOR 3060735-7 951309700640 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C				26-OCT-2017 9478:31 5665		
771220	NO. 1 ENGINE - N2 TRANSDUCER 3070722-4 SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
772210	NO. 1 ENGINE - ITT THERMOCOUPLE HARNESS 3060763-4 1616901746146 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			26-OCT-2017 9478:31 5665		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4

771210	NO. 2 ENGINE - N1 COMPENSATOR 3060735-7 991309700583 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C				27-OCT-2017 9478:31 5665		
--------	---	-----------------------	-----	--	--	--	--------------------------------	--	--

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
771220	NO. 2 ENGINE - N2 TRANSDUCER									
77.020	3070722-4 SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0			
772210	NO. 2 ENGINE - ITT THERMOCOUPLE HARNESS									
77.030	3060763-4 1616901746132 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			27-OCT-2017 9478:31 5665			
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4										
771210	NO. 3 ENGINE - N1 COMPENSATOR									
77.010	3060735-6 981309700992 REF: LMM 77-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0			
771220	NO. 3 ENGINE - N2 TRANSDUCER									
77.020	3070722-4 SN-UNKNOWN REF: LMM 77-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0			
772210	NO. 3 ENGINE - ITT THERMOCOUPLE HARNESS									
77.030	3060763-2 071789305729 REF: LMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			15-APR-2008 6691:18 4181			
CHAPTER 78 EXHAUST										
+ 78-30-00-210-801-01 (s)	GENERAL VISUAL INSPECTION OF THE THRUST REVERSER						PKG			
78.010	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 800	+1m +40			01-JUN-2018 9855:36 5896			
+ 78-30-00-720-801-01 (s)	FUNCTIONAL TEST OF THE THRUST REVERSER SYSTEM WITH ENGINE SHUT DOWN						PKG			
78.020	PKG 31 REF: See Workcard	MOS HRS/MSC AFL	72 3750	+2m			01-JUN-2018 9855:36 5896			

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-00-640-802-01	GREASING OF THE THRUST REVERSER DOOR HINGE BOLTS								
78.030	REF: See Workcard	MOS HRS/MSC AFL	12 400	+1m +40			01-JUN-2018 9855:36 5896	01-JUN-2019 10255:36	01-JUL-2019 10295:36
78-31-00-640-803-01 (s)	GREASING OF THE LINK ROD HINGE BOLTS								
78.050	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
78-31-00-640-803-02 (s)	GREASING OF THE DOOR LATCH HOOKS								
78.210	PKG 16 REF: See Workcard	MOS HRS/MSC AFL	24	+1m			PKG 01-JUN-2018 9855:36 5896		
78-31-01-250-801-01	SPECIAL DETAILED INSPECTION LEFT THRUST REVERSER CLAMSHELL DOOR CLOSE OUT FITTING								
78.060	FGFB583701100D3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			27-JUL-2012 9012:54 5520	7520	7580
78-31-01-250-801-02	SPECIAL DETAILED INSPECTION RIGHT THRUST REVERSER CLAMSHELL DOOR CLOSE OUT FITTING								
78.060	FGFB583701200D3 SL040 REF: See Workcard	MOS HRS/MSC AFL	2000	+3%			27-JUL-2012 9012:54 5520	7520	7580
78-31-01-250-801-03	SPECIAL DETAILED INSPECTION LEFT THRUST REVERSER CLAMSHELL DOOR BEAMS AND FITTINGS								
78.060	FGFB583701100D3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			19-APR-2006 5778:48 3578	7578	7698
78-31-01-250-801-04	SPECIAL DETAILED INSPECTION RIGHT THRUST REVERSER CLAMSHELL DOOR BEAMS AND FITTINGS								
78.060	FGFB583701200D3 SL040 REF: See Workcard	MOS HRS/MSC AFL	4000	+3%			3578	7578	7698

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-31-13-900-801-01	THRUST REVERSER CONTROL HYDRAULIC ACTUATOR								
78.070	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
78-31-13-960-801-01	DISCARD THRUST REVERSER UPPER PRIMARY ACTUATOR								
78.110	F2MA581717-015 5695 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-DEC-2007 7254 4505		
78-31-13-960-801-02	DISCARD THRUST REVERSER LOWER PRIMARY ACTUATOR								
78.110	F2MA581717-015 5748 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSI:3978			16-JUN-2006 5918:48 3650		
+ 78-32-00-760-801-01 (s)	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT								
78.080	PKG 21 REF: See Workcard	MOS HRS/MSC AFL	1600	+40			PKG 03-JUN-2014 9560:43 5737		
+ 78-32-00-760-801-01A	TEST OF THE GROUND / FLIGHT RELAY AND TRCU INPUT CIRCUIT (MANDATORY REF 5-40-20)								
78.080 MANDATORY 5-40	REF: See Workcard	MOS HRS/MSC AFL	1800				03-JUN-2014 9560:43 5737	11360:43	
78-32-09-900-801-01	THRUST REVERSER ASSEMBLY								
78.170	FGFB583D1 TR065SL067 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783801	THRUST REVERSER SYSTEM ACCUMULATOR								
78.130	60909-1 EFS9929 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783806	THRUST REVERSER ACCUMULATOR PRESSURE GAUGE								
78.140	GP12-105 90330105 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783811	THRUST REVERSER HYDRAULIC CONTROL VALVE								
78.150	F2MA581792-007 A30040063 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783816	THRUST REVERSER HYDRAULIC PRESSURE SWITCH								
78.160	2365-15 2326 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783826	LEFT THRUST REVERSER CLAMSHELL DOOR								
78.060	FGFB583701100D3 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783831	RIGHT THRUST REVERSER CLAMSHELL DOOR								
78.060	FGFB583701200D3 SL040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				15-APR-2008 7501 4649		
783836	THRUST REVERSER UPPER PRIMARY ACTUATOR								
78.110	F2MA581717-015 5695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-DEC-2007 7254 4505		
783841	THRUST REVERSER LOWER PRIMARY ACTUATOR								
78.110	F2MA581717-015 5748 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSN:3978 TSO:0 TSO:0			16-JUN-2006 5918:48 3650		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783846	UPPER BOX LATCH ACTUATOR								
78.120	DS260-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783851	LOWER BOX LATCH ACTUATOR								
78.120	DS260-1 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
783856	THRUST REVERSER CONTROL UNIT PRINTED CIRCUIT BOARD								
78.200	DS232-101 120 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:1 TSR:0 TSR:0			16-NOV-2009 8294:25 5239		
784801	NO. 2 ENGINE THROTTLE CONTROL LEVER ELECTRO-MAGNET								
78.180	A861TS4RF900 1394 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
784806	THRUST REVERSER CONTROL LEVER ELECTRO-MAGNET								
78.190	A861TS4RF50 1413 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
CHAPTER 79 OIL									
793201	NO. 1 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 279 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793202	NO. 2 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 266 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793203	NO. 3 ENGINE OIL PRESSURE SWITCH								
79.030	8G1529 280 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793213	NO. 1 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 G1258 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAY-2003 2911:24 1803		
793214	NO. 2 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 H03075 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
793215	NO. 3 ENGINE OIL TEMPERATURE PROBE								
79.040	56B17 H03152 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2000 0 0		
793801	NO. 1 ENGINE OIL PRESSURE TRANSMITTER								
79.160	64279-543-1 4510 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793802	NO. 2 ENGINE OIL PRESSURE TRANSMITTER								
79.160	64279-543-1 4313 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793803	NO. 3 ENGINE OIL PRESSURE TRANSMITTER								
79.160	64279-543-1 4508 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793811	NO. 1 ENGINE OIL LEVEL GAUGE 029-907-004 79.170 306 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-AUG-2005 5245:06 3250		
793812	NO. 2 ENGINE OIL LEVEL GAUGE 029-907-004 79.170 2088 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793813	NO. 3 ENGINE OIL LEVEL GAUGE 029-907-004 79.170 2008 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
793816	ENGINE OIL GAUGE AMPLIFIER 360-967-006 79.180 188 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-AUG-2003 3211:48 1996		
793821	ENGINE OIL LEVEL INDICATOR GAUGE 267-968-004 79.190 389 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0			23-MAR-2000 0 0		
ENGINE NO. 1 Model : TFE731-60-1C Serial # P112311 Part # 3060000-4									
790110	NO. 1 ENGINE - OIL PUMP 3060785-2 79.010 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0			20-MAY-2005 4675:30 2915		
+ 790130 (s)	NO. 1 ENGINE - ANALYZE ENGINE OIL AND FILTER PKG 1 79.020 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			PKG 06-NOV-2017 9478:31 5665		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790140 (s)	NO. 1 ENGINE - CHANGE OIL PKG 4	MOS					PKG		
79.030	REF: LMM 72-00-00	HRS/MSC ENC	1200	+100			26-OCT-2017 9478:31 5665		
+ 790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK PKG 2	MOS					PKG		
79.040	REF: See Workcard	HRS/MSC ENC	600	+50			26-OCT-2017 9478:31 5665		
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 1	MOS					PKG		
79.040	REF: See Workcard	HRS/MSC ENC	150	+100			26-OCT-2017 9478:31 5665		
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE PN	MOS							
79.130	SN-UNKNOWN REF: LMM 79-20-08	HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		24-JUL-1999 0 0		
792210	NO. 1 ENGINE - UPPER RIGHT OIL COOLER 160556-5	MOS							
79.050	49-344 REF: LMM 79-20-10	HRS/MSC ENC	O/C		TSN:0 TSN:0		24-JUL-1999 0 0		
792220	NO. 1 ENGINE - UPPER LEFT OIL COOLER 160556-6	MOS							
79.060	49-327 REF: LMM 79-20-10	HRS/MSC ENC	O/C		TSN:0 TSN:0		24-JUL-1999 0 0		
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER 160554-5	MOS							
79.070	19-735 REF: LMM 79-20-10	HRS/MSC ENC	O/C		TSN:0 TSN:0		24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER 160554-6	MOS					24-JUL-1999		
79.080	49-735 REF: LMM 79-20-10	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE 3075323-3	MOS					24-JUL-1999		
79.090	SN-UNKNOWN REF: LMM 79-20-02	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
792260	NO. 1 ENGINE - OIL TEMPERATURE VALVE 158465-6	MOS					24-JUL-1999		
79.100	19-9346 REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
793001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTION UNIT PN	MOS					24-JUL-1999		
79.140	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0			0 0		
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE 3060782-2	MOS					01-AUG-2003		
79.110	30645100732 REF: LMM 79-30-01	HRS/MSC ENC	O/C				2867:24 1799		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH 3060782-2 PKG 4	DAYS		+100			PKG 26-OCT-2017		
79.110	30645100732 REF: LMM 79-30-01	HRS/MSC ENC	1200	+100			9478:31 5665		
793320	NO. 1 ENGINE - FUEL/OIL COOLER 3060709-4	MOS					12-DEC-2014		
79.120	77-531 REF: LMM 79-20-07	HRS/MSC ENC	O/C	TSO:0 TSO:0			9311:34 5585		

ENGINE NO. 2 Model : TFE731-60-1C Serial # P112312 Part # 3060000-4

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
790110	NO. 2 ENGINE - OIL PUMP 3060785-2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				07-JUN-2005 4675:30 2915		
+ 790130 (s)	NO. 2 ENGINE - ANALYZE ENGINE OIL AND FILTER PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			PKG 06-NOV-2017 9478:31 5665		
790140 (s)	NO. 2 ENGINE - CHANGE OIL PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			PKG 27-OCT-2017 9478:31 5665		
+ 790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			PKG 27-OCT-2017 9478:31 5665		
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 1 REF: See Workcard	MOS HRS/MSC ENC	150	+100			PKG 27-OCT-2017 9478:31 5665		
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE PN SN-UNKNOWN REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		24-JUL-1999 0 0		
792210	NO. 2 ENGINE - UPPER RIGHT OIL COOLER 160556-5 19-332 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0		24-JUL-1999 0 0		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792220	NO. 2 ENGINE - UPPER LEFT OIL COOLER 160556-6 48-267 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER 160554-5 48-660 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER 160554-6 49-738 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE 3075323-3 1800 REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSO:7 TSO:0 TSO:0			03-OCT-2013 9034:35 5473		
792260	NO. 2 ENGINE - OIL TEMPERATURE VALVE 158465-6 19-9348 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			24-JUL-1999 0 0		
793001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTION UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			24-JUL-1999 0 0		
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE 3060782-2 070645107906 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2009 7849 4995		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH						PKG		
79.110	3060782-2 PKG 4 070645107906 REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100			27-OCT-2017 9478:31 5665		
793320	NO. 2 ENGINE - FUEL/OIL COOLER								
79.120	160506-4 1057 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C			TSO:3 TSO:0 TSO:0	23-FEB-2015 9326:59 5596		
ENGINE NO. 3 Model : TFE731-60-1C Serial # P112313 Part # 3060000-4									
790110	NO. 3 ENGINE - OIL PUMP								
79.010	3060785-2 021405700144 REF: See Workcard	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0	05-NOV-2002 2154:30 1356		
+ 790130 (s)	NO. 3 ENGINE - ANALYZE ENGINE OIL AND FILTER						PKG		
79.020	PKG 1 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			08-SEP-2016 9067:27 5414		
790140 (s)	NO. 3 ENGINE - CHANGE OIL						PKG		
79.030	PKG 4 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100			08-SEP-2016 9067:27 5414		
+ 790150 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM ELECTRICAL RESISTANCE CHECK						PKG		
79.040	PKG 2 REF: See Workcard	MOS HRS/MSC ENC	600	+50			08-SEP-2016 9067:27 5414		
790160 (s)	NO. 3 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION						PKG		
79.040	PKG 1 REF: See Workcard	MOS HRS/MSC ENC	150	+100			08-SEP-2016 9067:27 5414		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792008	NO. 3 ENGINE - OIL FLOW REDUCTION VALVE								
79.130	PN SN-UNKNOWN REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
792210	NO. 3 ENGINE - UPPER RIGHT OIL COOLER								
79.050	160556-5 49-343 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
792220	NO. 3 ENGINE - UPPER LEFT OIL COOLER								
79.060	160556-6 49-328 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
792230	NO. 3 ENGINE - LOWER LEFT OIL COOLER								
79.070	160-554-5 48-665 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
792240	NO. 3 ENGINE - LOWER RIGHT OIL COOLER								
79.080	3060769-1 9906451A0253 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
792250	NO. 3 ENGINE - PRESSURE BREATHER VALVE								
79.090	3075323-3 SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
792260	NO. 3 ENGINE - OIL TEMPERATURE VALVE								
79.100	158465-6 10104 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0			05-NOV-2002 2154:30 1356		

Status Report

FALCON 900EX S/N 066 (N66FJ): 9855:36 HRS, 5896 AFL as of 01-Jun-2018

Owner/Operator: GLOBAL JET PARTNERS, LLC

Report Date: 08-JUN-2018

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793001	NO. 3 ENGINE - ENGINE OIL CHIP DETECTION UNIT								
79.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			10-AUG-1999 0 0		
793310	NO. 3 ENGINE - OIL FILTER BYPASS VALVE								
79.110	3060782-2 30645100740 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C				01-AUG-2003 2867:24 1799		
+ 793315 (s)	NO. 3 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH								
79.110	3060782-2 PKG 4 30645100740 REF: LMM 79-30-01	DAYS HRS/MSC ENC	1200	+100 +100			PKG 08-SEP-2016 9067:27 5414		
793320	NO. 3 ENGINE - FUEL/OIL COOLER								
79.120	160554-6 49-743 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0			10-AUG-1999 0 0		
CHAPTER 85	FUEL CELL SYSTEMS								
859999	NOTHING TO DO THIS BLOCK ...								
	REF:	MOS HRS/MSC AFL	N/R				28-AUG-2006 6073:48 3760		